

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K008

Asset: P.S. 8 - BROOKLYN, 37 HICKS STREET, New York, 11201

| Inspection Id | Inspection Type | Time In | Last Edited |
|---------------|-----------------|--------------------|--------------------|
| EE : K008 | Electrical | 2024-04-05 7:54 AM | 2024-04-26 9:57 AM |

Asset Data

| Question | Answer |
|---|--|
| Type of Service | Below Ground |
| Does Interactive Whiteboard (IWB) Exist? | Yes |
| Water Penetration in Electrical Room? | No |
| Have any Systems/Major Building Components been upgraded? | Yes |
| | Systems: LAN |
| | Years: 2023 |
| | Systems: Multipurpose Room, Motor Controller (Variable Frequency Drive) |
| | Years: 2022 |
| | Systems: Fire Alarm System (Printer) |
| | Years: 2020 |
| | Systems: Partial Emergency Lighting (Battery Pack), Exit Lights |
| | Years: 2015 |
| | Systems: Pendant Fluorescent Lighting, Surface Fluorescent Lighting, Security Lights |
| | Years: 2011, 2015 |
| | Systems: Recessed Fluorescent Lighting, Gymnasium, Library, Local Sound System, Fire Alarm System, Fused Disconnect Switch Type Panel Board, Public Address System, Intrusion Alarm System, Service Switch |
| | Years: 2011 |
| | Systems: Switchboard |
| | Years: 1985, 2011 |
| | Systems: Molded Case Circuit Breaker Type Panel Board |
| | Years: 1985, 2003, 2011, 2022 |

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

| Question | Response |
|---|----------|
| Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building? | Yes |
| Are dedicated intercoms available in all of these spaces for use during a fire? | Yes |
| Are all dedicated intercoms operational? | Yes |

Priority Condition

| Priority Condition Exist Last Year? | Priority Category | Condition Description | Component Affected | Location Description | Person(s) Notified | Person(s) Title | Status | PhotoImage |
|-------------------------------------|-------------------------------|-----------------------|--|----------------------|--------------------|-----------------|-------------|------------|
| No | Fire Alarm System - Defective | N/A | FIRE ALARM SYSTEM Main Panel Fire Alarm Control Panel (Electronic) | Main Entrance Lobby | Igor Rodionov | Custodian | Sent to DSF | |

Inspection

| Question | Response |
|----------------------|----------------|
| Electrical | |
| AUDITORIUM | Does not Exist |
| CAFETERIA | Inspected |
| Instance on Basement | Inspected |
| Lighting | Inspected |
| Instance on Basement | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K008

| Question | Response |
|--|---------------------------|
| CAFETERIA | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Instance on Basement | Inspected |
| Pendant Mounted | |
| Instance on Basement | Does not Exist |
| Surface Mounted | |
| Instance on Basement | Does not Exist |
| Recessed Mounted | |
| Instance on Basement | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on Basement | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Basement | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Basement | Does not Exist |
| Local Sound System | |
| Instance on Basement | Inspected |
| Installation Year | 2011 |
| Source of Installation | Documented |
| Condition | 4 - Between Fair and Poor |
| Deficiency | AMPLIFIER NOT OPERATIONAL |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPAIR |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Projection System | |
| Instance on Basement | Does not Exist |
| Theater Lighting System | |
| Instance on Basement | Does not Exist |
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | |
| Lighting | |
| Does a Chandelier exist? | No |
| Lighting Fixture - Fluorescent | |
| Pendant Mounted | |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on Basement | Does not Exist |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K008

| Question | Response |
|--|--------------------------|
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | Inspected |
| Lighting | |
| Lighting Fixture - Incandescent | Does not Exist |
| Lighting Fixture - LED | Does not Exist |
| COMPUTER LAB | Does not Exist |
| GYMNASIUM | Inspected |
| Instance on Basement | Inspected |
| Lighting | Inspected |
| Instance on Basement | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Basement | Inspected |
| Pendant Mounted | Does not Exist |
| Instance on Basement | Does not Exist |
| Surface Mounted | Inspected |
| Instance on Basement | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not Exist |
| Instance on Basement | Does not Exist |
| Lighting Fixture - HID | |
| Instance on Basement | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Basement | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Basement | Does not Exist |
| Local Sound System | Inspected |
| Instance on Basement | Inspected |
| Installation Year | 2011 |
| Source of Installation | Documented |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Projection System | Does not Exist |
| Instance on Basement | Does not Exist |
| Scoreboard | Does not Exist |
| Instance on Basement | Does not Exist |
| Theater Lighting System | Does not Exist |
| Instance on Basement | Does not Exist |
| KITCHEN | Inspected |
| Instance on Basement | Inspected |
| Lighting | Inspected |
| Instance on Basement | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Basement | Inspected |
| Pendant Mounted | Does not Exist |
| Instance on Basement | Does not Exist |
| Surface Mounted | Does not Exist |
| Instance on Basement | Does not Exist |
| Recessed Mounted | Inspected |
| Instance on Basement | Inspected |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K008

| Question | Response |
|--|--------------------------|
| KITCHEN | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Recessed Mounted | |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on Basement | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Basement | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Basement | Does not Exist |
| LIBRARY | Inspected |
| Instance on Room 313 | Inspected |
| Lighting | Inspected |
| Instance on Room 313 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 313 | Inspected |
| Pendant Mounted | Inspected |
| Instance on Room 313 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Does not Exist |
| Instance on Room 313 | Does not Exist |
| Recessed Mounted | Does not Exist |
| Instance on Room 313 | Does not Exist |
| Lighting Fixture - HID | |
| Instance on Room 313 | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 313 | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Room 313 | Does not Exist |
| Raceway With Receptacles | Inspected |
| Instance on Room 313 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Projection System | Does not Exist |
| Instance on Room 313 | Does not Exist |
| LOCKER ROOM | Does not Exist |
| MULTIPURPOSE ROOM | Inspected |
| Instance on 1st Floor | Inspected |
| Lighting | Inspected |
| Instance on 1st Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - HID | |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on 1st Floor | Does not Exist |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K008

| Question | Response |
|---|--------------------------|
| MULTIPURPOSE ROOM | |
| Lighting | |
| Lighting Fixture - LED | |
| Instance on 1st Floor | Inspected |
| Pendant Mounted | |
| Instance on 1st Floor | Does not Exist |
| Surface Mounted | |
| Instance on 1st Floor | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Instance on 1st Floor | Does not Exist |
| Local Sound System | |
| Instance on 1st Floor | Inspected |
| Installation Year | 2022 |
| Source of Installation | Documented |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Projection System | |
| Is the projector on a cart or installed on the ceiling? | Ceiling |
| Instance on 1st Floor | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Theater Lighting System | |
| Instance on 1st Floor | Does not Exist |
| SCIENCE DEMO ROOM | |
| Does not Exist | |
| SCIENCE LAB | |
| Inspected | |
| Instance on Room 320 | Inspected |
| Power Panel | No |
| Alternative use | No |
| Lighting | |
| Instance on Room 320 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 320 | Inspected |
| Pendant Mounted | |
| Instance on Room 320 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on Room 320 | Does not Exist |
| Recessed Mounted | |
| Instance on Room 320 | Does not Exist |
| Lighting Fixture - HID | |
| Instance on Room 320 | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 320 | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Room 320 | Does not Exist |
| Emergency Gas Shut-Off Valve | |
| Instance on Room 320 | Does not Exist |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K008

| Question | Response |
|--|--|
| SCIENCE LAB | |
| Emergency Shut-Off Power | Does not Exist |
| Instance on Room 320 | Does not Exist |
| Power Supply | Does not Exist |
| Instance on Room 320 | Does not Exist |
| Projection System | Does not Exist |
| Instance on Room 320 | Does not Exist |
| SCIENCE PREP ROOM | Does not Exist |
| SWIMMING POOL | Does not Exist |
| TOILET ROOM - STAFF | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | Does not Exist |
| Lighting Fixture - Incandescent | Does not Exist |
| Lighting Fixture - LED | Does not Exist |
| TOILET ROOM - STUDENT | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | Does not Exist |
| Lighting Fixture - Incandescent | Does not Exist |
| Lighting Fixture - LED | Does not Exist |
| AUXILIARY SIGNAL/BELL SYSTEM | Inspected |
| Replacement Quantity | 72,000 |
| Replacement Uom | S.F. |
| Condition | 4 - Between Fair and Poor |
| Deficiency | BELL TRANSFORMER PANEL NOT OPERATIONAL |
| Deficiency Location/Instance | Boiler Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE PANEL |
| Urgency of Action | PRIORITY 3 |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K008

| Question | Response |
|---|------------------------------|
| AUXILIARY SIGNAL/BELL SYSTEM | Inspected |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| EMERGENCY DC STANDBY BATTERY POWER | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| EMERGENCY GENERATOR SET | Does not Exist |
| EMERGENCY LIGHT/EXIT LIGHT PANEL | Does not Exist |
| EMERGENCY LIGHTING | Inspected |
| Battery Pack | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Non Battery Pack | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| EXIT LIGHT | Inspected |
| Battery Pack | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | FIXTURE LAMP NOT OPERATIONAL |
| Deficiency Location/Instance | Kitchen |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Non Battery Pack | Does not Exist |
| EXIT/EMERGENCY LIGHT | Does not Exist |
| FIRE ALARM SYSTEM | Inspected |
| Replacement Quantity | 72,000 |
| Replacement Uom | S.F. |
| Bell/Horn | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Strobe | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Manual Pull Station | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Fan Shutdown Control | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Duct Smoke Detector | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Area Smoke Detector | Inspected |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K008

| Question | Response |
|--|------------------------------|
| FIRE ALARM SYSTEM | |
| Area Smoke Detector | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| CO Detector | Does not Exist |
| Heat Detector | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Elevator Recall | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Magnetic Door Holder/Contactor | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Fused Cutout Panel | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Fire Alarm Digital Communicator | Inspected |
| Instance | Main Entrance Lobby |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Silent Knight |
| Equipment | Central Station Communicator |
| Installation Year | 2011 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Main Panel | Inspected |
| Bell At Panel | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Fire Alarm Control Panel (Electronic) | Inspected |
| Instance | Main Entrance Lobby |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | General Electric |
| Equipment | Fire Alarm Control |
| Model | EST 2 |
| Installation Year | 2011 |
| Source of Installation | Documented |
| Deficiency | PANEL DEFECTIVE |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPAIR |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Fire Alarm Control Panel (Standard) | Does not Exist |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K008

| Question | Response |
|---|---------------------------|
| FIRE ALARM SYSTEM | |
| Sub-Panel | Does not Exist |
| Remote Annunciator | Inspected |
| Display Monitor | Does not Exist |
| Panel | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Printer | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Punch Register | Does not Exist |
| Sprinkler Flow/Air Pressure Switch | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Tamper Flow Switch/Chain | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| GROUNDING SYSTEM | |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| INTERCOM SYSTEM | |
| Elevator | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Holding Area | Does not Exist |
| LAN | |
| Local Distribution Frame (I/LDF) | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Main Equipment Rack (MDF) | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| LIGHTNING PROTECTION | |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| MOTOR CONTROLLER | |
| Motor Control Center | Does not Exist |
| Motor Starter/Contactor | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Variable Frequency Drive | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| PANEL BOARD | |
| Fused Disconnect Switch Type | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Fused Knife Switch Type | Does not Exist |
| Fused Toggle Switch Type | Does not Exist |
| Molded Case Circuit Breaker Type | Inspected |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K008

| Question | Response |
|---|----------------------------------|
| PANEL BOARD | |
| Molded Case Circuit Breaker Type | |
| Condition | 3 - Fair |
| Deficiency | PANEL BOARD COVER IS MISSING |
| Deficiency Location/Instance | Boiler Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | PANEL BOARD COVER IS MISSING |
| Deficiency Location/Instance | Cafeteria |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | PANEL BOARD DOOR LOCK IS MISSING |
| Deficiency Location/Instance | Boiler Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| PUBLIC ADDRESS SYSTEM | Inspected |
| Replacement Quantity | 72,000 |
| Replacement Uom | S.F. |
| Instance | Server Room 212 |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Bogen Multicom - 2000 |
| Installation Year | 2011 |
| Source of Installation | Documented |
| Deficiency | CLOCK NOT OPERATIONAL |
| Deficiency Location/Instance | Rooms (C08, 215, 306) |
| Deficiency Quantity | 3 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K008

| Question | Response |
|-------------------------------|--|
| SECURITY | Inspected |
| IPDVS/CCTV System | Does not Exist |
| Intrusion Alarm System | Inspected |
| Replacement Quantity | 72,000 |
| Replacement Uom | S.F. |
| Central Control Panel | Inspected |
| Instance | Custodian's Office |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Vista-128BP |
| Installation Year | 2011 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Infrared Sensor | Inspected |
| Condition | 3 - Fair |
| Deficiency | SENSOR NOT OPERATIONAL |
| Deficiency Location/Instance | Corridor by Room C16, Dietician Office, Cafeteria, Kitchen |
| Deficiency Quantity | 4 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 4 |
| Purpose of Action | LEVEL 3 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Panic Switch | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Remote Annunciator | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Siren/Strobe | Inspected |
| Condition | 3 - Fair |
| Deficiency | SIREN/STROBE NOT ACTIVE |
| Deficiency Location/Instance | Exterior Wall facing Hicks Street, Corridor by Rooms (116, 213, 313), Corridor by (MultiPurpose Room, Gymnasium) |
| Deficiency Quantity | 6 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 4 |
| Purpose of Action | LEVEL 3 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Lighting - Security | Inspected |
| Replacement Uom | EACH |
| Condition | 2 - Between Good and Fair |
| Deficiency | LIGHTING FIXTURE PHOTOCELL NOT OPERATIONAL |
| Deficiency Location/Instance | Roof (Building Perimeter) |
| Deficiency Quantity | 5 |
| Quantity Uom | EACH |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K008

| Question | Response |
|----------------------------|---------------------------|
| SECURITY | |
| Lighting - Security | |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 3 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| SERVICE SWITCH | |
| | Inspected |
| Instance | Electrical Room C04B |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Siemens |
| Equipment | 1600 Amp DP-A |
| Capacity/Size Quantity | 1,600 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2011 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Instance | Electrical Room C04B |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Siemens |
| Equipment | N/A |
| Capacity/Size Quantity | 1,200 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2011 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Instance | Electrical Room C04B |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Siemens |
| Equipment | 600 Amp EDP-A |
| Capacity/Size Quantity | 600 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2011 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Instance | Electrical Room C04B |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Siemens |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K008

| Question | Response |
|-------------------------------------|---------------------------|
| SERVICE SWITCH | |
| Equipment | Fire Pump |
| Capacity/Size Quantity | 400 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2011 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| SWITCHBOARD | |
| | Inspected |
| Number of Spares | 9 |
| Fused Disconnect Switch Type | |
| | Inspected |
| Instance | Boiler Room |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Metropolitan Electric |
| Equipment | N/A |
| Capacity/Size Quantity | 1,200 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size2 Quantity | 1 |
| Capacity/Size2 UOM | Section(S) |
| Source of Capacity/Size | Nameplate |
| Installation Year | 1985 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Instance | Electrical Room C04B |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Siemens |
| Equipment | Switchboard DP-A |
| Capacity/Size Quantity | 1,600 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size2 Quantity | 2 |
| Capacity/Size2 UOM | Section(S) |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2011 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Instance | Electrical Room C04B |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Siemens |
| Equipment | EDP-A |
| Capacity/Size Quantity | 600 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size2 Quantity | 1 |
| Capacity/Size2 UOM | Section(S) |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K008

| Question | Response |
|---|--------------------------|
| SWITCHBOARD | |
| Fused Disconnect Switch Type | |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2011 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Fused Knife Switch Type | |
| | Does not Exist |
| Molded Case Circuit Breaker Type | |
| | Does not Exist |
| TELEPHONE SYSTEM | |
| | Inspected |
| PBX/Intercom | |
| | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Standard | |
| | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| TRANSFORMER | |
| | Does not Exist |