

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K017

Asset: P.S. 17 - BROOKLYN, 208 NORTH 5 STREET, New York, 11211

Inspection Id	Inspection Type	Time In	Last Edited
EE : K017	Electrical	2024-02-02 8:03 AM	2024-06-20 9:17 AM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: LAN, Fire Alarm System (Remote Annunciator Panel)
	Years: 2023
	Systems: Public Address System (Most Clock), Service Switch, Switchboard, Fused Disconnect Switch Type Panel Board, Grounding System, Motor Controller (Variable Frequency Drive, Most Motor Starter/Contactor), Fire Alarm System (Fused Cutout Panel)
	Years: 2021
	Systems: Intrusion Alarm System (Central Control Panel, Infrared Sensor, Partial Remote Annunciator)
	Years: 2019
	Systems: Exit Lights (Battery Pack)
	Years: 2017
	Systems: Telephone System
	Years: 2016
	Systems: LED Lighting
	Years: 2015
	Systems: Auditorium (Local Sound System), Security Lights, Public Address System (Amplifier)
	Years: 2011
	Systems: Science Lab, Intrusion Alarm System
	Years: 2009
	Systems: Emergency Light/Exit Light Panel
	Years: 2005
	Systems: Library
	Years: 2003
	Systems: Interior Fluorescent Lighting, Cafeteria (Retrofitted Fluorescent Lighting)
	Years: 2002
	Systems: Most Molded Case Circuit Breaker Type Panel Board
	Years: 1986, 2000, 2004, 2009, 2016, 2019

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Public Address System - System Defective	The system operates intermittently and stops working periodically.	PUBLIC ADDRESS SYSTEM	General Office	Rafael Rodriguez	Fireman	Sent to DSF	
Yes	Exposed Electrical Wires	N/A	Raceway With Receptacles	Room 302	Rafael Rodriguez	Fireman	Sent to DSF	

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K017

Inspection

Question	Response
Electrical	
AUDITORIUM	Inspected
Instance on 2nd Floor	Inspected
House Lighting	Inspected
Does a Chandelier exist?	No
Instance on 2nd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Inspected
Pendant Mounted	Inspected
Instance on 2nd Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	Does not Exist
Instance on 2nd Floor	Does not Exist
Recessed Mounted	Does not Exist
Instance on 2nd Floor	Does not Exist
Lighting Fixture - HID	
Instance on 2nd Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not Exist
Lighting Fixture - LED	
Instance on 2nd Floor	Does not Exist
Local Sound System	Inspected
Instance on 2nd Floor	Inspected
Installation Year	2011
Source of Installation	Inspector Estimate
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Inspected
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 2nd Floor	Inspected
Condition	5 - Poor
Deficiency	VIDEO PROJECTOR IS NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Theater Lighting System	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K017

Question	Response
AUDITORIUM	
Theater Lighting System	
Instance on 2nd Floor	Inspected
Dimming System	
Instance on 2nd Floor	Does not Exist
Theater Lighting	
Instance on 2nd Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	28
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
CAFETERIA	
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not Exist
Surface Mounted	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	
Instance on 1st Floor	Inspected
Installation Year	1980
Source of Installation	Inspector Estimate
Condition	5 - Poor
Deficiency	AMPLIFIER NOT OPERATIONAL

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K017

Question	Response
CAFETERIA	
Local Sound System	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Projection System	
Instance on 1st Floor	Does not Exist
Theater Lighting System	
Instance on 1st Floor	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	Inspected
Does a Chandelier exist?	Yes
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	
Does not Exist	
Lighting Fixture - HID	
Does not Exist	
Lighting Fixture - Incandescent	
Pendant Mounted	
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K017

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Incandescent	
Pendant Mounted	Inspected
Violations	No violations recorded.
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Does not Exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
COMPUTER LAB	Inspected
Instance on Room 307	Inspected
Power Panel	Yes
Lighting	Inspected
Instance on Room 307	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 307	Inspected
Pendant Mounted	Inspected
Instance on Room 307	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 307	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 307	Does not Exist
Lighting Fixture - HID	
Instance on Room 307	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 307	Does not Exist
Lighting Fixture - LED	
Instance on Room 307	Does not Exist
Raceway With Receptacles	Inspected
Instance on Room 307	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Does not Exist
KITCHEN	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K017

Question	Response
KITCHEN	
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
LIBRARY	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K017

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - Incandescent	
Pendant Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Raceway With Receptacles	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 1st Floor	Does not Exist
LOCKER ROOM	Does not Exist
MULTIPURPOSE ROOM	Inspected
Instance on 1st Floor - East, 1st Floor - West	Inspected
Instance on 5th Floor	Inspected
Lighting	Inspected
Instance on 5th Floor	Inspected
Instance on 1st Floor - East, 1st Floor - West	Inspected
Lighting Fixture - Fluorescent	
Instance on 5th Floor	Inspected
Instance on 1st Floor - East, 1st Floor - West	Inspected
Pendant Mounted	Does not Exist
Instance on 5th Floor	Does not Exist
Instance on 1st Floor - East, 1st Floor - West	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on 5th Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - East, 1st Floor - West	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K017

Question	Response
MULTIPURPOSE ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Instance on 5th Floor	Does not Exist
Instance on 1st Floor - East, 1st Floor - West	Does not Exist
Lighting Fixture - HID	
Instance on 5th Floor	Does not Exist
Instance on 1st Floor - East, 1st Floor - West	Does not Exist
Lighting Fixture - Incandescent	
Instance on 5th Floor	Does not Exist
Instance on 1st Floor - East, 1st Floor - West	Does not Exist
Lighting Fixture - LED	
Instance on 5th Floor	Does not Exist
Instance on 1st Floor - East, 1st Floor - West	Does not Exist
Local Sound System	Does not Exist
Instance on 5th Floor	Does not Exist
Instance on 1st Floor - East, 1st Floor - West	Does not Exist
Projection System	Does not Exist
Instance on 5th Floor	Does not Exist
Instance on 1st Floor - East, 1st Floor - West	Does not Exist
Theater Lighting System	Does not Exist
Instance on 5th Floor	Does not Exist
Instance on 1st Floor - East, 1st Floor - West	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Inspected
Instance on Room 502	Inspected
Power Panel	Yes
Alternative use	No
Lighting	Inspected
Instance on Room 502	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 502	Inspected
Pendant Mounted	Inspected
Instance on Room 502	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on Room 502	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Room 502	Does not Exist
Lighting Fixture - HID	
Instance on Room 502	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 502	Does not Exist
Lighting Fixture - LED	
Instance on Room 502	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K017

Question	Response
SCIENCE LAB	
Emergency Gas Shut-Off Valve	Does not Exist
Instance on Room 502	Does not Exist
Emergency Shut-Off Power	Inspected
Instance on Room 502	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Power Supply	Inspected
Instance on Room 502	Inspected
Instructor Unit	
Instance on Room 502	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 502	Does not Exist
Student Unit	
Instance on Room 502	Does not Exist
Projection System	Does not Exist
Instance on Room 502	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	76,000

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K017

Question	Response
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Does not Exist
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	76,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Strobe	Does not Exist
Manual Pull Station	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Does not Exist
Duct Smoke Detector	Does not Exist
Area Smoke Detector	Does not Exist
CO Detector	Does not Exist
Heat Detector	Does not Exist
Elevator Recall	Does not Exist
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	1 - Good

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K017

Question	Response
FIRE ALARM SYSTEM	
Fused Cutout Panel	Inspected
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not Exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards
Equipment	Fire Alarm Control Panel
Installation Year	1956
Source of Installation	Documented
Deficiency	No deficiencies recorded
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Printer	Does not Exist
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Does not Exist
Tamper Flow Switch/Chain	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K017

Question	Response
MOTOR CONTROLLER	
Variable Frequency Drive	
Condition	2 - Between Good and Fair
Deficiency	VARIABLE FREQUENCY DRIVE NOT OPERATIONAL
Deficiency Location/Instance	Auditorium's Fan Room (GX3, GX-4)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PANEL BOARD	
	Inspected
Fused Disconnect Switch Type	
	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Fused Knife Switch Type	
	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Penthouse's Fan Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Toggle Switch Type	
	Does not Exist
Molded Case Circuit Breaker Type	
	Inspected
Condition	3 - Fair
Deficiency	NO SPARE
Deficiency Location/Instance	2nd Floor Corridor - by Auditorium
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Corridors by (Room 305, Auditorium), Cafeteria, Multipurpose Room - West, Boiler Room
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K017

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	4th Floor - Room 409
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	
	Inspected
Replacement Quantity	76,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	4 - Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	1980
Source of Installation	Inspector Estimate
Deficiency	SYSTEM DEFECTIVE
Deficiency Location/Instance	General Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SECURITY	
	Inspected
IPDVS/CCTV System	
	Does not Exist
Intrusion Alarm System	
	Inspected
Replacement Quantity	76,000
Replacement Uom	S.F.
Central Control Panel	
	Inspected
Instance	Custodian's Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista-128BPT
Installation Year	2019
Source of Installation	Custodial Staff
Deficiency	PANEL NOT CONNECTED TO DOE CENTRAL STATION
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REWIRE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K017

Question	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	Inspected
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Infrared Sensor	
Condition	Inspected
Deficiency	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	
Condition	Inspected
Deficiency	3 - Fair
Deficiency	No deficiencies recorded
Remote Annunciator	
Condition	Inspected
Deficiency	3 - Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
Condition	Inspected
Deficiency	3 - Fair
Deficiency	No deficiencies recorded
Lighting - Security	
Replacement Uom	Inspected
Condition	EACH
Deficiency	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Building Perimeter
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SERVICE SWITCH	
Instance	Inspected
Instance Condition	Electrical Service Room
Instance Quantity	1 - Good
Instance Quantity Uom	1
Instance Manufacturer	EACH
Equipment	Electrotech
Capacity/Size Quantity	MBD 2500A
Capacity/Size UOM	2,500
Source of Capacity/Size	Amps
Installation Year	Nameplate
Source of Installation	2021
Deficiency	Custodial Staff
Deficiency	No deficiencies recorded
SWITCHBOARD	
Number of Spares	Inspected
Number of Spares	16
Fused Disconnect Switch Type	
Instance	Inspected
Instance Condition	Electrical Service Room
Instance Quantity	1 - Good
Instance Quantity Uom	1
Instance Quantity Uom	EACH

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K017

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Instance Manufacturer	Electrotech
Equipment	SERV SWITCHBOARD
Capacity/Size Quantity	2,500
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	4
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2021
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	
	Inspected
PBX/Intercom	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Standard	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	
	Does not Exist