

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K050

Asset: J.H.S. 50 - BROOKLYN, 183 SOUTH 3RD STREET, New York, 11211

Inspection Id	Inspection Type	Time In	Last Edited
EE : K050	Electrical	2024-01-31 8:18 AM	2024-02-07 2:48 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: LAN (MDF, Partial I/LDF), Auditorium (Local Sound System, Projection System)
	Years: 2023
	Systems: Fire Alarm System (Printer), Gymnasium (Scoreboard, Local Sound System)
	Years: 2022
	Systems: Intrusion Alarm System (Central Control Panel, Remote Annunciator, Infrared Sensors), Public Address System (Amplifier)
	Years: 2021
	Systems: Library
	Years: 2018
	Systems: Interior Lighting - Except (Library, Science Lab, Science Prep Room), Auditorium (Theater Lighting System)
	Years: 2013
	Systems: IPDVS/CCTV System
	Years: 2012
	Systems: Science Lab, Science Prep Room
	Years: 2010
	Systems: Security Lights
	Years: 2006, 2020
	Systems: Fire Alarm System, Public Address System, Cafeteria (Local Sound System), Switchboard
	Years: 2006
	Systems: Emergency Light/Exit Light Panel
	Years: 1999
	Systems: Most Molded Case Circuit Breaker Type Panel Board
	Years: 1990, 1999, 2006, 2010, 2013

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	No
Which spaces do not have dedicated intercoms?	Rooms 115, 215, 315, 415, 515

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Local Sound System - Not Connected to Public Address System	N/A	GYMNASIUM Local Sound System	Gymnasium	Ignacio Espinal	Fireman	Sent to DSF	

Inspection

Question	Response
----------	----------

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K050

Question	Response
Electrical	
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	Inspected
Does a Chandelier exist?	No
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2023
Source of Installation	Custodial Staff
Condition	1 - Good
Deficiency	No deficiencies recorded
Projection System	Inspected
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Theater Lighting System	Inspected
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CAFETERIA	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K050

Question	Response
CAFETERIA	
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not Exist
Surface Mounted	
Instance on 1st Floor	Does not Exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	
Instance on 1st Floor	Inspected
Installation Year	2006
Source of Installation	Inspector Estimate
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not Exist
Theater Lighting System	
Instance on 1st Floor	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Lighting Fixture - Incandescent	
Lighting Fixture - LED	
COMPUTER LAB	
Does not Exist	
GYMNASIUM	
Instance on 3rd Floor	Inspected
Lighting	
Inspected	

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K050

Question	Response
GYMNASIUM	
Lighting	
Instance on 3rd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 3rd Floor	Does not Exist
Lighting Fixture - HID	
Instance on 3rd Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 3rd Floor	Does not Exist
Lighting Fixture - LED	
Instance on 3rd Floor	Inspected
Pendant Mounted	
Instance on 3rd Floor	Does not Exist
Surface Mounted	
Instance on 3rd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 3rd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Local Sound System	
Instance on 3rd Floor	Inspected
Installation Year	2022
Source of Installation	Custodial Staff
Condition	1 - Good
Deficiency	NOT CONNECTED TO PUBLIC ADDRESS SYSTEM
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Projection System	
Instance on 3rd Floor	Does not Exist
Scoreboard	
Instance on 3rd Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 3rd Floor	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K050

Question	Response
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
LIBRARY	Inspected
Instance on Room 303	Inspected
Lighting	Inspected
Instance on Room 303	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 303	Does not Exist
Lighting Fixture - HID	
Instance on Room 303	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 303	Does not Exist
Lighting Fixture - LED	
Instance on Room 303	Inspected
Pendant Mounted	Inspected
Instance on Room 303	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on Room 303	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Instance on Room 303	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Raceway With Receptacles	Does not Exist
Instance on Room 303	Does not Exist
Projection System	Does not Exist
Instance on Room 303	Does not Exist
LOCKER ROOM	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K050

Question	Response
LOCKER ROOM	
Instance on 4th Floor - Boys, 4th Floor - Girls	Inspected
Alternative use	No
Lighting	Inspected
Instance on 4th Floor - Boys, 4th Floor - Girls	Inspected
Lighting Fixture - Fluorescent	
Instance on 4th Floor - Boys, 4th Floor - Girls	Inspected
Pendant Mounted	
Instance on 4th Floor - Boys, 4th Floor - Girls	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 4th Floor - Boys, 4th Floor - Girls	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 4th Floor - Boys, 4th Floor - Girls	Does not Exist
Lighting Fixture - HID	
Instance on 4th Floor - Boys, 4th Floor - Girls	Does not Exist
Lighting Fixture - Incandescent	
Instance on 4th Floor - Boys, 4th Floor - Girls	Does not Exist
Lighting Fixture - LED	
Instance on 4th Floor - Boys, 4th Floor - Girls	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Inspected
Instance on Room 523	Inspected
Power Panel	Yes
Alternative use	No
Lighting	Inspected
Instance on Room 523	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 523	Inspected
Pendant Mounted	
Instance on Room 523	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 523	Does not Exist
Recessed Mounted	
Instance on Room 523	Does not Exist
Lighting Fixture - HID	
Instance on Room 523	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 523	Inspected
Pendant Mounted	
Instance on Room 523	Does not Exist
Surface Mounted	
Instance on Room 523	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K050

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Incandescent	
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Room 523	Does not Exist
Lighting Fixture - LED	
Instance on Room 523	Does not Exist
Emergency Gas Shut-Off Valve	
Instance on Room 523	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 523	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 523	Does not Exist
Projection System	
Instance on Room 523	Does not Exist
SCIENCE PREP ROOM	
Instance on Room 521	Inspected
Power Panel	No
Alternative use	No
Lighting	
Instance on Room 521	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 521	Inspected
Pendant Mounted	
Instance on Room 521	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 521	Does not Exist
Recessed Mounted	
Instance on Room 521	Does not Exist
Lighting Fixture - HID	
Instance on Room 521	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 521	Does not Exist
Lighting Fixture - LED	
Instance on Room 521	Does not Exist
Emergency Gas Shut-Off Valve	
Instance on Room 521	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 521	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K050

Question	Response
SCIENCE PREP ROOM	
Emergency Shut-Off Power	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Power Supply	Does not Exist
Instance on Room 521	Does not Exist
SWIMMING POOL	
	Does not Exist
TOILET ROOM - STAFF	
	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	
	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	
	Inspected
Replacement Quantity	115,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	
	Does not Exist
EMERGENCY GENERATOR SET	
	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	
	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K050

Question	Response
EMERGENCY LIGHTING	Inspected
Non Battery Pack	Inspected
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Corridors by Rooms (417, B9), 1st Floor - Exit 6 Vestibule
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Corridors - by Rooms (515, 203, 140, 111), 2nd Floor - Room 230, Boys Locker Room, Girls Locker Room
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
EXIT/EMERGENCY LIGHT	Does not Exist
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	115,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
CO Detector	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K050

Question	Response
FIRE ALARM SYSTEM	
Heat Detector	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Elevator Recall	Does not Exist
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards System Technology
Equipment	Fire Alarm Control Panel
Model	EST 2
Installation Year	2006
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	2 - Between Good and Fair

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K050

Question	Response
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not Exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	NO SPARE
Deficiency Location/Instance	3rd Floor - Room 313
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	5th Floor Corridor - by Room 530
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	115,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	2006
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
SECURITY	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K050

Question	Response
SECURITY	
IPDVS/CCTV System	Inspected
Replacement Quantity	115,000
Replacement Uom	S.F.
Installation Year	2012
Source of Installation	Inspector Estimate
Condition	2 - Between Good and Fair
Deficiency	MONITOR NOT OPERATIONAL
Deficiency Location/Instance	Security Desk (Main Entrance Lobby)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Intrusion Alarm System	Inspected
Replacement Quantity	115,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista-128BPT
Installation Year	2021
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3 - Fair
Deficiency	SIREN/STROBE NOT ACTIVE
Deficiency Location/Instance	Exterior Wall - facing South 3rd Street
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting - Security	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K050

Question	Response
SECURITY	Inspected
Lighting - Security	
Replacement Uom	EACH
Condition	1 - Good
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room B14
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	N/A
Equipment	Sect A
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Inspector Estimate
Installation Year	1959
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room B14
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	N/A
Equipment	Sect B
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Inspector Estimate
Installation Year	1959
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	0
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Instance	Electrical Room B14
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	DB-1 Section A
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2006
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K050

Question	Response
SWITCHBOARD	
Molded Case Circuit Breaker Type	
Instance	Electrical Room B14
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	DB-1 Section B
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2006
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3 - Fair
Deficiency	TELEPHONE MISSING
Deficiency Location/Instance	5th Floor - Room 502
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL TELEPHONE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Standard	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist