

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K066

Asset: P.S. 66 - BROOKLYN, 845 EAST 96TH STREET, New York, 11236

Inspection Id	Inspection Type	Time In	Last Edited
EE : K066	Electrical	2024-03-19 8:14 AM	2024-04-01 2:48 PM


Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Fire Alarm System, IPDVS/CCTV System
	Years: Under Construction
	Systems: LAN, Auditorium (Local Sound System, Projection System)
	Years: 2023
	Systems: Science Lab - Room 308, Science Prep Room 310
	Years: 2009
	Systems: All Other Electrical Systems and Components
	Years: 2003

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
Yes	Lightning Protection - Lightning Air Terminal (Rod) Defective	N/A	LIGHTNING PROTECTION	Gymnasium Roof	Yubar Hunter	Fireman	Sent to DSF	

Inspection

Question	Response
Electrical	
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	Inspected
Does a Chandelier exist?	No
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on 1st Floor	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K066

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not Exist
Surface Mounted	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	
Instance on 1st Floor	Inspected
Installation Year	2023
Source of Installation	Custodial Staff
Condition	1 - Good
Deficiency	No deficiencies recorded
Projection System	
Is the projector on a cart or installed on the ceiling?	Cart
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K066

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not Exist
Surface Mounted	
Instance on 1st Floor	Does not Exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	
Instance on 1st Floor	Inspected
Installation Year	2003
Source of Installation	Documented
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not Exist
Theater Lighting System	
Instance on 1st Floor	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Pendant Mounted	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K066

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	
Lighting Fixture - HID	Inspected
Recessed Mounted	
Deficiency	No deficiencies recorded
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
COMPUTER LAB	Inspected
Instance on Room 217	Inspected
Power Panel	Yes
Lighting	Inspected
Instance on Room 217	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 217	Inspected
Pendant Mounted	Does not Exist
Instance on Room 217	Does not Exist
Surface Mounted	Does not Exist
Instance on Room 217	Does not Exist
Recessed Mounted	Inspected
Instance on Room 217	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 217	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 217	Does not Exist
Lighting Fixture - LED	
Instance on Room 217	Does not Exist
Raceway With Receptacles	Inspected
Instance on Room 217	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
Instance on 2nd Floor	Inspected
Lighting	Inspected
Instance on 2nd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Does not Exist
Lighting Fixture - HID	
Instance on 2nd Floor	Inspected
Pendant Mounted	Inspected
Instance on 2nd Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on 2nd Floor	Does not Exist
Recessed Mounted	Does not Exist
Instance on 2nd Floor	Does not Exist
Lighting Fixture - Incandescent	

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K066

Question	Response
GYMNASIUM	
Lighting	Inspected
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not Exist
Lighting Fixture - LED	
Instance on 2nd Floor	Does not Exist
Local Sound System	Inspected
Instance on 2nd Floor	Inspected
Installation Year	2003
Source of Installation	Documented
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 2nd Floor	Does not Exist
Scoreboard	Does not Exist
Instance on 2nd Floor	Does not Exist
Theater Lighting System	Does not Exist
Instance on 2nd Floor	Does not Exist
KITCHEN	
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
LIBRARY	
Instance on Room 215	Inspected
Lighting	Inspected
Instance on Room 215	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 215	Inspected
Pendant Mounted	Does not Exist
Instance on Room 215	Does not Exist
Surface Mounted	Does not Exist
Instance on Room 215	Does not Exist
Recessed Mounted	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K066

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Instance on Room 215	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 215	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 215	Does not Exist
Lighting Fixture - LED	
Instance on Room 215	Does not Exist
Raceway With Receptacles	Inspected
Instance on Room 215	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on Room 215	Does not Exist
LOCKER ROOM	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Inspected
Instance on Room 218	Inspected
Power Panel Alternative use	No No
Instance on Room 308	Inspected
Power Panel Alternative use	No No
Lighting	Inspected
Instance on Room 308	Inspected
Instance on Room 218	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 308	Inspected
Instance on Room 218	Inspected
Pendant Mounted	Does not Exist
Instance on Room 308	Does not Exist
Instance on Room 218	Does not Exist
Surface Mounted	Does not Exist
Instance on Room 308	Does not Exist
Instance on Room 218	Does not Exist
Recessed Mounted	Inspected
Instance on Room 308	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 218	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 308	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K066

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - HID	
Instance on Room 218	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 308	Inspected
Instance on Room 218	Does not Exist
Pendant Mounted	
Instance on Room 308	Does not Exist
Surface Mounted	
Instance on Room 308	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 308	Does not Exist
Lighting Fixture - LED	
Instance on Room 308	Does not Exist
Instance on Room 218	Does not Exist
Emergency Gas Shut-Off Valve	
Instance on Room 308	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 218	Does not Exist
Emergency Shut-Off Power	
Instance on Room 308	Does not Exist
Instance on Room 218	Does not Exist
Power Supply	
Instance on Room 308	Does not Exist
Instance on Room 218	Does not Exist
Projection System	
Instance on Room 308	Does not Exist
Instance on Room 218	Does not Exist
SCIENCE PREP ROOM	
Instance on Room 310	Inspected
Power Panel Alternative use	No No
Instance on Room 216	Inaccessible
Lighting	
Instance on Room 310	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 310	Inspected
Pendant Mounted	
Instance on Room 310	Does not Exist
Surface Mounted	
Instance on Room 310	Does not Exist
Recessed Mounted	
Instance on Room 310	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K066

Question	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - HID	
Instance on Room 310	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 310	Does not Exist
Lighting Fixture - LED	
Instance on Room 310	Does not Exist
Emergency Gas Shut-Off Valve	Inspected
Instance on Room 310	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	Does not Exist
Instance on Room 310	Does not Exist
Power Supply	Does not Exist
Instance on Room 310	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	106,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Basement - EMER. POWER DIST. ROOM B02A

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K066

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	N/A
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Basement - EMER. POWER DIST. ROOM B02A
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	Fire Alarm Automatic Transfer Switch
Capacity/Size Quantity	30
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Basement - Sprinkler Booster Room B16
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Master Control Systems
Equipment	Transfer Switch
Capacity/Size Quantity	40
Capacity/Size UOM	HP
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
Battery Charger	Inspected
Instance	Penthouse - EMER. GENERATOR ROOM P01B
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Charles Industries
Equipment	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size2 Quantity	24
Capacity/Size2 UOM	VDC
Source of Capacity/Size	Nameplate

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K066

Question	Response
EMERGENCY GENERATOR SET	
Battery Charger	Inspected
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
Emergency Distribution Board	Inspected
Number of Spares	6
Fused Disconnect Switch Type	Inspected
Instance	Basement - EMER. POWER DIST. ROOM B02A
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	EMDB
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Emergency Distribution Board Mains Size
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
Molded Case Circuit Breaker Type	Does not Exist
Diesel	Inspected
Instance	Penthouse - EMER. GENERATOR ROOM P01B
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Caterpillar
Equipment	Emergency Generator
Capacity/Size Quantity	500
Capacity/Size UOM	KVA
Capacity/Size2 Quantity	400
Capacity/Size2 UOM	KW
Capacity/Size3Quantity	1,388
Capacity/Size3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
Natural Gas	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Does not Exist
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K066

Question	Response
EXIT LIGHT	Inspected
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Does not Exist
FIRE ALARM SYSTEM	Under Construction
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Holding Area	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	3 - Fair
Deficiency	LIGHTNING AIR TERMINAL (ROD) DEFECTIVE
Deficiency Location/Instance	Gymnasium Roof
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo 1	No photo recorded
Violations	No violations recorded.
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not Exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	106,000

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K066

Question	Response
PUBLIC ADDRESS SYSTEM	
Replacement Uom	S.F.
Instance	Telecommunication Room 115
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland Telecenter
Installation Year	2003
Source of Installation	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	13
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SECURITY	Inspected
IPDVS/CCTV System	Under Construction
Intrusion Alarm System	Inspected
Replacement Quantity	106,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Room B07 (Old Custodian's Office)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista-128BP
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3 - Fair
Deficiency	SENSOR NOT OPERATIONAL
Deficiency Location/Instance	Room B11
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Panic Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K066

Question	Response
SECURITY	
Intrusion Alarm System	Inspected
Siren/Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Replacement Uom	EACH
Condition	4 - Between Fair and Poor
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Exterior Walls and Roof (Building Perimeter)
Deficiency Quantity	23
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SERVICE SWITCH	Inspected
Instance	Electrical Service Room B02
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	SERVICE SWITCH #1B
Capacity/Size Quantity	2,500
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Service Room B02
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	SERVICE SWITCH #2B
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Service Room B02
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	SERVICE SWITCH #3A
Capacity/Size Quantity	1,200

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K066

Question	Response
SERVICE SWITCH	
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Service Room B02
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	SERVICE SWITCH #4A
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Service Room B02
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	SERVICE SWITCH #5A
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Service Room B02
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	Fire Pump
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	14
Fused Disconnect Switch Type	Inspected
Instance	Electrical Service Room B02
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K066

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Instance Manufacturer	All City Switchboard
Equipment	DISTRIBUTION SECTION "MDB" SECTION #1, #2, #3
Capacity/Size Quantity	2,500
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Service Room B02
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	PHA SECTION #1, #2
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist