# **Building Condition Assessment Survey 2023 - 2024**

Inspection I	d Inspection	п Туре				Time In		Last Edited
EE : K0	67 Electrical					2024-02-1	4 8:19 AM	2024-02-20 3:03 PN
sset Data								
Question					Answer			
Type of Servi	ce				Below Grou	ınd		
Does Interacti	ive Whiteboard	(IWB) Exist?			Yes			
Water Penetra	ntion in Electric	al Room?			No			
Have any Sys	tems/Major Bui	lding Components b	een upgraded?		Yes			
					Systems:	Security Lights		
					Years:	2023		
					Systems:	LAN, Motor Cont	roller (Variabl	e Frequency Drive)
					Years:	2022		
					Systems:	LED Lighting (Gy Floor Locker Roo		ltipurpose Room), 4th t Lighting)
					Years:	2016		
					Systems:	•	n, Public Addr	ess System (Amplifier)
					Years:	2015		
					Systems:	Motor Controller	(Most Motor S	tarter/Contactor)
					Years:	2014		
					Systems: Years:	Interior Fluoresce 2012	nt Lighting - E	xcept (Kitchen, Cafeteri
							vatam I agal C	ound Crystam
					Systems: Years:	Public Address Sy 2004	stem, Local St	ound System
					Systems:			Kitchen), Partial Servic
					Years:	2003	riciooaru	
					Systems:	Emergency Light/	Evit Light Pan	el
					Years:	2001	LAR LIGHT I an	ici
					Systems:	Auditorium (Thea	ter Lighting Sy	vetem)
					Years:	1998	ici Lighting 5	ystem)
					Systems:		se Circuit Bre	aker Type Panel Board
					Years:	1996, 2000, 2007,		and Type Tune Board
DEDICATE	D INTERCOM	S IN FIRE RESCU	JE AREAS				· -	
Question					Response			
	Life Rescue A	ssistance Areas, Fire	e Rescue Areas,		No			
riority Conditi								
Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Emergency Lighting - Battery Not Operational	All Emergency Lighting in Gymnasium were not working.	EMERGENCY LIGHTING   Battery Pack	Gymnasium, Cafeteria, Multipurpose Room	Cedric Holmes	Fireman	Sent to DSF	
nspection								
Question					Response	e		
Electrical								
AUDITORIU	J <b>M</b>				Inspected			
	tance on 1st Flo	oor			Inspected			
			Inspected					
House Lighting  Does a Chandelier exist?			mspecieu					

# **Building Condition Assessment Survey 2023 - 2024**

icai inspection	13
stion	Response
UDITORIUM	
House Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	
Condition	Inspected 3 - Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	8 EACH
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	36
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2004
Source of Installation	Inspector Estimate
Condition	4 - Between Fair and Poor
	AMPLIFIER NOT OPERATIONAL
Deficiency Deficiency Quantity	AMPLIFIER NOT OPERATIONAL  1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 2
Orgency of Action	LEVEL 2
Purpose of Action	LEVEL 2
Purpose of Action	No photo recorded
Deficiency Photo1	No photo recorded
	No photo recorded  No violations recorded.  Does not Exist

# **Building Condition Assessment Survey 2023 - 2024**

estion	Response
AUDITORIUM	
Theater Lighting System	Inspected
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Does not Exist
Theater Lighting	Does not Exist
Instance on 1st Floor	Increased
Condition	Inspected 3 - Fair
Deficiency	No deficiencies recorded
CAFETERIA	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2004
Source of Installation	Inspector Estimate
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 1st Floor	Does not Exist
Theater Lighting System	Does not Exist
Instance on 1st Floor	Does not Exist
instance on 1st 1 tool	Does not Daist

# **Building Condition Assessment Survey 2023 - 2024**

ilear inspection		
estion	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting	Inspected	
Does a Chandelier exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Inspected	
Pendant Mounted	Inspected	
Condition	3 - Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	59	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Surface Mounted	Inspected	
Condition	3 - Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	33	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Recessed Mounted	Inspected	
Condition	3 - Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	4	
Quantity Uom	EACH PERMACE LIBERADE	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Deficiency Photo1 Violations	No photo recorded  No violations recorded.	
Lighting Fixture - LED	Does not Exist	
OMPUTER LAB	Inspected	
Instance on Room 233	Inspected	
Power Panel	No	
Lighting	Inspected	
Instance on Room 233	Inspected	

# **Building Condition Assessment Survey 2023 - 2024**

estion	Response	
COMPUTER LAB		
Lighting		
Lighting Fixture - Fluorescent		
Instance on Room 233	Inspected	
Pendant Mounted	Inspected	
Instance on Room 233	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Instance on Room 233	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	
Instance on Room 233	Does not Exist	
Lighting Fixture - HID	DOGS HOLDAIST	
Instance on Room 233	Does not Exist	
Lighting Fixture - Incandescent	Does not Daist	
Instance on Room 233	Does not Exist	
	Does not Exist	
Lighting Fixture - LED	D	
Instance on Room 233	Does not Exist	
Raceway With Receptacles	Inspected	
Instance on Room 233	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
SYMNASIUM	Inspected	
Instance on 4th Floor	Inspected	
Lighting	Inspected	
Instance on 4th Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 4th Floor	Does not Exist	
Lighting Fixture - HID		
Instance on 4th Floor	Does not Exist	
Lighting Fixture - Incandescent		
Instance on 4th Floor	Does not Exist	
Lighting Fixture - LED		
Instance on 4th Floor	Inspected	
Pendant Mounted	Does not Exist	
Instance on 4th Floor	Does not Exist	
Surface Mounted	Does not Exist	
Instance on 4th Floor	Does not Exist  Does not Exist	
Recessed Mounted	Inspected	
Instance on 4th Floor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System	Inspected	
Instance on 4th Floor	Inspected	
Installation Year	2004	
Source of Installation	Inspector Estimate	

# **Building Condition Assessment Survey 2023 - 2024**

Question	Response
GYMNASIUM	
Local Sound System	
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Projection System	Does not Exist
Instance on 4th Floor	Does not Exist
Scoreboard	Does not Exist
Instance on 4th Floor	Does not Exist
Theater Lighting System	Does not Exist
Instance on 4th Floor	Does not Exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
LIBRARY	Does not Exist
LOCKER ROOM	Inspected
Instance on 4th Floor - Mezzanine	Inspected
Alternative use	Yes
Instance on 4th Floor	Inaccessible
Lighting Instance on 4th Floor - Mezzanine	Inspected
	Inspected
Lighting Fixture - Fluorescent	December Print
Instance on 4th Floor - Mezzanine	Does not Exist
Lighting Fixture - HID	D. (P.)
Instance on 4th Floor - Mezzanine	Does not Exist
Lighting Fixture - Incandescent	
Instance on 4th Floor - Mezzanine	Inspected

# **Building Condition Assessment Survey 2023 - 2024**

estion	Response
LOCKER ROOM	
Lighting	
Lighting Fixture - Incandescent	
Pendant Mounted	Does not Exist
Instance on 4th Floor - Mezzanine	Does not Exist
Surface Mounted	Inspected
Instance on 4th Floor - Mezzanine	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Does not Exist
Instance on 4th Floor - Mezzanine	Does not Exist
Lighting Fixture - LED	
Instance on 4th Floor - Mezzanine	Does not Exist
MULTIPURPOSE ROOM	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	
Instance on 1st Floor	Inspected
Condition	Inspected  2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Local Sound System	Inspected
Instance on 1st Floor Installation Year	Inspected 2004
Source of Installation	Inspector Estimate
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 1st Floor	Does not Exist

#### **Building Condition Assessment Survey 2023 - 2024**

**Electrical Inspection** K067 Ouestion Response MULTIPURPOSE ROOM Inspected **Theater Lighting System** Instance on 1st Floor Does not Exist SCIENCE DEMO ROOM Does not Exist SCIENCE LAB Does not Exist SCIENCE PREP ROOM Does not Exist SWIMMING POOL Does not Exist **TOILET ROOM - STAFF** Inspected Lighting Inspected **Lighting Fixture - Fluorescent** Inspected **Pendant Mounted** Inspected Condition 2 - Between Good and Fair Deficiency No deficiencies recorded **Surface Mounted** Inspected Condition 2 - Between Good and Fair Deficiency No deficiencies recorded **Recessed Mounted** Does not Exist **Lighting Fixture - HID** Does not Exist **Lighting Fixture - Incandescent** Inspected **Pendant Mounted** Inspected Condition 3 - Fair LIGHTING FIXTURE BEYOND USEFUL LIFE Deficiency **Deficiency Quantity EACH** Quantity Uom REPLACE-UPGRADE Potential Action PRIORITY 1 Urgency of Action LEVEL 2 Purpose of Action Deficiency Photo1 No photo recorded Violations No violations recorded. **Surface Mounted** Inspected Condition 3 - Fair Deficiency LIGHTING FIXTURE BEYOND USEFUL LIFE **Deficiency Quantity** Quantity Uom **EACH** Potential Action REPLACE-UPGRADE Urgency of Action PRIORITY 1 LEVEL 2 Purpose of Action Deficiency Photo1 No photo recorded Violations No violations recorded. Recessed Mounted Does not Exist **Lighting Fixture - LED** Does not Exist **TOILET ROOM - STUDENT** Inspected Lighting Inspected **Lighting Fixture - Fluorescent** Inspected **Pendant Mounted** Inspected Condition 2 - Between Good and Fair Deficiency No deficiencies recorded **Surface Mounted** Does not Exist

# **Building Condition Assessment Survey 2023 - 2024**

arical hispection	
uestion	Response
TOILET ROOM - STUDENT	
Lighting	
Lighting Fixture - Fluorescent	Inspected
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	Does not Exist
Recessed Mounted	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	93,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Gymnasium, Cafeteria, Multipurpose Room
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	35671720N
(P)	Page 9 of 16 Print Date: 6/25/20

# **Building Condition Assessment Survey 2023 - 2024**

estion	Response
EMERGENCY LIGHTING	
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Auditorium, Multipurpose Room, Gymnasium, Cafeteria
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Deficiency Photo1	No photo recorded
Violations	35671720N
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
TIRE ALARM SYSTEM	Inspected
Replacement Quantity	93,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Does not Exist

#### **Building Condition Assessment Survey 2023 - 2024**

Question	Response
FIRE ALARM SYSTEM	
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Gamewell
Equipment	Fire Alarm Control Panel
Model	E3 Series
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	4 - Between Fair and Poor
Deficiency	PANEL NOT OPERATIONAL
Deficiency Location/Instance	Rooms (522, 428, 308)
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Printer	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Does not Exist
Tamper Flow Switch/Chain	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not Exist
LAN	Inspected

# **Building Condition Assessment Survey 2023 - 2024**

nestion	Response
LAN	
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	
Condition Condition	Inspected  3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Rooms (Room 306, above Gymnasium, Boiler Room, Basement), Penthouse Fan Room, Room 534, Boiler Room
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	
Detroiting Decision Instance	Auditorium, Electrical Room
Deficiency Quantity	Auditorium, Electrical Room 2
-	
Deficiency Quantity	2
Deficiency Quantity Quantity Uom	2 EACH
Deficiency Quantity Quantity Uom Potential Action	2 EACH REPLACE-UPGRADE
Deficiency Quantity Quantity Uom Potential Action Urgency of Action	2 EACH REPLACE-UPGRADE PRIORITY 1
Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action	2 EACH REPLACE-UPGRADE PRIORITY 1 LEVEL 2
Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations	EACH REPLACE-UPGRADE PRIORITY 1 LEVEL 2 No photo recorded No violations recorded.
Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1	EACH REPLACE-UPGRADE PRIORITY 1 LEVEL 2 No photo recorded
Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations  Molded Case Circuit Breaker Type Condition	EACH REPLACE-UPGRADE PRIORITY 1 LEVEL 2 No photo recorded No violations recorded.  Inspected 3 - Fair
Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations  Molded Case Circuit Breaker Type  Condition  Deficiency	EACH REPLACE-UPGRADE PRIORITY 1 LEVEL 2 No photo recorded No violations recorded.  Inspected 3 - Fair PANEL BOARD COVER IS MISSING
Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations  Molded Case Circuit Breaker Type Condition  Deficiency Deficiency Location/Instance	EACH REPLACE-UPGRADE PRIORITY 1 LEVEL 2 No photo recorded No violations recorded.  Inspected 3 - Fair PANEL BOARD COVER IS MISSING Corridors by Rooms (534, 428), Gymnasium
Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations  Molded Case Circuit Breaker Type Condition  Deficiency Deficiency Location/Instance Deficiency Quantity	EACH REPLACE-UPGRADE PRIORITY 1 LEVEL 2 No photo recorded No violations recorded.  Inspected 3 - Fair PANEL BOARD COVER IS MISSING Corridors by Rooms (534, 428), Gymnasium 3
Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations  Molded Case Circuit Breaker Type  Condition  Deficiency Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom	2 EACH REPLACE-UPGRADE PRIORITY 1 LEVEL 2 No photo recorded No violations recorded.  Inspected 3 - Fair PANEL BOARD COVER IS MISSING Corridors by Rooms (534, 428), Gymnasium 3 EACH
Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations  Molded Case Circuit Breaker Type Condition  Deficiency Deficiency Location/Instance Deficiency Quantity	EACH REPLACE-UPGRADE PRIORITY 1 LEVEL 2 No photo recorded No violations recorded.  Inspected 3 - Fair PANEL BOARD COVER IS MISSING Corridors by Rooms (534, 428), Gymnasium 3

# **Building Condition Assessment Survey 2023 - 2024**

uestion	Response	
PANEL BOARD		
Molded Case Circuit Breaker Type		
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Deficiency	NO SPARE	
Deficiency Location/Instance	Cafeteria	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE PANEL BOARD	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE	
Deficiency Location/Instance	Corridors - by Rooms (102, 204, 207, 223, 228, 305, 307, 323, 328, 409, 423, 428, 534, 528), Multipurpose Room, Cafeteria, Gymnasium Vestibule between Auditorium and Cafeteria	
Deficiency Quantity	19	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
PUBLIC ADDRESS SYSTEM	Inspected	
Replacement Quantity	93,000	
Replacement Uom	S.F.	
Instance	General Office	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Dukane 250	
Installation Year	2004	
Source of Installation	Documented	
Deficiency	CLOCK NOT OPERATIONAL	
Deficiency Location/Instance	Classrooms and Corridors	
Deficiency Quantity	20	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
SECURITY	Inspected	
IPDVS/CCTV System	Does not Exist	
T.A. C. Al C	Inspected	
Intrusion Alarm System		
Replacement Quantity	93,000	
	93,000 S.F.	

# **Building Condition Assessment Survey 2023 - 2024**

icai hispection		130
stion	Response	
ECURITY		
Intrusion Alarm System		
Central Control Panel		
Instance	Custodian's Office	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	4140XMPT	
Installation Year	1992	
Source of Installation	Inspector Estimate	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3 - Fair	
Deficiency	SIREN/STROBE NOT ACTIVE	
Deficiency Location/Instance	Exterior Wall facing St. Edward's Street	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 4	
Purpose of Action	LEVEL 3	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Lighting - Security	Inspected	
Replacement Uom	EACH	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
ERVICE SWITCH	Inspected	
Instance	Electrical Room	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	American Switchboard Co.	
Equipment	N/A	
Capacity/Size Quantity	2,000	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1940	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Deficiency	140 deficiencies recorded	
Instance	Electrical Room	

# **Building Condition Assessment Survey 2023 - 2024**

Question	Response
SERVICE SWITCH	
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	N/A
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	0
Fused Disconnect Switch Type	Inspected
Instance	Basement - by Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	Panel BLR-DB 1, 2
Capacity/Size Quantity	400
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	2003
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	ЕАСН
Instance Manufacturer	American Switchboard Co.
Equipment	N/A
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	1940
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3 - Fair
Deficiency	TELEPHONE MISSING
Deficiency Location/Instance	Gymnasium Office
	Symmonth Office

# **Building Condition Assessment Survey 2023 - 2024**

nestion	Response
TELEPHONE SYSTEM	
PBX/Intercom	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL TELEPHONE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Standard	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
CRANSFORMER	Does not Exist