

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

K135

Asset: P.S. 135 - BROOKLYN, 684 LINDEN BLVD, New York, 11203

Inspection Id	Inspection Type	Time In	Last Edited
SA : K135	Architectural - Senior	2024-05-21 7:38 AM	2024-06-04 9:37 AM
AA : K135	Architectural - Associate	2024-05-21 7:36 AM	2024-06-05 11:59 AM

Asset Data

Question	Answer
Was the building fully accessible for inspection	Yes
Building Square Footage	59,000
Comments on the Area (for Athletic Field, Playing Surfaces, Leased Spaces)	None
Comments on the Stories (Floors) plus Basements	5+B
Comments on the Number of Classrooms	32
Comments on the Year Built	1923
Student Population	347
Staff Population	55
Weather	Fair
Principal(s) Information	
Principal Name	Trevlyn McRae
Organization	P.S. 135 - Brooklyn
Did you meet with this Principal?	Yes
Did this Principal provide feedback?	Yes
Summary of Principal's Feedback	The Principal's comment is as follow: the PA system is defective.
Custodian	Was not present
Fireman	Milton Rios
Facade Photo	




Corner of Linden Boulevard and E 48th Street - Southwest View

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K135

Main Entrance Photo



Facade A - Linden Boulevard

Roof Photo



Roof 1 - West View

Have any Systems/Major Building Components been upgraded?

Yes

Systems: Coping, Doors/Frames, Parapets, Stairs, Railings, Roof Drains, Ash Hoist Vault Doors - replacement; Areaways, Cornice, Exterior Walls, Bulkheads - repairs

Year: 2022

Systems: Roofing - repairs

Year: 2018

Systems: Structure, Ash Hoist Vault - repairs

Year: 2012

Systems: Roofing - replacement; Foundation Walls - repairs

Year: 2011

Systems: Doors, Exterior Guards, Windows - replacement

Year: 2002

Have there been any Building Additions?

No

Tandem Schools?

No

Leased Space?

No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	PhotoImage
-------------------------------------	-------------------	-----------------------	--------------------	----------------------	--------------------	-----------------	------------

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

K135

No condition recorded

Structural Engineer Required

Structural Condition Type	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	PhotoImage
---------------------------	-----------------------	--------------------	----------------------	--------------------	-----------------	------------

No condition recorded

Programmatic Accessibility

Programmatic Accessibility Status Question	Response
Is the primary or secondary entrance on an accessible route?	Yes
Is the building a multi-story building?	Yes
Are all floors of the building accessible through compliant means?	No
Are SOME floors other than the 1st floor and basement accessible through compliant means?	No
Do any of the following spaces exist on the 1st Floor or Basement? Classroom, Art Room, Auditorium, Cafeteria, Computer, Gymnasiums, Library, Multipurpose Room, Science Labs	Yes
For the rooms that do exist, are SOME of them accessible on the 1st Floor or Basement?	Yes
Boys and Girls or Unisex accessible toilets exist on the 1st floor?	No
Boys and Girls or Unisex accessible toilets exist in the Basement?	No

Physical Breakdown Structure	Exists	Required	Complies	Deficiency	Assistive Listening System	Fire Alarm Strobe
------------------------------	--------	----------	----------	------------	----------------------------	-------------------

PROGRAMMATIC ACCESSIBILITY

Exterior Routes

Exterior Entrances & Exits			Yes			
Exterior H/C Lifts	No	No				
Exterior Ramps and Railings	No	No				

Interior Routes

Corridor and Lobby H/C Lifts	No	No				
Interior Corridor Doors and Hardware	Yes		Yes			
Interior Corridors and Lobbies			Yes			
Interior Elevators	No					
Interior Lobby Doors and Hardware			Yes			
Interior Ramps	No					

Rooms & Spaces

Art Rooms		No				
Auditorium	2nd Floor	Yes	No	No Stage Access Not on Accessible Route	No	Yes
Cafeteria	1st Floor	Yes	Yes		No	Yes
Classrooms	None on Accessible Route	Yes	No	Not on Accessible Route		
Computer Rooms	Room 207	Yes	No	Not on Accessible Route		
Gymnasium		No				
Library	1st Floor	Yes	Yes			
Main Office	Room 203	Yes	No	Not on Accessible Route		
Multi-purpose Room		No				
Nurse's Room	Room 251	Yes	No	Not on Accessible Route		
Pool		No				
Science Lab		No				


**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K135

Physical Breakdown Structure		Exists	Required	Complies	Deficiency	Assistive Listening System	Fire Alarm Strobe
Rooms & Spaces							
Toilet Rooms (Boys)	1st Floor	Yes		No	Accessory Arrangement Sink Arrangement Urinal Arrangement Water Closet Arrangement		
Toilet Rooms (Girls)	1st Floor	Yes		No	Accessory Arrangement No Lever-type Hardware Sink Arrangement Water Closet Arrangement		
Toilet Rooms (Staff)	1st Floor	Yes		No	Accessory Arrangement Clear opening < 32" No Lever-type Hardware Sink Arrangement Water Closet Arrangement		

Building Template



Inspection

Question	Response
Architectural	
EXTERIOR	Inspected
AREAWAY	Inspected
Instance on AW1	Inspected
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	AREAWAY GRATINGS: MAJOR RUSTING / OR BROKEN

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K135


Question

Response

EXTERIOR

AREAWAY

Roof Plan reference



Deficiency Quantity

20

Quantity Uom

S.F.

Potential Action

REPLACE


Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 2

Deficiency Photo1



AW1


Violations

No violations recorded.

Deficiency

AREAWAY WALLS: CRACKS AND SPALLING

Roof Plan reference



Deficiency Quantity

20

Quantity Uom

S.F.

Potential Action

REPAIR

Urgency of Action

PRIORITY 3


Purpose of Action

LEVEL 2

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

K135

Question	Response
EXTERIOR	
AREAWAY	
Deficiency Photo1	
Violations	AW1 No violations recorded.
Instance on AW2 - AW4	Inspected
Instance Condition	2 - Between Good and Fair
Instance Quantity	3
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
AWNINGS AND CANOPIES	Does not Exist
CHIMNEY	Inspected
Material Type(s)	Masonry
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
COPING	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
CORNICE	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
DOORS	Inspected
DOORS AND FRAMES	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
DOOR HARDWARE	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LINTELS	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
TRANSOM/SIDE LIGHT	Inspected
Condition	5 - Poor
Deficiency	WOOD: BROKEN GLASS

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K135

Question


Response

EXTERIOR

DOORS

TRANSOM/SIDE LIGHT

Roof Plan reference




Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action
Deficiency Photo1
Violations

10
S.F.
MAINTENANCE
PRIORITY 3
LEVEL 2
No photo recorded
No violations recorded.

Deficiency


Roof Plan reference

WOOD: EXCESSIVELY WEATHERED



Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action
Deficiency Photo1

40
S.F.
REPLACE
PRIORITY 4
LEVEL 2



Facade A
No violations recorded.

Violations

EXTERIOR WALLS

Material Type(s)




Replacement Quantity

Inspected
Masonry
34,000

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K135

Question	Response
EXTERIOR	
EXTERIOR WALLS	
Replacement Uom	S.F.
Instance on All Facades	Inspected
Instance Condition	3 - Fair
Instance Quantity	34,000
Instance Quantity Uom	S.F.
Deficiency	BRICK: MAJOR / THRU CRACKS
Roof Plan reference	
Elevation	
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REMOVE AND REBUILD
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Facade G No violations recorded.
Deficiency	STONE: CHIPPED/SPALLED/BROKEN PIECES - MINOR

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K135


Question

Response


EXTERIOR

EXTERIOR WALLS

Roof Plan reference



Elevation



Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

REPAIR

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade H


Violations

No violations recorded.

Deficiency

BRICK: CRACKS/DISPLACED/SPALLED BRICK AT BUILDING CORNERS

Roof Plan reference



**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K135

Question

Response

EXTERIOR

EXTERIOR WALLS

Elevation



Deficiency Quantity

60

Quantity Uom

S.F.

Potential Action

REMOVE AND REBUILD

Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade B


Violations

No violations recorded.


Deficiency

BRICK: MINOR CRACKS AND SPALLING

Roof Plan reference



Elevation



Deficiency Quantity

100

Quantity Uom

S.F.

Potential Action

RESTITCH

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K135

Question

Response

EXTERIOR

EXTERIOR WALLS

Urgency of Action
Purpose of Action
Deficiency Photo1

PRIORITY 3
LEVEL 2



Facade G


Violations

No violations recorded.


Deficiency

BRICK: EFFLORESCENCE

Roof Plan reference



Elevation



Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action
Deficiency Photo1
Violations

100
S.F.
MAINTENANCE
PRIORITY 1
LEVEL 1
No photo recorded
No violations recorded.

Deficiency

BRICK: DETERIORATED MASONRY SILLS - MINOR

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K135


Question

Response

EXTERIOR

EXTERIOR WALLS

Roof Plan reference



Elevation



Deficiency Quantity

60

Quantity Uom

L.F.

Potential Action

REPAIR


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade C

No violations recorded.

Violations

EXTERIOR SOFFITS

Does not Exist

LOADING DOCK

Does not Exist

LOUVER

Inspected

Condition

2 - Between Good and Fair

Deficiency

No deficiencies recorded

PARAPETS

Inspected

Material Type(s)

Masonry

Replacement Quantity

4,000

Replacement Uom

C.F.

Instance on All Roofs

Inspected

Instance Condition

3 - Fair

Instance Quantity

4,000

Instance Quantity Uom

C.F.

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

K135

Question

Response


EXTERIOR

PARAPETS

Deficiency

BRICK: EFFLORESCENCE

Roof Plan reference



Deficiency Quantity

60

Quantity Uom

S.F.

Potential Action

MAINTENANCE

Urgency of Action

PRIORITY 1

Purpose of Action

LEVEL 1

Deficiency Photo1

No photo recorded


Violations

No violations recorded.

Deficiency

BRICK: DETERIORATED JOINTS

Roof Plan reference



Deficiency Quantity

40

Quantity Uom

S.F.

Potential Action

REPOINT

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Violations

Roof 1

No violations recorded.

PLAZA DECK

Does not Exist

ROOF

Inspected



Roofing

Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

K135

Question	Response
EXTERIOR	
ROOF	
Roofing	
Replacement Quantity	14,000
Replacement Uom	S.F.
ROOF HATCH/SMOKE HATCH	Does not Exist
LEADERS, GUTTERS, DOWNSPOUTS, SCUPPERS	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
ROOF BARRIER/FENCE	Does not Exist
ROOF CAGE	Does not Exist
ROOFING	Inspected
Instance on Modified Bitumen: All Roofs	Inspected
Instance Condition	3 - Fair
Instance Photo	
	Roof 1
Instance Quantity	14,000
Instance Quantity Uom	S.F.
Does the roof have major mechanical equipment sitting on Dunnage Steel less than 18" above the Roofing?	No
Does this roof instance have a Sustainable Roof System?	Yes
Sustainable Roof Type	White Roof
Sustainable Roof Location (Roof Number)	All Roofs
Do solar panels exist on these roofs?	No
Is/Are the roof(s) suitable for Solar Panel installation?	Yes
Installation Year	2011
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
ROOFING DRAINS	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Specialties	Inspected
BULKHEAD/PENTHOUSE	Inspected
Condition	3 - Fair
Deficiency	BULKHEAD/PENTHOUSE WALLS/EXTERIOR: EFFLORESCENCE
Roof Plan reference	
Deficiency Quantity	20

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

K135

Question	Response
----------	----------

EXTERIOR

ROOF


Specialties

BULKHEAD/PENTHOUSE


Quantity Uom	S.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Deficiency Photo1	No photo recorded
Violations	No violations recorded.

Deficiency	BULKHEAD/PENTHOUSE DOORS: DETERIORATED DOOR AND FRAME
------------	---

Roof Plan reference



Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE DOOR AND FRAME
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Deficiency Photo1	




BH1 (does not close)
 No violations recorded.

Violations

Deficiency	BULKHEAD/PENTHOUSE WALLS/INTERIOR: PLASTER CRACKS/SPALLING
------------	--

Roof Plan reference






Deficiency Quantity	80
---------------------	----

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K135

Question	Response
EXTERIOR	
ROOF	
Specialties	
BULKHEAD/PENTHOUSE	
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Deficiency Photo1	
	BH2
Violations	No violations recorded.
Deficiency	BULKHEAD/PENTHOUSE WALLS/EXTERIOR: DETERIORATED JOINTS
Roof Plan reference	
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPOINT
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	BH2
Violations	No violations recorded.
CUPOLA/ SPIRES/ TOWERS	Does not Exist
DORMER	Does not Exist
DUNNAGE STEEL	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K135

Question	Response
----------	----------

EXTERIOR

ROOF

Specialties

SKYLIGHT/ROOF VENT

Inspected

Material Type(s)

Glass


Condition

3 - Fair

Deficiency

DAMAGED GUARDS

Roof Plan reference



Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action
Deficiency Photo1

50
S.F.
MAINTENANCE
PRIORITY 3
LEVEL 2




Violations

SK3
No violations recorded.

Deficiency

BROKEN GLASS

Roof Plan reference



Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action

10
S.F.
MAINTENANCE
PRIORITY 3
LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K135

Question	Response
EXTERIOR	
ROOF	
Specialties	
SKYLIGHT/ROOF VENT	
Deficiency Photo1	
Violations	SK2 No violations recorded.
ROOF/GRAVITY TANK	Does not Exist
STAIRS/RAMPS: EXTERIOR	Inspected
BUILDING CHEEK/FLANK WALLS	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
RAILINGS	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
STAIRS/RAMPS	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
WINDOWS	Inspected
Replacement Quantity	9,200
Replacement Uom	S.F.
EXTERIOR GUARDS	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
LINTELS	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
WINDOWS	Inspected
Material Type(s)	Aluminum, Solid Wood
Instance on Aluminum - Double Hung: All Facades	Inspected
Instance Condition	3 - Fair
Instance Quantity	9,000
Instance Quantity Uom	S.F.
Are these windows insulated	No
Installation Year	2002
Source of Installation	Custodial Staff
Deficiency	ALUMINUM - DOUBLE HUNG: INOPERABLE BALANCE

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K135


Question	Response
----------	----------

EXTERIOR


WINDOWS

WINDOWS

Roof Plan reference



Elevation



Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action
Deficiency Photo1

70
EACH
REPLACE BALANCES
PRIORITY 3
LEVEL 2



Facade A - Room 207 (Custodians Office, Room 506 similar)
No violations recorded.

Violations

Instance on Wood: Basement	Inspected
Instance Condition	5 - Poor
Instance Quantity	200
Instance Quantity Uom	S.F.
Are these windows insulated	No
Installation Year	1923
Source of Installation	Custodial Staff
Deficiency	WOOD: DETERIORATED

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



K135

Question	Response
EXTERIOR	
WINDOWS	
WINDOWS	
Roof Plan reference	
Elevation	
Deficiency Quantity	200
Quantity Uom	S.F.
Potential Action	REPLACE WINDOW
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Facade C - Boiler Room No violations recorded.
INTERIOR	Inspected
POOLS	Does not Exist
STRUCTURAL	Inspected
COLUMNS/BEAMS/BEARING WALLS	Inspected
Condition	3 - Fair
Deficiency	STEEL COLUMNS/BEAMS: DETERIORATED CONCRETE FIREPROOFING
Deficiency Location/Instance	Basement - near House Exhaust Fan
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 4

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection


K135

Question	Response
INTERIOR	
STRUCTURAL	
COLUMNS/BEAMS/BEARING WALLS	
Purpose of Action	LEVEL 5
Deficiency Photo1	
Violations	Basement - near House Exhaust Fan No violations recorded.
FLOOR STRUCTURE	
Condition	Inspected 3 - Fair
Deficiency	CONCRETE SLAB ON GRADE: THRU CRACKS
Deficiency Location/Instance	Basement - near Oil Tank Room, near Ash Hoist Vault
Deficiency Quantity	40
Quantity Uom	S.F.
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 5
Deficiency Photo1	
Violations	Basement - near Ash Hoist Vault No violations recorded.
FOUNDATION WALLS	
Material Type(s)	Inspected Concrete, Masonry
Condition	3 - Fair
Deficiency	BRICK: CRACKED/SPALLED
Deficiency Location/Instance	Basement - Boiler Room
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	RESTITCH
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 5

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

K135

Question	Response
INTERIOR	
STRUCTURAL	
FOUNDATION WALLS	
Deficiency Photo1	
Violations	Basement - Boiler Room No violations recorded.
ROOF STRUCTURE	
Condition	Inspected
Deficiency	2 - Between Good and Fair
VAULTS-BUNKERS	
Condition	Inspected
Deficiency	No deficiencies recorded
Foundation Walls	
Condition	Inspected
Deficiency	2 - Between Good and Fair
Slab Structure	
Condition	Inspected
Deficiency	2 - Between Good and Fair
Vault/Ash Hoist Doors and Framing	
Condition	Inspected
Deficiency	1 - Good
AUDITORIUM	
Instance on 2nd Floor (380 Seats)	Inspected
Ceiling	
Instance on 2nd Floor (380 Seats)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Door(s)	
Instance on 2nd Floor (380 Seats)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fixed H/C Lift	
Instance on 2nd Floor (380 Seats)	Does not Exist
Fixed Seating	
Instance on 2nd Floor (380 Seats)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Floor Finish	
Instance on 2nd Floor (380 Seats)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Sliding-folding Partition	
Instance on 2nd Floor (380 Seats)	Does not Exist
Stage	

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K135

Question	Response
INTERIOR	
AUDITORIUM	
Stage	
Instance on 2nd Floor (380 Seats)	Inspected
Stage	Inspected
Instance on 2nd Floor (380 Seats)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Stage Curtain Rigging	Inspected
Instance on 2nd Floor (380 Seats)	Inspected
Condition	3 - Fair
Deficiency	DAMAGED/DETERIORATED
Deficiency Location/Instance	Right Stage
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Right Stage
Violations	No violations recorded.
Stage Curtains	Inspected
Instance on 2nd Floor (380 Seats)	Inspected
Condition	3 - Fair
Deficiency	WORN/DETERIORATED
Deficiency Location/Instance	Main Curtain
Deficiency Quantity	200
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Main Curtain
Violations	No violations recorded.

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection


K135

Question	Response
INTERIOR	
AUDITORIUM	
Walls	
Instance on 2nd Floor (380 Seats)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Window Curtains/Shades/Blinds	
Instance on 2nd Floor (380 Seats)	Inspected
Condition	3 - Fair
Deficiency	WORN/DAMAGED CURTAINS
Deficiency Location/Instance	Left, Right Aisle
Deficiency Quantity	150
Quantity Uom	S.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Left Aisle
Violations	No violations recorded.
CAFETERIA	
Instance on 1st Floor	Inspected
Instance on 1st Floor	Inspected
Ceiling	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	ACOUSTIC TILES ON PLASTER: DAMAGED/MISSING
Deficiency Location/Instance	Near the entrance side, center
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	In the Cafeteria
Violations	No violations recorded.

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K135

Question	Response
INTERIOR	
CAFETERIA	
Door(s)	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fixed Equipment	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Floor Finish	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	VINYL TILES: BROKEN/DETERIORATED/MISSING TILES
Deficiency Location/Instance	Near the center
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near the center No violations recorded.
Sliding-folding Partition	
Instance on 1st Floor	Does not Exist
Stage	
Instance on 1st Floor	Does not Exist
Walls	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	WALL PADDING: DETERIORATED
Deficiency Location/Instance	Columns
Deficiency Quantity	100
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K135

Question	Response
INTERIOR	
CAFETERIA	
Walls	
Deficiency Photo1	
Violations	Columns No violations recorded.
Window Curtains/Shades/Blinds	
Instance on 1st Floor	Does not Exist
CLASSROOMS/CORRIDORS/ADMIN SPACES	
Ceiling	Inspected
Condition	2 - Between Good and Fair
Deficiency	PLASTER: CRACKS/SPALLING
Deficiency Location/Instance	Rooms 207, 301
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 207 No violations recorded.
Door(s)	
Condition	Inspected
Condition	5 - Poor
Deficiency	WOOD: DETERIORATED DOOR AND FRAME
Deficiency Location/Instance	Room 302
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K135

Question

Response

INTERIOR

CLASSROOMS/CORRIDORS/ADMIN SPACES

Door(s)

Deficiency Photo1



Room 302

Violations

No violations recorded.

Deficiency

METAL: DETERIORATED DOOR

Deficiency Location/Instance

Room 506

Deficiency Quantity

1

Quantity Uom

EACH

Potential Action

MAINTENANCE

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Room 506

Violations

No violations recorded.

Deficiency

WOOD: DETERIORATED DOOR

Deficiency Location/Instance

Rooms 202, 301, 409, 502, 506,and others

Deficiency Quantity

7

Quantity Uom

EACH

Potential Action

MAINTENANCE


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Room 506



Violations

No violations recorded.

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K135

Question	Response
INTERIOR	
CLASSROOMS/CORRIDORS/ADMIN SPACES	
Floor Finish	Inspected
Condition	3 - Fair
Deficiency	VINYL TILES: DETERIORATED SUBSTRATE
Deficiency Location/Instance	Rooms 301, 403, 404, 407, 509, and others
Deficiency Quantity	1,500
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 405 No violations recorded.
Deficiency	VINYL TILES: BROKEN/DETERIORATED/MISSING TILES
Deficiency Location/Instance	Rooms 260, 401, 402, 508, Corridor near Room 406, and others
Deficiency Quantity	500
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 260 No violations recorded.
Deficiency	TERRAZZO: CRACKS
Deficiency Location/Instance	Main Entrance Vestibule, in the Lobby, near the Auditorium
Deficiency Quantity	200
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K135

Question	Response
----------	----------

INTERIOR

CLASSROOMS/CORRIDORS/ADMIN SPACES

Floor Finish

Deficiency Photo1



In the Lobby

No violations recorded.

Violations

Walls

Inspected

Condition

2 - Between Good and Fair

Deficiency

PLASTER: CRACKS/SPALLING

Deficiency Location/Instance

Rooms 307, 409

Deficiency Quantity

30

Quantity Uom

S.F.

Potential Action

REPLACE

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Room 307

No violations recorded.

Violations

Deficiency

CERAMIC TILE: BROKEN/ MISSING

Deficiency Location/Instance

Room 507

Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

REPLACE


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2


Deficiency Photo1



**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K135

Question	Response
INTERIOR	
CLASSROOMS/CORRIDORS/ADMIN SPACES	Inspected
Walls	Inspected
Violations	Room 507 No violations recorded.
Specialties	Does not Exist
GYMNASIUM	Does not Exist
INTERIOR DOOR HARDWARE	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERIOR GUARDS	Inspected
Condition	4 - Between Fair and Poor
Deficiency	DETERIORATED/TORN-OUT/MISSING
Deficiency Location/Instance	In the Cafeteria
Deficiency Quantity	400
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	In the Cafeteria No violations recorded.
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Ceiling	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Door(s)	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Floor Finish	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Walls	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	CERAMIC TILE: BROKEN/ MISSING
Deficiency Location/Instance	Servery, Storage Room
Deficiency Quantity	10

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection


K135

Question	Response
INTERIOR	
KITCHEN	
Walls	
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Storage Room
Violations	No violations recorded.
LIBRARY	
	Inspected
Instance on 1st Floor	Inspected
Built-in Furnishing	
Instance on 1st Floor	Does not Exist
Ceiling	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	PLASTER: CRACKS/SPALLING
Deficiency Location/Instance	Near the windows by the circulation desk
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Near the windows by the circulation desk
Violations	No violations recorded.
Door(s)	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Floor Finish	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K135

Question	Response
INTERIOR	
LIBRARY	
Floor Finish	
Deficiency	No deficiencies recorded
Walls	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	GYPSON BOARD: DETERIORATED
Deficiency Location/Instance	Near the electrical panel/ entrance wall side, near the windows
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Near the electrical panel/ entrance wall side
Violations	No violations recorded.
LOCKER ROOM	Does not Exist
MULTI-PURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SHOWER ROOM	Does not Exist
STAIRS/RAMPS: INTERIOR	Inspected
Do Letter Stair Signs Exist?	Partially
Ceiling	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Door(s)	
Condition	5 - Poor
Deficiency	METAL: DETERIORATED DOOR
Deficiency Location/Instance	Stair F/1 Vestibule
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K135

Question	Response
----------	----------

INTERIOR

STAIRS/RAMPS: INTERIOR

Door(s)

Deficiency Photo1



Stair F/1 Vestibule

No violations recorded.

Violations

Deficiency

METAL CLAD WOOD: DETERIORATED DOOR

Deficiency Location/Instance

Stairs DE/5, F/1, G/1

Deficiency Quantity

3

Quantity Uom

EACH

Potential Action

MAINTENANCE

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Stair G/1

No violations recorded.

Violations

Partition

Inspected

Condition

3 - Fair

Deficiency

GLASS PANEL: DAMAGED/DETERIORATED

Deficiency Location/Instance

Stairs BC/3, DE/1,3,5

Deficiency Quantity

60

Quantity Uom

S.F.

Potential Action

REPLACE

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection


K135

Question	Response
INTERIOR	
STAIRS/RAMPS: INTERIOR	
Partition	Inspected
	Stair DE/1
Violations	No violations recorded.
Railings	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Stairs and Landings	Inspected
Condition	5 - Poor
Deficiency	STONE: BROKEN/MISSING
Deficiency Location/Instance	Lobby Stair
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Lobby Stair No violations recorded.
Deficiency	ROLLED ASPHALT: DETERIORATED SUBSTRATE
Deficiency Location/Instance	Stairs BC/Bulkhead, DE/Bulkhead
Deficiency Quantity	500
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Stair BC/Bulkhead No violations recorded.
Deficiency	VINYL TILES: BROKEN/DETERIORATED/MISSING TILES
Deficiency Location/Instance	StairsD/2, G/1
Deficiency Quantity	10
Quantity Uom	S.F.

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



K135

Question	Response
INTERIOR	
STAIRS/RAMPS: INTERIOR	
Stairs and Landings	
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Stair G/1
Violations	No violations recorded.
Walls	
Condition	Inspected
	2 - Between Good and Fair
Deficiency	PLASTER: CRACKS/SPALLING
Deficiency Location/Instance	Stair G/1
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Stair G/1
Violations	No violations recorded.
Deficiency	CERAMIC TILE: BROKEN/ MISSING
Deficiency Location/Instance	Stair BC/1 Vestibule, G/1
Deficiency Quantity	60
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K135

Question	Response
INTERIOR	
STAIRS/RAMPS: INTERIOR	
Walls	
Deficiency Photo1	
Violations	Stair BC/1 Vestibule No violations recorded.
TOILET ROOMS - STAFF	
Ceiling	Inspected
Condition	4 - Between Fair and Poor
Deficiency	PLASTER: CRACKS/SPALLING
Deficiency Location/Instance	Room 553
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 553 No violations recorded.
Door(s)	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Floor Finish	
Condition	5 - Poor
Deficiency	CERAMIC TILE: BROKEN/MISSING TILES
Deficiency Location/Instance	Room 553, 4th Floor Staff
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K135

Question	Response
----------	----------

INTERIOR

TOILET ROOMS - STAFF

Floor Finish

Deficiency Photo1



Room 553

Violations

No violations recorded.

Deficiency

VINYL TILES: BROKEN/DETERIORATED/MISSING TILES

Deficiency Location/Instance

Kitchen Toilet Room

Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

REPLACE

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Kitchen Toilet Room

Violations

No violations recorded.

Stalls

Inspected

Condition

5 - Poor

Deficiency

RUST - MAJOR

Deficiency Location/Instance

Kitchen Toilet Room

Deficiency Quantity

1

Quantity Uom

EACH

Potential Action

REPLACE


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2



Deficiency Photo1



**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K135

Question	Response
INTERIOR	
TOILET ROOMS - STAFF	
Stalls	Inspected
Violations	Kitchen Toilet Room No violations recorded.
Walls	Inspected
Condition	2 - Between Good and Fair
Deficiency	CERAMIC TILE: BROKEN/ MISSING
Deficiency Location/Instance	Staff 4th Floor, Room 553
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 553 No violations recorded.
Deficiency	PLASTER: CRACKS/SPALLING
Deficiency Location/Instance	Kitchen Toilet Room
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Kitchen Toilet Room No violations recorded.
TOILET ROOMS - STUDENTS	
Ceiling	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Door(s)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K135

Question	Response
INTERIOR	
TOILET ROOMS - STUDENTS	
Floor Finish	Inspected
Condition	2 - Between Good and Fair
Deficiency	CERAMIC TILE: BROKEN/MISSING TILES
Deficiency Location/Instance	1st Floor Girls
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	1st Floor Girls No violations recorded.
Stalls	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Walls	Inspected
Condition	2 - Between Good and Fair
Deficiency	CERAMIC TILE: BROKEN/ MISSING
Deficiency Location/Instance	1st Floor Girls, PreK Toilet Rooms near Left, Right Stage
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	1st Floor Girls No violations recorded.
LIFE SAFETY	Inspected
F.D. HOLDING AREA	Does not Exist
STEEL STAIRS	Does not Exist
SITE	Inspected
CONTAINERIZATION	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



K135

Question	Response
SITE	
CONTAINERIZATION	
Condition	5 - Poor
Deficiency	CONTAINER DAMAGED
Deficiency Location/Instance	Schoolyard
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	FENCING MISSING
Deficiency Location/Instance	Schoolyard
Deficiency Quantity	900
Quantity Uom	S.F.
Potential Action	INSTALL NEW
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Schoolyard No violations recorded.
Drainage System for Asphalt	Inspected
Catch Basins/Manhole - Surrounded by asphalt	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Culverts - Asphalt Covering	Does not Exist
Drainage System for Concrete	Inspected
Catch Basins/Manhole - Surrounded by concrete	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Culverts - Concrete Covering	Does not Exist
Drainage System for Soil	Does not Exist
DRINKING FOUNTAINS	Does not Exist
FENCES	Inspected
Condition	3 - Fair
Deficiency	CONCRETE CURB: DAMAGED/DETERIORATED
Deficiency Location/Instance	Schoolyard
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	REPLACE

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K135

Question	Response
SITE	
FENCES	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Schoolyard
Violations	No violations recorded.
Deficiency	WROUGHT IRON: RUST - MAJOR
Deficiency Location/Instance	E.48th Street
Deficiency Quantity	40
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	E.48th Street
Violations	No violations recorded.
Deficiency	WROUGHT IRON: DAMAGED/DETERIORATED
Deficiency Location/Instance	E.48th Street, Linden Boulevard, Schenectady Avenue
Deficiency Quantity	280
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Linden Boulevard

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

K135

Question	Response
SITE	
FENCES	
Violations	No violations recorded.
Deficiency	CHAIN LINK: DAMAGED POST/RAIL
Deficiency Location/Instance	Schoolyard
Deficiency Quantity	60
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Schoolyard No violations recorded.
IRRIGATION SYSTEM	Does not Exist
PAVING	Inspected
Student Non-Use	Inspected
Gravel Exists?	No
Asphalt	Does not Exist
Concrete	Inspected
Condition	2 - Between Good and Fair
Deficiency	CRACKS - MINOR
Deficiency Location/Instance	In the schoolyard at the fence off area
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Pavers	Does not Exist
Student Use	Inspected
Gravel Exists?	No
Asphalt	Inspected
Condition	4 - Between Fair and Poor
Deficiency	CRACKS - MAJOR
Deficiency Location/Instance	Schoolyard
Deficiency Quantity	1,600
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection


K135

Question	Response
SITE	
PAVING	
Student Use	
Asphalt	
Deficiency Photo1	
Violations	Schoolyard No violations recorded.
Concrete	Inspected
Condition	3 - Fair
Deficiency	CRACKS - MAJOR
Deficiency Location/Instance	Schoolyard
Deficiency Quantity	75
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Schoolyard No violations recorded.
Pavers	Does not Exist
Site Sidewalks & Walkways	Inspected
Asphalt	Does not Exist
Concrete	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Pavers	Does not Exist
DOT Sidewalk	Inspected
Asphalt	Does not Exist
Concrete	Inspected
Condition	4 - Between Fair and Poor
Deficiency	DAMAGED CURBS
Deficiency Location/Instance	E.48th Street, Linden Boulevard, Schenectady Avenue
Deficiency Quantity	30

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection


K135

Question	Response
SITE	
PAVING	
DOT Sidewalk	
Concrete	
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	E.48th Street
Violations	No violations recorded.
Deficiency	HEAVING
Deficiency Location/Instance	E.48th Street
Deficiency Quantity	25
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	E.48th Street
Violations	No violations recorded.
Deficiency	DAMAGED/DETERIORATED/MISSING SECTIONS
Deficiency Location/Instance	E.48th Street, Linden Boulevard, Schenectady Avenue
Deficiency Quantity	1,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

K135

Question	Response
SITE	
PAVING	
DOT Sidewalk	
Concrete	
Deficiency Photo1	
Violations	Linden Boulevard No violations recorded.
Pavers	Does not Exist
PLAYGROUNDS	Inspected
Instance on Schoolyard	Inspected
Benches	
Instance on Schoolyard	Does not Exist
Fence	
Instance on Schoolyard	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Pavement	
Instance on Schoolyard	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Play Equipment	
Instance on Schoolyard	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Safety Surfacing	
Instance on Schoolyard	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Unpaved Area	
Instance on Schoolyard	Does not Exist
PLAYING SURFACE	Does not Exist
RETAINING WALLS	Does not Exist
SEATING	Does not Exist
SITE WALLS (NOT RETAINING WALLS)	Inspected
Condition	3 - Fair
Deficiency	CAST IN PLACE CONCRETE: CRACKS/SPALLING - MAJOR
Deficiency Location/Instance	Schoolyard
Deficiency Quantity	25
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

K135

Question

Response

SITE

SITE WALLS (NOT RETAINING WALLS)

Deficiency Photo1



Violations

Schoolyard

No violations recorded.

STAIRS/RAMPS: EXTERIOR

Does not Exist

ARTWORK

Does not Exist