

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K152**

**Asset: P.S. 152 - BROOKLYN, 725 EAST 23RD STREET, New York, 11210**

Inspection Id	Inspection Type	Time In	Last Edited
EE : K152	Electrical	2024-03-27 8:51 AM	2024-04-02 9:54 AM

**Asset Data**

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	Yes
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Fire Alarm System
	Years: Under Construction
	Systems: Partial Exit/Emergency Light, LAN, Public Address System (Amplifier)
	Years: 2023
	Systems: Transformer
	Years: 2021
	Systems: LED Lighting, Science Demo Room (Pendant Fluorescent Lighting), Kitchen, Auditorium (House Lighting)
	Years: 2015
	Systems: Auditorium (Local Sound System)
	Years: 2011
	Systems: 1st Floor Library
	Years: 2010
	Systems: Auditorium (Theater Lighting System)
	Years: 2006
	Systems: Security Lights
	Years: 1999, 2017
	Systems: Molded Case Circuit Breaker Type Panel Board
	Years: 1999, 2010, 2019
	Systems: Interior Fluorescent Lighting, Emergency Generator Set, Most Fused Disconnect Switch Type Panel Board, Public Address System, Intrusion Alarm System, Partial Service Switch, Partial Switchboard
	Years: 1999

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

**Priority Condition**

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Water Leaks onto Electrical Equipment	N/A	Lighting Fixture	Room 413	Jean Testamar	Fireman	Sent to DSF	
No	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electrical Room	Jean Testamar	Fireman	Sent to DSF	
Yes	Local Sound System - Not Connected to Public Address System	N/A	AUDITORIUM   Local Sound System	Auditorium	Jean Testamar	Fireman	Sent to DSF	

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K152

Inspection

Question	Response
<b>Electrical</b>	
<b>AUDITORIUM</b>	Inspected
Instance on 2nd Floor	Inspected
<b>House Lighting</b>	Inspected
Does a Chandelier exist?	No
Instance on 2nd Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 2nd Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 2nd Floor	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on 2nd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
Instance on 2nd Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 2nd Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 2nd Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 2nd Floor	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on 2nd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on 2nd Floor	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on 2nd Floor	Does not Exist
<b>Local Sound System</b>	Inspected
Instance on 2nd Floor	Inspected
Installation Year	2011
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	NOT CONNECTED TO PUBLIC ADDRESS SYSTEM
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Projection System</b>	Inspected
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 2nd Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K152

Question	Response
<b>AUDITORIUM</b>	
<b>Theater Lighting System</b>	Inspected
Instance on 2nd Floor	Inspected
<b>Dimming System</b>	
Instance on 2nd Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting</b>	
Instance on 2nd Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>CAFETERIA</b>	
	Inspected
Instance on 1st Floor - Staff	Inspected
Instance on 1st Floor - Students	Inspected
<b>Lighting</b>	Inspected
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on 1st Floor - Students	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - Staff	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on 1st Floor - Students	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - Staff	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K152

Question	Response
<b>CAFETERIA</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Recessed Mounted</b>	
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
<b>Local Sound System</b>	
Instance on 1st Floor - Students	Inspected
Installation Year	1999
Source of Installation	Documented
Condition	5 - Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - Staff	Does not Exist
<b>Projection System</b>	
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
<b>Theater Lighting System</b>	
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	
Does a Chandelier exist?	No
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K152

Question	Response
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>COMPUTER LAB</b>	Does not Exist
<b>GYMNASIUM</b>	Inspected
Instance on 1st Floor	Inspected
<b>Lighting</b>	Inspected
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K152

Question	Response
<b>GYMNASIUM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - LED</b>	
<b>Pendant Mounted</b>	Inspected
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Local Sound System</b>	Inspected
Instance on 1st Floor	Inspected
Installation Year	1999
Source of Installation	Documented
Condition	5 - Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Projection System</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Scoreboard</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Theater Lighting System</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>KITCHEN</b>	Inspected
Instance on 1st Floor	Inspected
<b>Lighting</b>	Inspected
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not Exist
<b>LIBRARY</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K152

Question	Response
<b>LIBRARY</b>	
Instance on 1st Floor	Inspected
Instance on Room 303	Inspected
<b>Lighting</b>	Inspected
Instance on Room 303	Inspected
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 303	Inspected
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on Room 303	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	
Instance on Room 303	Does not Exist
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Room 303	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 303	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 303	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 303	Inspected
Instance on 1st Floor	Does not Exist
<b>Pendant Mounted</b>	
Instance on Room 303	Does not Exist
<b>Surface Mounted</b>	
Instance on Room 303	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Room 303	Does not Exist
<b>Raceway With Receptacles</b>	
Instance on Room 303	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K152

Question	Response
<b>LIBRARY</b>	
<b>Raceway With Receptacles</b>	Does not Exist
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Does not Exist
Instance on Room 303	Does not Exist
Instance on 1st Floor	Does not Exist
<b>LOCKER ROOM</b>	Does not Exist
<b>MULTIPURPOSE ROOM</b>	Does not Exist
<b>SCIENCE DEMO ROOM</b>	Inspected
Instance on Room 240	Inspected
Power Panel	No
Alternative use	No
<b>Lighting</b>	Inspected
Instance on Room 240	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 240	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Room 240	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on Room 240	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on Room 240	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on Room 240	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 240	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 240	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	Does not Exist
Instance on Room 240	Does not Exist
<b>Emergency Shut-Off Power</b>	Inspected
Instance on Room 240	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	Does not Exist
Instance on Room 240	Does not Exist
<b>Projection System</b>	Does not Exist
Instance on Room 240	Does not Exist
<b>SCIENCE LAB</b>	Does not Exist
<b>SCIENCE PREP ROOM</b>	Does not Exist
<b>SWIMMING POOL</b>	Does not Exist
<b>TOILET ROOM - STAFF</b>	Inspected
Lighting	Inspected



**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K152

Question	Response
<b>TOILET ROOM - STAFF</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Inspected
Replacement Quantity	151,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not Exist
<b>EMERGENCY GENERATOR SET</b>	Inspected
<b>Automatic Transfer Switch (ATS)</b>	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Cummins Onan
Equipment	Fire Alarm Automatic Transfer Switch
Capacity/Size Quantity	70
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1999
Source of Installation	Documented
Deficiency	PILOT LIGHT NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K152

Question	Response
<b>EMERGENCY GENERATOR SET</b>	
<b>Automatic Transfer Switch (ATS)</b>	
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Cummins Onan
Equipment	N/A
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1999
Source of Installation	Documented
Deficiency	PILOT LIGHT NOT OPERATIONAL
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Battery Charger</b>	
Instance	Inspected
Instance	3rd Floor - Emergency Generator Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Cummins Onan
Equipment	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size2 Quantity	24
Capacity/Size2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	1999
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Emergency Distribution Board</b>	
Instance	Inspected
Number of Spares	3
<b>Fused Disconnect Switch Type</b>	
Instance	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	DPE SEC. 1, 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K152

Question	Response
<b>EMERGENCY GENERATOR SET</b>	
<b>Emergency Distribution Board</b>	
<b>Fused Disconnect Switch Type</b>	
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1999
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Molded Case Circuit Breaker Type</b>	Does not Exist
<b>Diesel</b>	Inspected
Instance	3rd Floor - Emergency Generator Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Cummins Onan
Equipment	Emergency Generator
Capacity/Size Quantity	288
Capacity/Size UOM	KVA
Capacity/Size2 Quantity	230
Capacity/Size2 UOM	KW
Capacity/Size3Quantity	798
Capacity/Size3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1999
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Natural Gas</b>	Does not Exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Does not Exist
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EXIT/EMERGENCY LIGHT</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>FIRE ALARM SYSTEM</b>	Under Construction

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K152

<b>Question</b>	<b>Response</b>
<b>GROUNDING SYSTEM</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>INTERCOM SYSTEM</b>	Inspected
<b>Elevator</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Holding Area</b>	Does not Exist
<b>LAN</b>	Inspected
<b>Local Distribution Frame (LDF)</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	Does not Exist
<b>MOTOR CONTROLLER</b>	Inspected
<b>Motor Control Center</b>	Does not Exist
<b>Motor Starter/Contactor</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Variable Frequency Drive</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Basement - Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Fused Toggle Switch Type</b>	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room, Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Molded Case Circuit Breaker Type</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K152

Question	Response
<b>PANEL BOARD</b>	
<b>Molded Case Circuit Breaker Type</b>	
Condition	3 - Fair
Deficiency	NO SPARE
Deficiency Location/Instance	Corridor by Room 127
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Corridor by Rooms (306, 417)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>PUBLIC ADDRESS SYSTEM</b>	
	Inspected
Replacement Quantity	151,000
Replacement Uom	S.F.
Instance	Telecom Room 102E (Inside General Office)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane
Installation Year	1999
Source of Installation	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	18
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>SECURITY</b>	
	Inspected
<b>IPDVS/CCTV System</b>	
	Does not Exist
<b>Intrusion Alarm System</b>	
	Inspected
Replacement Quantity	151,000
Replacement Uom	S.F.
<b>Central Control Panel</b>	
	Inspected
Instance	Custodian's Office
Instance Condition	3 - Fair
Instance Quantity	1

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K152

Question	Response
<b>SECURITY</b>	
<b>Intrusion Alarm System</b>	
<b>Central Control Panel</b>	
Instance Quantity Uom	EACH
Model	Vista-128B
Installation Year	1999
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Infrared Sensor</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting - Security</b>	Inspected
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>SERVICE SWITCH</b>	
	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Gallagher
Equipment	Main Service Switch #1
Capacity/Size Quantity	4,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1999
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	American Switchboard Co.
Equipment	Main Service Switch #2
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1952
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>SWITCHBOARD</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K152

Question	Response
<b>SWITCHBOARD</b>	
Number of Spares	1
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	N/A
Capacity/Size Quantity	4,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1999
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	American Switchboard Co.
Equipment	N/A
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	1952
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Does not Exist
<b>TELEPHONE SYSTEM</b>	Inspected
<b>PBX/Intercom</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Standard</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>TRANSFORMER</b>	Inspected
Instance	By Electrical Room (Inside Staircase J)
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Hammond Power Solutions
Equipment	N/A
Capacity/Size Quantity	75
Capacity/Size UOM	KVA

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K152**

<b>Question</b>	<b>Response</b>
<b>TRANSFORMER</b>	
Source of Capacity/Size	Nameplate
Installation Year	2021
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded