

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K175**

**Asset: TEACHERS PREP HS(OL REDIRECTION)-K, 226 BRISTOL STREET, New York, 11212**

Inspection Id	Inspection Type	Time In	Last Edited
EE : K175	Electrical	2023-11-15 8:11 AM	2024-06-20 3:12 PM

**Asset Data**

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Fire Alarm System (CO Detector)
	Years: 2023
	Systems: Retrofitted LED Lighting - Except (Gymnasium)
	Years: 2022
	Systems: LAN
	Years: 2020
	Systems: Security Lights
	Years: 2019, 2022
	Systems: Gymnasium (Projection System), Local Sound System, Auxiliary Signal/Bell System, Fire Alarm System, Motor Controller (Variable Frequency Drive), Public Address System
	Years: 2018
	Systems: Telephone System
	Years: 2017
	Systems: Gymnasium (Lighting), Most Emergency Lighting (Battery Pack), Emergency Lighting (Non Battery Pack), Exit Lights (Battery Pack)
	Years: 2016
	Systems: Computer Lab (Raceway With Receptacles)
	Years: 2015
	Systems: IPDVS/CCTV System
	Years: 2012
	Systems: Intrusion Alarm System
	Years: 2000
	Systems: Emergency Generator Set (Automatic Transfer Switch)
	Years: 1998, 2018
	Systems: All Other Electrical Systems and Components
	Years: 1998
	Systems: Fused Disconnect Switch Type Panel Board
	Years: 1992
	Systems: Molded Case Circuit Breaker Type Panel Board
	Years: 1987, 1998, 2010, 2016

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

**Priority Condition**

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
-------------------------------------	-------------------	-----------------------	--------------------	----------------------	--------------------	-----------------	--------	------------

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

**K175**

Electrical Inspection

Yes	Emergency Generator - Defective Engine Cooling System	N/A	EMERGENCY GENERATOR SET   Diesel	Lower Roof - Generator Enclosure	David Feliciano	Custodian	Sent to DSF
-----	---	-----	----------------------------------	----------------------------------	-----------------	-----------	-------------

Inspection

Question	Response
<b>Electrical</b>	
<b>AUDITORIUM</b>	Does not Exist
<b>CAFETERIA</b>	Inspected
Instance on 1st Floor	Inspected
<b>Lighting</b>	Inspected
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Local Sound System</b>	Inspected
Instance on 1st Floor	Inspected
Installation Year	2018
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Theater Lighting System</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	Inspected
<b>Lighting</b>	Inspected
Does a Chandelier exist?	No
<b>Lighting Fixture - Fluorescent</b>	Does not Exist
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K175

Question	Response
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	
<b>Lighting Fixture - LED</b>	
<b>Surface Mounted</b>	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>COMPUTER LAB</b>	
Instance on Room 202	Inspected
Power Panel	No
<b>Lighting</b>	
Instance on Room 202	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 202	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 202	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 202	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 202	Inspected
<b>Pendant Mounted</b>	
Instance on Room 202	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 202	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Room 202	Does not Exist
<b>Raceway With Receptacles</b>	
Instance on Room 202	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>GYMNASIUM</b>	
Instance on 1st Floor	Inspected
<b>Lighting</b>	
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K175

Question	Response
<b>GYMNASIUM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - LED</b>	
<b>Pendant Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Local Sound System</b>	Inspected
Instance on 1st Floor	Inspected
Installation Year	2018
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Inspected
Is the projector on a cart or installed on the ceiling?	Cart
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Scoreboard</b>	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	Inspected
Instance on 1st Floor	Inspected
<b>Dimming System</b>	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting</b>	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>KITCHEN</b>	
Instance on 1st Floor	Inspected
<b>Lighting</b>	Inspected
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K175

Question	Response
<b>KITCHEN</b>	
<b>Lighting</b>	
<b>Lighting Fixture - LED</b>	
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>LIBRARY</b>	Inspected
Instance on Room 503	Inspected
<b>Lighting</b>	Inspected
Instance on Room 503	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 503	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 503	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 503	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 503	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Room 503	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on Room 503	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on Room 503	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Raceway With Receptacles</b>	Inspected
Instance on Room 503	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Does not Exist
Instance on Room 503	Does not Exist
<b>LOCKER ROOM</b>	Inspected
Instance on Basement - Boys, Basement - Girls	Inspected
Alternative use	No
Instance on Basement - Visitors	Inspected
Alternative use	No
<b>Lighting</b>	Inspected
Instance on Basement - Visitors	Inspected
Instance on Basement - Boys, Basement - Girls	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement - Visitors	Does not Exist
Instance on Basement - Boys, Basement - Girls	Does not Exist
<b>Lighting Fixture - HID</b>	

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K175

Question	Response
<b>LOCKER ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - HID</b>	
Instance on Basement - Visitors	Does not Exist
Instance on Basement - Boys, Basement - Girls	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement - Visitors	Does not Exist
Instance on Basement - Boys, Basement - Girls	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Basement - Visitors	Inspected
Instance on Basement - Boys, Basement - Girls	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Basement - Visitors	Does not Exist
Instance on Basement - Boys, Basement - Girls	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on Basement - Visitors	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Basement - Boys, Basement - Girls	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
Instance on Basement - Visitors	Does not Exist
Instance on Basement - Boys, Basement - Girls	Does not Exist
<b>MULTIPURPOSE ROOM</b>	Does not Exist
<b>SCIENCE DEMO ROOM</b>	Does not Exist
<b>SCIENCE LAB</b>	Inspected
Instance on Room 406	Inspected
Power Panel	Yes
Alternative use	No
<b>Lighting</b>	Inspected
Instance on Room 406	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 406	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 406	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 406	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 406	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Room 406	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Instance on Room 406	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K175

Question	Response
<b>SCIENCE LAB</b>	
<b>Lighting</b>	Inspected
<b>Lighting Fixture - LED</b>	
<b>Recessed Mounted</b>	
Instance on Room 406	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	Inspected
Instance on Room 406	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	Inspected
Instance on Room 406	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	Does not Exist
Instance on Room 406	Does not Exist
<b>Projection System</b>	Does not Exist
Instance on Room 406	Does not Exist
<b>SCIENCE PREP ROOM</b>	Inspected
Instance on Room 408	Inspected
Power Panel	No
Alternative use	No
<b>Lighting</b>	Inspected
Instance on Room 408	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 408	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 408	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 408	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 408	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Room 408	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on Room 408	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 408	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	Inspected
Instance on Room 408	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	Inspected
Instance on Room 408	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	Does not Exist
Instance on Room 408	Does not Exist
<b>SWIMMING POOL</b>	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K175

Question	Response
<b>TOILET ROOM - STAFF</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Does not Exist
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Does not Exist
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Inspected
Replacement Quantity	89,000
Replacement Uom	S.F.
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not Exist
<b>EMERGENCY GENERATOR SET</b>	Inspected
<b>Automatic Transfer Switch (ATS)</b>	Inspected
Instance	Electrical Room B9
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	N/A
Capacity/Size Quantity	80
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2018
Source of Installation	Documented



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K175

<b>Question</b>	<b>Response</b>
<b>EMERGENCY GENERATOR SET</b>	
<b>Automatic Transfer Switch (ATS)</b>	
Deficiency	No deficiencies recorded
Instance	Electrical Room B9
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Kohler Power Systems
Equipment	N/A
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1998
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Battery Charger</b>	
Instance	Inspected
Instance	Electrical Room B9
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Kohler Power Systems
Equipment	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size2 Quantity	13
Capacity/Size2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	1998
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Emergency Distribution Board</b>	
Number of Spares	Inspected
Number of Spares	2
<b>Fused Disconnect Switch Type</b>	
Instance	Inspected
Instance	Electrical Room B9
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	EMDP
Capacity/Size Quantity	400
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1998
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Molded Case Circuit Breaker Type</b>	
Molded Case Circuit Breaker Type	Does not Exist
<b>Diesel</b>	
Diesel	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K175

Question	Response
<b>EMERGENCY GENERATOR SET</b>	
<b>Diesel</b>	
Instance	Lower Roof - Generator Enclosure
Instance Condition	4 - Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Kohler Power Systems
Equipment	Emergency Generator
Capacity/Size Quantity	188
Capacity/Size UOM	KVA
Capacity/Size2 Quantity	150
Capacity/Size2 UOM	KW
Capacity/Size3Quantity	520
Capacity/Size3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1998
Source of Installation	Documented
Deficiency	DEFECTIVE ENGINE COOLING SYSTEM
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Natural Gas</b>	Does not Exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Does not Exist
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EXIT/EMERGENCY LIGHT</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>FIRE ALARM SYSTEM</b>	Inspected
Replacement Quantity	89,000
Replacement Uom	S.F.
<b>Bell/Horn</b>	Inspected
Condition	2 - Between Good and Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K175

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	
<b>Bell/Horn</b>	Inspected
Deficiency	No deficiencies recorded
<b>Strobe</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Manual Pull Station</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fan Shutdown Control</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Duct Smoke Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Area Smoke Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>CO Detector</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Heat Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Elevator Recall</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Magnetic Door Holder/Contactor</b>	Does not Exist
<b>Fused Cutout Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	Does not Exist
<b>Main Panel</b>	Inspected
<b>Bell At Panel</b>	Does not Exist
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Gamewell
Equipment	Fire Alarm Control Panel
Model	EST3X
Installation Year	2018
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	Does not Exist
<b>Sub-Panel</b>	Does not Exist
<b>Remote Annunciator</b>	Inspected
<b>Display Monitor</b>	Does not Exist
<b>Panel</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K175

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Remote Annunciator</b>	
<b>Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Printer</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Punch Register</b>	Does not Exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Tamper Flow Switch/Chain</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>GROUNDING SYSTEM</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>INTERCOM SYSTEM</b>	Inspected
<b>Elevator</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Holding Area</b>	Does not Exist
<b>LAN</b>	Inspected
<b>Local Distribution Frame (I/LDF)</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	Does not Exist
<b>MOTOR CONTROLLER</b>	Inspected
<b>Motor Control Center</b>	Does not Exist
<b>Motor Starter/Contactor</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Variable Frequency Drive</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Fused Toggle Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	3 - Fair
Deficiency	NO SPARE
Deficiency Location/Instance	Corridor by 205
Deficiency Quantity	1

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K175

Question	Response
<b>PANEL BOARD</b>	
<b>Molded Case Circuit Breaker Type</b>	
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Electrical Room B9
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>PUBLIC ADDRESS SYSTEM</b>	Inspected
Replacement Quantity	89,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Bogen HTA250A
Installation Year	2018
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
<b>SECURITY</b>	Inspected
<b>IPDVS/CCTV System</b>	Inspected
Replacement Quantity	89,000
Replacement Uom	S.F.
Installation Year	2012
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Intrusion Alarm System</b>	Inspected
Replacement Quantity	89,000
Replacement Uom	S.F.
<b>Central Control Panel</b>	Inspected
Instance	Custodian's Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista-128B
Installation Year	2000
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Infrared Sensor</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K175

Question	Response
<b>SECURITY</b>	
<b>Intrusion Alarm System</b>	
<b>Infrared Sensor</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting - Security</b>	Inspected
Replacement Uom	EACH
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>SERVICE SWITCH</b>	Inspected
Instance	Electrical Room B9
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	MAIN SERVC DISC
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1998
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room B9
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	Kitchen
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1998
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room B9
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	EMDP
Capacity/Size Quantity	400

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K175

Question	Response
<b>SERVICE SWITCH</b>	
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1998
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>SWITCHBOARD</b>	Inspected
Number of Spares	2
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	Electrical Room B8
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	N/A
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1998
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Does not Exist
<b>TELEPHONE SYSTEM</b>	Inspected
<b>PBX/Intercom</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Standard</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>TRANSFORMER</b>	Does not Exist