

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K211**

**Asset: I.S. 211 - BROOKLYN, 1001 EAST 100 STREET, New York, 11236**

Inspection Id	Inspection Type	Time In	Last Edited
EE : K211	Electrical	2023-11-30 8:23 AM	2024-06-11 4:11 PM

**Asset Data**

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Retrofitted LED Lighting - Except (Gymnasium), Security Lights
	Years: 2023
	Systems: Motor Controller (Partial Motor Starter/Contactor), Intrusion Alarm System (Infrared Sensor, Panic Switch, Remote Annunciator)
	Years: 2022
	Systems: Emergency Generator Set - Except (Emergency Distribution Board)
	Years: 2019
	Systems: Library (Raceway With Receptacles)
	Years: 2018
	Systems: Most Exit Lights (Battery Pack)
	Years: 2017, 2019, 2022
	Systems: Intrusion Alarm System (Central Control Panel)
	Years: 2017
	Systems: Motor Controller (Variable Frequency Drive)
	Years: 2016
	Systems: Gymnasium (LED Lighting), Most Emergency Lighting (Non Battery Pack), IPDVS/CCTV System
	Years: 2015
	Systems: Local Sound System, Auxiliary Signal/Bell System, Fire Alarm System - Except (Sprinkler Flow/Air Pressure Switch), Public Address System
	Years: 2013
	Systems: Emergency Generator Set (Emergency Distribution Board), Partial Service Switch
	Years: 1996
	Systems: Partial Molded Case Circuit Breaker Type Panel Board
	Years: 1990, 2002, 2007, 2013, 2019

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

**Priority Condition**

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Intercom System - Does Not Exist	N/A	Intercom System - Holding Area	Room 301	Vinod Harripaul	Custodian	Sent to DSF	
No	Water Leaks onto Electrical Equipment	N/A	Lighting Fixture	Room B38	Jonathan Jewnath	Fireman	Sent to DSF	

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K211**

Inspection

<b>Question</b>	<b>Response</b>
<b>Electrical</b>	
<b>AUDITORIUM</b>	Inspected
Instance on 1st Floor	Inspected
<b>House Lighting</b>	Inspected
Does a Chandelier exist?	No
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Local Sound System</b>	Inspected
Instance on 1st Floor	Inspected
Installation Year	2013
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Theater Lighting System</b>	Inspected
Instance on 1st Floor	Inspected
<b>Dimming System</b>	
Instance on 1st Floor	Inspected
Condition	5 - Poor
Deficiency	DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Theater Lighting</b>	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	108

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K211

Question	Response
<b>AUDITORIUM</b>	
<b>Theater Lighting System</b>	
<b>Theater Lighting</b>	
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo	No photo recorded
Violations	No violations recorded.
<b>CAFETERIA</b>	
	Inspected
Instance on Basement - Staff	Inspected
Instance on Basement - Students	Inspected
<b>Lighting</b>	Inspected
Instance on Basement - Students	Inspected
Instance on Basement - Staff	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement - Students	Does not Exist
Instance on Basement - Staff	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Basement - Students	Does not Exist
Instance on Basement - Staff	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement - Students	Does not Exist
Instance on Basement - Staff	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Basement - Students	Inspected
Instance on Basement - Staff	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Basement - Students	Does not Exist
Instance on Basement - Staff	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on Basement - Students	Does not Exist
Instance on Basement - Staff	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on Basement - Students	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Basement - Staff	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Local Sound System</b>	Inspected
Instance on Basement - Students	Inspected
Installation Year	2013
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Basement - Staff	Does not Exist
<b>Projection System</b>	Does not Exist
Instance on Basement - Students	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K211

Question	Response
<b>CAFETERIA</b>	
<b>Projection System</b>	Does not Exist
Instance on Basement - Staff	Does not Exist
<b>Theater Lighting System</b>	Does not Exist
Instance on Basement - Students	Does not Exist
Instance on Basement - Staff	Does not Exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	Inspected
Does a Chandelier exist?	No
<b>Lighting Fixture - Fluorescent</b>	Does not Exist
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>COMPUTER LAB</b>	
Instance on Room 204	Inspected
Power Panel	Yes
<b>Lighting</b>	Inspected
Instance on Room 204	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 204	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 204	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 204	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 204	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Room 204	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on Room 204	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 204	Does not Exist
<b>Raceway With Receptacles</b>	Inspected
Instance on Room 204	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>GYMNASIUM</b>	
Instance on 1st Floor	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K211

Question	Response
<b>GYMNASIUM</b>	
<b>Lighting</b>	Inspected
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Local Sound System</b>	Inspected
Instance on 1st Floor	Inspected
Installation Year	2013
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Scoreboard</b>	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>KITCHEN</b>	
Instance on Basement	Inspected
<b>Lighting</b>	Inspected
Instance on Basement	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Basement	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K211

Question	Response
<b>KITCHEN</b>	
<b>Lighting</b>	
<b>Lighting Fixture - LED</b>	
<b>Surface Mounted</b>	Does not Exist
Instance on Basement	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>LIBRARY</b>	Inspected
Instance on 2nd Floor	Inspected
<b>Lighting</b>	Inspected
Instance on 2nd Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 2nd Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 2nd Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 2nd Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 2nd Floor	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on 2nd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on 2nd Floor	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on 2nd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Raceway With Receptacles</b>	Inspected
Instance on 2nd Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Projection System</b>	Does not Exist
Instance on 2nd Floor	Does not Exist
<b>LOCKER ROOM</b>	Does not Exist
<b>MULTIPURPOSE ROOM</b>	Does not Exist
<b>SCIENCE DEMO ROOM</b>	Inspected
Instance on Rooms 101, 201, 205	Inspected
Power Panel	No
Alternative use	Yes
<b>Lighting</b>	Inspected
Instance on Rooms 101, 201, 205	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Rooms 101, 201, 205	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Rooms 101, 201, 205	Does not Exist
<b>Lighting Fixture - Incandescent</b>	

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K211

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
Instance on Rooms 101, 201, 205	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Rooms 101, 201, 205	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Rooms 101, 201, 205	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on Rooms 101, 201, 205	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
Instance on Rooms 101, 201, 205	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	Does not Exist
Instance on Rooms 101, 201, 205	Does not Exist
<b>Emergency Shut-Off Power</b>	Does not Exist
Instance on Rooms 101, 201, 205	Does not Exist
<b>Power Supply</b>	Does not Exist
Instance on Rooms 101, 201, 205	Does not Exist
<b>Projection System</b>	Does not Exist
Instance on Rooms 101, 201, 205	Does not Exist
<b>SCIENCE LAB</b>	Inspected
Instance on Room 209	Inaccessible
<b>SCIENCE PREP ROOM</b>	Inspected
Instance on Room 203	Inaccessible
Instance on Room 303	Inspected
Power Panel	No
Alternative use	Yes
<b>Lighting</b>	Inspected
Instance on Room 303	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 303	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 303	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 303	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 303	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Room 303	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on Room 303	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 303	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	Does not Exist
Instance on Room 303	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K211

Question	Response
<b>SCIENCE PREP ROOM</b>	Inspected
<b>Emergency Shut-Off Power</b>	Does not Exist
Instance on Room 303	Does not Exist
<b>Power Supply</b>	Does not Exist
Instance on Room 303	Does not Exist
<b>SWIMMING POOL</b>	Does not Exist
<b>TOILET ROOM - STAFF</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Does not Exist
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Does not Exist
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Inspected
Replacement Quantity	140,000
Replacement Uom	S.F.
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not Exist
<b>EMERGENCY GENERATOR SET</b>	Inspected
<b>Automatic Transfer Switch (ATS)</b>	Inspected
Instance	Electrical Room B21
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	ATS-1
Capacity/Size Quantity	200
Capacity/Size UOM	Amps



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K211

Question	Response
<b>EMERGENCY GENERATOR SET</b>	
<b>Automatic Transfer Switch (ATS)</b>	
Source of Capacity/Size	Nameplate
Installation Year	2019
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Electrical Room B21
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	F.A.C.P ATS-2
Capacity/Size Quantity	30
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2019
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
<b>Battery Charger</b>	Inspected
Instance	Roof - Outdoor Generator Enclosure
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	SENS
Equipment	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size2 Quantity	24
Capacity/Size2 UOM	VDC
Source of Capacity/Size	Inspector Estimate
Installation Year	2019
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
<b>Emergency Distribution Board</b>	Inspected
Number of Spares	4
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	Electrical Room B21
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Cutler Hammer
Equipment	DP-EM
Capacity/Size Quantity	200
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	1996
Source of Installation	Documented

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K211

Question	Response
<b>EMERGENCY GENERATOR SET</b>	
<b>Emergency Distribution Board</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Inspected
Deficiency	No deficiencies recorded
<b>Molded Case Circuit Breaker Type</b>	Does not Exist
<b>Diesel</b>	Does not Exist
<b>Natural Gas</b>	Inspected
Instance	Roof - Outdoor Generator Enclosure
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	MTU onsite energy
Equipment	Emergency Generator
Capacity/Size Quantity	87
Capacity/Size UOM	KVA
Capacity/Size2 Quantity	70
Capacity/Size2 UOM	KW
Capacity/Size3Quantity	242
Capacity/Size3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2019
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Does not Exist
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Does not Exist
<b>EXIT/EMERGENCY LIGHT</b>	Does not Exist
<b>FIRE ALARM SYSTEM</b>	Inspected
Replacement Quantity	140,000
Replacement Uom	S.F.
<b>Bell/Horn</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Strobe</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Manual Pull Station</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K211

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Fan Shutdown Control</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Duct Smoke Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Area Smoke Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>CO Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Heat Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Elevator Recall</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Magnetic Door Holder/Contactor</b>	Does not Exist
<b>Fused Cutout Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	Does not Exist
<b>Main Panel</b>	Inspected
<b>Bell At Panel</b>	Does not Exist
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards System Technology
Equipment	Fire Alarm Control Panel
Model	EST
Installation Year	2013
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	Does not Exist
<b>Sub-Panel</b>	Does not Exist
<b>Remote Annunciator</b>	Inspected
<b>Display Monitor</b>	Does not Exist
<b>Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Printer</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Punch Register</b>	Does not Exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected
Condition	3 - Fair

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K211**

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected
Deficiency	No deficiencies recorded
<b>Tamper Flow Switch/Chain</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>GROUNDING SYSTEM</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>INTERCOM SYSTEM</b>	Inspected
<b>Elevator</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Holding Area</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>LAN</b>	Inspected
<b>Local Distribution Frame (I/LDF)</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	Does not Exist
<b>MOTOR CONTROLLER</b>	Inspected
<b>Motor Control Center</b>	Does not Exist
<b>Motor Starter/Contactor</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Variable Frequency Drive</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Does not Exist
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Fused Toggle Switch Type</b>	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B21, Auditorium
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	3 - Fair
Deficiency	NO SPARE
Deficiency Location/Instance	Kitchen, Basement - Mechanical Room

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K211**

<b>Question</b>	<b>Response</b>
<b>PANEL BOARD</b>	
<b>Molded Case Circuit Breaker Type</b>	
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Cafeteria - Students, Cafeteria - Mechanical Room, Corridor by Rooms (B3, B24,115, 125, 215, 225, 315, 327), Room 204, Projection Room, Gymnasium
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>PUBLIC ADDRESS SYSTEM</b>	Inspected
Replacement Quantity	140,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland Telecenter
Installation Year	2013
Source of Installation	Inspector Estimate
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Library
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>SECURITY</b>	Inspected
<b>IPDVS/CCTV System</b>	Inspected
Replacement Quantity	140,000
Replacement Uom	S.F.
Installation Year	2015
Source of Installation	Inspector Estimate
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Intrusion Alarm System</b>	Inspected
Replacement Quantity	140,000
Replacement Uom	S.F.

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K211**

<b>Question</b>	<b>Response</b>
<b>SECURITY</b>	
<b>Intrusion Alarm System</b>	
<b>Central Control Panel</b>	Inspected
Instance	Custodian's Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista-128BPT
Installation Year	2017
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
<b>Infrared Sensor</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	Inspected
Condition	3 - Fair
Deficiency	SIREN/STROBE NOT ACTIVE
Deficiency Location/Instance	Exterior Wall facing East 100th Street
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting - Security</b>	Inspected
Replacement Uom	EACH
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>SERVICE SWITCH</b>	
Instance	Electrical Room B21
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Empire Switchboard
Equipment	SER A
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1958
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room B21
Instance Condition	3 - Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K211

Question	Response
<b>SERVICE SWITCH</b>	
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Empire Switchboard
Equipment	SER B
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1958
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room B21
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Cutler Hammer
Equipment	MAIN SW. EMERG. LTG. PANELS
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1996
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>SWITCHBOARD</b>	Inspected
Number of Spares	3
<b>Fused Disconnect Switch Type</b>	Does not Exist
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Inspected
Instance	Electrical Room B21
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Empire Switchboard
Equipment	SER A
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	1958
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room B21
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Empire Switchboard
Equipment	SER B
Capacity/Size Quantity	1,200

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K211**

Question	Response
<b>SWITCHBOARD</b>	
<b>Molded Case Circuit Breaker Type</b>	
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	1958
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>TELEPHONE SYSTEM</b>	Inspected
<b>PBX/Intercom</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Standard</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>TRANSFORMER</b>	Does not Exist