

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K223**

**Asset: I.S. 223 - BROOKLYN, 4200 16 AVENUE, New York, 11204**

| Inspection Id | Inspection Type | Time In            | Last Edited         |
|---------------|-----------------|--------------------|---------------------|
| EE : K223     | Electrical      | 2024-05-23 7:44 AM | 2024-06-03 12:44 PM |

**Asset Data**

| Question  | Answer   |
|---|--|
| Type of Service   | Below Ground   |
| Does Interactive Whiteboard (IWB) Exist?                  | Yes  |
| Water Penetration in Electrical Room?                     | No   |
| Have any Systems/Major Building Components been upgraded? | Yes  |
|   | Systems: LAN   |
|   | Years: 2023  |
|   | Systems: Auditorium (Local Sound System, Projection System), Science Lab - Room 411 - Except (Fluorescent Lighting), Public Address System (Amplifier)     |
|   | Years: 2018  |
|   | Systems: Interior Lighting, Most Emergency Lighting (Non Battery Pack)   |
|   | Years: 2014  |
|   | Systems: IPDVS/CCTV System   |
|   | Years: 2011  |
|   | Systems: Fire Alarm System (Strobe, Elevator Recall, Electronic Sub-Panel, Sprinkler Flow/Air Pressure Switch), Public Address System (Tuner), Transformer |
|   | Years: 2009  |
|   | Systems: Most Fused Disconnect Switch Type Panel Board   |
|   | Years: 2001, 2009  |
|   | Systems: Emergency Light/Exit Light Panel  |
|   | Years: 2001  |
|   | Systems: Intrusion Alarm System  |
|   | Years: 1998  |
|   | Systems: Security Lights   |
|   | Years: 1996, 2001, 2015  |
|   | Systems: Partial Molded Case Circuit Breaker Type Panel Board  |
|   | Years: 1987, 1996, 2000, 2009, 2016  |

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

| Question  | Response |
|---|----------|
| Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building? | No       |

**Priority Condition**

| Priority Condition Exist Last Year? | Priority Category | Condition Description | Component Affected | Location Description | Person(s) Notified | Person(s) Title | Status | PhotoImage |
|-------------------------------------|-------------------|-----------------------|--------------------|----------------------|--------------------|-----------------|--------|------------|
| No condition recorded               |                   |                       |                    |                      |                    |                 |        |            |

**Inspection**

| Question                              | Response       |
|---------------------------------------|----------------|
| <b>Electrical</b>                     |                |
| <b>AUDITORIUM</b>                     | Inspected      |
| Instance on 1st Floor                 | Inspected      |
| <b>House Lighting</b>                 | Inspected      |
| Does a Chandelier exist?              | No             |
| Instance on 1st Floor                 | Inspected      |
| <b>Lighting Fixture - Fluorescent</b> |                |
| Instance on 1st Floor                 | Does not Exist |
| <b>Lighting Fixture - HID</b>         |                |

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K223

| Question  | Response                            |
|---|-------------------------------------|
| <b>AUDITORIUM</b>                                       |                                     |
| <b>House Lighting</b>                                   |                                     |
| <b>Lighting Fixture - HID</b>                           |                                     |
| Instance on 1st Floor                                   | Does not Exist                      |
| <b>Lighting Fixture - Incandescent</b>                  |                                     |
| Instance on 1st Floor                                   | Does not Exist                      |
| <b>Lighting Fixture - LED</b>                           |                                     |
| Instance on 1st Floor                                   | Inspected                           |
| <b>Pendant Mounted</b>                                  |                                     |
| Instance on 1st Floor                                   | Inspected                           |
| Condition   | 2 - Between Good and Fair           |
| Deficiency  | No deficiencies recorded            |
| <b>Surface Mounted</b>                                  |                                     |
| Instance on 1st Floor                                   | Does not Exist                      |
| <b>Recessed Mounted</b>                                 |                                     |
| Instance on 1st Floor                                   | Does not Exist                      |
| <b>Local Sound System</b>                               |                                     |
| Instance on 1st Floor                                   | Inspected                           |
| Installation Year                                       | 2018                                |
| Source of Installation                                  | Custodial Staff                     |
| Condition   | 2 - Between Good and Fair           |
| Deficiency  | No deficiencies recorded            |
| <b>Projection System</b>                                |                                     |
| Is the projector on a cart or installed on the ceiling? | Ceiling                             |
| Instance on 1st Floor                                   | Inspected                           |
| Condition   | 1 - Good                            |
| Deficiency  | No deficiencies recorded            |
| <b>Theater Lighting System</b>                          |                                     |
| Instance on 1st Floor                                   | Inspected                           |
| <b>Dimming System</b>                                   |                                     |
| Instance on 1st Floor                                   | Does not Exist                      |
| <b>Theater Lighting</b>                                 |                                     |
| Instance on 1st Floor                                   | Inspected                           |
| Condition   | 3 - Fair                            |
| Deficiency  | LIGHTING FIXTURE BEYOND USEFUL LIFE |
| Deficiency Quantity                                     | 27                                  |
| Quantity Uom  | EACH                                |
| Potential Action  | REPLACE-UPGRADE                     |
| Urgency of Action                                       | PRIORITY 1                          |
| Purpose of Action                                       | LEVEL 2                             |
| Deficiency Photo1                                       | No photo recorded                   |
| Violations  | No violations recorded.             |
| <b>CAFETERIA</b>  |                                     |
| Instance on Basement                                    | Inspected                           |
| <b>Lighting</b>   |                                     |
| Instance on Basement                                    | Inspected                           |
| <b>Lighting Fixture - Fluorescent</b>                   |                                     |
| Instance on Basement                                    | Inspected                           |
| <b>Pendant Mounted</b>                                  |                                     |
|   | Inspected                           |

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K223

| Question                                       | Response                  |
|--|---------------------------|
| <b>CAFETERIA</b>                               |                           |
| <b>Lighting</b>                                |                           |
| <b>Lighting Fixture - Fluorescent</b>          |                           |
| <b>Pendant Mounted</b>                         | Inspected                 |
| Instance on Basement                           | Inspected                 |
| Condition                                      | 2 - Between Good and Fair |
| Deficiency                                     | No deficiencies recorded  |
| <b>Surface Mounted</b>                         | Inspected                 |
| Instance on Basement                           | Inspected                 |
| Condition                                      | 2 - Between Good and Fair |
| Deficiency                                     | No deficiencies recorded  |
| <b>Recessed Mounted</b>                        | Does not Exist            |
| Instance on Basement                           | Does not Exist            |
| <b>Lighting Fixture - HID</b>                  |                           |
| Instance on Basement                           | Does not Exist            |
| <b>Lighting Fixture - Incandescent</b>         |                           |
| Instance on Basement                           | Does not Exist            |
| <b>Lighting Fixture - LED</b>                  |                           |
| Instance on Basement                           | Does not Exist            |
| <b>Local Sound System</b>                      | Inspected                 |
| Instance on Basement                           | Inspected                 |
| Installation Year                              | 2001                      |
| Source of Installation                         | Inspector Estimate        |
| Condition                                      | 3 - Fair                  |
| Deficiency                                     | No deficiencies recorded  |
| <b>Projection System</b>                       | Does not Exist            |
| Instance on Basement                           | Does not Exist            |
| <b>Theater Lighting System</b>                 | Does not Exist            |
| Instance on Basement                           | Does not Exist            |
| <b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b> | Inspected                 |
| <b>Lighting</b>                                | Inspected                 |
| Does a Chandelier exist?                       | No                        |
| <b>Lighting Fixture - Fluorescent</b>          | Inspected                 |
| <b>Pendant Mounted</b>                         | Inspected                 |
| Condition                                      | 2 - Between Good and Fair |
| Deficiency                                     | No deficiencies recorded  |
| <b>Surface Mounted</b>                         | Inspected                 |
| Condition                                      | 2 - Between Good and Fair |
| Deficiency                                     | No deficiencies recorded  |
| <b>Recessed Mounted</b>                        | Does not Exist            |
| <b>Lighting Fixture - HID</b>                  | Does not Exist            |
| <b>Lighting Fixture - Incandescent</b>         | Does not Exist            |
| <b>Lighting Fixture - LED</b>                  | Does not Exist            |
| <b>COMPUTER LAB</b>                            | Inspected                 |
| Instance on Room 105                           | Inspected                 |
| Power Panel                                    | No                        |
| <b>Lighting</b>                                | Inspected                 |
| Instance on Room 105                           | Inspected                 |
| <b>Lighting Fixture - Fluorescent</b>          |                           |

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K223

| Question                               | Response                  |
|--|---------------------------|
| <b>COMPUTER LAB</b>                    |                           |
| <b>Lighting</b>                        |                           |
| <b>Lighting Fixture - Fluorescent</b>  |                           |
| Instance on Room 105                   | Inspected                 |
| <b>Pendant Mounted</b>                 |                           |
| Instance on Room 105                   | Inspected                 |
| Condition                              | 2 - Between Good and Fair |
| Deficiency                             | No deficiencies recorded  |
| <b>Surface Mounted</b>                 |                           |
| Instance on Room 105                   | Does not Exist            |
| <b>Recessed Mounted</b>                |                           |
| Instance on Room 105                   | Does not Exist            |
| <b>Lighting Fixture - HID</b>          |                           |
| Instance on Room 105                   | Does not Exist            |
| <b>Lighting Fixture - Incandescent</b> |                           |
| Instance on Room 105                   | Does not Exist            |
| <b>Lighting Fixture - LED</b>          |                           |
| Instance on Room 105                   | Does not Exist            |
| <b>Raceway With Receptacles</b>        |                           |
| Instance on Room 105                   | Inspected                 |
| Condition                              | 3 - Fair                  |
| Deficiency                             | No deficiencies recorded  |
| <b>GYMNASIUM</b>                       |                           |
| Instance on 3rd Floor                  | Inspected                 |
| Instance on 4th Floor                  | Inspected                 |
| <b>Lighting</b>                        |                           |
| Instance on 4th Floor                  | Inspected                 |
| Instance on 3rd Floor                  | Inspected                 |
| <b>Lighting Fixture - Fluorescent</b>  |                           |
| Instance on 4th Floor                  | Does not Exist            |
| Instance on 3rd Floor                  | Does not Exist            |
| <b>Lighting Fixture - HID</b>          |                           |
| Instance on 4th Floor                  | Does not Exist            |
| Instance on 3rd Floor                  | Does not Exist            |
| <b>Lighting Fixture - Incandescent</b> |                           |
| Instance on 4th Floor                  | Does not Exist            |
| Instance on 3rd Floor                  | Does not Exist            |
| <b>Lighting Fixture - LED</b>          |                           |
| Instance on 4th Floor                  | Inspected                 |
| Instance on 3rd Floor                  | Inspected                 |
| <b>Pendant Mounted</b>                 |                           |
| Instance on 4th Floor                  | Inspected                 |
| Condition                              | 2 - Between Good and Fair |
| Deficiency                             | No deficiencies recorded  |
| Instance on 3rd Floor                  | Inspected                 |
| Condition                              | 2 - Between Good and Fair |
| Deficiency                             | No deficiencies recorded  |
| <b>Surface Mounted</b>                 |                           |
| Instance on 4th Floor                  | Inspected                 |

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K223

| Question                              | Response                  |
|---------------------------------------|---------------------------|
| <b>GYMNASIUM</b>                      |                           |
| <b>Lighting</b>                       |                           |
| <b>Lighting Fixture - LED</b>         |                           |
| <b>Surface Mounted</b>                | Inspected                 |
| Condition                             | 2 - Between Good and Fair |
| Deficiency                            | No deficiencies recorded  |
| Instance on 3rd Floor                 | Does not Exist            |
| <b>Recessed Mounted</b>               | Does not Exist            |
| Instance on 4th Floor                 | Does not Exist            |
| Instance on 3rd Floor                 | Does not Exist            |
| <b>Local Sound System</b>             | Does not Exist            |
| Instance on 4th Floor                 | Does not Exist            |
| Instance on 3rd Floor                 | Inspected                 |
| Installation Year                     | 2001                      |
| Source of Installation                | Inspector Estimate        |
| Condition                             | 3 - Fair                  |
| Deficiency                            | No deficiencies recorded  |
| <b>Projection System</b>              | Does not Exist            |
| Instance on 4th Floor                 | Does not Exist            |
| Instance on 3rd Floor                 | Does not Exist            |
| <b>Scoreboard</b>                     | Inspected                 |
| Instance on 4th Floor                 | Inspected                 |
| Condition                             | 5 - Poor                  |
| Deficiency                            | NOT OPERATIONAL           |
| Deficiency Quantity                   | 1                         |
| Quantity Uom                          | EACH                      |
| Potential Action                      | REPLACE                   |
| Urgency of Action                     | PRIORITY 3                |
| Purpose of Action                     | LEVEL 2                   |
| Deficiency Photo1                     | No photo recorded         |
| Violations                            | No violations recorded.   |
| Instance on 3rd Floor                 | Inspected                 |
| Condition                             | 3 - Fair                  |
| Deficiency                            | No deficiencies recorded  |
| <b>Theater Lighting System</b>        | Does not Exist            |
| Instance on 4th Floor                 | Does not Exist            |
| Instance on 3rd Floor                 | Does not Exist            |
| <b>KITCHEN</b>                        |                           |
| Instance on Basement                  | Inspected                 |
| <b>Lighting</b>                       | Inspected                 |
| Instance on Basement                  | Inspected                 |
| <b>Lighting Fixture - Fluorescent</b> |                           |
| Instance on Basement                  | Inspected                 |
| <b>Pendant Mounted</b>                | Does not Exist            |
| Instance on Basement                  | Does not Exist            |
| <b>Surface Mounted</b>                | Inspected                 |
| Instance on Basement                  | Inspected                 |
| Condition                             | 2 - Between Good and Fair |
| Deficiency                            | No deficiencies recorded  |

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K223

| Question                               | Response                  |
|--|---------------------------|
| <b>KITCHEN</b>                         |                           |
| <b>Lighting</b>                        |                           |
| <b>Lighting Fixture - Fluorescent</b>  |                           |
| <b>Recessed Mounted</b>                | Does not Exist            |
| Instance on Basement                   | Does not Exist            |
| <b>Lighting Fixture - HID</b>          |                           |
| Instance on Basement                   | Does not Exist            |
| <b>Lighting Fixture - Incandescent</b> |                           |
| Instance on Basement                   | Does not Exist            |
| <b>Lighting Fixture - LED</b>          |                           |
| Instance on Basement                   | Does not Exist            |
| <b>LIBRARY</b>                         | Inspected                 |
| Instance on Room 307                   | Inaccessible              |
| <b>LOCKER ROOM</b>                     | Inspected                 |
| Instance on 4th Floor                  | Inspected                 |
| Alternative use                        | Yes                       |
| <b>Lighting</b>                        | Inspected                 |
| Instance on 4th Floor                  | Inspected                 |
| <b>Lighting Fixture - Fluorescent</b>  |                           |
| Instance on 4th Floor                  | Inspected                 |
| <b>Pendant Mounted</b>                 | Does not Exist            |
| Instance on 4th Floor                  | Does not Exist            |
| <b>Surface Mounted</b>                 | Inspected                 |
| Instance on 4th Floor                  | Inspected                 |
| Condition                              | 2 - Between Good and Fair |
| Deficiency                             | No deficiencies recorded  |
| <b>Recessed Mounted</b>                | Does not Exist            |
| Instance on 4th Floor                  | Does not Exist            |
| <b>Lighting Fixture - HID</b>          |                           |
| Instance on 4th Floor                  | Does not Exist            |
| <b>Lighting Fixture - Incandescent</b> |                           |
| Instance on 4th Floor                  | Does not Exist            |
| <b>Lighting Fixture - LED</b>          |                           |
| Instance on 4th Floor                  | Does not Exist            |
| <b>MULTIPURPOSE ROOM</b>               | Does not Exist            |
| <b>SCIENCE DEMO ROOM</b>               | Inspected                 |
| Instance on Room 213                   | Inspected                 |
| Power Panel                            | No                        |
| Alternative use                        | No                        |
| Instance on Room 313                   | Inspected                 |
| Power Panel                            | No                        |
| Alternative use                        | No                        |
| <b>Lighting</b>                        | Inspected                 |
| Instance on Room 313                   | Inspected                 |
| Instance on Room 213                   | Inspected                 |
| <b>Lighting Fixture - Fluorescent</b>  |                           |
| Instance on Room 313                   | Inspected                 |
| Instance on Room 213                   | Inspected                 |
| <b>Pendant Mounted</b>                 | Inspected                 |

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K223

| Question                               | Response                  |
|--|---------------------------|
| <b>SCIENCE DEMO ROOM</b>               |                           |
| <b>Lighting</b>                        |                           |
| <b>Lighting Fixture - Fluorescent</b>  |                           |
| <b>Pendant Mounted</b>                 |                           |
| Instance on Room 313                   | Inspected                 |
| Condition                              | 2 - Between Good and Fair |
| Deficiency                             | No deficiencies recorded  |
| Instance on Room 213                   | Inspected                 |
| Condition                              | 2 - Between Good and Fair |
| Deficiency                             | No deficiencies recorded  |
| <b>Surface Mounted</b>                 | Does not Exist            |
| Instance on Room 313                   | Does not Exist            |
| Instance on Room 213                   | Does not Exist            |
| <b>Recessed Mounted</b>                | Does not Exist            |
| Instance on Room 313                   | Does not Exist            |
| Instance on Room 213                   | Does not Exist            |
| <b>Lighting Fixture - HID</b>          |                           |
| Instance on Room 313                   | Does not Exist            |
| Instance on Room 213                   | Does not Exist            |
| <b>Lighting Fixture - Incandescent</b> |                           |
| Instance on Room 313                   | Does not Exist            |
| Instance on Room 213                   | Does not Exist            |
| <b>Lighting Fixture - LED</b>          |                           |
| Instance on Room 313                   | Does not Exist            |
| Instance on Room 213                   | Does not Exist            |
| <b>Emergency Gas Shut-Off Valve</b>    | Does not Exist            |
| Instance on Room 313                   | Does not Exist            |
| Instance on Room 213                   | Does not Exist            |
| <b>Emergency Shut-Off Power</b>        | Does not Exist            |
| Instance on Room 313                   | Does not Exist            |
| Instance on Room 213                   | Does not Exist            |
| <b>Power Supply</b>                    | Does not Exist            |
| Instance on Room 313                   | Does not Exist            |
| Instance on Room 213                   | Does not Exist            |
| <b>Projection System</b>               | Does not Exist            |
| Instance on Room 313                   | Does not Exist            |
| Instance on Room 213                   | Does not Exist            |
| <b>SCIENCE LAB</b>                     | Inspected                 |
| Instance on Room 128                   | Inspected                 |
| Power Panel<br>Alternative use         | No<br>No                  |
| Instance on Room 421                   | Inspected                 |
| Power Panel<br>Alternative use         | No<br>Yes                 |
| Instance on Rooms 425, 427, 429        | Inspected                 |
| Power Panel<br>Alternative use         | No<br>No                  |
| Instance on Room 411                   | Inspected                 |
| Power Panel<br>Alternative use         | No<br>No                  |

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K223

| Question                               | Response                  |
|--|---------------------------|
| <b>SCIENCE LAB</b>                     |                           |
| <b>Lighting</b>                        | Inspected                 |
| Instance on Room 411                   | Inspected                 |
| Instance on Rooms 425, 427, 429        | Inspected                 |
| Instance on Room 421                   | Inspected                 |
| Instance on Room 128                   | Inspected                 |
| <b>Lighting Fixture - Fluorescent</b>  |                           |
| Instance on Room 411                   | Inspected                 |
| Instance on Rooms 425, 427, 429        | Inspected                 |
| Instance on Room 421                   | Inspected                 |
| Instance on Room 128                   | Inspected                 |
| <b>Pendant Mounted</b>                 |                           |
| Instance on Room 411                   | Inspected                 |
| Condition                              | 2 - Between Good and Fair |
| Deficiency                             | No deficiencies recorded  |
| Instance on Rooms 425, 427, 429        | Inspected                 |
| Condition                              | 2 - Between Good and Fair |
| Deficiency                             | No deficiencies recorded  |
| Instance on Room 421                   | Inspected                 |
| Condition                              | 2 - Between Good and Fair |
| Deficiency                             | No deficiencies recorded  |
| Instance on Room 128                   | Inspected                 |
| Condition                              | 2 - Between Good and Fair |
| Deficiency                             | No deficiencies recorded  |
| <b>Surface Mounted</b>                 |                           |
| Instance on Room 411                   | Does not Exist            |
| Instance on Rooms 425, 427, 429        | Does not Exist            |
| Instance on Room 421                   | Does not Exist            |
| Instance on Room 128                   | Does not Exist            |
| <b>Recessed Mounted</b>                |                           |
| Instance on Room 411                   | Does not Exist            |
| Instance on Rooms 425, 427, 429        | Does not Exist            |
| Instance on Room 421                   | Does not Exist            |
| Instance on Room 128                   | Does not Exist            |
| <b>Lighting Fixture - HID</b>          |                           |
| Instance on Room 411                   | Does not Exist            |
| Instance on Rooms 425, 427, 429        | Does not Exist            |
| Instance on Room 421                   | Does not Exist            |
| Instance on Room 128                   | Does not Exist            |
| <b>Lighting Fixture - Incandescent</b> |                           |
| Instance on Room 411                   | Inspected                 |
| Instance on Rooms 425, 427, 429        | Does not Exist            |
| Instance on Room 421                   | Does not Exist            |
| Instance on Room 128                   | Inspected                 |
| <b>Pendant Mounted</b>                 |                           |
| Instance on Room 411                   | Does not Exist            |
| Instance on Room 128                   | Does not Exist            |
| <b>Surface Mounted</b>                 |                           |
|  | Inspected                 |



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K223

| Question                               | Response                  |
|--|---------------------------|
| <b>SCIENCE LAB</b>                     |                           |
| <b>Lighting</b>                        |                           |
| <b>Lighting Fixture - Incandescent</b> |                           |
| <b>Surface Mounted</b>                 |                           |
| Instance on Room 411                   | Inspected                 |
| Condition                              | 2 - Between Good and Fair |
| Deficiency                             | No deficiencies recorded  |
| Instance on Room 128                   | Inspected                 |
| Condition                              | 2 - Between Good and Fair |
| Deficiency                             | No deficiencies recorded  |
| <b>Recessed Mounted</b>                |                           |
| Instance on Room 411                   | Does not Exist            |
| Instance on Room 128                   | Does not Exist            |
| <b>Lighting Fixture - LED</b>          |                           |
| Instance on Room 411                   | Does not Exist            |
| Instance on Rooms 425, 427, 429        | Does not Exist            |
| Instance on Room 421                   | Does not Exist            |
| Instance on Room 128                   | Does not Exist            |
| <b>Emergency Gas Shut-Off Valve</b>    |                           |
| Instance on Room 411                   | Does not Exist            |
| Instance on Rooms 425, 427, 429        | Inspected                 |
| Condition                              | 3 - Fair                  |
| Deficiency                             | No deficiencies recorded  |
| Instance on Room 421                   | Inspected                 |
| Condition                              | 3 - Fair                  |
| Deficiency                             | No deficiencies recorded  |
| Instance on Room 128                   | Inspected                 |
| Condition                              | 3 - Fair                  |
| Deficiency                             | No deficiencies recorded  |
| <b>Emergency Shut-Off Power</b>        |                           |
| Instance on Room 411                   | Inspected                 |
| Condition                              | 1 - Good                  |
| Deficiency                             | No deficiencies recorded  |
| Instance on Rooms 425, 427, 429        | Does not Exist            |
| Instance on Room 421                   | Does not Exist            |
| Instance on Room 128                   | Inspected                 |
| Condition                              | 3 - Fair                  |
| Deficiency                             | No deficiencies recorded  |
| <b>Power Supply</b>                    |                           |
| Instance on Room 411                   | Inspected                 |
| Instance on Rooms 425, 427, 429        | Does not Exist            |
| Instance on Room 421                   | Does not Exist            |
| Instance on Room 128                   | Inspected                 |
| <b>Instructor Unit</b>                 |                           |
| Instance on Room 411                   | Inspected                 |
| Condition                              | 1 - Good                  |
| Deficiency                             | No deficiencies recorded  |
| Instance on Room 128                   | Inspected                 |
| Condition                              | 3 - Fair                  |
| Deficiency                             | No deficiencies recorded  |

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K223

| Question                              | Response                  |
|---------------------------------------|---------------------------|
| <b>SCIENCE LAB</b>                    |                           |
| <b>Power Supply</b>                   |                           |
| <b>Meter Demonstration Unit</b>       |                           |
| Instance on Room 411                  | Inspected                 |
| Condition                             | 1 - Good                  |
| Deficiency                            | No deficiencies recorded  |
| Instance on Room 128                  | Inspected                 |
| Condition                             | 3 - Fair                  |
| Deficiency                            | No deficiencies recorded  |
| <b>Student Unit</b>                   |                           |
| Instance on Room 411                  | Does not Exist            |
| Instance on Room 128                  | Does not Exist            |
| <b>Projection System</b>              | Does not Exist            |
| Instance on Room 411                  | Does not Exist            |
| Instance on Rooms 425, 427, 429       | Does not Exist            |
| Instance on Room 421                  | Does not Exist            |
| Instance on Room 128                  | Does not Exist            |
| <b>SCIENCE PREP ROOM</b>              | Inspected                 |
| Instance on Room 128A                 | Inspected                 |
| Power Panel<br>Alternative use        | Yes<br>No                 |
| Instance on Room 211                  | Inspected                 |
| Power Panel<br>Alternative use        | No<br>Yes                 |
| Instance on Room 413                  | Inspected                 |
| Power Panel<br>Alternative use        | Yes<br>No                 |
| <b>Lighting</b>                       | Inspected                 |
| Instance on Room 413                  | Inspected                 |
| Instance on Room 211                  | Inspected                 |
| Instance on Room 128A                 | Inspected                 |
| <b>Lighting Fixture - Fluorescent</b> |                           |
| Instance on Room 413                  | Inspected                 |
| Instance on Room 211                  | Inspected                 |
| Instance on Room 128A                 | Inspected                 |
| <b>Pendant Mounted</b>                | Inspected                 |
| Instance on Room 413                  | Inspected                 |
| Condition                             | 2 - Between Good and Fair |
| Deficiency                            | No deficiencies recorded  |
| Instance on Room 211                  | Inspected                 |
| Condition                             | 2 - Between Good and Fair |
| Deficiency                            | No deficiencies recorded  |
| Instance on Room 128A                 | Inspected                 |
| Condition                             | 2 - Between Good and Fair |
| Deficiency                            | No deficiencies recorded  |
| <b>Surface Mounted</b>                | Does not Exist            |
| Instance on Room 413                  | Does not Exist            |
| Instance on Room 211                  | Does not Exist            |
| Instance on Room 128A                 | Does not Exist            |
| <b>Recessed Mounted</b>               | Does not Exist            |

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K223

| Question                               | Response                  |
|--|---------------------------|
| <b>SCIENCE PREP ROOM</b>               |                           |
| <b>Lighting</b>                        |                           |
| <b>Lighting Fixture - Fluorescent</b>  |                           |
| <b>Recessed Mounted</b>                |                           |
| Instance on Room 413                   | Does not Exist            |
| Instance on Room 211                   | Does not Exist            |
| Instance on Room 128A                  | Does not Exist            |
| <b>Lighting Fixture - HID</b>          |                           |
| Instance on Room 413                   | Does not Exist            |
| Instance on Room 211                   | Does not Exist            |
| Instance on Room 128A                  | Does not Exist            |
| <b>Lighting Fixture - Incandescent</b> |                           |
| Instance on Room 413                   | Does not Exist            |
| Instance on Room 211                   | Does not Exist            |
| Instance on Room 128A                  | Does not Exist            |
| <b>Lighting Fixture - LED</b>          |                           |
| Instance on Room 413                   | Does not Exist            |
| Instance on Room 211                   | Does not Exist            |
| Instance on Room 128A                  | Does not Exist            |
| <b>Emergency Gas Shut-Off Valve</b>    | Does not Exist            |
| Instance on Room 413                   | Does not Exist            |
| Instance on Room 211                   | Inspected                 |
| Condition                              | 3 - Fair                  |
| Deficiency                             | No deficiencies recorded  |
| Instance on Room 128A                  | Inspected                 |
| Condition                              | 3 - Fair                  |
| Deficiency                             | No deficiencies recorded  |
| <b>Emergency Shut-Off Power</b>        | Does not Exist            |
| Instance on Room 413                   | Does not Exist            |
| Instance on Room 211                   | Does not Exist            |
| Instance on Room 128A                  | Inspected                 |
| Condition                              | 3 - Fair                  |
| Deficiency                             | No deficiencies recorded  |
| <b>Power Supply</b>                    | Does not Exist            |
| Instance on Room 413                   | Does not Exist            |
| Instance on Room 211                   | Does not Exist            |
| Instance on Room 128A                  | Does not Exist            |
| <b>SWIMMING POOL</b>                   | Does not Exist            |
| <b>TOILET ROOM - STAFF</b>             | Inspected                 |
| <b>Lighting</b>                        | Inspected                 |
| <b>Lighting Fixture - Fluorescent</b>  | Inspected                 |
| <b>Pendant Mounted</b>                 | Inspected                 |
| Condition                              | 2 - Between Good and Fair |
| Deficiency                             | No deficiencies recorded  |
| <b>Surface Mounted</b>                 | Inspected                 |
| Condition                              | 2 - Between Good and Fair |
| Deficiency                             | No deficiencies recorded  |
| <b>Recessed Mounted</b>                | Does not Exist            |

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K223

| <b>Question</b>                           | <b>Response</b>              |
|---|------------------------------|
| <b>TOILET ROOM - STAFF</b>                | Inspected                    |
| <b>Lighting</b>                           | Inspected                    |
| <b>Lighting Fixture - HID</b>             | Does not Exist               |
| <b>Lighting Fixture - Incandescent</b>    | Does not Exist               |
| <b>Lighting Fixture - LED</b>             | Does not Exist               |
| <b>TOILET ROOM - STUDENT</b>              | Inspected                    |
| <b>Lighting</b>                           | Inspected                    |
| <b>Lighting Fixture - Fluorescent</b>     | Inspected                    |
| <b>Pendant Mounted</b>                    | Inspected                    |
| Condition                                 | 2 - Between Good and Fair    |
| Deficiency                                | No deficiencies recorded     |
| <b>Surface Mounted</b>                    | Inspected                    |
| Condition                                 | 2 - Between Good and Fair    |
| Deficiency                                | No deficiencies recorded     |
| <b>Recessed Mounted</b>                   | Does not Exist               |
| <b>Lighting Fixture - HID</b>             | Does not Exist               |
| <b>Lighting Fixture - Incandescent</b>    | Does not Exist               |
| <b>Lighting Fixture - LED</b>             | Does not Exist               |
| <b>AUXILIARY SIGNAL/BELL SYSTEM</b>       | Inspected                    |
| Replacement Quantity                      | 121,000                      |
| Replacement Uom                           | S.F.                         |
| Condition                                 | 3 - Fair                     |
| Deficiency                                | No deficiencies recorded     |
| <b>EMERGENCY DC STANDBY BATTERY POWER</b> | Does not Exist               |
| <b>EMERGENCY GENERATOR SET</b>            | Does not Exist               |
| <b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>   | Inspected                    |
| Condition                                 | 3 - Fair                     |
| Deficiency                                | No deficiencies recorded     |
| <b>EMERGENCY LIGHTING</b>                 | Inspected                    |
| <b>Battery Pack</b>                       | Inspected                    |
| Condition                                 | 3 - Fair                     |
| Deficiency                                | No deficiencies recorded     |
| <b>Non Battery Pack</b>                   | Inspected                    |
| Condition                                 | 2 - Between Good and Fair    |
| Deficiency                                | FIXTURE LAMP NOT OPERATIONAL |
| Deficiency Location/Instance              | Auditorium                   |
| Deficiency Quantity                       | 2                            |
| Quantity Uom                              | EACH                         |
| Potential Action                          | MAINTENANCE                  |
| Urgency of Action                         | PRIORITY 5                   |
| Purpose of Action                         | LEVEL 2                      |
| Deficiency Photo1                         | No photo recorded            |
| Violations                                | No violations recorded.      |
| <b>EXIT LIGHT</b>                         | Inspected                    |
| <b>Battery Pack</b>                       | Inspected                    |
| Condition                                 | 3 - Fair                     |
| Deficiency                                | No deficiencies recorded     |
| <b>Non Battery Pack</b>                   | Inspected                    |
| Condition                                 | 3 - Fair                     |

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K223

| Question                                     | Response                  |
|--|---------------------------|
| <b>EXIT LIGHT</b>                            | Inspected                 |
| <b>Non Battery Pack</b>                      |                           |
| Deficiency                                   | No deficiencies recorded  |
| <b>EXIT/EMERGENCY LIGHT</b>                  | Does not Exist            |
| <b>FIRE ALARM SYSTEM</b>                     | Inspected                 |
| Replacement Quantity                         | 121,000                   |
| Replacement Uom                              | S.F.                      |
| <b>Bell/Horn</b>                             | Inspected                 |
| Condition                                    | 3 - Fair                  |
| Deficiency                                   | No deficiencies recorded  |
| <b>Strobe</b>                                | Inspected                 |
| Condition                                    | 2 - Between Good and Fair |
| Deficiency                                   | No deficiencies recorded  |
| <b>Manual Pull Station</b>                   | Inspected                 |
| Condition                                    | 3 - Fair                  |
| Deficiency                                   | No deficiencies recorded  |
| <b>Fan Shutdown Control</b>                  | Does not Exist            |
| <b>Duct Smoke Detector</b>                   | Does not Exist            |
| <b>Area Smoke Detector</b>                   | Does not Exist            |
| <b>CO Detector</b>                           | Does not Exist            |
| <b>Heat Detector</b>                         | Does not Exist            |
| <b>Elevator Recall</b>                       | Inspected                 |
| Condition                                    | 2 - Between Good and Fair |
| Deficiency                                   | No deficiencies recorded  |
| <b>Magnetic Door Holder/Contactor</b>        | Does not Exist            |
| <b>Fused Cutout Panel</b>                    | Inspected                 |
| Condition                                    | 3 - Fair                  |
| Deficiency                                   | No deficiencies recorded  |
| <b>Fire Alarm Digital Communicator</b>       | Does not Exist            |
| <b>Main Panel</b>                            | Inspected                 |
| <b>Bell At Panel</b>                         | Inspected                 |
| Condition                                    | 3 - Fair                  |
| Deficiency                                   | No deficiencies recorded  |
| <b>Fire Alarm Control Panel (Electronic)</b> | Does not Exist            |
| <b>Fire Alarm Control Panel (Standard)</b>   | Inspected                 |
| Instance                                     | Boiler Room               |
| Instance Condition                           | 3 - Fair                  |
| Instance Quantity                            | 1                         |
| Instance Quantity Uom                        | EACH                      |
| Instance Manufacturer                        | ACME                      |
| Equipment                                    | Fire Alarm Control Board  |
| Installation Year                            | 1966                      |
| Source of Installation                       | Documented                |
| Deficiency                                   | No deficiencies recorded  |
| <b>Sub-Panel</b>                             | Inspected                 |
| <b>Bell At Panel</b>                         | Inspected                 |
| Condition                                    | 3 - Fair                  |
| Deficiency                                   | No deficiencies recorded  |
| <b>Fire Alarm Control Panel (Electronic)</b> | Inspected                 |

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K223

| Question                                     | Response                      |
|--|-------------------------------|
| <b>FIRE ALARM SYSTEM</b>                     | Inspected                     |
| <b>Sub-Panel</b>                             |                               |
| <b>Fire Alarm Control Panel (Electronic)</b> |                               |
| Instance                                     | Boiler Room                   |
| Instance Condition                           | 2 - Between Good and Fair     |
| Instance Quantity                            | 1                             |
| Instance Quantity Uom                        | EACH                          |
| Instance Manufacturer                        | Edwards System Technology     |
| Equipment                                    | Smoke Control Panel           |
| Model  | EST 2                         |
| Installation Year                            | 2009                          |
| Source of Installation                       | Documented                    |
| Deficiency                                   | No deficiencies recorded      |
| <b>Fire Alarm Control Panel (Standard)</b>   | Inspected                     |
| Instance                                     | Boiler Room                   |
| Instance Condition                           | 3 - Fair                      |
| Instance Quantity                            | 1                             |
| Instance Quantity Uom                        | EACH                          |
| Instance Manufacturer                        | ACME                          |
| Equipment                                    | Sprinkler Alarm Control Board |
| Installation Year                            | 1966                          |
| Source of Installation                       | Inspector Estimate            |
| Deficiency                                   | No deficiencies recorded      |
| Instance                                     | Boiler Room                   |
| Instance Condition                           | 3 - Fair                      |
| Instance Quantity                            | 1                             |
| Instance Quantity Uom                        | EACH                          |
| Instance Manufacturer                        | ACME                          |
| Equipment                                    | Register Control Panel        |
| Installation Year                            | 1966                          |
| Source of Installation                       | Inspector Estimate            |
| Deficiency                                   | No deficiencies recorded      |
| <b>Remote Annunciator</b>                    | Inspected                     |
| <b>Display Monitor</b>                       | Does not Exist                |
| <b>Panel</b>                                 | Does not Exist                |
| <b>Printer</b>                               | Does not Exist                |
| <b>Punch Register</b>                        | Inspected                     |
| Condition                                    | 3 - Fair                      |
| Deficiency                                   | No deficiencies recorded      |
| <b>Sprinkler Flow/Air Pressure Switch</b>    | Inspected                     |
| Condition                                    | 2 - Between Good and Fair     |
| Deficiency                                   | No deficiencies recorded      |
| <b>Tamper Flow Switch/Chain</b>              | Inspected                     |
| Condition                                    | 3 - Fair                      |
| Deficiency                                   | No deficiencies recorded      |
| <b>GROUNDING SYSTEM</b>                      | Inspected                     |
| Condition                                    | 3 - Fair                      |
| Deficiency                                   | No deficiencies recorded      |
| <b>INTERCOM SYSTEM</b>                       | Inspected                     |

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K223

| Question                                | Response   |
|---|--|
| <b>INTERCOM SYSTEM</b>                  | Inspected  |
| <b>Elevator</b>                         | Inspected  |
| Condition                               | 3 - Fair   |
| Deficiency                              | No deficiencies recorded   |
| <b>Holding Area</b>                     | Does not Exist   |
| <b>LAN</b>                              | Inspected  |
| <b>Local Distribution Frame (I/LDF)</b> | Inspected  |
| Condition                               | 1 - Good   |
| Deficiency                              | No deficiencies recorded   |
| <b>Main Equipment Rack (MDF)</b>        | Inspected  |
| Condition                               | 1 - Good   |
| Deficiency                              | No deficiencies recorded   |
| <b>LIGHTNING PROTECTION</b>             | Does not Exist   |
| <b>MOTOR CONTROLLER</b>                 | Inspected  |
| <b>Motor Control Center</b>             | Does not Exist   |
| <b>Motor Starter/Contactor</b>          | Inspected  |
| Condition                               | 3 - Fair   |
| Deficiency                              | No deficiencies recorded   |
| <b>Variable Frequency Drive</b>         | Does not Exist   |
| <b>PANEL BOARD</b>                      | Inspected  |
| <b>Fused Disconnect Switch Type</b>     | Inspected  |
| Condition                               | 3 - Fair   |
| Deficiency                              | PANEL BOARD BEYOND USEFUL LIFE                                       |
| Deficiency Location/Instance            | Basement Mechanical Rooms (South, North)                             |
| Deficiency Quantity                     | 2  |
| Quantity Uom                            | EACH   |
| Potential Action                        | REPLACE-UPGRADE  |
| Urgency of Action                       | PRIORITY 1   |
| Purpose of Action                       | LEVEL 2  |
| Deficiency Photo1                       | No photo recorded  |
| Violations                              | No violations recorded.  |
| <b>Fused Knife Switch Type</b>          | Inspected  |
| Condition                               | 3 - Fair   |
| Deficiency                              | PANEL BOARD BEYOND USEFUL LIFE                                       |
| Deficiency Location/Instance            | Corridor by Rooms (125, 207, 217, 226, 307, 317, 326, 407, 417, 426) |
| Deficiency Quantity                     | 10   |
| Quantity Uom                            | EACH   |
| Potential Action                        | REPLACE-UPGRADE  |
| Urgency of Action                       | PRIORITY 1   |
| Purpose of Action                       | LEVEL 2  |
| Deficiency Photo1                       | No photo recorded  |
| Violations                              | No violations recorded.  |
| <b>Fused Toggle Switch Type</b>         | Inspected  |
| Condition                               | 3 - Fair   |
| Deficiency                              | PANEL BOARD BEYOND USEFUL LIFE                                       |
| Deficiency Location/Instance            | Electrical Room  |
| Deficiency Quantity                     | 1  |
| Quantity Uom                            | EACH   |
| Potential Action                        | REPLACE-UPGRADE  |

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K223**

| <b>Question</b>                         | <b>Response</b>  |
|---|--|
| <b>PANEL BOARD</b>                      |  |
| <b>Fused Toggle Switch Type</b>         | Inspected  |
| Urgency of Action                       | PRIORITY 1   |
| Purpose of Action                       | LEVEL 2  |
| Deficiency Photo1                       | No photo recorded  |
| Violations                              | No violations recorded.  |
| <b>Molded Case Circuit Breaker Type</b> | Inspected  |
| Condition                               | 3 - Fair   |
| Deficiency                              | NO SPARE   |
| Deficiency Location/Instance            | Boiler Room  |
| Deficiency Quantity                     | 1  |
| Quantity Uom                            | EACH   |
| Potential Action                        | INSTALL NEW PANEL BOARD  |
| Urgency of Action                       | PRIORITY 3   |
| Purpose of Action                       | LEVEL 2  |
| Deficiency Photo1                       | No photo recorded  |
| Violations                              | No violations recorded.  |
| Deficiency                              | NO SPARE   |
| Deficiency Location/Instance            | Auditorium, Kitchen, Corridor by Room 120  |
| Deficiency Quantity                     | 4  |
| Quantity Uom                            | EACH   |
| Potential Action                        | REPLACE PANEL BOARD  |
| Urgency of Action                       | PRIORITY 3   |
| Purpose of Action                       | LEVEL 2  |
| Deficiency Photo1                       | No photo recorded  |
| Violations                              | No violations recorded.  |
| Deficiency                              | PANEL BOARD BEYOND USEFUL LIFE   |
| Deficiency Location/Instance            | Basement Mechanical Room - South, Room 104, Corridor by Rooms (101, 107, 119A, 125, 207, 226, 229, 307, 317, 326, 407, 417, 426) |
| Deficiency Quantity                     | 15   |
| Quantity Uom                            | EACH   |
| Potential Action                        | REPLACE-UPGRADE  |
| Urgency of Action                       | PRIORITY 1   |
| Purpose of Action                       | LEVEL 2  |
| Deficiency Photo1                       | No photo recorded  |
| Violations                              | No violations recorded.  |
| <b>PUBLIC ADDRESS SYSTEM</b>            |  |
| Replacement Quantity                    | 121,000  |
| Replacement Uom                         | S.F.   |
| Instance                                | General Office   |
| Instance Condition                      | 3 - Fair   |
| Instance Quantity                       | 1  |
| Instance Quantity Uom                   | EACH   |
| Model                                   | Telecor XL   |
| Installation Year                       | 1966   |
| Source of Installation                  | Inspector Estimate   |
| Deficiency                              | CLOCK NOT OPERATIONAL  |
| Deficiency Location/Instance            | Classrooms and Corridors   |
| Deficiency Quantity                     | 22   |



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K223

| Question                      | Response                                   |
|-------------------------------|--|
| <b>PUBLIC ADDRESS SYSTEM</b>  |  |
| Quantity Uom                  | EACH                                       |
| Potential Action              | REPLACE                                    |
| Urgency of Action             | PRIORITY 3                                 |
| Purpose of Action             | LEVEL 2                                    |
| Deficiency Photo1             | No photo recorded                          |
| Violations                    | No violations recorded.                    |
| <b>SECURITY</b>               |  |
|                               | Inspected                                  |
| <b>IPDVS/CCTV System</b>      |  |
|                               | Inspected                                  |
| Replacement Quantity          | 121,000                                    |
| Replacement Uom               | S.F.                                       |
| Installation Year             | 2011                                       |
| Source of Installation        | Custodial Staff                            |
| Condition                     | 3 - Fair                                   |
| Deficiency                    | No deficiencies recorded                   |
| <b>Intrusion Alarm System</b> |  |
|                               | Inspected                                  |
| Replacement Quantity          | 121,000                                    |
| Replacement Uom               | S.F.                                       |
| <b>Central Control Panel</b>  |  |
|                               | Inspected                                  |
| Instance                      | Custodian's Office                         |
| Instance Condition            | 3 - Fair                                   |
| Instance Quantity             | 1  |
| Instance Quantity Uom         | EACH                                       |
| Model                         | N/A  |
| Installation Year             | 1988                                       |
| Source of Installation        | Inspector Estimate                         |
| Deficiency                    | No deficiencies recorded                   |
| <b>Infrared Sensor</b>        |  |
|                               | Inspected                                  |
| Condition                     | 3 - Fair                                   |
| Deficiency                    | No deficiencies recorded                   |
| <b>Panic Switch</b>           |  |
|                               | Inspected                                  |
| Condition                     | 3 - Fair                                   |
| Deficiency                    | No deficiencies recorded                   |
| <b>Remote Annunciator</b>     |  |
|                               | Inspected                                  |
| Condition                     | 3 - Fair                                   |
| Deficiency                    | No deficiencies recorded                   |
| <b>Siren/Strobe</b>           |  |
|                               | Inspected                                  |
| Condition                     | 3 - Fair                                   |
| Deficiency                    | No deficiencies recorded                   |
| <b>Lighting - Security</b>    |  |
|                               | Inspected                                  |
| Replacement Uom               | EACH                                       |
| Condition                     | 4 - Between Fair and Poor                  |
| Deficiency                    | LIGHTING FIXTURE PHOTOCELL NOT OPERATIONAL |
| Deficiency Location/Instance  | Exterior Wall (Building Perimeters)        |
| Deficiency Quantity           | 7  |
| Quantity Uom                  | EACH                                       |
| Potential Action              | REPLACE                                    |
| Urgency of Action             | PRIORITY 3                                 |
| Purpose of Action             | LEVEL 3                                    |
| Deficiency Photo1             | No photo recorded                          |

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K223

| Question                                | Response                     |
|---|------------------------------|
| <b>SECURITY</b>                         | Inspected                    |
| <b>Lighting - Security</b>              |                              |
| Violations                              | No violations recorded.      |
| <b>SERVICE SWITCH</b>                   | Inspected                    |
| Instance                                | Electrical Room              |
| Instance Condition                      | 3 - Fair                     |
| Instance Quantity                       | 1                            |
| Instance Quantity Uom                   | EACH                         |
| Instance Manufacturer                   | Empire Switchboard           |
| Equipment                               | Service Switch               |
| Capacity/Size Quantity                  | 2,000                        |
| Capacity/Size UOM                       | Amps                         |
| Source of Capacity/Size                 | Nameplate                    |
| Installation Year                       | 1966                         |
| Source of Installation                  | Inspector Estimate           |
| Deficiency                              | No deficiencies recorded     |
| <b>SWITCHBOARD</b>                      | Inspected                    |
| Number of Spares                        | 0                            |
| <b>Fused Disconnect Switch Type</b>     | Inspected                    |
| Instance                                | Electrical Room              |
| Instance Condition                      | 3 - Fair                     |
| Instance Quantity                       | 1                            |
| Instance Quantity Uom                   | EACH                         |
| Instance Manufacturer                   | Electric Switchboard         |
| Equipment                               | N/A                          |
| Capacity/Size Quantity                  | 2,000                        |
| Capacity/Size UOM                       | Amps Total                   |
| Capacity/Size2 Quantity                 | 5                            |
| Capacity/Size2 UOM                      | Section(S)                   |
| Source of Capacity/Size                 | Service Switch Size          |
| Installation Year                       | 1966                         |
| Source of Installation                  | Inspector Estimate           |
| Deficiency                              | No deficiencies recorded     |
| <b>Fused Knife Switch Type</b>          | Does not Exist               |
| <b>Molded Case Circuit Breaker Type</b> | Does not Exist               |
| <b>TELEPHONE SYSTEM</b>                 | Inspected                    |
| <b>PBX/Intercom</b>                     | Inspected                    |
| Condition                               | 3 - Fair                     |
| Deficiency                              | No deficiencies recorded     |
| <b>Standard</b>                         | Inspected                    |
| Condition                               | 3 - Fair                     |
| Deficiency                              | No deficiencies recorded     |
| <b>TRANSFORMER</b>                      | Inspected                    |
| Instance                                | Roof - Elevator Machine Room |
| Instance Condition                      | 2 - Between Good and Fair    |
| Instance Quantity                       | 1                            |
| Instance Quantity Uom                   | EACH                         |
| Instance Manufacturer                   | Hammond Power Solutions      |
| Equipment                               | N/A                          |

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K223**

| <b>Question</b>         | <b>Response</b>          |
|-------------------------|--------------------------|
| <b>TRANSFORMER</b>      |                          |
| Capacity/Size Quantity  | 63                       |
| Capacity/Size UOM       | KVA                      |
| Source of Capacity/Size | Nameplate                |
| Installation Year       | 2009                     |
| Source of Installation  | Documented               |
| Deficiency              | No deficiencies recorded |