

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K288

Asset: P.S. 288 - BROOKLYN, 2950 WEST 25 STREET, New York, 11224

Inspection Id	Inspection Type	Time In	Last Edited
EE : K288	Electrical	2024-03-12 8:41 AM	2024-06-21 12:38 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Gymnasium (Scoreboard)
	Years: 2021
	Systems: Emergency Generator Set, Grounding System, LAN, Lightning Protection, Motor Controller (Partial Motor Starter/Contactor, Variable Frequency Drive), Service Switch, Switchboard
	Years: 2016
	Systems: Local Sound System, Public Address System
	Years: 2015
	Systems: LED Lighting, Interior Fluorescent Lighting - Except (Science Lab, Science Prep Room), Exit Lights (Battery Pack), Telephone System
	Years: 2013
	Systems: Science Lab, Science Prep Room
	Years: 2009
	Systems: Auditorium (Theater Lighting System), Fire Alarm System
	Years: 2008
	Systems: Security Lights
	Years: 1996, 2008, 2021
	Systems: Intrusion Alarm System
	Years: 1996
	Systems: Molded Case Circuit Breaker Type Panel Board
	Years: 1990, 2000, 2009, 2016, 2019

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No condition recorded								

Inspection

Question	Response
Electrical	
AUDITORIUM	Inspected
Instance on 2nd Floor	Inaccessible
CAFETERIA	Inspected
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
Lighting	Inspected
Instance on 1st Floor - Staff	Inspected
Instance on 1st Floor - Students	Inspected
Lighting Fixture - Fluorescent	

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K288

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Staff	Inspected
Instance on 1st Floor - Students	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
Instance on 1st Floor - Students	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor - Staff	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Students	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
Instance on 1st Floor - Students	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor - Staff	Does not Exist
Instance on 1st Floor - Students	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Staff	Does not Exist
Instance on 1st Floor - Students	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor - Staff	Does not Exist
Instance on 1st Floor - Students	Does not Exist
Local Sound System	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
Instance on 1st Floor - Students	Inspected
Installation Year	2015
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
Instance on 1st Floor - Students	Does not Exist
Theater Lighting System	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
Instance on 1st Floor - Students	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K288

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
COMPUTER LAB	Does not Exist
GYMNASIUM	Inspected
Instance on 2nd Floor	Inspected
Lighting	Inspected
Instance on 2nd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Does not Exist
Lighting Fixture - HID	
Instance on 2nd Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not Exist
Lighting Fixture - LED	
Instance on 2nd Floor	Inspected
Pendant Mounted	Inspected
Instance on 2nd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K288

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - LED	
Pendant Mounted	Inspected
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	Does not Exist
Instance on 2nd Floor	Does not Exist
Recessed Mounted	Does not Exist
Instance on 2nd Floor	Does not Exist
Local Sound System	Inspected
Instance on 2nd Floor	Inspected
Installation Year	2015
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 2nd Floor	Does not Exist
Scoreboard	Inspected
Instance on 2nd Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Theater Lighting System	Does not Exist
Instance on 2nd Floor	Does not Exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
LIBRARY	Does not Exist
LOCKER ROOM	Inspected
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Inaccessible
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K288

Question	Response
SCIENCE DEMO ROOM	
Instance on Room 353	Inspected
Power Panel	Yes
Alternative use	No
Lighting	Inspected
Instance on Room 353	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 353	Inspected
Pendant Mounted	
Instance on Room 353	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 353	Does not Exist
Recessed Mounted	
Instance on Room 353	Does not Exist
Lighting Fixture - HID	
Instance on Room 353	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 353	Does not Exist
Lighting Fixture - LED	
Instance on Room 353	Does not Exist
Emergency Gas Shut-Off Valve	
Instance on Room 353	Does not Exist
Emergency Shut-Off Power	
Instance on Room 353	Does not Exist
Power Supply	
Instance on Room 353	Does not Exist
Projection System	
Instance on Room 353	Does not Exist
SCIENCE LAB	
Instance on Room 349	Inspected
Power Panel	Yes
Alternative use	No
Lighting	Inspected
Instance on Room 349	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 349	Inspected
Pendant Mounted	
Instance on Room 349	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 349	Does not Exist
Recessed Mounted	
Instance on Room 349	Does not Exist
Lighting Fixture - HID	
Instance on Room 349	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 349	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K288

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Incandescent	
Pendant Mounted	Does not Exist
Instance on Room 349	Does not Exist
Surface Mounted	Inspected
Instance on Room 349	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Room 349	Does not Exist
Lighting Fixture - LED	
Instance on Room 349	Does not Exist
Emergency Gas Shut-Off Valve	Inspected
Instance on Room 349	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	Inspected
Instance on Room 349	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Power Supply	Inspected
Instance on Room 349	Inspected
Instructor Unit	
Instance on Room 349	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 349	Does not Exist
Student Unit	
Instance on Room 349	Does not Exist
Projection System	
Instance on Room 349	Does not Exist
SCIENCE PREP ROOM	
Instance on Room 351	Inspected
Power Panel	No
Alternative use	No
Lighting	Inspected
Instance on Room 351	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 351	Inspected
Pendant Mounted	Inspected
Instance on Room 351	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 351	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 351	Does not Exist
Lighting Fixture - HID	

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K288

Question	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - HID	
Instance on Room 351	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 351	Does not Exist
Lighting Fixture - LED	
Instance on Room 351	Does not Exist
Emergency Gas Shut-Off Valve	Inspected
Instance on Room 351	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	Inspected
Instance on Room 351	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Power Supply	Does not Exist
Instance on Room 351	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K288

Question	Response
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Incandescent	Inspected
Recessed Mounted	
Violations	No violations recorded.
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	35
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	82,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	ATS Room 242
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	ATS #1 Panel ELP IN Electrical Room
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation	Custodial Staff

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K288

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Deficiency	No deficiencies recorded
Instance	ATS Room 242
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	ATS #2 Fire Alarm System
Capacity/Size Quantity	70
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Instance	ATS Room 242
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	ATS #3 Panel EPP-FP
Capacity/Size Quantity	150
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Battery Charger	Inspected
Instance	Roof - Outdoor Generator Enclosure
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Cummins Onan
Equipment	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size2 Quantity	24
Capacity/Size2 UOM	VDC
Source of Capacity/Size	Inspector Estimate
Installation Year	2016
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Emergency Distribution Board	Does not Exist
Diesel	Does not Exist
Natural Gas	Inspected
Instance	Roof - Outdoor Generator Enclosure
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K288

Question	Response
EMERGENCY GENERATOR SET	
Natural Gas	
Instance Manufacturer	Cummins Onan
Equipment	Emergency Generator
Capacity/Size Quantity	88
Capacity/Size UOM	KVA
Capacity/Size2 Quantity	70
Capacity/Size2 UOM	KW
Capacity/Size3Quantity	242
Capacity/Size3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation	Documented
Deficiency	DEFECTIVE ENGINE COOLING SYSTEM
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Gymnasium, Boiler Room, Corridor by Students Cafeteria
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Does not Exist
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	82,000
Replacement Uom	S.F.
Bell/Horn	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K288

Question	Response
FIRE ALARM SYSTEM	
Bell/Horn	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Does not Exist
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Honeywell
Equipment	FA Digital Alarm Communicator
Installation Year	2008
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K288

Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Electronic)	
Equipment	Fire Alarm Control Panel
Model	EST 2
Installation Year	2008
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	5 - Poor
Deficiency	PRINTER NOT OPERATIONAL
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K288

Question	Response
MOTOR CONTROLLER	
Motor Starter/Contactor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	4 - Between Fair and Poor
Deficiency	VARIABLE FREQUENCY DRIVE NOT OPERATIONAL
Deficiency Location/Instance	Mechanical Room 308 (AUH 1, REF 1)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PANEL BOARD	
	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Room 308
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	NO SPARE
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Science Lab Room 249
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K288

Question	Response
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	82,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	2015
Source of Installation	Custodial Staff
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SECURITY	Inspected
IPDVS/CCTV System	Does not Exist
Intrusion Alarm System	Inspected
Replacement Quantity	82,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista-50P
Installation Year	1996
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3 - Fair
Deficiency	SIREN/STROBE NOT ACTIVE
Deficiency Location/Instance	Exterior Wall by Main Entrance
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K288

Question	Response
SECURITY	
Intrusion Alarm System	
Siren/Strobe	
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting - Security	
Replacement Uom	Inspected
Condition	EACH
Deficiency	3 - Fair
SERVICE SWITCH	
Instance	Inspected
Instance Condition	Electrical Room
Instance Quantity	2 - Between Good and Fair
Instance Quantity Uom	1
Instance Manufacturer	EACH
Equipment	Eaton
Capacity/Size Quantity	Service Disconnect MAIN
Capacity/Size UOM	1,600
Source of Capacity/Size	Amps
Installation Year	Nameplate
Source of Installation	2016
Deficiency	Documented
SWITCHBOARD	
Number of Spares	Inspected
Fused Disconnect Switch Type	
Instance	3
Instance Condition	Inspected
Instance Quantity	Electrical Room
Instance Quantity Uom	2 - Between Good and Fair
Instance Manufacturer	1
Equipment	EACH
Capacity/Size Quantity	Eaton
Capacity/Size UOM	N/A
Capacity/Size2 Quantity	1,600
Capacity/Size2 UOM	Amps Total
Source of Capacity/Size	3
Installation Year	Section(S)
Source of Installation	Nameplate
Deficiency	2016
Fused Knife Switch Type	
Does not Exist	
Molded Case Circuit Breaker Type	
Does not Exist	
TELEPHONE SYSTEM	
Inspected	
PBX/Intercom	
Condition	Inspected
Deficiency	2 - Between Good and Fair
Standard	
Condition	Inspected
2 - Between Good and Fair	

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K288

Question	Response
TELEPHONE SYSTEM	Inspected
Standard	
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist