

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K317

Asset: P.S. 133 WILLIAM A. BUTLER - BROOKLYN, 610 BALTIC STREET, New York, 11217

Inspection Id	Inspection Type	Time In	Last Edited
EE : K317	Electrical	2024-02-28 7:56 AM	2024-03-07 9:15 AM


Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	Yes
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: LAN
	Years: 2023
	Systems: Retrofitted LED Lighting, Gymnasium (Lighting)
	Years: 2022
	Systems: Security Lights
	Years: 2013, 2022
	Systems: All Other Electrical Systems and Components
	Years: 2013

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Lightning Protection - Lightning Protection Conductor Clamps Not Properly Attached	N/A	LIGHTNING PROTECTION	Roof 1 (RTU-4, on top Exhaust Fans by RTU-7), Penthouse (Roof Hatch), Roof 1 (Radon Exhaust Fan)	Hector Serrano	Fireman	Sent to DSF	
Yes	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electrical Room C16	Hector Serrano	Fireman	Sent to DSF	

Inspection

Question	Response
Electrical	
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	Inspected
Does a Chandelier exist?	No
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K317

Question	Response
AUDITORIUM	
House Lighting	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2013
Source of Installation	Documented
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Inspected
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting System	Inspected
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CAFETERIA	Inspected
Instance on Cellar	Inspected
Lighting	Inspected
Instance on Cellar	Inspected
Lighting Fixture - Fluorescent	
Instance on Cellar	Does not Exist
Lighting Fixture - HID	
Instance on Cellar	Does not Exist
Lighting Fixture - Incandescent	
Instance on Cellar	Does not Exist
Lighting Fixture - LED	
Instance on Cellar	Inspected
Pendant Mounted	Does not Exist
Instance on Cellar	Does not Exist
Surface Mounted	Does not Exist
Instance on Cellar	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K317

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - LED	
Recessed Mounted	Inspected
Instance on Cellar	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	Inspected
Instance on Cellar	Inspected
Installation Year	2013
Source of Installation	Documented
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on Cellar	Does not Exist
Theater Lighting System	Does not Exist
Instance on Cellar	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
COMPUTER LAB	
	Does not Exist
GYMNASIUM	
Instance on 3rd Floor	Inspected
Lighting	Inspected
Instance on 3rd Floor	Inspected
Lighting Fixture - Fluorescent	Does not Exist
Instance on 3rd Floor	Does not Exist
Lighting Fixture - HID	Does not Exist
Instance on 3rd Floor	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Instance on 3rd Floor	Does not Exist
Lighting Fixture - LED	Inspected
Instance on 3rd Floor	Inspected
Pendant Mounted	Inspected
Instance on 3rd Floor	Inspected
Condition	1 - Good

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K317

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - LED	
Pendant Mounted	Inspected
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on 3rd Floor	Does not Exist
Recessed Mounted	Does not Exist
Instance on 3rd Floor	Does not Exist
Local Sound System	
Instance on 3rd Floor	Inspected
Installation Year	2013
Source of Installation	Documented
Condition	4 - Between Fair and Poor
Deficiency	SYSTEM DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Projection System	
Instance on 3rd Floor	Does not Exist
Scoreboard	
Instance on 3rd Floor	Inspected
Condition	4 - Between Fair and Poor
Deficiency	NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Theater Lighting System	
Instance on 3rd Floor	Does not Exist
KITCHEN	
Instance on Cellar	Inspected
Lighting	Inspected
Instance on Cellar	Inspected
Lighting Fixture - Fluorescent	
Instance on Cellar	Does not Exist
Lighting Fixture - HID	
Instance on Cellar	Does not Exist
Lighting Fixture - Incandescent	
Instance on Cellar	Does not Exist
Lighting Fixture - LED	
Instance on Cellar	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K317

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - LED	
Pendant Mounted	Does not Exist
Instance on Cellar	Does not Exist
Surface Mounted	Inspected
Instance on Cellar	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Instance on Cellar	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
LIBRARY	Inspected
Instance on Room 207	Inspected
Lighting	Inspected
Instance on Room 207	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 207	Does not Exist
Lighting Fixture - HID	
Instance on Room 207	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 207	Does not Exist
Lighting Fixture - LED	
Instance on Room 207	Inspected
Pendant Mounted	Inspected
Instance on Room 207	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 207	Does not Exist
Recessed Mounted	Inspected
Instance on Room 207	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Raceway With Receptacles	Inspected
Instance on Room 207	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on Room 207	Does not Exist
LOCKER ROOM	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Inspected
Instance on Rooms 503, 504	Inspected
Power Panel	No
Alternative use	No
Lighting	Inspected
Instance on Rooms 503, 504	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K317

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Rooms 503, 504	Does not Exist
Lighting Fixture - HID	
Instance on Rooms 503, 504	Does not Exist
Lighting Fixture - Incandescent	
Instance on Rooms 503, 504	Inspected
Pendant Mounted	Does not Exist
Instance on Rooms 503, 504	Does not Exist
Surface Mounted	Inspected
Instance on Rooms 503, 504	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Rooms 503, 504	Does not Exist
Lighting Fixture - LED	
Instance on Rooms 503, 504	Inspected
Pendant Mounted	Inspected
Instance on Rooms 503, 504	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Rooms 503, 504	Does not Exist
Recessed Mounted	Does not Exist
Instance on Rooms 503, 504	Does not Exist
Emergency Gas Shut-Off Valve	Does not Exist
Instance on Rooms 503, 504	Does not Exist
Emergency Shut-Off Power	Does not Exist
Instance on Rooms 503, 504	Does not Exist
Power Supply	Does not Exist
Instance on Rooms 503, 504	Does not Exist
Projection System	Does not Exist
Instance on Rooms 503, 504	Does not Exist
SCIENCE PREP ROOM	Inspected
Instance on Room 501	Inaccessible
Instance on Room 502	Inspected
Power Panel	No
Alternative use	Yes
Lighting	Inspected
Instance on Room 502	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 502	Does not Exist
Lighting Fixture - HID	
Instance on Room 502	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 502	Does not Exist
Lighting Fixture - LED	
Instance on Room 502	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K317

Question	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - LED	
Pendant Mounted	Does not Exist
Instance on Room 502	Does not Exist
Surface Mounted	Does not Exist
Instance on Room 502	Does not Exist
Recessed Mounted	Inspected
Instance on Room 502	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Gas Shut-Off Valve	Does not Exist
Instance on Room 502	Does not Exist
Emergency Shut-Off Power	Does not Exist
Instance on Room 502	Does not Exist
Power Supply	Does not Exist
Instance on Room 502	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	117,000
Replacement Uom	S.F.
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K317

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Instance	Electrical Transfer Room C06
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	Fire Alarm Automatic Transfer Switch
Capacity/Size Quantity	30
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2013
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Transfer Room C06
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	ATS-3
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2013
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Transfer Room C06
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	ATS-4
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2013
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Water Meter Room C10
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Firetrol
Equipment	Fire Pump Power Transfer Switch
Capacity/Size Quantity	40
Capacity/Size UOM	HP
Source of Capacity/Size	Nameplate
Installation Year	2013
Source of Installation	Documented

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K317

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	Inspected
Deficiency	No deficiencies recorded
Battery Charger	Inspected
Instance	Generator Room C08
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	SENS
Equipment	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size2 Quantity	24
Capacity/Size2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	2013
Source of Installation	Documented
Deficiency	No deficiencies recorded
Emergency Distribution Board	Inspected
Number of Spares	0
Fused Disconnect Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Instance	Generator Room C08
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	N/A
Equipment	N/A
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	2013
Source of Installation	Documented
Deficiency	No deficiencies recorded
Diesel	Inspected
Instance	Generator Room C08
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Caterpillar
Equipment	Emergency Generator
Capacity/Size Quantity	500
Capacity/Size UOM	KVA
Capacity/Size2 Quantity	400
Capacity/Size2 UOM	KW
Capacity/Size3Quantity	1,388
Capacity/Size3 UOM	Amps

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K317

Question	Response
EMERGENCY GENERATOR SET	
Diesel	
Source of Capacity/Size	Nameplate
Installation Year	2013
Source of Installation	Documented
Deficiency	No deficiencies recorded
Natural Gas	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Does not Exist
Non Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Gymnasium
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Does not Exist
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	117,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K317

Question	Response
FIRE ALARM SYSTEM	
Heat Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fused Cutout Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Inspected
Instance	Water Meter Room C10
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Silent Knight
Equipment	Central Station Communicator
Installation Year	2013
Source of Installation	Documented
Deficiency	No deficiencies recorded
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Simplex
Equipment	Fire Alarm Control Panel
Model	4100
Installation Year	2013
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K317

Question	Response
FIRE ALARM SYSTEM	
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	
Elevator	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Holding Area	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	
Condition	2 - Between Good and Fair
Deficiency	LIGHTNING PROTECTION CONDUCTOR CLAMPS NOT PROPERLY ATTACHED
Deficiency Location/Instance	Roof 1 (RTU-4, on top Exhaust Fans by RTU-7), Penthouse (Roof Hatch), Roof 1 (Radon Exhaust Fan)
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
MOTOR CONTROLLER	
Motor Control Center	Does not Exist
Motor Starter/Contactor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
PANEL BOARD	
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	NO SPARE

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K317

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Deficiency Location/Instance	Electrical Room C25
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	
	Inspected
Replacement Quantity	117,000
Replacement Uom	S.F.
Instance	Telecom Room 125
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Telecor II
Installation Year	2013
Source of Installation	Documented
Deficiency	No deficiencies recorded
SECURITY	
	Inspected
IPDVS/CCTV System	
	Inspected
Replacement Quantity	117,000
Replacement Uom	S.F.
Installation Year	2013
Source of Installation	Documented
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Intrusion Alarm System	
	Inspected
Replacement Quantity	117,000
Replacement Uom	S.F.
Central Control Panel	
	Inspected
Instance	Custodian's Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista-128BP
Installation Year	2013
Source of Installation	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	
	Inspected
Condition	4 - Between Fair and Poor
Deficiency	SWITCH NOT OPERATIONAL
Deficiency Location/Instance	General Office - Room 111
Deficiency Quantity	1

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K317

Question	Response
SECURITY	
Intrusion Alarm System	
Panic Switch	
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo	No photo recorded
Violations	No violations recorded.
Remote Annunciator	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	SIREN/STROBE NOT ACTIVE
Deficiency Location/Instance	Exterior Wall - facing Baltic Street
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo	No photo recorded
Violations	No violations recorded.
Lighting - Security	
	Inspected
Replacement Uom	EACH
Condition	1 - Good
Deficiency	No deficiencies recorded
SERVICE SWITCH	
	Inspected
Instance	Electrical Room C16
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	Main Service Switchboard
Capacity/Size Quantity	5,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2013
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C16
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	Fire Pump
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K317

Question	Response
SERVICE SWITCH	Inspected
Installation Year	2013
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	4
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room C16
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	N/A
Capacity/Size Quantity	5,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	4
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	2013
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist