

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K335

Asset: P.S. 335 - BROOKLYN, 130 ROCHESTER AVENUE, New York, 11213

Inspection Id	Inspection Type	Time In	Last Edited
EE : K335	Electrical	2024-05-28 8:07 AM	2024-06-07 9:31 AM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: LED Lighting (Auditorium - Pendant and Surface Mounted, Students Cafeteria, Gymnasium), Auditorium (Retrofitted LED Lighting - Recessed Mounted), LAN
	Years: 2023
	Systems: LED Lighting (Main Entrance Lobby, Corridors, Staircases), Transformer
	Years: 2022
	Systems: Exit Lights (Battery Pack), Students Cafeteria (Local Sound System)
	Years: 2020
	Systems: Security Lights
	Years: 2019
	Systems: Intrusion Alarm System (Remote Annunciator)
	Years: 2018
	Systems: Telephone System
	Years: 2017
	Systems: Computer Lab (Raceway With Receptacles)
	Years: 2015
	Systems: Interior Lighting - Except (Science Lab, Library), Emergency Lighting (Non Battery Pack)
	Years: 2014
	Systems: Intrusion Alarm System (Panic Switch)
	Years: 2013
	Systems: IPDVS/CCTV System
	Years: 2011
	Systems: Science Lab
	Years: 2010
	Systems: Library
	Years: 2009
	Systems: Local Sound System, Public Address System
	Years: 2006
	Systems: Partial Molded Case Circuit Breaker Type Panel Board
	Years: 1995, 2000, 2014, 2017
	Systems: Partial Fused Disconnect Switch Type Panel Board
	Years: 1992, 2022
	Systems: Emergency Light/Exit Light Panel
	Years: 1992

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
-------------------------------------	-------------------	-----------------------	--------------------	----------------------	--------------------	-----------------	--------	------------

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

K335

Electrical Inspection

Yes	Emergency Lighting - Battery Not Operational	N/A	EMERGENCY LIGHTING Battery Pack	Boiler Room, Auditorium (Stage, Exit 5 Vestibule), Gymnasium, Students Cafeteria, Closet Rooms (226, 326), Ground Floor - Staircases (B, C)	Jose Garcia	Custodian	Sent to DSF
-----	--	-----	-----------------------------------	---	-------------	-----------	-------------

Inspection

Question	Response
Electrical	
AUDITORIUM	Inspected
Instance on Ground Floor	Inspected
House Lighting	Inspected
Does a Chandelier exist?	No
Instance on Ground Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on Ground Floor	Does not Exist
Lighting Fixture - HID	
Instance on Ground Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on Ground Floor	Does not Exist
Lighting Fixture - LED	
Instance on Ground Floor	Inspected
Pendant Mounted	Inspected
Instance on Ground Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on Ground Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Instance on Ground Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	Inspected
Instance on Ground Floor	Inspected
Installation Year	2006
Source of Installation	Inspector Estimate
Condition	3 - Fair
Deficiency	MICROPHONE / JACK NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo	No photo recorded
Violations	No violations recorded.

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K335

Question	Response
AUDITORIUM	
Projection System	Does not Exist
Instance on Ground Floor	Does not Exist
Theater Lighting System	Inspected
Instance on Ground Floor	Inspected
Dimming System	
Instance on Ground Floor	Does not Exist
Theater Lighting	
Instance on Ground Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	32
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
CAFETERIA	Inspected
Instance on Ground Floor - Staff	Inspected
Instance on Ground Floor - Students	Inspected
Lighting	Inspected
Instance on Ground Floor - Students	Inspected
Instance on Ground Floor - Staff	Inspected
Lighting Fixture - Fluorescent	
Instance on Ground Floor - Students	Does not Exist
Instance on Ground Floor - Staff	Inspected
Pendant Mounted	Does not Exist
Instance on Ground Floor - Staff	Does not Exist
Surface Mounted	Does not Exist
Instance on Ground Floor - Staff	Does not Exist
Recessed Mounted	Inspected
Instance on Ground Floor - Staff	Inspected
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K335

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Violations	No violations recorded.
Lighting Fixture - HID	
Instance on Ground Floor - Students	Does not Exist
Instance on Ground Floor - Staff	Does not Exist
Lighting Fixture - Incandescent	
Instance on Ground Floor - Students	Does not Exist
Instance on Ground Floor - Staff	Does not Exist
Lighting Fixture - LED	
Instance on Ground Floor - Students	Inspected
Instance on Ground Floor - Staff	Does not Exist
Pendant Mounted	
Instance on Ground Floor - Students	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Ground Floor - Students	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Ground Floor - Students	Does not Exist
Local Sound System	
Instance on Ground Floor - Students	Inspected
Installation Year	2020
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Ground Floor - Staff	Does not Exist
Projection System	
Instance on Ground Floor - Students	Does not Exist
Instance on Ground Floor - Staff	Does not Exist
Theater Lighting System	
Instance on Ground Floor - Students	Does not Exist
Instance on Ground Floor - Staff	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Condition	2 - Between Good and Fair

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K335

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	Inspected
Recessed Mounted	
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
COMPUTER LAB	Inspected
Instance on Room 235	Inspected
Power Panel	Yes
Lighting	Inspected
Instance on Room 235	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 235	Inspected
Pendant Mounted	Inspected
Instance on Room 235	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 235	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 235	Does not Exist
Lighting Fixture - HID	
Instance on Room 235	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 235	Does not Exist
Lighting Fixture - LED	
Instance on Room 235	Does not Exist
Raceway With Receptacles	Inspected
Instance on Room 235	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
Instance on Ground Floor	Inspected
Lighting	Inspected
Instance on Ground Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on Ground Floor	Does not Exist
Lighting Fixture - HID	

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K335

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - HID	
Instance on Ground Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on Ground Floor	Does not Exist
Lighting Fixture - LED	
Instance on Ground Floor	Inspected
Pendant Mounted	
Instance on Ground Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Ground Floor	Does not Exist
Recessed Mounted	
Instance on Ground Floor	Does not Exist
Local Sound System	
Instance on Ground Floor	Inspected
Installation Year	2006
Source of Installation	Inspector Estimate
Condition	4 - Between Fair and Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo	No photo recorded
Violations	No violations recorded.
Projection System	
Instance on Ground Floor	Does not Exist
Scoreboard	
Instance on Ground Floor	Does not Exist
Theater Lighting System	
Instance on Ground Floor	Does not Exist
KITCHEN	
Instance on Ground Floor	Inspected
Lighting	
Instance on Ground Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on Ground Floor	Inspected
Pendant Mounted	
Instance on Ground Floor	Does not Exist
Surface Mounted	
Instance on Ground Floor	Does not Exist
Recessed Mounted	
Instance on Ground Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K335

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	
Instance on Ground Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on Ground Floor	Does not Exist
Lighting Fixture - LED	
Instance on Ground Floor	Does not Exist
LIBRARY	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K335

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Raceway With Receptacles	
Instance on 1st Floor	Does not Exist
Projection System	
Instance on 1st Floor	Does not Exist
LOCKER ROOM	
MULTIPURPOSE ROOM	
SCIENCE DEMO ROOM	
SCIENCE LAB	
Instance on Room 302	Inspected
Power Panel Alternative use	No No
Lighting	
Instance on Room 302	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 302	Inspected
Pendant Mounted	
Instance on Room 302	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 302	Does not Exist
Recessed Mounted	
Instance on Room 302	Does not Exist
Lighting Fixture - HID	
Instance on Room 302	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 302	Inspected
Pendant Mounted	
Instance on Room 302	Does not Exist
Surface Mounted	
Instance on Room 302	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 302	Does not Exist
Lighting Fixture - LED	
Instance on Room 302	Does not Exist
Emergency Gas Shut-Off Valve	
Instance on Room 302	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K335

Question	Response
SCIENCE LAB	
Emergency Shut-Off Power	Inspected
Instance on Room 302	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Power Supply	Inspected
Instance on Room 302	Inspected
Instructor Unit	
Instance on Room 302	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 302	Does not Exist
Student Unit	
Instance on Room 302	Does not Exist
Projection System	Inspected
Instance on Room 302	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	107,000
Replacement Uom	S.F.
Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K335

Question	Response
AUXILIARY SIGNAL/BELL SYSTEM	
Deficiency	INDICATOR PANEL NOT OPERATIONAL
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE PANEL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
EMERGENCY DC STANDBY BATTERY POWER	
	Does not Exist
EMERGENCY GENERATOR SET	
	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	
	Inspected
Battery Pack	
	Inspected
Condition	3 - Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Gymnasium
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Deficiency Photo1	No photo recorded
Violations	35578474K
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Boiler Room, Auditorium (Stage, Exit 5 Vestibule), Gymnasium, Students Cafeteria, Closet Rooms (226, 326), Ground Floor - Staircases (B, C)
Deficiency Quantity	13
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	35578474K, 35635986M
Non Battery Pack	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	
	Inspected
Battery Pack	
	Inspected
Condition	1 - Good
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	3rd Floor Corridor by Staircase C
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K335

Question	Response
EXIT LIGHT	Inspected
Battery Pack	Inspected
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Does not Exist
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	107,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Strobe	Does not Exist
Manual Pull Station	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Does not Exist
Duct Smoke Detector	Does not Exist
Area Smoke Detector	Does not Exist
CO Detector	Does not Exist
Heat Detector	Does not Exist
Elevator Recall	Does not Exist
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not Exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ACME
Equipment	Fire Alarm Control Board
Installation Year	1968
Source of Installation	Documented
Deficiency	No deficiencies recorded
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not Exist
Fire Alarm Control Panel (Standard)	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K335

Question	Response
FIRE ALARM SYSTEM	
Sub-Panel	
Fire Alarm Control Panel (Standard)	
Instance	Boiler Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ACME
Equipment	Sprinkler Alarm Control Board
Installation Year	1968
Source of Installation	Documented
Deficiency	No deficiencies recorded
Remote Annunciator	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not Exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room, Mechanical Room 146
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K335

Question	Response
PANEL BOARD	
Fused Disconnect Switch Type	
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Knife Switch Type	
	Does not Exist
Fused Toggle Switch Type	
	Inspected
Condition	3 - Fair
Fused Toggle Switch Type	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room 25
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Molded Case Circuit Breaker Type	
	Inspected
Condition	3 - Fair
Molded Case Circuit Breaker Type	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Auditorium, Gymnasium, Corridors by Rooms (6, 26, 49, 103, 120, 147, 203, 247, 303, 319)
Deficiency Quantity	13
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Molded Case Circuit Breaker Type	
Deficiency	NO SPARE
Deficiency Location/Instance	Students Cafeteria, Corridors by Rooms (47, 215A)
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Molded Case Circuit Breaker Type	
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Electrical Room 25
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K335

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	IDF Room 228
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Auditorium, 1st Floor Corridor by Room 147
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	107,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland Telecenter
Installation Year	2006
Source of Installation	Inspector Estimate
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Corridors and Classrooms
Deficiency Quantity	25
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Replacement Quantity	107,000
Replacement Uom	S.F.
Installation Year	2011
Source of Installation	Inspector Estimate
Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K335

Question	Response
SECURITY	
IPDVS/CCTV System	
Deficiency	CAMERA NOT OPERATIONAL
Deficiency Location/Instance	Exterior Wall by Exit 4 (E1-04)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Intrusion Alarm System	
	Inspected
Replacement Quantity	107,000
Replacement Uom	S.F.
Central Control Panel	
	Inspected
Instance	Custodian's Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista-50P
Installation Year	1995
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Infrared Sensor	
	Inspected
Condition	3 - Fair
Deficiency	SENSOR NOT OPERATIONAL
Deficiency Location/Instance	Room 247
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Panic Switch	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting - Security	
	Inspected
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	
	Inspected
Instance	Electrical Room 25
Instance Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K335

Question	Response
SERVICE SWITCH	
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Lexington
Equipment	MAIN SWITCH 1600 AMP FUSES
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1968
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room 25
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Federal Pacific Electric
Equipment	MAIN SERV SW
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1968
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	0
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room 25
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Lexington
Equipment	MAIN SW BD
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1968
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K335

Question	Response
TRANSFORMER	Inspected
Instance	Sprinkler Valve Main Control Room 27
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Hammond Power Solutions
Equipment	N/A
Capacity/Size Quantity	225
Capacity/Size UOM	KVA
Source of Capacity/Size	Inspector Estimate
Installation Year	2022
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded