# NYC Department of Education

# **Building Condition Assessment Survey 2023 - 2024**

### Architectural Inspection

Asset:	P.S. 396 (TANDEM K327-D23) - K, 110 CHESTER STREET, New York, 11212					
Inspection Id	Inspection Type	Time In	Last Edited			
SA : K396	Architectural - Senior	2023-11-16 7:30 AM	2023-11-29 4:20 PM			
AA : K396	Architectural - Associate	2023-11-16 8:18 AM	2023-11-28 1:43 PM			

Asset Data

Question	Answer				
Was the building fully accessible for inspection	Yes				
Building Square Footage	0				
Comments on the Area (for Athletic Field, Playing Surfaces, Leased Spaces)	Reported in K327, Tandem with K396				
Comments on the Stories (Floors) plus Basements	3+B				
Comments on the Number of Classrooms	30				
Comments on the Year Built	1966				
Student Population	194				
Staff Population	200				
Weather	Fair				
Principal(s) Information					
Principal Name	Keisha McCoy-Dailey				
Organization	P.S. 396 - Brooklyn				
Did you meet with this Principal?	No				
Did this Principal provide feedback?	Yes				
Summary of Principal's Feedback	Assistant Principal Dr. Chana Max, speaking on behalf of the Principal, commented that Room 378 has damages to wall finishes.				

Jonathan Ranzie

Custodian

Fireman

Facade Photo



Chester Street - Southwest View

K396

# **NYC Department of Education Building Condition Assessment Survey 2023 - 2024**

#### Architectural Inspection

Main Entrance Photo

Roof Photo



Facade E - Chester Street



Roof 1 - North View Have any Systems/Major Building Components been upgraded? Yes Systems: See Main Asset K327 Year: For Information No Yes K327 Leased Space? No Priority Priority Condition Component Location Person(s) Person(s) Title PhotoImage **Condition Exist** Category Description Affected Description Notified Last Year? No condition recorded Structural Engineer Required Structural Condition Component Location Person(s) Person(s) Title PhotoImage **Condition Type** Description Notified Affected Description

#### No condition recorded

Programmatic Accessibility

Have there been any Building Additions? Tandem Schools? Asset Number(s)

#### **Priority Condition**

# NYC Department of Education

# **Building Condition Assessment Survey 2023 - 2024**

# Architectural Inspection


Programmatic Accessibility Sta	tus Question			Respo	nse		
Is the primary or secondary entrar	nce on an accessible route?			Yes			
Is the building a multi-story building?				Yes			
Are all floors of the building accessible through compliant means?				Yes			
Accessible classrooms exists on each floor?				Yes			
Boys and Girls or Unises	Boys and Girls or Unisex accessible toilets exist on at least every other			Yes			
If the following spaces Cafeteria, Computer, C	If the following spaces exist, are they ALL accessible? Art Room, Aud Cafeteria, Computer, Gymnasiums, Library, Multipurpose Room, Scient						
Physical Breakdown Structure			Required	Complies	Deficiency	Assistive Listening System	
PROGRAMMATIC ACCESSI	BILITY						
Exterior Routes							
Exterior Entrances & I	Exits			Yes			
Exterior H/C Lifts		No	No				
Exterior Ramps and Ra	ailings	Yes		Yes			
Interior Routes							
Corridor and Lobby H	/C Lifts	No	No				
Interior Corridor Door	s and Hardware	Yes		Yes			
Interior Corridors and	Lobbies			Yes			
Interior Elevators		Yes		Yes			
Interior Lobby Doors a	nd Hardware			Yes			
Interior Ramps		Yes		Yes			
Rooms & Spaces							
Art Rooms		No					
Auditorium		No					
Cafeteria	1st Floor	Yes		Yes		FM System	Yes
Classrooms	1st-3rd Floors	Yes		Yes			
<b>Computer Rooms</b>		No					
Gymnasium		No					
Library		No					
Main Office	Room 164	Yes		Yes			
Multi-purpose Room		No					
Nurse's Room	Room 174	Yes		Yes			
Pool		No					
Science Lab		No					
<b>Toilet Rooms (Boys)</b>	2nd, 3rd Floors	Yes		Yes			
<b>Toilet Rooms (Girls)</b>	2nd, 3rd Floors	Yes		Yes			
Toilet Rooms (Staff)	3rd Floor	Yes		Yes			

### NYC Department of Education

# **Building Condition Assessment Survey 2023 - 2024**

# Architectural Inspection

### **Building Template**



**Chester Street** 

spection				
Question	Response			
Architectural				
EXTERIOR	Not Required			
INTERIOR	Not Required			
LIFE SAFETY	Not Required			
SITE	Not Required			
ARTWORK	Does not Exist			

K396