

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K410**

**Asset: ABRAHAM LINCOLN HS - K, 2800 OCEAN PARKWAY, New York, 11235**

Inspection Id	Inspection Type	Time In	Last Edited
EE : K410	Electrical	2024-02-27 8:00 AM	2024-06-17 10:01 AM

**Asset Data**

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Emergency Generator Set
	Years: Under Construction
	Systems: Most Exit Lights (Battery Pack)
	Years: 2022
	Systems: Fused Disconnect Switch Type Panel Board, LAN
	Years: 2020
	Systems: Fire Alarm System, Service Switch, Partial Switchboard, Transformer, Lightning Protection, Grounding System
	Years: 2017
	Systems: Public Address System, Local Sound System (Auditorium, Gymnasiums), Auditorium (Projection System), LED Lighting, Partial Emergency Lighting (Non Battery Pack)
	Years: 2016
	Systems: Intercom System (Elevator)
	Years: 2014
	Systems: Motor Controller (Most Motor Starter/Contactor), Exit/Emergency Light
	Years: 2013
	Systems: Cafeteria (Local Sound System), Fluorescent Lighting (Students Toilet Rooms, Cafeteria)
	Years: 2010
	Systems: Science Lab - Rooms 239, 334, Science Prep Room 239A
	Years: 2009
	Systems: IPDVS/CCTV System
	Years: 2005
	Systems: Interior Fluorescent Lighting, Retrofitted Fluorescent Lighting (Corridors, Library)
	Years: 2003
	Systems: Emergency Light/Exit Light Panel
	Years: 1996
	Systems: Most Security Lights
	Years: 1995, 2013, 2019
	Systems: Most Molded Case Circuit Breaker Type Panel Board
	Years: 1990, 1996, 2003, 2010, 2016, 2018

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	No
Which spaces do not have dedicated intercoms?	Rooms 109, 125, 209, 223A, 309, 323

**Priority Condition**

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Water Leaks onto Electrical Equipment	N/A	Power Outlet	Room B10, Pool Mechanical Room	Vincenzo Failla	Cleaner	Sent to DSF	

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K410

Inspection

Question	Response
<b>Electrical</b>	
<b>AUDITORIUM</b>	Inspected
Instance on 1st Floor	Inspected
<b>House Lighting</b>	Inspected
Does a Chandelier exist?	Yes
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	4 - Between Fair and Poor
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K410**

<b>Question</b>	<b>Response</b>
<b>AUDITORIUM</b>	
<b>House Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
<b>Pendant Mounted</b>	
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Surface Mounted</b>	
Instance on 1st Floor	Does not Exist
<b>Recessed Mounted</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not Exist
<b>Local Sound System</b>	
Instance on 1st Floor	Inspected
Installation Year	2016
Source of Installation	Inspector Estimate
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	
Instance on 1st Floor	Inspected
<b>Dimming System</b>	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	DIMMING RACK/LIGHT CONSOLE BEYOND USEFUL LIFE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Theater Lighting</b>	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K410**

<b>Question</b>	<b>Response</b>
<b>AUDITORIUM</b>	
<b>Theater Lighting System</b>	
<b>Theater Lighting</b>	
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	183
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>CAFETERIA</b>	Inspected
Instance on Basement	Inspected
<b>Lighting</b>	Inspected
Instance on Basement	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement	Inspected
<b>Pendant Mounted</b>	
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Basement	Does not Exist
<b>Recessed Mounted</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Basement	Does not Exist
<b>Local Sound System</b>	
Instance on Basement	Inspected
Installation Year	2010
Source of Installation	Inspector Estimate
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on Basement	Does not Exist
<b>Theater Lighting System</b>	
Instance on Basement	Does not Exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K410**

<b>Question</b>	<b>Response</b>
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	
Does a Chandelier exist?	No
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	11
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Surface Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	13
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Does not Exist
<b>Recessed Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>COMPUTER LAB</b>	Does not Exist
<b>GYMNASIUM</b>	Inspected
Instance on 1st Floor - Boys	Inspected
Instance on 1st Floor - Girls S, 1st Floor - Girls G	Inspected
<b>Lighting</b>	Inspected
Instance on 1st Floor - Girls S, 1st Floor - Girls G	Inspected
Instance on 1st Floor - Boys	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K410**

<b>Question</b>	<b>Response</b>
<b>GYMNASIUM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor - Girls S, 1st Floor - Girls G	Does not Exist
Instance on 1st Floor - Boys	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor - Girls S, 1st Floor - Girls G	Does not Exist
Instance on 1st Floor - Boys	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor - Girls S, 1st Floor - Girls G	Does not Exist
Instance on 1st Floor - Boys	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor - Girls S, 1st Floor - Girls G	Inspected
Instance on 1st Floor - Boys	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor - Girls S, 1st Floor - Girls G	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Boys	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on 1st Floor - Girls S, 1st Floor - Girls G	Does not Exist
Instance on 1st Floor - Boys	Inspected
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	
Instance on 1st Floor - Girls S, 1st Floor - Girls G	Does not Exist
Instance on 1st Floor - Boys	Does not Exist
<b>Local Sound System</b>	
Instance on 1st Floor - Girls S, 1st Floor - Girls G	Inspected
Installation Year	2016
Source of Installation	Inspector Estimate
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Boys	Inspected
Installation Year	2016
Source of Installation	Inspector Estimate
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on 1st Floor - Girls S, 1st Floor - Girls G	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K410**

<b>Question</b>	<b>Response</b>
<b>GYMNASIUM</b>	
<b>Projection System</b>	Does not Exist
Instance on 1st Floor - Boys	Does not Exist
<b>Scoreboard</b>	Does not Exist
Instance on 1st Floor - Girls S, 1st Floor - Girls G	Does not Exist
Instance on 1st Floor - Boys	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	Does not Exist
Instance on 1st Floor - Girls S, 1st Floor - Girls G	Does not Exist
Instance on 1st Floor - Boys	Does not Exist
<b>KITCHEN</b>	
	Inspected
Instance on Basement	Inspected
<b>Lighting</b>	Inspected
Instance on Basement	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Basement	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Does not Exist
Instance on Basement	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Basement	Does not Exist
<b>LIBRARY</b>	
	Inspected
Instance on Room 300	Inspected
<b>Lighting</b>	Inspected
Instance on Room 300	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 300	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Room 300	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K410**

<b>Question</b>	<b>Response</b>
<b>LIBRARY</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	Inspected
Instance on Room 300	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 300	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 300	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 300	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 300	Does not Exist
<b>Raceway With Receptacles</b>	
Instance on Room 300	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on Room 300	Does not Exist
<b>LOCKER ROOM</b>	
Instance on Basement - Boys	Inspected
Alternative use	No
Instance on Basement - Girls	Inspected
Alternative use	No
<b>Lighting</b>	
Instance on Basement - Girls	Inspected
Instance on Basement - Boys	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement - Girls	Inspected
Instance on Basement - Boys	Inspected
<b>Pendant Mounted</b>	
Instance on Basement - Girls	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Basement - Boys	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K410**

<b>Question</b>	<b>Response</b>
<b>LOCKER ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Surface Mounted</b>	Inspected
Instance on Basement - Girls	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Basement - Boys	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Does not Exist
Instance on Basement - Girls	Does not Exist
Instance on Basement - Boys	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Basement - Girls	Does not Exist
Instance on Basement - Boys	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement - Girls	Does not Exist
Instance on Basement - Boys	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Basement - Girls	Does not Exist
Instance on Basement - Boys	Does not Exist
<b>MULTIPURPOSE ROOM</b>	Does not Exist
<b>SCIENCE DEMO ROOM</b>	Inspected
Instance on Room 232	Inspected
Power Panel	Yes
Alternative use	Yes
Instance on Room 138	Inspected
Power Panel	No
Alternative use	Yes
Instance on Rooms 139, 233, 235, 336, 338, 341	Inspected
Power Panel	No
Alternative use	No
Instance on Room 141	Inspected
Power Panel	No
Alternative use	No
<b>Lighting</b>	Inspected
Instance on Room 141	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K410**

<b>Question</b>	<b>Response</b>
<b>SCIENCE DEMO ROOM</b>	
<b>Lighting</b>	
Instance on Rooms 139, 233, 235, 336, 338, 341	Inspected
Instance on Room 138	Inspected
Instance on Room 232	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 141	Inspected
Instance on Rooms 139, 233, 235, 336, 338, 341	Inspected
Instance on Room 138	Inspected
Instance on Room 232	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Room 141	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Rooms 139, 233, 235, 336, 338, 341	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 138	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 232	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on Room 141	Does not Exist
Instance on Rooms 139, 233, 235, 336, 338, 341	Does not Exist
Instance on Room 138	Does not Exist
Instance on Room 232	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 141	Does not Exist
Instance on Rooms 139, 233, 235, 336, 338, 341	Does not Exist
Instance on Room 138	Does not Exist
Instance on Room 232	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 141	Does not Exist
Instance on Rooms 139, 233, 235, 336, 338, 341	Does not Exist
Instance on Room 138	Does not Exist
Instance on Room 232	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 141	Does not Exist
Instance on Rooms 139, 233, 235, 336, 338, 341	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K410

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 138	Does not Exist
Instance on Room 232	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 141	Does not Exist
Instance on Rooms 139, 233, 235, 336, 338, 341	Does not Exist
Instance on Room 138	Does not Exist
Instance on Room 232	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 141	Does not Exist
Instance on Rooms 139, 233, 235, 336, 338, 341	Does not Exist
Instance on Room 138	Does not Exist
Instance on Room 232	Does not Exist
<b>Emergency Shut-Off Power</b>	
Instance on Room 141	Does not Exist
Instance on Rooms 139, 233, 235, 336, 338, 341	Does not Exist
Instance on Room 138	Does not Exist
Instance on Room 232	Does not Exist
<b>Power Supply</b>	
Instance on Room 141	Inspected
Instance on Rooms 139, 233, 235, 336, 338, 341	Inspected
Instance on Room 138	Inspected
Instance on Room 232	Inspected
<b>Instructor Unit</b>	
Instance on Room 141	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 139, 233, 235, 336, 338, 341	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 138	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 232	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Meter Demonstration Unit</b>	
Instance on Room 141	Does not Exist
Instance on Rooms 139, 233, 235, 336, 338, 341	Does not Exist
Instance on Room 138	Does not Exist
Instance on Room 232	Does not Exist
<b>Projection System</b>	
Instance on Room 141	Does not Exist
Instance on Rooms 139, 233, 235, 336, 338, 341	Does not Exist
Instance on Room 138	Does not Exist
Instance on Room 232	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K410**

<b>Question</b>	<b>Response</b>
<b>SCIENCE LAB</b>	Inspected
Instance on Room 140	Inspected
Power Panel Alternative use	No No
Instance on Room 240	Inspected
Power Panel Alternative use	No No
Instance on Rooms 239, 334	Inspected
Power Panel Alternative use	Yes No
<b>Lighting</b>	Inspected
Instance on Rooms 239, 334	Inspected
Instance on Room 240	Inspected
Instance on Room 140	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Rooms 239, 334	Inspected
Instance on Room 240	Inspected
Instance on Room 140	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Rooms 239, 334	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 240	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 140	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Surface Mounted</b>	Does not Exist
Instance on Rooms 239, 334	Does not Exist
Instance on Room 240	Does not Exist
Instance on Room 140	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on Rooms 239, 334	Does not Exist
Instance on Room 240	Does not Exist
Instance on Room 140	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Rooms 239, 334	Does not Exist
Instance on Room 240	Does not Exist
Instance on Room 140	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Rooms 239, 334	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K410

Question	Response
<b>SCIENCE LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 240	Does not Exist
Instance on Room 140	Does not Exist
<b>Pendant Mounted</b>	
Instance on Rooms 239, 334	Does not Exist
<b>Surface Mounted</b>	
Instance on Rooms 239, 334	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Rooms 239, 334	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Rooms 239, 334	Does not Exist
Instance on Room 240	Does not Exist
Instance on Room 140	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Rooms 239, 334	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 240	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 140	Does not Exist
<b>Emergency Shut-Off Power</b>	
Instance on Rooms 239, 334	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 240	Does not Exist
Instance on Room 140	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	
Instance on Rooms 239, 334	Inspected
Instance on Room 240	Inspected
Instance on Room 140	Inspected
<b>Instructor Unit</b>	
Instance on Rooms 239, 334	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 240	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 140	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Meter Demonstration Unit</b>	
Instance on Rooms 239, 334	Does not Exist
Instance on Room 240	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K410**

<b>Question</b>	<b>Response</b>
<b>SCIENCE LAB</b>	
<b>Power Supply</b>	
<b>Meter Demonstration Unit</b>	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 140	Does not Exist
<b>Student Unit</b>	
Instance on Rooms 239, 334	Does not Exist
Instance on Room 240	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 140	Does not Exist
<b>Projection System</b>	Inspected
Instance on Rooms 239, 334	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 240	Does not Exist
Instance on Room 140	Does not Exist
<b>SCIENCE PREP ROOM</b>	Inspected
Instance on Room 138B	Inspected
Power Panel Alternative use	Yes No
Instance on Room 236A	Inspected
Power Panel Alternative use	No Yes
Instance on Room 239A	Inspected
Power Panel Alternative use	No No
<b>Lighting</b>	Inspected
Instance on Room 239A	Inspected
Instance on Room 236A	Inspected
Instance on Room 138B	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 239A	Inspected
Instance on Room 236A	Inspected
Instance on Room 138B	Inspected
<b>Pendant Mounted</b>	
Instance on Room 239A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 236A	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K410

Question	Response
<b>SCIENCE PREP ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	Inspected
Instance on Room 138B	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on Room 239A	Does not Exist
Instance on Room 236A	Does not Exist
Instance on Room 138B	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 239A	Does not Exist
Instance on Room 236A	Does not Exist
Instance on Room 138B	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 239A	Does not Exist
Instance on Room 236A	Does not Exist
Instance on Room 138B	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 239A	Does not Exist
Instance on Room 236A	Does not Exist
Instance on Room 138B	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 239A	Does not Exist
Instance on Room 236A	Does not Exist
Instance on Room 138B	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	Inspected
Instance on Room 239A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 236A	Does not Exist
Instance on Room 138B	Does not Exist
<b>Emergency Shut-Off Power</b>	Inspected
Instance on Room 239A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 236A	Does not Exist
Instance on Room 138B	Does not Exist
<b>Power Supply</b>	Does not Exist
Instance on Room 239A	Does not Exist
Instance on Room 236A	Does not Exist
Instance on Room 138B	Inspected
<b>Instructor Unit</b>	
Instance on Room 138B	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>SWIMMING POOL</b>	
Instance on Basement	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K410

Question	Response
<b>SWIMMING POOL</b>	
<b>Lighting</b>	Inspected
Instance on Basement	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Basement	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
Instance on Basement	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Basement	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Basement	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
Instance on Basement	Does not Exist
<b>Local Sound System</b>	Does not Exist
Instance on Basement	Does not Exist
<b>Scoreboard</b>	Inspected
Instance on Basement	Inspected
Condition	5 - Poor
Deficiency	NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>TOILET ROOM - STAFF</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded



**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K410**

<b>Question</b>	<b>Response</b>
<b>TOILET ROOM - STAFF</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Recessed Mounted</b>	Does not Exist
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Does not Exist
<b>Recessed Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Does not Exist
<b>Recessed Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Inspected
Replacement Quantity	245,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not Exist
<b>EMERGENCY GENERATOR SET</b>	Under Construction
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Boys Locker Room, Cafeteria, Library
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K410**

<b>Question</b>	<b>Response</b>
<b>EMERGENCY LIGHTING</b>	
<b>Battery Pack</b>	
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	FIXTURE LENS MISSING
Deficiency Location/Instance	Swimming Pool
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL LENS
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Non Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	
<b>Battery Pack</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Auditorium Stage
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>EXIT/EMERGENCY LIGHT</b>	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>FIRE ALARM SYSTEM</b>	
Replacement Quantity	245,000
Replacement Uom	S.F.
<b>Bell/Horn</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Strobe</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Manual Pull Station</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fan Shutdown Control</b>	Inspected
Condition	2 - Between Good and Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K410

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Fan Shutdown Control</b>	Inspected
Deficiency	No deficiencies recorded
<b>Duct Smoke Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Area Smoke Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>CO Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Heat Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Elevator Recall</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Magnetic Door Holder/Contactor</b>	Does not Exist
<b>Fused Cutout Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	Does not Exist
<b>Main Panel</b>	Inspected
<b>Bell At Panel</b>	Does not Exist
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards System Technology
Equipment	Fire Alarm Control Panel
Model	EST3X
Installation Year	2017
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	Does not Exist
<b>Sub-Panel</b>	Inspected
<b>Bell At Panel</b>	Does not Exist
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Auditorium - Stage
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards System Technology
Equipment	N/A
Model	EST3X
Installation Year	2017
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K410**

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	
<b>Sub-Panel</b>	Inspected
<b>Fire Alarm Control Panel (Standard)</b>	Does not Exist
<b>Remote Annunciator</b>	Inspected
<b>Display Monitor</b>	Does not Exist
<b>Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Printer</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Punch Register</b>	Does not Exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Tamper Flow Switch/Chain</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>GROUNDING SYSTEM</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>INTERCOM SYSTEM</b>	Inspected
<b>Elevator</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Holding Area</b>	Does not Exist
<b>LAN</b>	Inspected
<b>Local Distribution Frame (I/LDF)</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>MOTOR CONTROLLER</b>	Inspected
<b>Motor Control Center</b>	Does not Exist
<b>Motor Starter/Contactor</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Variable Frequency Drive</b>	Does not Exist
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Fused Toggle Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	2 - Between Good and Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K410**

<b>Question</b>	<b>Response</b>
<b>PANEL BOARD</b>	
<b>Molded Case Circuit Breaker Type</b>	
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	2nd Floor Corridor by Room 239
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Mechanical Room above Girls Gymnasium
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	2nd Floor Boiler Room 231
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Room above Girls Gymnasium, Library Mechanical Room, Corridor by Rooms (104, 110, 123, 139, 149, 206, 210, 221, 231, 239, 249, 308, 310, 321, 331, 335, 349)
Deficiency Quantity	27
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>PUBLIC ADDRESS SYSTEM</b>	Inspected
Replacement Quantity	245,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Telecor II
Installation Year	2016
Source of Installation	Custodial Staff

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K410

Question	Response
<b>PUBLIC ADDRESS SYSTEM</b>	
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>SECURITY</b>	
	Inspected
<b>IPDVS/CCTV System</b>	
	Inspected
Replacement Quantity	245,000
Replacement Uom	S.F.
Installation Year	2005
Source of Installation	Inspector Estimate
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Intrusion Alarm System</b>	
	Inspected
Replacement Quantity	245,000
Replacement Uom	S.F.
<b>Central Control Panel</b>	
	Inspected
Instance	Room Inside Electrical Meter Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	4140XMPT
Installation Year	1992
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
<b>Infrared Sensor</b>	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting - Security</b>	
	Inspected
Replacement Uom	EACH
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance	Exterior Walls facing (Ocean Parkway, West Avenue)
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K410**

<b>Question</b>	<b>Response</b>
<b>SECURITY</b>	
<b>Lighting - Security</b>	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>SERVICE SWITCH</b>	
	Inspected
Instance	Electrical Meter Room (Inside Boiler Room)
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	East Coast
Equipment	Main #2 - Service Switch B
Capacity/Size Quantity	2,500
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2017
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Meter Room (Inside Boiler Room)
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	East Coast
Equipment	Main #1 - Service Switch A
Capacity/Size Quantity	2,500
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2017
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Meter Room (Inside Boiler Room)
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	East Coast
Equipment	Kitchen Disconnect Switch
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2017
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Meter Room (Inside Boiler Room)
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	East Coast
Equipment	Field Lighting Switch

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K410**

<b>Question</b>	<b>Response</b>
<b>SERVICE SWITCH</b>	
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2017
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Meter Room (Inside Boiler Room)
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	East Coast
Equipment	Service Switch
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2017
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>SWITCHBOARD</b>	Inspected
Number of Spares	0
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	Electrical Meter Room (Inside Boiler Room)
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	Kitchen Dist.
Capacity/Size Quantity	600
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2017
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room (inside Cafeteria)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Royal Switchboard Co.
Equipment	Main Disc. SW. A
Capacity/Size Quantity	2,500
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1971
Source of Installation	Inspector Estimate



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K410**

<b>Question</b>	<b>Response</b>
<b>SWITCHBOARD</b>	
<b>Fused Disconnect Switch Type</b>	
Deficiency	No deficiencies recorded
Instance	Electrical Room (inside Cafeteria)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Royal Switchboard Co.
Equipment	Main Disc. SW. B
Capacity/Size Quantity	2,500
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	4
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1971
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Does not Exist
<b>TELEPHONE SYSTEM</b>	
<b>PBX/Intercom</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Standard</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>TRANSFORMER</b>	
Instance	Electrical Meter Room (Inside Boiler Room)
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	N/A
Capacity/Size Quantity	113
Capacity/Size UOM	KVA
Source of Capacity/Size	Nameplate
Installation Year	2017
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Electrical Meter Room (Inside Boiler Room)
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	N/A
Capacity/Size Quantity	45
Capacity/Size UOM	KVA
Source of Capacity/Size	Nameplate
Installation Year	2017

NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K410

Question	Response
<b>TRANSFORMER</b>	
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded