Asset: TILDEN AF - BROOKLYN, 5800 TILDEN AVE	NUE, New York, 11203	
Inspection Id Inspection Type	Time In	Last Edited
ME: K416 Mechanical	2024-02-08 7:49 AM	2024-02-21 11:30 A
Asset Data	2021.02.00.77,320	
Question	Answer	
Are there fuel tanks?	No	
Total # of water main service entries to the asset	1	
MERs/Fan Rooms Locations	None	
Are there any spaces with Missing or Defective CO Detectors?	No	
Are there any Emergency Stop Switches with Missing Hammers?	No	
Are there any Painted/Obstructed Sprinkler Heads?	No	
Have any Systems/Major Building Components been upgraded?	No	
Priority Condition		
Priority Priority Condition Component Locatio Condition Exist Category Description Affected Descrip Last Year?		PhotoImage
No condition recorded		
Inspection	Decreases	
Question	Response	
Mechanical		
AIR CONDITIONING	Inspected	
Chilled Water System	Does not Exist	
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not Exist	
Cooling Coil in Ductwork	Does not Exist	
Cooling Tower	Does not Exist	
DX Split System	Does not Exist	
Dry Cooler	Does not Exist	
Packaged / Rooftop Unit	Inspected	
Instance	Roof	
Instance Condition	4 - Between Fair and Poor	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Source of Heating	Gas	
Refrigerant Type	R-22	
Instance Manufacturer	Trane	
Equipment	RTU-1	
Capacity/Size Quantity	10	
Capacity/Size UOM	Tons	
Source of Capacity/Size	Inspector Estimate	
Installation Year	2002	
Source of Installation	Documented	
Deficiency	UP TO 20 TONS: DEFECTIVE UNIT	
Deficiency Location/Instance	Roof	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	

Does not Exist	
Does not Exist	
Inspected	
Does not Exist	
Inspected	
<u> </u>	
EACH	
PVI	
•	
Gallons	
Documented	
Inspected	
Inspected	
2 D	
2 - Between Good and Fair	
2 - Between Good and Fair No deficiencies recorded Inspected	
	Does not Exist Does not Exist Does not Exist Does not Exist Inspected Inspected Does not Exist Does not Exist Inspected Water Meter Room 2 - Between Good and Fair 1 EACH No deficiencies recorded Inspected Does not Exist Inspected Water Meter Room 3 - Fair 1 EACH Water Meter Room 3 - Fair 1 EACH PVI N/A 1,000 MBH Input 900 Gallons Documented 2002 Documented No deficiencies recorded Does not Exist Inspected Vater Meter Room Documented Vater Room Documented Does not Exist Unspected Unspected

uestion	Response	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Sewage/Waste/Vent Piping	Inspected	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Does not Exist	
Sump Pump	Does not Exist	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not Exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Urinal	Does not Exist	
Student	Inspected	
Drinking Fountain	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3 - Fair	
Deficiency	CRACKED/PHYSICAL DAMAGE	
Deficiency Location/Instance	Boys Toilet Room inside North Locker Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Locker Room Shower		
Instance on 1st Floor - North	Inspected	
Instance Condition	Inspected 3 - Fair	
Alternative use	Yes	
Deficiency	No deficiencies recorded	
Instance on 1st Floor - South	Inspected	
Instance Condition	3 - Fair	
Alternative use		
	Yes	
Deficiency Sink And Fountain Combo Unit	No deficiencies recorded	
	Does not Exist	
Toilet	Inspected	
Condition	3 - Fair	
Deficiency	CRACKED/PHYSICAL DAMAGE	
Deficiency Location/Instance	Boys Toilet Room inside North Locker Room	
Deficiency Quantity	1	

chanical Inspection Ka		
uestion	Response	
FIXTURES		
Student		
Toilet		
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Deficiency	DEFECTIVE FLUSHOMETER VALVE	
Deficiency Location/Instance	1st Floor Boys Toilet Room, 1st Floor Girls Toilet Room	
Deficiency Quantity	6	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Urinal	Does not Exist	
GAS FIRED FURNACE	Inspected	
Condition	3 - Fair	
Deficiency	DIRTY/CLOGGED/RESTRICTED FILTER	
Deficiency Location/Instance	Roof / HV-2	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
GAS SERVICE	Inspected	
Gas Distribution Piping	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Gas Meter Room Exhaust Fan	Does not Exist	
Gas Meter Room Vent	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Gas Pressure Booster	Does not Exist	
CO/Gas Leak Detection	Inspected	
Instance	Gas Meter Room, Water Heater Room	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Installation Year	2011	
Source of Installation	Inspector Estimate	
Deficiency	No deficiencies recorded	
HEATING	Inspected	
Heating Coil In Ductwork	Does not Exist	

Building Condition Assessment Survey 2023 - 2024

K416

Mechanical Inspection Question Response HEATING Radiator/Convector/Fin Tube Inspected Condition 2 - Between Good and Fair Deficiency No deficiencies recorded **Steam Heating** Does not Exist Steam supplied by External Sources Does not Exist **Unit Heater/Cabinet Heater** Inspected Condition 3 - Fair Deficiency No deficiencies recorded HEATING PLANT Does not Exist **Enclosed IDF Room** Does not Exist **MDF Room** Does not Exist SPRINKLERS, STANDPIPE, FIRE SYSTEM Does not Exist VENTILATION Inspected Is the building mechanically ventilated? Partial **Exhaust Fan** Inspected Approximate Total # of Fans 1-25 Condition 3 - Fair Deficiency No deficiencies recorded **Heating And Ventilating Unit** Does not Exist **Metal Ductwork** Inspected Are there any uninsulated ductwork by design in Mechanical Yes Are there chain operated dampers? No Condition 2 - Between Good and Fair Deficiency DEFECTIVE REGISTER/DIFFUSER 1st Floor - North Locker Room, 1st Floor - South Locker Room Deficiency Location/Instance **Deficiency Quantity** 4 Quantity Uom **EACH** MAINTENANCE Potential Action PRIORITY 3 Urgency of Action Purpose of Action LEVEL 2 Deficiency Photo1 No photo recorded Violations No violations recorded. **Supply Fan** Does not Exist **Unit Ventilator** Does not Exist