Building Condition Assessment Survey 2023 - 2024

Inspection Id	Inspection Type		Time In	Last Edited
EE: K421	Electrical		2024-03-12 8:15 AM	2024-03-22 2:45 PM
et Data				
Question		Answer		
Type of Service		Below Gro	ound	
Does Interactive	Whiteboard (IWB) Exist?	No		
Water Penetratio	n in Electrical Room?	No		
Have any System	ns/Major Building Components been upgraded?	Yes		
		Systems:	Security Lights, Retrofitted LED	Lighting
		Years:	2022	
		Systems:	All Other Electrical Systems and	Components
		Years:	1991	
DEDICATED I	NTERCOMS IN FIRE RESCUE AREAS			
Question		Response		
•	fe Rescue Assistance Areas, Fire Rescue Areas, Rooms in your building?	No		

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Fire Alarm System - Components Not Operational	N/A	FIRE ALARM SYSTEM Main Panel Fire Alarm Control Panel (Electronic)	Field House - Mechanical Room	Michael Pizzo	Custodian	Sent to DSF	
Yes	Water Leaks onto Electrical Equipment	N/A	Lighting Fixture, Light Switch	Visitors Shower Room, Men's and Women's Toilet Rooms	Michael Pizzo	Custodian	Sent to DSF	
Yes	Fire Alarm System - Defective	N/A	FIRE ALARM SYSTEM Main Panel Fire Alarm Control Panel (Electronic)	Field House - Mechanical Room	Michael Pizzo	Custodian	Resolved	

Inspection		
Question	Response	
Electrical		
ATHLETIC FIELD	Inspected	

ecti cui		
ATHLETIC FIELD	Inspected	
Exterior Lighting	Inspected	
Replacement Uom	EACH	
Condition	3 - Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	16	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Local Sound System	Inspected	
Installation Year	1991	

Building Condition Assessment Survey 2023 - 2024

Question	Response
ATHLETIC FIELD	
Local Sound System	
Source of Installation	Inspector Estimate
Condition	5 - Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Scoreboard	Inspected
Instance	Athletic Field - West Side
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
LOCKER ROOM	Inspected
Instance on 1st Floor - Visitors	Inspected
Alternative use	No
Instance on 1st Floor - Home	Inspected
Alternative use	No
Lighting	Inspected
Instance on 1st Floor - Home	Inspected
Instance on 1st Floor - Visitors	Inspected
Lighting Fixture - Fluorescent	•
Instance on 1st Floor - Home	Does not Exist
Instance on 1st Floor - Visitors	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor - Home	Does not Exist
Instance on 1st Floor - Visitors	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Home	Inspected
Instance on 1st Floor - Visitors	Inspected
Pendant Mounted	
rendant Mounted	Does not Exist

Building Condition Assessment Survey 2023 - 2024

Electrical Inspection K421 Question Response LOCKER ROOM Lighting **Lighting Fixture - Incandescent Pendant Mounted** Does not Exist Instance on 1st Floor - Home Does not Exist Instance on 1st Floor - Visitors Does not Exist **Surface Mounted** Inspected Instance on 1st Floor - Home Inspected Condition 3 - Fair LIGHTING FIXTURE BEYOND USEFUL LIFE Deficiency **Deficiency Quantity** Quantity Uom **EACH** REPLACE-UPGRADE Potential Action PRIORITY 1 Urgency of Action LEVEL 2 Purpose of Action Deficiency Photo1 No photo recorded Violations No violations recorded. Instance on 1st Floor - Visitors Inspected 3 - Fair Condition LIGHTING FIXTURE NOT OPERATIONAL Deficiency **Deficiency Quantity** Quantity Uom EACH REPLACE Potential Action PRIORITY 3 Urgency of Action LEVEL 2 Purpose of Action Deficiency Photo1 No photo recorded Violations No violations recorded.

Deficiency

Deficiency Quantity

Instance on 1st Floor - Visitors

Instance on 1st Floor - Home

Instance on 1st Floor - Visitors

Surface Mounted

Deficiency

Condition

Quantity Uom

Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Recessed Mounted	Does not Exist	
Instance on 1st Floor - Home	Does not Exist	
Instance on 1st Floor - Visitors	Does not Exist	
Lighting Fixture - LED		
Instance on 1st Floor - Home	Inspected	
Instance on 1st Floor - Visitors	Inspected	
Pendant Mounted	Does not Exist	
Instance on 1st Floor - Home	Does not Exist	

6 EACH

Does not Exist

2 - Between Good and Fair

No deficiencies recorded

Inspected

Inspected

Inspected

LIGHTING FIXTURE BEYOND USEFUL LIFE

Building Condition Assessment Survey 2023 - 2024

Question	Response
LOCKER ROOM	
Lighting	
Lighting Fixture - LED	
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor - Home	Does not Exist
Instance on 1st Floor - Visitors	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not Exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Does not Exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Does not Exist
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Does not Exist Does not Exist
EXIT LIGHT	Inspected
Battery Pack	Inspected

Building Condition Assessment Survey 2023 - 2024

uestion	Response
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Does not Exist
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	2,200
Replacement Uom	S.F.
Bell/Horn	Does not Exist
Strobe	Does not Exist
Manual Pull Station	Does not Exist
Fan Shutdown Control	Inspected
Condition	3 - Fair No deficiencies recorded
Duct Smoke Detector	
	Inspected
Condition	3 - Fair No deficiencies recorded
Deficiency Area Smoke Detector	
Condition	Inspected 3 - Fair
Deficiency	No deficiencies recorded
CO Detector	Does not Exist
Heat Detector	Does not Exist
Fused Cutout Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Field House - Mechanical Room
Instance Condition	4 - Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Simplex
Equipment	Fire Alarm Control
Model	4002
Installation Year	1991
Source of Installation	Inspector Estimate
Deficiency	PANEL NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.

Building Condition Assessment Survey 2023 - 2024

Question	Response
FIRE ALARM SYSTEM	
Main Panel	Inspected
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Does not Exist
Sprinkler Flow/Air Pressure Switch	Does not Exist
Tamper Flow Switch/Chain	Does not Exist
GROUNDING SYSTEM	Does not Exist
LAN	Does not Exist
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	
Condition	Inspected 3 - Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not Exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type Condition	Inspected 3 - Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Does not Exist
SECURITY	Inspected
SECURITY IPDVS/CCTV System	Inspected Does not Exist
SECURITY IPDVS/CCTV System Intrusion Alarm System	Inspected Does not Exist Inspected
SECURITY IPDVS/CCTV System Intrusion Alarm System Replacement Quantity	Inspected Does not Exist Inspected 2,200
SECURITY IPDVS/CCTV System Intrusion Alarm System Replacement Quantity Replacement Uom	Inspected Does not Exist Inspected 2,200 S.F.
SECURITY IPDVS/CCTV System Intrusion Alarm System Replacement Quantity Replacement Uom Central Control Panel	Inspected Does not Exist Inspected 2,200 S.F. Inspected
SECURITY IPDVS/CCTV System Intrusion Alarm System Replacement Quantity Replacement Uom Central Control Panel Instance	Inspected Does not Exist Inspected 2,200 S.F. Inspected Field House - Mechanical Room
SECURITY IPDVS/CCTV System Intrusion Alarm System Replacement Quantity Replacement Uom Central Control Panel Instance Instance Condition	Inspected Does not Exist Inspected 2,200 S.F. Inspected Field House - Mechanical Room 5 - Poor
IPDVS/CCTV System Intrusion Alarm System Replacement Quantity Replacement Uom Central Control Panel Instance Instance Condition Instance Quantity	Inspected Does not Exist Inspected 2,200 S.F. Inspected Field House - Mechanical Room 5 - Poor
SECURITY IPDVS/CCTV System Intrusion Alarm System Replacement Quantity Replacement Uom Central Control Panel Instance Instance Condition Instance Quantity Instance Quantity	Inspected Does not Exist Inspected 2,200 S.F. Inspected Field House - Mechanical Room 5 - Poor 1 EACH
IPDVS/CCTV System Intrusion Alarm System Replacement Quantity Replacement Uom Central Control Panel Instance Instance Condition Instance Quantity Instance Quantity Instance Quantity Instance Quantity Uom Model	Inspected Does not Exist Inspected 2,200 S.F. Inspected Field House - Mechanical Room 5 - Poor 1 EACH Simplex 3001
IPDVS/CCTV System Intrusion Alarm System Replacement Quantity Replacement Uom Central Control Panel Instance Instance Condition Instance Quantity Instance Quantity Instance Quantity Uom Model Installation Year	Inspected Does not Exist Inspected 2,200 S.F. Inspected Field House - Mechanical Room 5 - Poor 1 EACH Simplex 3001 1991
IPDVS/CCTV System Intrusion Alarm System Replacement Quantity Replacement Uom Central Control Panel Instance Instance Condition Instance Quantity Instance Quantity Instance Operation Instance Quantity Instance Operation Model Installation Year Source of Installation	Inspected Does not Exist Inspected 2,200 S.F. Inspected Field House - Mechanical Room 5 - Poor 1 EACH Simplex 3001 1991 Documented
IPDVS/CCTV System Intrusion Alarm System Replacement Quantity Replacement Uom Central Control Panel Instance Instance Condition Instance Quantity Instance Quantity Instance Quantity Source of Installation Deficiency	Inspected Does not Exist Inspected 2,200 S.F. Inspected Field House - Mechanical Room 5 - Poor 1 EACH Simplex 3001 1991 Documented PANEL NOT OPERATIONAL
IPDVS/CCTV System Intrusion Alarm System Replacement Quantity Replacement Uom Central Control Panel Instance Instance Condition Instance Quantity Instance Quantity Instance Quantity Instance Ondition Model Installation Year Source of Installation Deficiency Deficiency Quantity	Inspected Does not Exist Inspected 2,200 S.F. Inspected Field House - Mechanical Room 5 - Poor 1 EACH Simplex 3001 1991 Documented PANEL NOT OPERATIONAL 2,200
IPDVS/CCTV System Intrusion Alarm System Replacement Quantity Replacement Uom Central Control Panel Instance Instance Condition Instance Quantity Instance Quantity Instance Quantity Source of Installation Deficiency	Inspected Does not Exist Inspected 2,200 S.F. Inspected Field House - Mechanical Room 5 - Poor 1 EACH Simplex 3001 1991 Documented PANEL NOT OPERATIONAL 2,200 S.F.
IPDVS/CCTV System Intrusion Alarm System Replacement Quantity Replacement Uom Central Control Panel Instance Instance Condition Instance Quantity Instance Quantity Instance Operative Uom Model Installation Year Source of Installation Deficiency Deficiency Quantity Quantity Uom	Inspected Does not Exist Inspected 2,200 S.F. Inspected Field House - Mechanical Room 5 - Poor 1 EACH Simplex 3001 1991 Documented PANEL NOT OPERATIONAL 2,200
IPDVS/CCTV System Intrusion Alarm System Replacement Quantity Replacement Uom Central Control Panel Instance Instance Condition Instance Quantity Instance Quantity Instance Quantity Uom Model Installation Year Source of Installation Deficiency Deficiency Quantity Quantity Uom Potential Action	Inspected Does not Exist Inspected 2,200 S.F. Inspected Field House - Mechanical Room 5 - Poor 1 EACH Simplex 3001 1991 Documented PANEL NOT OPERATIONAL 2,200 S.F. REPLACE SYSTEM
IPDVS/CCTV System Intrusion Alarm System Replacement Quantity Replacement Uom Central Control Panel Instance Instance Condition Instance Quantity Instance Quantity Instance Ondition Deficiency Deficiency Deficiency Deficiency Quantity Quantity Uom Potential Action Urgency of Action	Inspected Does not Exist Inspected 2,200 S.F. Inspected Field House - Mechanical Room 5 - Poor 1 EACH Simplex 3001 1991 Documented PANEL NOT OPERATIONAL 2,200 S.F. REPLACE SYSTEM PRIORITY 4
IPDVS/CCTV System Intrusion Alarm System Replacement Quantity Replacement Uom Central Control Panel Instance Instance Condition Instance Quantity Instance Quantity Instance Quantity Uom Model Installation Year Source of Installation Deficiency Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action	Inspected Does not Exist Inspected 2,200 S.F. Inspected Field House - Mechanical Room 5 - Poor 1 EACH Simplex 3001 1991 Documented PANEL NOT OPERATIONAL 2,200 S.F. REPLACE SYSTEM PRIORITY 4 LEVEL 3
Intrusion Alarm System Replacement Quantity Replacement Uom Central Control Panel Instance Instance Condition Instance Quantity Instance Quantity Instance Quantity Installation Year Source of Installation Deficiency Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations	Inspected Does not Exist Inspected 2,200 S.F. Inspected Field House - Mechanical Room 5 - Poor 1 EACH Simplex 3001 1991 Documented PANEL NOT OPERATIONAL 2,200 S.F. REPLACE SYSTEM PRIORITY 4 LEVEL 3 No photo recorded No violations recorded.
Intrusion Alarm System Replacement Quantity Replacement Uom Central Control Panel Instance Instance Condition Instance Quantity Instance Quantity Instance Quantity Uom Model Installation Year Source of Installation Deficiency Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photol Violations Infrared Sensor	Inspected Does not Exist Inspected 2,200 S.F. Inspected Field House - Mechanical Room 5 - Poor 1 EACH Simplex 3001 1991 Documented PANEL NOT OPERATIONAL 2,200 S.F. REPLACE SYSTEM PRIORITY 4 LEVEL 3 No photo recorded No violations recorded. Does not Exist
Intrusion Alarm System Replacement Quantity Replacement Uom Central Control Panel Instance Instance Condition Instance Quantity Instance Quantity Instance Quantity Installation Year Source of Installation Deficiency Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations	Inspected Does not Exist Inspected 2,200 S.F. Inspected Field House - Mechanical Room 5 - Poor 1 EACH Simplex 3001 1991 Documented PANEL NOT OPERATIONAL 2,200 S.F. REPLACE SYSTEM PRIORITY 4 LEVEL 3 No photo recorded No violations recorded.

Building Condition Assessment Survey 2023 - 2024

Question	Response	
SECURITY		
Intrusion Alarm System	Inspected	
Remote Annunciator	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Does not Exist	
Lighting - Security	Inspected	
Replacement Uom	EACH	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
SERVICE SWITCH	Does not Exist	
SWITCHBOARD	Does not Exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Standard	Does not Exist	
TRANSFORMER	Does not Exist	