

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Asset: GRAND STREET CAMPUS (OLD E.D.HS)-K, 850 GRAND STREET, New York, 11225

Inspection Id	Inspection Type	Time In	Last Edited
EE : K450	Electrical	2024-01-08 9:08 AM	2024-06-21 3:37 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	Yes
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: IPDVS/CCTV System, LED Lighting (1st Floor - Gymnasium 1, Staff Toilet Rooms AF2, AF3)
	Years: 2023
	Systems: Most Security Lights, Intrusion Alarm System
	Years: 2022
	Systems: LAN
	Years: 2021
	Systems: Motor Controller (Variable Frequency Drive)
	Years: 2020
	Systems: Auditorium (Theater Lighting System)
	Years: 2016
	Systems: Exit Lights (Battery Pack)
	Years: 2015
	Systems: Auditorium (Local Sound System), Public Address System (Amplifier)
	Years: 2013
	Systems: Gymnasiums (Pendant Fluorescent Lighting)
	Years: 2012
	Systems: Science Lab - Rooms G280, G283, Science Prep Room G280A
	Years: 2009
	Systems: Emergency Generator Set
	Years: 2007
	Systems: Transformer
	Years: 2000, 2020
	Systems: Fused Disconnect Switch Type Panel Board
	Years: 2000
	Systems: Partial Molded Case Circuit Breaker Type Panel Board
	Years: 1990, 2002, 2009, 2016, 2019

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Intercom System - Does Not Exist	Intercom System exist in Holding Rooms 320, 420 and it Does Not Exist in Room 211	Intercom System - Holding Area	Room 211	Philip Navetta	Custodian	Resolved	

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

K450

Electrical Inspection

No	Intercom System - Does Not Exist	N/A	Intercom System - Holding Area	Rooms 211, 321, 421	John Chung	Fireman	Sent to DSF
No	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electrical Room	Philip Navetta	Custodian	Sent to DSF
Yes	Fire Alarm System - Defective	N/A	FIRE ALARM SYSTEM Main Panel Fire Alarm Control Panel (Electronic)	Main Entrance Lobby	Philip Navetta	Custodian	Sent to DSF
Yes	Fire Alarm System - Components Not Operational	N/A	FIRE ALARM SYSTEM Strobe	Girls Locker Room	Philip Navetta	Custodian	Sent to DSF

Inspection

Question	Response
Electrical	
AUDITORIUM	Inspected
Instance on 2nd Floor	Inspected
House Lighting	Inspected
Does a Chandelier exist?	No
Instance on 2nd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 2nd Floor	Does not Exist
Surface Mounted	Inspected
Instance on 2nd Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Does not Exist
Instance on 2nd Floor	Does not Exist
Lighting Fixture - HID	
Instance on 2nd Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Incandescent	
Pendant Mounted	Inspected
Instance on 2nd Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	Does not Exist
Instance on 2nd Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 2nd Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	125
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - LED	
Instance on 2nd Floor	Does not Exist
Local Sound System	Inspected
Instance on 2nd Floor	Inspected
Installation Year	2013
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Inspected
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 2nd Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Theater Lighting System	Inspected
Instance on 2nd Floor	Inspected
Dimming System	
Instance on 2nd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 2nd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
CAFETERIA	Inspected
Instance on 1st Floor - Staff	Inspected
Instance on 1st Floor - Students A	Inspected
Instance on 1st Floor - Students B	Inspected
Lighting	Inspected
Instance on 1st Floor - Students B	Inspected
Instance on 1st Floor - Students A	Inspected
Instance on 1st Floor - Staff	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Students B	Inspected
Instance on 1st Floor - Students A	Inspected
Instance on 1st Floor - Staff	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor - Students B	Does not Exist
Instance on 1st Floor - Students A	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor - Students B	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	105
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - Students A	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	105
Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K450

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - Staff	Does not Exist
Recessed Mounted	
Instance on 1st Floor - Students B	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - Students A	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - Staff	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	
Instance on 1st Floor - Students B	Does not Exist
Instance on 1st Floor - Students A	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Students B	Does not Exist
Instance on 1st Floor - Students A	Does not Exist
Instance on 1st Floor - Staff	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - LED	
Instance on 1st Floor - Students B	Does not Exist
Instance on 1st Floor - Students A	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
Local Sound System	Inspected
Instance on 1st Floor - Students B	Inspected
Installation Year	1980
Source of Installation	Documented
Condition	5 - Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - Students A	Inspected
Installation Year	1980
Source of Installation	Documented
Condition	5 - Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - Staff	Does not Exist
Projection System	Does not Exist
Instance on 1st Floor - Students B	Does not Exist
Instance on 1st Floor - Students A	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
Theater Lighting System	Does not Exist
Instance on 1st Floor - Students B	Does not Exist
Instance on 1st Floor - Students A	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	15
Quantity Uom	EACH

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	3,250
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	
	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	525
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	
	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	995
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE BALLAST

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	
	Does not Exist
Lighting Fixture - Incandescent	
	Does not Exist
Lighting Fixture - LED	
	Does not Exist
COMPUTER LAB	
	Inspected
Instance on Room 330	Inspected
Power Panel	Yes
Instance on Room 450A	Inspected
Power Panel	No
Instance on Room 462	Inspected
Power Panel	No
Instance on Rooms G297, G298	Inspected
Power Panel	Yes
Lighting	
	Inspected
Instance on Rooms G297, G298	Inspected
Instance on Room 462	Inspected
Instance on Room 450A	Inspected
Instance on Room 330	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms G297, G298	Inspected
Instance on Room 462	Inspected
Instance on Room 450A	Inspected
Instance on Room 330	Inspected
Pendant Mounted	
	Does not Exist
Instance on Rooms G297, G298	Does not Exist
Instance on Room 462	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	27
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 450A	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	16
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
----------	----------

COMPUTER LAB

Lighting

Lighting Fixture - Fluorescent

Pendant Mounted

Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.

Instance on Room 330	Inspected
----------------------	-----------

Condition	3 - Fair
-----------	----------

Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
------------	-------------------------------------

Deficiency Quantity	25
---------------------	----

Quantity Uom	EACH
--------------	------

Potential Action	REPLACE-UPGRADE
------------------	-----------------

Urgency of Action	PRIORITY 1
-------------------	------------

Purpose of Action	LEVEL 2
-------------------	---------

Deficiency Photo1	No photo recorded
-------------------	-------------------

Violations	No violations recorded.
------------	-------------------------

Surface Mounted	Does not Exist
------------------------	----------------

Instance on Rooms G297, G298	Does not Exist
------------------------------	----------------

Instance on Room 462	Does not Exist
----------------------	----------------

Instance on Room 450A	Does not Exist
-----------------------	----------------

Instance on Room 330	Does not Exist
----------------------	----------------

Recessed Mounted	Inspected
-------------------------	-----------

Instance on Rooms G297, G298	Inspected
------------------------------	-----------

Condition	3 - Fair
-----------	----------

Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
------------	-------------------------------------

Deficiency Quantity	16
---------------------	----

Quantity Uom	EACH
--------------	------

Potential Action	REPLACE-UPGRADE
------------------	-----------------

Urgency of Action	PRIORITY 1
-------------------	------------

Purpose of Action	LEVEL 2
-------------------	---------

Deficiency Photo1	No photo recorded
-------------------	-------------------

Violations	No violations recorded.
------------	-------------------------

Instance on Room 462	Does not Exist
----------------------	----------------

Instance on Room 450A	Does not Exist
-----------------------	----------------

Instance on Room 330	Does not Exist
----------------------	----------------

Lighting Fixture - HID

Instance on Rooms G297, G298	Does not Exist
------------------------------	----------------

Instance on Room 462	Does not Exist
----------------------	----------------

Instance on Room 450A	Does not Exist
-----------------------	----------------

Instance on Room 330	Does not Exist
----------------------	----------------

Lighting Fixture - Incandescent

Instance on Rooms G297, G298	Does not Exist
------------------------------	----------------

Instance on Room 462	Does not Exist
----------------------	----------------

Instance on Room 450A	Does not Exist
-----------------------	----------------

Instance on Room 330	Does not Exist
----------------------	----------------

Lighting Fixture - LED

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
COMPUTER LAB	
Lighting	
Lighting Fixture - LED	
Instance on Rooms G297, G298	Does not Exist
Instance on Room 462	Does not Exist
Instance on Room 450A	Does not Exist
Instance on Room 330	Does not Exist
Raceway With Receptacles	Inspected
Instance on Rooms G297, G298	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 462	Inspected
Condition	4 - Between Fair and Poor
Deficiency	RECEPTACLES NOT OPERATIONAL
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 450A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 330	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
Instance on 1st Floor - Gymnasium 1	Inspected
Instance on 1st Floor - Gymnasium 2	Inspected
Instance on 1st Floor - Gymnasium 3, 1st Floor - Gymnasium 4	Inspected
Lighting	Inspected
Instance on 1st Floor - Gymnasium 3, 1st Floor - Gymnasium 4	Inspected
Instance on 1st Floor - Gymnasium 2	Inspected
Instance on 1st Floor - Gymnasium 1	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Gymnasium 3, 1st Floor - Gymnasium 4	Inspected
Instance on 1st Floor - Gymnasium 2	Inspected
Instance on 1st Floor - Gymnasium 1	Inspected
Pendant Mounted	Inspected
Instance on 1st Floor - Gymnasium 3, 1st Floor - Gymnasium 4	Inspected
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Violations	No violations recorded.
Instance on 1st Floor - Gymnasium 2	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - Gymnasium 1	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	
Instance on 1st Floor - Gymnasium 3, 1st Floor - Gymnasium 4	Does not Exist
Instance on 1st Floor - Gymnasium 2	Does not Exist
Instance on 1st Floor - Gymnasium 1	Does not Exist
Recessed Mounted	
Instance on 1st Floor - Gymnasium 3, 1st Floor - Gymnasium 4	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - Gymnasium 2	Does not Exist
Instance on 1st Floor - Gymnasium 1	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor - Gymnasium 3, 1st Floor - Gymnasium 4	Does not Exist
Instance on 1st Floor - Gymnasium 2	Does not Exist
Instance on 1st Floor - Gymnasium 1	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Gymnasium 3, 1st Floor - Gymnasium 4	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - Incandescent	
Instance on 1st Floor - Gymnasium 2	Does not Exist
Instance on 1st Floor - Gymnasium 1	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor - Gymnasium 3, 1st Floor - Gymnasium 4	Does not Exist
Instance on 1st Floor - Gymnasium 2	Does not Exist
Instance on 1st Floor - Gymnasium 1	Inspected
Pendant Mounted	Inspected
Instance on 1st Floor - Gymnasium 1	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on 1st Floor - Gymnasium 1	Does not Exist
Recessed Mounted	Does not Exist
Instance on 1st Floor - Gymnasium 1	Does not Exist
Local Sound System	Does not Exist
Instance on 1st Floor - Gymnasium 3, 1st Floor - Gymnasium 4	Does not Exist
Instance on 1st Floor - Gymnasium 2	Inspected
Installation Year	1980
Source of Installation	Documented
Condition	5 - Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - Gymnasium 1	Inspected
Installation Year	1980
Source of Installation	Documented
Condition	5 - Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Projection System	Does not Exist
Instance on 1st Floor - Gymnasium 3, 1st Floor - Gymnasium 4	Does not Exist
Instance on 1st Floor - Gymnasium 2	Does not Exist
Instance on 1st Floor - Gymnasium 1	Does not Exist
Scoreboard	Does not Exist
Instance on 1st Floor - Gymnasium 3, 1st Floor - Gymnasium 4	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
GYMNASIUM	
Scoreboard	
Instance on 1st Floor - Gymnasium 2	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Gymnasium 1	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor - Gymnasium 3, 1st Floor - Gymnasium 4	Does not Exist
Instance on 1st Floor - Gymnasium 2	Does not Exist
Instance on 1st Floor - Gymnasium 1	Does not Exist
KITCHEN	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not Exist
Surface Mounted	
Instance on 1st Floor	Does not Exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	61
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
LIBRARY	
Instance on Room 235	Inspected
Lighting	
Instance on Room 235	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 235	Inspected
Pendant Mounted	
Instance on Room 235	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Deficiency Quantity	24
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	Does not Exist
Instance on Room 235	Does not Exist
Recessed Mounted	Inspected
Instance on Room 235	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	105
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	
Instance on Room 235	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 235	Does not Exist
Lighting Fixture - LED	
Instance on Room 235	Does not Exist
Raceway With Receptacles	Inspected
Instance on Room 235	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on Room 235	Does not Exist
LOCKER ROOM	Inspected
Instance on Basement - Boys	Inspected
Alternative use	Yes
Instance on Basement - Girls	Inspected
Alternative use	Yes
Lighting	Inspected
Instance on Basement - Girls	Inspected
Instance on Basement - Boys	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement - Girls	Inspected
Instance on Basement - Boys	Inspected
Pendant Mounted	Does not Exist
Instance on Basement - Girls	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
LOCKER ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on Basement - Boys	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	
Instance on Basement - Girls	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	16
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Basement - Boys	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	16
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	
Instance on Basement - Girls	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	106
Quantity Uom	EACH

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
LOCKER ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Basement - Boys	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	106
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	
Instance on Basement - Girls	Does not Exist
Instance on Basement - Boys	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement - Girls	Does not Exist
Instance on Basement - Boys	Does not Exist
Lighting Fixture - LED	
Instance on Basement - Girls	Does not Exist
Instance on Basement - Boys	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Inspected
Instance on Room 354	Inspected
Power Panel	Yes
Alternative use	Yes

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
SCIENCE DEMO ROOM	
Instance on Rooms 305, 440	Inspected
Power Panel	No
Alternative use	No
Instance on Room 438	Inspected
Power Panel	No
Alternative use	No
Instance on Room 454	Inspected
Power Panel	No
Alternative use	No
Instance on Room 456	Inspected
Power Panel	Yes
Alternative use	No
Instance on Room 352	Inspected
Power Panel	No
Alternative use	No
Instance on Room 356	Inspected
Power Panel	No
Alternative use	Yes
Instance on Room 452	Inspected
Power Panel	No
Alternative use	Yes
Instance on Rooms 435, 437	Inspected
Power Panel	No
Alternative use	No
Instance on Room 357	Inspected
Power Panel	No
Alternative use	No
Lighting	Inspected
Instance on Room 357	Inspected
Instance on Rooms 435, 437	Inspected
Instance on Room 452	Inspected
Instance on Room 356	Inspected
Instance on Room 352	Inspected
Instance on Room 456	Inspected
Instance on Room 454	Inspected
Instance on Room 438	Inspected
Instance on Rooms 305, 440	Inspected
Instance on Room 354	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 357	Inspected
Instance on Rooms 435, 437	Inspected
Instance on Room 452	Inspected
Instance on Room 356	Inspected
Instance on Room 352	Inspected
Instance on Room 456	Inspected
Instance on Room 454	Inspected
Instance on Room 438	Inspected
Instance on Rooms 305, 440	Inspected
Instance on Room 354	Inspected
Pendant Mounted	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
SCIENCE DEMO ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on Room 357	Does not Exist
Instance on Rooms 435, 437	Does not Exist
Instance on Room 452	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 356	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	18
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 352	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	18
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 456	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 454	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
SCIENCE DEMO ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 438	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	27
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Rooms 305, 440	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	42
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 354	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	18
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	Inspected
Instance on Room 357	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	21
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
SCIENCE DEMO ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Rooms 435, 437	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	42
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 452	Does not Exist
Instance on Room 356	Does not Exist
Instance on Room 352	Does not Exist
Instance on Room 456	Does not Exist
Instance on Room 454	Does not Exist
Instance on Room 438	Does not Exist
Instance on Rooms 305, 440	Does not Exist
Instance on Room 354	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 357	Does not Exist
Instance on Rooms 435, 437	Does not Exist
Instance on Room 452	Does not Exist
Instance on Room 356	Does not Exist
Instance on Room 352	Does not Exist
Instance on Room 456	Does not Exist
Instance on Room 454	Does not Exist
Instance on Room 438	Does not Exist
Instance on Rooms 305, 440	Does not Exist
Instance on Room 354	Does not Exist
Lighting Fixture - HID	
Instance on Room 357	Does not Exist
Instance on Rooms 435, 437	Does not Exist
Instance on Room 452	Does not Exist
Instance on Room 356	Does not Exist
Instance on Room 352	Does not Exist
Instance on Room 456	Does not Exist
Instance on Room 454	Does not Exist
Instance on Room 438	Does not Exist
Instance on Rooms 305, 440	Does not Exist
Instance on Room 354	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K450

Question	Response
SCIENCE DEMO ROOM	
Lighting	
Lighting Fixture - Incandescent	
Instance on Room 357	Inspected
Instance on Rooms 435, 437	Does not Exist
Instance on Room 452	Inspected
Instance on Room 356	Inspected
Instance on Room 352	Inspected
Instance on Room 456	Inspected
Instance on Room 454	Inspected
Instance on Room 438	Inspected
Instance on Rooms 305, 440	Inspected
Instance on Room 354	Inspected
Pendant Mounted	Does not Exist
Instance on Room 357	Does not Exist
Instance on Room 452	Does not Exist
Instance on Room 356	Does not Exist
Instance on Room 352	Does not Exist
Instance on Room 456	Does not Exist
Instance on Room 454	Does not Exist
Instance on Room 438	Does not Exist
Instance on Rooms 305, 440	Does not Exist
Instance on Room 354	Does not Exist
Surface Mounted	Inspected
Instance on Room 357	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 452	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 356	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
SCIENCE DEMO ROOM	
Lighting	
Lighting Fixture - Incandescent	
Surface Mounted	
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 352	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 456	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 454	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 438	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
SCIENCE DEMO ROOM	
Lighting	
Lighting Fixture - Incandescent	
Surface Mounted	
Violations	No violations recorded.
Instance on Rooms 305, 440	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 354	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	
Instance on Room 357	Does not Exist
Instance on Room 452	Does not Exist
Instance on Room 356	Does not Exist
Instance on Room 352	Does not Exist
Instance on Room 456	Does not Exist
Instance on Room 454	Does not Exist
Instance on Room 438	Does not Exist
Instance on Rooms 305, 440	Does not Exist
Instance on Room 354	Does not Exist
Lighting Fixture - LED	
Instance on Room 357	Does not Exist
Instance on Rooms 435, 437	Does not Exist
Instance on Room 452	Does not Exist
Instance on Room 356	Does not Exist
Instance on Room 352	Does not Exist
Instance on Room 456	Does not Exist
Instance on Room 454	Does not Exist
Instance on Room 438	Does not Exist
Instance on Rooms 305, 440	Does not Exist
Instance on Room 354	Does not Exist
Emergency Gas Shut-Off Valve	
Instance on Room 357	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
SCIENCE DEMO ROOM	
Emergency Gas Shut-Off Valve	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 435, 437	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 452	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 356	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 352	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 456	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 454	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 438	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 305, 440	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 354	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	Does not Exist
Instance on Room 357	Does not Exist
Instance on Rooms 435, 437	Does not Exist
Instance on Room 452	Does not Exist
Instance on Room 356	Does not Exist
Instance on Room 352	Does not Exist
Instance on Room 456	Does not Exist
Instance on Room 454	Does not Exist
Instance on Room 438	Does not Exist
Instance on Rooms 305, 440	Does not Exist
Instance on Room 354	Does not Exist
Power Supply	Inspected
Instance on Room 357	Inspected
Instance on Rooms 435, 437	Inspected
Instance on Room 452	Inspected
Instance on Room 356	Inspected
Instance on Room 352	Inspected
Instance on Room 456	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
SCIENCE DEMO ROOM	
Power Supply	
Instance on Room 454	Inspected
Instance on Room 438	Inspected
Instance on Rooms 305, 440	Inspected
Instance on Room 354	Inspected
Instructor Unit	
Instance on Room 357	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 435, 437	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 452	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 356	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 352	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 456	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 454	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 438	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 305, 440	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 354	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 357	Does not Exist
Instance on Rooms 435, 437	Does not Exist
Instance on Room 452	Does not Exist
Instance on Room 356	Does not Exist
Instance on Room 352	Does not Exist
Instance on Room 456	Does not Exist
Instance on Room 454	Does not Exist
Instance on Room 438	Does not Exist
Instance on Rooms 305, 440	Does not Exist
Instance on Room 354	Does not Exist
Projection System	
	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
SCIENCE DEMO ROOM	
Projection System	
Instance on Room 357	Does not Exist
Instance on Rooms 435, 437	Does not Exist
Instance on Room 452	Does not Exist
Instance on Room 356	Does not Exist
Instance on Room 352	Does not Exist
Instance on Room 456	Does not Exist
Instance on Room 454	Does not Exist
Instance on Room 438	Does not Exist
Instance on Rooms 305, 440	Does not Exist
Instance on Room 354	Does not Exist
SCIENCE LAB	
	Inspected
Instance on Room A369	Inspected
Power Panel	Yes
Alternative use	No
Instance on Room A375	Inspected
Power Panel	Yes
Alternative use	No
Instance on Room A377	Inspected
Power Panel	Yes
Alternative use	No
Instance on Rooms 453, 457	Inspected
Power Panel	Yes
Alternative use	No
Instance on Rooms G280, G283	Inspected
Power Panel	Yes
Alternative use	No
Lighting	
	Inspected
Instance on Rooms G280, G283	Inspected
Instance on Rooms 453, 457	Inspected
Instance on Room A377	Inspected
Instance on Room A375	Inspected
Instance on Room A369	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms G280, G283	Inspected
Instance on Rooms 453, 457	Inspected
Instance on Room A377	Inspected
Instance on Room A375	Inspected
Instance on Room A369	Inspected
Pendant Mounted	
	Inspected
Instance on Rooms G280, G283	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 453, 457	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	60
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room A377	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	32
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room A375	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	33
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room A369	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	32
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	Does not Exist
Instance on Rooms G280, G283	Does not Exist
Instance on Rooms 453, 457	Does not Exist
Instance on Room A377	Does not Exist
Instance on Room A375	Does not Exist
Instance on Room A369	Does not Exist
Recessed Mounted	Does not Exist
Instance on Rooms G280, G283	Does not Exist
Instance on Rooms 453, 457	Does not Exist
Instance on Room A377	Does not Exist
Instance on Room A375	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Instance on Room A369	Does not Exist
Lighting Fixture - HID	
Instance on Rooms G280, G283	Does not Exist
Instance on Rooms 453, 457	Does not Exist
Instance on Room A377	Does not Exist
Instance on Room A375	Does not Exist
Instance on Room A369	Does not Exist
Lighting Fixture - Incandescent	
Instance on Rooms G280, G283	Does not Exist
Instance on Rooms 453, 457	Inspected
Instance on Room A377	Inspected
Instance on Room A375	Inspected
Instance on Room A369	Inspected
Pendant Mounted	
Instance on Rooms 453, 457	Does not Exist
Instance on Room A377	Does not Exist
Instance on Room A375	Does not Exist
Instance on Room A369	Does not Exist
Surface Mounted	
Instance on Rooms 453, 457	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room A377	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room A375	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Incandescent	
Surface Mounted	
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room A369	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	
Instance on Rooms 453, 457	Does not Exist
Instance on Room A377	Does not Exist
Instance on Room A375	Does not Exist
Instance on Room A369	Does not Exist
Lighting Fixture - LED	
Instance on Rooms G280, G283	Does not Exist
Instance on Rooms 453, 457	Does not Exist
Instance on Room A377	Does not Exist
Instance on Room A375	Does not Exist
Instance on Room A369	Does not Exist
Emergency Gas Shut-Off Valve	
Instance on Rooms G280, G283	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 453, 457	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room A377	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room A375	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room A369	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Rooms G280, G283	Inspected
Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
SCIENCE LAB	
Emergency Shut-Off Power	
Deficiency	No deficiencies recorded
Instance on Rooms 453, 457	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room A377	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room A375	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room A369	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Power Supply	Inspected
Instance on Rooms G280, G283	Inspected
Instance on Rooms 453, 457	Inspected
Instance on Room A377	Inspected
Instance on Room A375	Inspected
Instance on Room A369	Inspected
Instructor Unit	
Instance on Rooms G280, G283	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 453, 457	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room A377	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room A375	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room A369	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Rooms G280, G283	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 453, 457	Does not Exist
Instance on Room A377	Does not Exist
Instance on Room A375	Does not Exist
Instance on Room A369	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Rooms G280, G283	Does not Exist
Instance on Rooms 453, 457	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
SCIENCE LAB	
Power Supply	
Student Unit	
Instance on Room A377	Does not Exist
Instance on Room A375	Does not Exist
Instance on Room A369	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Inspected
Instance on Rooms G280, G283	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 453, 457	Does not Exist
Instance on Room A377	Does not Exist
Instance on Room A375	Does not Exist
Instance on Room A369	Does not Exist
SCIENCE PREP ROOM	Inspected
Instance on Room 455	Inspected
Power Panel Alternative use	Yes No
Instance on Room A371/A373	Inspected
Power Panel Alternative use	No No
Instance on Room G280A	Inspected
Power Panel Alternative use	No No
Lighting	Inspected
Instance on Room G280A	Inspected
Instance on Room A371/A373	Inspected
Instance on Room 455	Inspected
Lighting Fixture - Fluorescent	
Instance on Room G280A	Inspected
Instance on Room A371/A373	Inspected
Instance on Room 455	Inspected
Pendant Mounted	Inspected
Instance on Room G280A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room A371/A373	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	22
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 455	Inspected
Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	18
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	
	Does not Exist
Instance on Room G280A	Does not Exist
Instance on Room A371/A373	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	14
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 455	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	
	Does not Exist
Instance on Room G280A	Does not Exist
Instance on Room A371/A373	Does not Exist
Instance on Room 455	Does not Exist
Lighting Fixture - HID	
Instance on Room G280A	Does not Exist
Instance on Room A371/A373	Does not Exist
Instance on Room 455	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room G280A	Does not Exist
Instance on Room A371/A373	Does not Exist
Instance on Room 455	Does not Exist
Lighting Fixture - LED	
Instance on Room G280A	Does not Exist
Instance on Room A371/A373	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
SCIENCE PREP ROOM	
Lighting	Inspected
Lighting Fixture - LED	
Instance on Room 455	Does not Exist
Emergency Gas Shut-Off Valve	Inspected
Instance on Room G280A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room A371/A373	Does not Exist
Instance on Room 455	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	Inspected
Instance on Room G280A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room A371/A373	Does not Exist
Instance on Room 455	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Power Supply	Does not Exist
Instance on Room G280A	Does not Exist
Instance on Room A371/A373	Inspected
Instance on Room 455	Inspected
Instructor Unit	
Instance on Room A371/A373	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 455	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
TOILET ROOM - STAFF	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	78
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	480,000

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Room Adjacent to Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	ATS #1
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2007
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Room Adjacent to Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	ATS #2
Capacity/Size Quantity	260
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2007
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Room Adjacent to Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	ATS - Fire Alarm (ATS #3)
Capacity/Size Quantity	70
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2007
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Battery Charger	Inspected
Instance	Outdoor Generator Enclosure
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Detroit Diesel Spectrum

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
EMERGENCY GENERATOR SET	Inspected
Battery Charger	
Equipment	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size2 Quantity	26
Capacity/Size2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	2007
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Emergency Distribution Board	Inspected
Number of Spares	1
Fused Disconnect Switch Type	Inspected
Instance	Room Adjacent to Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	N/A
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	2007
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Molded Case Circuit Breaker Type	Does not Exist
Diesel	Inspected
Instance	Outdoor Generator Enclosure
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Detroit Diesel Spectrum
Equipment	Emergency Generator
Capacity/Size Quantity	456
Capacity/Size UOM	KVA
Capacity/Size2 Quantity	365
Capacity/Size2 UOM	KW
Capacity/Size3Quantity	1,266
Capacity/Size3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2007
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Natural Gas	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
EMERGENCY LIGHTING	
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	1st Floor Corridor - by Room G192, Kitchen
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	1st Floor Corridor - by Room 115G
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	
	Inspected
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	
	Inspected
Replacement Quantity	480,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	3 - Fair
Deficiency	STROBE NOT OPERATIONAL
Deficiency Location/Instance	Girls Locker Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
FIRE ALARM SYSTEM	
Manual Pull Station	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
CO Detector	Does not Exist
Heat Detector	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	4 - Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Fire Alarm & Systems Technology Inc
Equipment	N/A
Model	IRC-3
Installation Year	1980
Source of Installation	Documented
Deficiency	SYSTEM DEFECTIVE
Deficiency Quantity	480,000
Quantity Uom	S.F.
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	E630862
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Inspected
Bell At Panel	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
FIRE ALARM SYSTEM	
Sub-Panel	
Bell At Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Basement - Workshop
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Simplex
Equipment	Fire Panel 4001
Model	4001
Installation Year	1980
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Basement - Workshop
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Kidde Automated Systems
Equipment	N/A
Model	KAS - 200
Installation Year	1980
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Basement - Workshop
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards
Equipment	Sprinkler Panel
Model	Custom - 6500
Installation Year	1980
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	5 - Poor
Deficiency	PRINTER NOT OPERATIONAL
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	
Printer	Inspected
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	
Inspected	
Elevator	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Holding Area	Does not Exist
LAN	
Inspected	
Local Distribution Frame (L/DF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	
Does not Exist	
MOTOR CONTROLLER	
Inspected	
Motor Control Center	Inspected
Instance	Basement - Room LM89 (by Boiler Room)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Federal Pacific Electric
Equipment	N/A
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	1980
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Mechanical Room (above Auditorium)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
MOTOR CONTROLLER	
Motor Control Center	
Instance Manufacturer	Federal Pacific Electric
Equipment	N/A
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	1980
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Penthouse #1
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Federal Pacific Electric
Equipment	N/A
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	1980
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Penthouse #2
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Federal Pacific Electric
Equipment	N/A
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	1980
Source of Installation	Documented
Deficiency	No deficiencies recorded
Motor Starter/Contactor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
PANEL BOARD	
Fused Disconnect Switch Type	Inspected
Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
PANEL BOARD	
Fused Disconnect Switch Type	Inspected
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	3 - Fair
Deficiency	NO SPARE
Deficiency Location/Instance	Corridors by Rooms (406, 305, L34), Student's Cafeteria B, Mechanical Room - Above Auditorium
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Corridors by Rooms (454, 438, 420, 354, 336, 320, 305, G295, G287, G280, 256, 235, 220, 210, G193, G190T, G182, 154, 106, 138, L36, L34), Rooms (457, 453, A377, A375, A369, G287, G278/G279, A267A, 162, G192, G184, G182, LM89), Auditorium, Gymnasium 2, Mechanical Room - Above Auditorium, Kitchen, Penthouses, Electrical Room, Room Adjacent to Electrical Room
Deficiency Quantity	61
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Science Demo Room 455
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	
	Inspected
Replacement Quantity	480,000

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
PUBLIC ADDRESS SYSTEM	
Replacement Uom	S.F.
Instance	General Office - Room A362
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	1980
Source of Installation	Documented
Deficiency	No deficiencies recorded
SECURITY	
	Inspected
IPDVS/CCTV System	
	Inspected
Replacement Quantity	480,000
Replacement Uom	S.F.
Installation Year	2023
Source of Installation	Custodial Staff
Condition	1 - Good
Deficiency	CAMERA NOT OPERATIONAL
Deficiency Location/Instance	2nd Floor Corridor - by Room 254
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo	No photo recorded
Violations	No violations recorded.
Intrusion Alarm System	
	Inspected
Replacement Quantity	480,000
Replacement Uom	S.F.
Central Control Panel	
	Inspected
Instance	Room A267A
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista-128BPT
Installation Year	2022
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Infrared Sensor	
	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Panic Switch	
	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Remote Annunciator	
	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Siren/Strobe	
	Inspected
Condition	1 - Good

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K450

Question	Response
SECURITY	
Intrusion Alarm System	Inspected
Siren/Strobe	
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Replacement Uom	EACH
Condition	1 - Good
Deficiency	TIME CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance	On Poles by Main Entrance
Deficiency Quantity	16
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SERVICE SWITCH	
	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Federal Pacific Electric
Equipment	Main Switchboard "A"
Capacity/Size Quantity	5,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1980
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Federal Pacific Electric
Equipment	Main Switchboard "B"
Capacity/Size Quantity	5,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1980
Source of Installation	Documented

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
SERVICE SWITCH	
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Federal Pacific Electric
Equipment	Kitchen Distribution Panel
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1980
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	
Number of Spares	5
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Federal Pacific Electric
Equipment	N/A
Capacity/Size Quantity	5,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	6
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	1980
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Federal Pacific Electric
Equipment	N/A
Capacity/Size Quantity	5,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	7
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	1980
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room Adjacent to Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Instance Manufacturer	Federal Pacific Electric
Equipment	KIT DIST
Capacity/Size Quantity	400
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1980
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	
	Inspected
PBX/Intercom	
	Inspected
Condition	3 - Fair
Deficiency	TELEPHONE MISSING
Deficiency Location/Instance	Classrooms, Gymnasiums, Auditorium
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	INSTALL TELEPHONE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Standard	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
TRANSFORMER	
	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Federal Pacific
Equipment	AC Auditorium
Capacity/Size Quantity	150
Capacity/Size UOM	KVA
Source of Capacity/Size	Nameplate
Installation Year	2000
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Instance	Mechanical Room (above Auditorium)
Instance Condition	1 - Good
Instance Quantity	2
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	N/A
Capacity/Size Quantity	30

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K450

Question	Response
TRANSFORMER	
Capacity/Size UOM	KVA
Source of Capacity/Size	Nameplate
Installation Year	2020
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded