

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K480**

**Asset: BUSHWICK HS - K, 400 IRVING AVENUE, New York, 11237**

Inspection Id	Inspection Type	Time In	Last Edited
EE : K480	Electrical	2024-04-11 7:55 AM	2024-04-26 1:29 PM

**Asset Data**

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	Yes
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: LAN
	Years: 2024
	Systems: Public Address System, Fire Alarm System - Except (Sprinkler Flow/Air Pressure Switch, Tamper Flow Switch/Chain), Local Sound System (Swimming Pool, Cafeteria - Students), Most Exit Light (Battery Pack), Retrofitted LED Lighting - Except (Rooms 104, 426, 426A)
	Years: 2022
	Systems: IPDVS/CCTV System
	Years: 2020
	Systems: LED Lighting (Health Center - Room 104), Gymnasium (Scoreboard), Science Lab - Room 426, Science Prep Room 426A, Partial Grounding System
	Years: 2019
	Systems: Interior Lighting - Except (New Addition, Gymnasium), Most Emergency Lighting (Non Battery Pack)
	Years: 2015
	Systems: Gymnasium (Lighting)
	Years: 2012
	Systems: Security Lights
	Years: 2010, 2023
	Systems: Auditorium (Theater Lighting System), Emergency Generator Set (Battery Charger)
	Years: 2010
	Systems: Science Lab - Room A365 (Incandescent Lighting)
	Years: 2009
	Systems: Intrusion Alarm System
	Years: 2003
	Systems: Fused Disconnect Switch Type Panel Board
	Years: 1998, 2020, 2023
	Systems: Interior Fluorescent Lighting (New Addition)
	Years: 1998
	Systems: Partial Molded Case Circuit Breaker Type Panel Board
	Years: 1986, 1989, 1998, 2000, 2006, 2009, 2020, 2023

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

**Priority Condition**

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Water Leaks onto Electrical Equipment	N/A	Lighting Fixture, Fire Alarm Strobe	1st Floor Girls Locker Room, 1st Floor Girls Pool Locker Room	Jose Cruz	Fireman	Sent to DSF	

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

**K480**

**Electrical Inspection**

No	Fire Alarm System - Components Not Operational	Sprinkler Flow Switch in Room B24 is not operational.	FIRE ALARM SYSTEM   Sprinkler Flow/Air Pressure Switch	Room B24	Jose Cruz	Fireman	Sent to DSF
Yes	Emergency Lighting - Battery Not Operational	N/A	EMERGENCY LIGHTING   Battery Pack	Corridor by Rooms (105, 205, 219, 222, 312), 1st Floor near Exits (3, 5), Staff Cafeteria, Rooms (111, 216, 120, 120-A), Stair L at 1st Floor, Stair K Landing Between 1st and 2nd Floor	Jose Cruz	Fireman	Sent to DSF
Yes	Fire Alarm System - Components Not Operational	N/A	FIRE ALARM SYSTEM   Magnetic Door Holder/Contacto r	Corridor By Exit 2A, Corridor By Rooms (A250, A350)	Jose Cruz	Fireman	Sent to DSF
Yes	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electric Meter Room B8	Jose Cruz	Fireman	Sent to DSF

**Inspection**

<b>Question</b>	<b>Response</b>
<b>Electrical</b>	
<b>AUDITORIUM</b>	Inspected
Instance on 1st Floor	Inspected
<b>House Lighting</b>	Inspected
Does a Chandelier exist?	No
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	6
Quantity Uom	EACH

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K480

Question	Response
<b>AUDITORIUM</b>	
<b>House Lighting</b>	
<b>Lighting Fixture - LED</b>	
<b>Pendant Mounted</b>	
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Surface Mounted</b>	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Local Sound System</b>	
Instance on 1st Floor	Inspected
Installation Year	2010
Source of Installation	Inspector Estimate
Condition	4 - Between Fair and Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Projection System</b>	
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 1st Floor	Inspected
Condition	5 - Poor
Deficiency	VIDEO PROJECTOR IS NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Theater Lighting System</b>	
Instance on 1st Floor	Inspected
<b>Dimming System</b>	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting</b>	
Instance on 1st Floor	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K480

<b>Question</b>	<b>Response</b>
<b>AUDITORIUM</b>	Inspected
<b>Theater Lighting System</b>	
<b>Theater Lighting</b>	
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>CAFETERIA</b>	Inspected
Instance on 2nd Floor - Staff	Inspected
Instance on 2nd Floor - Students	Inspected
<b>Lighting</b>	Inspected
Instance on 2nd Floor - Students	Inspected
Instance on 2nd Floor - Staff	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 2nd Floor - Students	Does not Exist
Instance on 2nd Floor - Staff	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 2nd Floor - Students	Does not Exist
Instance on 2nd Floor - Staff	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 2nd Floor - Students	Does not Exist
Instance on 2nd Floor - Staff	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 2nd Floor - Students	Inspected
Instance on 2nd Floor - Staff	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 2nd Floor - Students	Does not Exist
Instance on 2nd Floor - Staff	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on 2nd Floor - Students	Does not Exist
Instance on 2nd Floor - Staff	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Instance on 2nd Floor - Students	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 2nd Floor - Staff	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Local Sound System</b>	Inspected
Instance on 2nd Floor - Students	Inspected
Installation Year	2022
Source of Installation	Custodial Staff
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on 2nd Floor - Staff	Does not Exist
<b>Projection System</b>	Does not Exist
Instance on 2nd Floor - Students	Does not Exist
Instance on 2nd Floor - Staff	Does not Exist
<b>Theater Lighting System</b>	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K480

<b>Question</b>	<b>Response</b>
<b>CAFETERIA</b>	Inspected
<b>Theater Lighting System</b>	Does not Exist
Instance on 2nd Floor - Students	Does not Exist
Instance on 2nd Floor - Staff	Does not Exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	Inspected
<b>Lighting</b>	Inspected
Does a Chandelier exist?	No
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>COMPUTER LAB</b>	Inspected
Instance on Room 316	Inspected
Power Panel	No
<b>Lighting</b>	Inspected
Instance on Room 316	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 316	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 316	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 316	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 316	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Room 316	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on Room 316	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on Room 316	Inspected
Condition	2 - Between Good and Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K480

Question	Response
<b>COMPUTER LAB</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - LED</b>	
<b>Recessed Mounted</b>	
Deficiency	No deficiencies recorded
<b>Raceway With Receptacles</b>	Does not Exist
Instance on Room 316	Does not Exist
<b>GYMNASIUM</b>	Inspected
Instance on 1st Floor	Inspected
<b>Lighting</b>	Inspected
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not Exist
<b>Local Sound System</b>	Inspected
Instance on 1st Floor	Inspected
Installation Year	2010
Source of Installation	Inspector Estimate
Condition	4 - Between Fair and Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Projection System</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Scoreboard</b>	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>KITCHEN</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K480

Question	Response
<b>KITCHEN</b>	
Instance on 2nd Floor	Inspected
<b>Lighting</b>	Inspected
Instance on 2nd Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 2nd Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 2nd Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 2nd Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 2nd Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 2nd Floor	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on 2nd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Instance on 2nd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>LIBRARY</b>	Does not Exist
<b>LOCKER ROOM</b>	Inspected
Instance on 1st Floor - Boys - Pool, 1st Floor - Girls - Pool	Inspected
Alternative use	No
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
Alternative use	No
<b>Lighting</b>	Inspected
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
Instance on 1st Floor - Boys - Pool, 1st Floor - Girls - Pool	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
Instance on 1st Floor - Boys - Pool, 1st Floor - Girls - Pool	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor - Boys - Pool, 1st Floor - Girls - Pool	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on 1st Floor - Boys - Pool, 1st Floor - Girls - Pool	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Instance on 1st Floor - Boys - Pool, 1st Floor - Girls - Pool	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
Instance on 1st Floor - Boys - Pool, 1st Floor - Girls - Pool	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K480

Question	Response
<b>LOCKER ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor - Boys - Pool, 1st Floor - Girls - Pool	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
Instance on 1st Floor - Boys - Pool, 1st Floor - Girls - Pool	Does not Exist
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>MULTIPURPOSE ROOM</b>	Does not Exist
<b>SCIENCE DEMO ROOM</b>	Inspected
Instance on Room 518	Inspected
Power Panel	Yes
Alternative use	Yes
<b>Lighting</b>	Inspected
Instance on Room 518	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 518	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 518	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 518	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 518	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Room 518	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on Room 518	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 518	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	Inspected
Instance on Room 518	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	Does not Exist
Instance on Room 518	Does not Exist
<b>Power Supply</b>	Inspected
Instance on Room 518	Inspected
<b>Instructor Unit</b>	
Instance on Room 518	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K480

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Power Supply</b>	
<b>Instructor Unit</b>	
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Meter Demonstration Unit</b>	
Instance on Room 518	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on Room 518	Does not Exist
<b>SCIENCE LAB</b>	
Instance on Room 326	Inspected
Power Panel Alternative use	Yes No
Instance on Room 426	Inspected
Power Panel Alternative use	Yes No
Instance on Room 526	Inspected
Power Panel Alternative use	Yes No
Instance on Room A361	Inspected
Power Panel Alternative use	Yes No
Instance on Room A365	Inspected
Power Panel Alternative use	Yes No
<b>Lighting</b>	
Instance on Room A365	Inspected
Instance on Room A361	Inspected
Instance on Room 526	Inspected
Instance on Room 426	Inspected
Instance on Room 326	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room A365	Does not Exist
Instance on Room A361	Does not Exist
Instance on Room 526	Does not Exist
Instance on Room 426	Does not Exist
Instance on Room 326	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room A365	Does not Exist
Instance on Room A361	Does not Exist
Instance on Room 526	Does not Exist
Instance on Room 426	Does not Exist
Instance on Room 326	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room A365	Inspected
Instance on Room A361	Does not Exist
Instance on Room 526	Does not Exist
Instance on Room 426	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K480

Question	Response
<b>SCIENCE LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 326	Does not Exist
<b>Pendant Mounted</b>	
Instance on Room A365	Does not Exist
<b>Surface Mounted</b>	
Instance on Room A365	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Room A365	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room A365	Inspected
Instance on Room A361	Inspected
Instance on Room 526	Inspected
Instance on Room 426	Inspected
Instance on Room 326	Inspected
<b>Pendant Mounted</b>	
Instance on Room A365	Does not Exist
Instance on Room A361	Does not Exist
Instance on Room 526	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 426	Does not Exist
Instance on Room 326	Does not Exist
<b>Surface Mounted</b>	
Instance on Room A365	Does not Exist
Instance on Room A361	Does not Exist
Instance on Room 526	Does not Exist
Instance on Room 426	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 326	Does not Exist
<b>Recessed Mounted</b>	
Instance on Room A365	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room A361	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 526	Does not Exist
Instance on Room 426	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 326	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Emergency Gas Shut-Off Valve</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K480

Question	Response
<b>SCIENCE LAB</b>	
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room A365	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room A361	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 526	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 426	Does not Exist
Instance on Room 326	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Room A365	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room A361	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 526	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 426	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on Room 326	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	
Instance on Room A365	Inspected
Instance on Room A361	Inspected
Instance on Room 526	Inspected
Instance on Room 426	Does not Exist
Instance on Room 326	Inspected
<b>Instructor Unit</b>	
Instance on Room A365	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room A361	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 526	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 326	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K480

Question	Response
<b>SCIENCE LAB</b>	
<b>Power Supply</b>	
<b>Meter Demonstration Unit</b>	
Instance on Room A365	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room A361	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 526	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 326	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Student Unit</b>	
Instance on Room A365	Does not Exist
Instance on Room A361	Does not Exist
Instance on Room 526	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 326	Does not Exist
<b>Projection System</b>	
Instance on Room A365	Inspected
Condition	5 - Poor
Deficiency	VIDEO PROJECTOR IS NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room A361	Does not Exist
Instance on Room 526	Does not Exist
Instance on Room 426	Does not Exist
Instance on Room 326	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>SCIENCE PREP ROOM</b>	
Instance on Room 326A	Inspected
Power Panel Alternative use	No
Instance on Room 426A	Inspected
Power Panel Alternative use	No
Instance on Room 435	Inspected
Power Panel Alternative use	No
Instance on Room 526A	Inaccessible

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K480

Question	Response
<b>SCIENCE PREP ROOM</b>	
Instance on Room A363	Inspected
Power Panel	No
Alternative use	No
<b>Lighting</b>	Inspected
Instance on Room A363	Inspected
Instance on Room 435	Inspected
Instance on Room 426A	Inspected
Instance on Room 326A	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room A363	Does not Exist
Instance on Room 435	Does not Exist
Instance on Room 426A	Does not Exist
Instance on Room 326A	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room A363	Does not Exist
Instance on Room 435	Does not Exist
Instance on Room 426A	Does not Exist
Instance on Room 326A	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room A363	Does not Exist
Instance on Room 435	Does not Exist
Instance on Room 426A	Does not Exist
Instance on Room 326A	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room A363	Inspected
Instance on Room 435	Inspected
Instance on Room 426A	Inspected
Instance on Room 326A	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Room A363	Does not Exist
Instance on Room 435	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 426A	Does not Exist
Instance on Room 326A	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on Room A363	Does not Exist
Instance on Room 435	Does not Exist
Instance on Room 426A	Does not Exist
Instance on Room 326A	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on Room A363	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 435	Does not Exist
Instance on Room 426A	Inspected
Condition	2 - Between Good and Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K480

Question	Response
<b>SCIENCE PREP ROOM</b>	
<b>Lighting</b>	Inspected
<b>Lighting Fixture - LED</b>	
<b>Recessed Mounted</b>	
Deficiency	No deficiencies recorded
Instance on Room 326A	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Emergency Gas Shut-Off Valve</b>	Inspected
Instance on Room A363	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 435	Does not Exist
Instance on Room 426A	Does not Exist
Instance on Room 326A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	Inspected
Instance on Room A363	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 435	Does not Exist
Instance on Room 426A	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on Room 326A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	Does not Exist
Instance on Room A363	Does not Exist
Instance on Room 435	Does not Exist
Instance on Room 426A	Does not Exist
Instance on Room 326A	Inspected
<b>Instructor Unit</b>	
Instance on Room 326A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>SWIMMING POOL</b>	
Instance on 1st Floor	Inspected
<b>Lighting</b>	Inspected
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K480

Question	Response
<b>SWIMMING POOL</b>	
<b>Lighting</b>	
<b>Lighting Fixture - LED</b>	
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Local Sound System</b>	Inspected
Instance on 1st Floor	Inspected
Installation Year	2022
Source of Installation	Custodial Staff
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Scoreboard</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>TOILET ROOM - STAFF</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Does not Exist
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K480

Question	Response
<b>TOILET ROOM - STUDENT</b>	
<b>Lighting</b>	
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Inspected
Replacement Quantity	202,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not Exist
<b>EMERGENCY GENERATOR SET</b>	Inspected
<b>Automatic Transfer Switch (ATS)</b>	Inspected
Instance	Electrical Room A004
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Cummins Onan
Equipment	N/A
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1998
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room Across Water Meter Room A002
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Cummins Onan
Equipment	N/A
Capacity/Size Quantity	40
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1998
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Battery Charger</b>	Inspected
Instance	New Addition Roof - Outdoor Generator Enclosure
Instance Condition	2 - Between Good and Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K480

Question	Response
<b>EMERGENCY GENERATOR SET</b>	
<b>Battery Charger</b>	
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	SENS
Equipment	Battery Charger
Capacity/Size Quantity	3
Capacity/Size UOM	AmpsDC
Capacity/Size2 Quantity	12
Capacity/Size2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
<b>Emergency Distribution Board</b>	Inspected
Number of Spares	4
<b>Fused Disconnect Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Inspected
Instance	Electrical Room A004
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Delta Metal Product
Equipment	EMDB
Capacity/Size Quantity	225
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1998
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Diesel</b>	Does not Exist
<b>Natural Gas</b>	Inspected
Instance	New Addition Roof - Outdoor Generator Enclosure
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Cummins Onan
Equipment	Emergency Generator
Capacity/Size Quantity	100
Capacity/Size UOM	KVA
Capacity/Size2 Quantity	80
Capacity/Size2 UOM	KW
Capacity/Size3Quantity	277
Capacity/Size3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1998
Source of Installation	Documented

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K480

<b>Question</b>	<b>Response</b>
<b>EMERGENCY GENERATOR SET</b>	Inspected
<b>Natural Gas</b>	
Deficiency	No deficiencies recorded
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Inspected
Condition	3 - Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Basement Corridor Across Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	4 - Between Fair and Poor
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Corridor by Rooms (105, 205, 219, 222, 312), 1st Floor near Exits (3, 5), Staff Cafeteria, Rooms (111, 216, 120, 120-A), Stair L at 1st Floor, Stair K Landing Between 1st and 2nd Floor
Deficiency Quantity	22
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	35643358L, 35672004R
<b>Non Battery Pack</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	1 - Good
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Science Lab - Room 426
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Non Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Pool Mechanical Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K480

Question	Response
<b>EXIT LIGHT</b>	Inspected
<b>Non Battery Pack</b>	
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>EXIT/EMERGENCY LIGHT</b>	Does not Exist
<b>FIRE ALARM SYSTEM</b>	Inspected
Replacement Quantity	202,000
Replacement Uom	S.F.
<b>Bell/Horn</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Strobe</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Manual Pull Station</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Fan Shutdown Control</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Duct Smoke Detector</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Area Smoke Detector</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>CO Detector</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Heat Detector</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Elevator Recall</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Magnetic Door Holder/Contactor</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	CONTACTOR NOT OPERATIONAL
Deficiency Location/Instance	Corridor By Exit 2A, Corridor By Rooms (A250, A350)
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Fused Cutout Panel</b>	Inspected
Condition	1 - Good

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K480

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Fused Cutout Panel</b>	Inspected
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	Does not Exist
<b>Main Panel</b>	Inspected
<b>Bell At Panel</b>	Does not Exist
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Main Entrance Lobby
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards System Technology
Equipment	FIRE COMMAND STATION
Model	EST 3
Installation Year	2022
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	Does not Exist
<b>Sub-Panel</b>	Does not Exist
<b>Remote Annunciator</b>	Inspected
<b>Display Monitor</b>	Does not Exist
<b>Panel</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Printer</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Punch Register</b>	Does not Exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected
Condition	4 - Between Fair and Poor
Deficiency	SWITCH NOT OPERATIONAL
Deficiency Location/Instance	Room B24
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo 1	No photo recorded
Violations	No violations recorded.
<b>Tamper Flow Switch/Chain</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>GROUNDING SYSTEM</b>	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>INTERCOM SYSTEM</b>	
<b>Elevator</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K480

<b>Question</b>	<b>Response</b>
<b>INTERCOM SYSTEM</b>	Inspected
<b>Holding Area</b>	Does not Exist
<b>LAN</b>	Inspected
<b>Local Distribution Frame (I/LDF)</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	Does not Exist
<b>MOTOR CONTROLLER</b>	Inspected
<b>Motor Control Center</b>	Does not Exist
<b>Motor Starter/Contactor</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Variable Frequency Drive</b>	Does not Exist
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Fused Toggle Switch Type</b>	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Auditorium, Basement - Custodial Staffs' Lunch Room
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Corridor by Room 535
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Mechanical Room B43
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K480

Question	Response
<b>PANEL BOARD</b>	
<b>Molded Case Circuit Breaker Type</b>	
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	Corridor by Room 104
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Cafeteria, Kitchen, Boiler Room, Basement - Custodial Staffs' Lunch Room, Mechanical Room B43, Gymnasium, Pool Mechanical Room, Room 225, Corridor by Rooms (A002, A004, P112, 104, 109, 118, 126, 134, 136, 229, 305, 306, 312, 320, 335, 403, 418, 535, 607)
Deficiency Quantity	33
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>PUBLIC ADDRESS SYSTEM</b>	Inspected
Replacement Quantity	202,000
Replacement Uom	S.F.
Instance	Room 221
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Telecor II
Installation Year	2022
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
<b>SECURITY</b>	Inspected
<b>IPDVS/CCTV System</b>	Inspected
Replacement Quantity	202,000
Replacement Uom	S.F.
Installation Year	2020
Source of Installation	Custodial Staff
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Intrusion Alarm System</b>	Inspected
Replacement Quantity	202,000
Replacement Uom	S.F.
<b>Central Control Panel</b>	Inspected
Instance	Basement - Custodial Staffs' Lunch Room

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K480

Question	Response
<b>SECURITY</b>	
<b>Intrusion Alarm System</b>	
<b>Central Control Panel</b>	
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista-128BP
Installation Year	2003
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
<b>Infrared Sensor</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting - Security</b>	Inspected
Replacement Uom	EACH
Condition	1 - Good
Deficiency	LIGHTING FIXTURE PHOTOCCELL NOT OPERATIONAL
Deficiency Location/Instance	Exterior wall of Addition Annex facing Athletic Field and Tennis Court
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>SERVICE SWITCH</b>	
	Inspected
Instance	ELECTRIC METER ROOM B8
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	N/A
Equipment	MAIN-SWITCH SERVICE-A
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1957
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	ELECTRIC METER ROOM B8
Instance Condition	3 - Fair
Instance Quantity	1

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K480

<b>Question</b>	<b>Response</b>
<b>SERVICE SWITCH</b>	
Instance Quantity Uom	EACH
Instance Manufacturer	N/A
Equipment	MAIN-SWITCH SERVICE-B
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1957
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	ELECTRIC METER ROOM B8
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Cole Electric
Equipment	DUAL-SERVICE-A-SW. FOR-HEATING PANEL
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1957
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	ELECTRIC METER ROOM B8
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Cole Electric
Equipment	Kitchen Power & Ref. Main Sw.
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1957
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room A004
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Delta Metal Product
Equipment	RHVACDB
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1998
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room A004
Instance Condition	3 - Fair
Instance Quantity	1

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K480

Question	Response
<b>SERVICE SWITCH</b>	
Instance Quantity Uom	EACH
Instance Manufacturer	Delta Metal Product
Equipment	MDB
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1998
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>SWITCHBOARD</b>	
Number of Spares	1
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	Basement - Custodial Staffs' Lunch Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	BRPP
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1998
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Basement - Custodial Staffs' Lunch Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	BRPP
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1998
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room A004
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Delta Metal Product
Equipment	MDB
Capacity/Size Quantity	600
Capacity/Size UOM	Amps Total

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K480

Question	Response
<b>SWITCHBOARD</b>	
<b>Fused Disconnect Switch Type</b>	
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	1998
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	
	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	
	Inspected
Instance	Basement - Custodial Staffs' Lunch Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Federal Pacific Electric
Equipment	N/A
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	1957
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Basement - Custodial Staffs' Lunch Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Federal Pacific Electric
Equipment	N/A
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	1957
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>TELEPHONE SYSTEM</b>	
	Inspected
<b>PBX/Intercom</b>	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Standard</b>	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>TRANSFORMER</b>	
	Does not Exist