

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K505**

**Asset: FRANKLIN D. ROOSEVELT HS - K, 5800 20 AVENUE, New York, 11204**

Inspection Id	Inspection Type	Time In	Last Edited
EE : K505	Electrical	2023-11-20 8:55 AM	2023-12-05 1:12 PM

**Asset Data**

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: LAN, Public Address System (Amplifier)
	Years: 2023
	Systems: Gymnasium AB (Scoreboard), Retrofitted LED Lighting - Except (Auditorium)
	Years: 2022
	Systems: Public Address System (Clocks)
	Years: 2021
	Systems: Exit Lights, Partial Fused Disconnect Switch Type Panel Board
	Years: 2020
	Systems: Auditorium (LED Lighting)
	Years: 2019
	Systems: Security Lights
	Years: 2018
	Systems: Computer Lab - Room 246 (Raceway with Receptacles), Gymnasiums (Lighting), Transformer
	Years: 2015
	Systems: IPDVS/CCTV System, Fire Alarm System
	Years: 2013
	Systems: Auditorium (Local Sound System, Dimming System)
	Years: 2011
	Systems: Partial Service Switch, Partial Switchboard
	Years: 2010
	Systems: Public Address System (Tuner), Intrusion Alarm System (Central Control Panel)
	Years: 2000
	Systems: Auditorium (Theater Lighting)
	Years: 1998
	Systems: Partial Molded Case Circuit Breaker Type Panel Board
	Years: 1986, 1999, 2006, 2011, 2017, 2020

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	No
Which spaces do not have dedicated intercoms?	Rooms 213, 251, 313, 351, 413, 451

**Priority Condition**

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
Yes	Grounding System - Detached Ground Conductor	N/A	GROUNDING SYSTEM	1st Floor - Gas Sprinkler Water Main	Phil Olszewski	Fireman	Sent to DSF	

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

Inspection

Question	Response
<b>Electrical</b>	
<b>AUDITORIUM</b>	Inspected
Instance on 1st Floor	Inspected
<b>House Lighting</b>	Inspected
Does a Chandelier exist?	No
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	50
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on 1st Floor	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

Question	Response
<b>AUDITORIUM</b>	
<b>House Lighting</b>	
<b>Lighting Fixture - LED</b>	
<b>Surface Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Local Sound System</b>	Inspected
Instance on 1st Floor	Inspected
Installation Year	2011
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Inspected
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	Inspected
Instance on 1st Floor	Inspected
<b>Dimming System</b>	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting</b>	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>CAFETERIA</b>	
Instance on 1st Floor	Inspected
<b>Lighting</b>	Inspected
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	90
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

Question	Response
<b>CAFETERIA</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Recessed Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not Exist
<b>Local Sound System</b>	
	Inspected
Instance on 1st Floor	Inspected
Installation Year	1965
Source of Installation	Documented
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Theater Lighting System</b>	
	Does not Exist
Instance on 1st Floor	Does not Exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
	Inspected
<b>Lighting</b>	
	Inspected
Does a Chandelier exist?	No
<b>Lighting Fixture - Fluorescent</b>	
	Inspected
<b>Pendant Mounted</b>	
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	300
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Surface Mounted</b>	
	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	17
Quantity Uom	EACH
Potential Action	REPLACE BALLAST

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

Question	Response
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2,600
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	
Condition	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	13
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	600
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	
Does not Exist	
<b>Lighting Fixture - Incandescent</b>	
Inspected	
<b>Pendant Mounted</b>	
Does not Exist	
<b>Surface Mounted</b>	
Does not Exist	
<b>Recessed Mounted</b>	
Inspected	
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - LED</b>	
Inspected	

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

Question	Response
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	
<b>Lighting Fixture - LED</b>	
<b>Pendant Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>COMPUTER LAB</b>	
	Inspected
Instance on Room 241	Inspected
Power Panel	No
Instance on Room 246	Inspected
Power Panel	Yes
Instance on Room 256	Inspected
Power Panel	Yes
Instance on Room 257	Inspected
Power Panel	Yes
Instance on Room 253	Inspected
Power Panel	Yes
<b>Lighting</b>	
	Inspected
Instance on Room 253	Inspected
Instance on Room 257	Inspected
Instance on Room 256	Inspected
Instance on Room 246	Inspected
Instance on Room 241	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 253	Inspected
Instance on Room 257	Inspected
Instance on Room 256	Inspected
Instance on Room 246	Inspected
Instance on Room 241	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Room 253	Does not Exist
Instance on Room 257	Does not Exist
Instance on Room 256	Does not Exist
Instance on Room 246	Does not Exist
Instance on Room 241	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on Room 253	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	29
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

Question	Response
<b>COMPUTER LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 257	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 256	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 246	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

Question	Response
<b>COMPUTER LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 241	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	
Instance on Room 253	Does not Exist
Instance on Room 257	Does not Exist
Instance on Room 256	Does not Exist
Instance on Room 246	Does not Exist
Instance on Room 241	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 253	Does not Exist
Instance on Room 257	Does not Exist
Instance on Room 256	Does not Exist
Instance on Room 246	Does not Exist
Instance on Room 241	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 253	Does not Exist
Instance on Room 257	Does not Exist
Instance on Room 256	Does not Exist
Instance on Room 246	Does not Exist
Instance on Room 241	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 253	Does not Exist
Instance on Room 257	Does not Exist
Instance on Room 256	Does not Exist



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

Question	Response
<b>COMPUTER LAB</b>	
<b>Lighting</b>	Inspected
<b>Lighting Fixture - LED</b>	
Instance on Room 246	Does not Exist
Instance on Room 241	Does not Exist
<b>Raceway With Receptacles</b>	Inspected
Instance on Room 253	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 257	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 256	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 246	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 241	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>GYMNASIUM</b>	Inspected
Instance on 1st Floor - Gymnasium AB	Inspected
Instance on 2nd Floor - Gymnasium C, 2nd Floor - Gymnasium D	Inspected
<b>Lighting</b>	Inspected
Instance on 2nd Floor - Gymnasium C, 2nd Floor - Gymnasium D	Inspected
Instance on 1st Floor - Gymnasium AB	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 2nd Floor - Gymnasium C, 2nd Floor - Gymnasium D	Does not Exist
Instance on 1st Floor - Gymnasium AB	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 2nd Floor - Gymnasium C, 2nd Floor - Gymnasium D	Does not Exist
Instance on 1st Floor - Gymnasium AB	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 2nd Floor - Gymnasium C, 2nd Floor - Gymnasium D	Does not Exist
Instance on 1st Floor - Gymnasium AB	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 2nd Floor - Gymnasium C, 2nd Floor - Gymnasium D	Inspected
Instance on 1st Floor - Gymnasium AB	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 2nd Floor - Gymnasium C, 2nd Floor - Gymnasium D	Does not Exist
Instance on 1st Floor - Gymnasium AB	Inspected
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

Question	Response
<b>GYMNASIUM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - LED</b>	
<b>Pendant Mounted</b>	Does not Exist
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Surface Mounted</b>	Does not Exist
Instance on 2nd Floor - Gymnasium C, 2nd Floor - Gymnasium D	Does not Exist
Instance on 1st Floor - Gymnasium AB	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on 2nd Floor - Gymnasium C, 2nd Floor - Gymnasium D	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Gymnasium AB	Does not Exist
<b>Local Sound System</b>	Inspected
Instance on 2nd Floor - Gymnasium C, 2nd Floor - Gymnasium D	Inspected
Installation Year	1965
Source of Installation	Documented
Condition	5 - Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - Gymnasium AB	Inspected
Installation Year	1965
Source of Installation	Documented
Condition	3 - Fair
Deficiency	MICROPHONE / JACK NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Projection System</b>	Does not Exist
Instance on 2nd Floor - Gymnasium C, 2nd Floor - Gymnasium D	Does not Exist
Instance on 1st Floor - Gymnasium AB	Does not Exist
<b>Scoreboard</b>	Does not Exist
Instance on 2nd Floor - Gymnasium C, 2nd Floor - Gymnasium D	Does not Exist
Instance on 1st Floor - Gymnasium AB	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	Does not Exist
Instance on 2nd Floor - Gymnasium C, 2nd Floor - Gymnasium D	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

<b>Question</b>	<b>Response</b>
<b>GYMNASIUM</b>	Inspected
<b>Theater Lighting System</b>	Does not Exist
Instance on 1st Floor - Gymnasium AB	Does not Exist
<b>KITCHEN</b>	Inspected
Instance on 1st Floor	Inspected
<b>Lighting</b>	Inspected
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	56
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not Exist
<b>LIBRARY</b>	Inspected
Instance on Room 201	Inspected
<b>Lighting</b>	Inspected
Instance on Room 201	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 201	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Room 201	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on Room 201	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

Question	Response
<b>LIBRARY</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	61
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 201	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 201	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 201	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 201	Does not Exist
<b>Raceway With Receptacles</b>	Inspected
Instance on Room 201	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Does not Exist
Instance on Room 201	Does not Exist
<b>LOCKER ROOM</b>	Inspected
Instance on 1st Floor - Boys	Inspected
Alternative use	No
Instance on 1st Floor - Room 147	Inspected
Alternative use	No
Instance on 1st Floor - Girls	Inspected
Alternative use	No
<b>Lighting</b>	Inspected
Instance on 1st Floor - Girls	Inspected
Instance on 1st Floor - Room 147	Inspected
Instance on 1st Floor - Boys	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor - Girls	Inspected
Instance on 1st Floor - Room 147	Inspected
Instance on 1st Floor - Boys	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor - Girls	Does not Exist
Instance on 1st Floor - Room 147	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	42
Quantity Uom	EACH

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

Question	Response
<b>LOCKER ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - Boys	Does not Exist
<b>Surface Mounted</b>	
Instance on 1st Floor - Girls	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	32
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - Room 147	Does not Exist
Instance on 1st Floor - Boys	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	35
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	
Instance on 1st Floor - Girls	Does not Exist
Instance on 1st Floor - Room 147	Does not Exist
Instance on 1st Floor - Boys	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

Question	Response
<b>LOCKER ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Recessed Mounted</b>	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor - Girls	Does not Exist
Instance on 1st Floor - Room 147	Does not Exist
Instance on 1st Floor - Boys	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor - Girls	Does not Exist
Instance on 1st Floor - Room 147	Does not Exist
Instance on 1st Floor - Boys	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor - Girls	Does not Exist
Instance on 1st Floor - Room 147	Does not Exist
Instance on 1st Floor - Boys	Does not Exist
<b>MULTIPURPOSE ROOM</b>	Does not Exist
<b>SCIENCE DEMO ROOM</b>	Inspected
Instance on Room 446	Inspected
Power Panel Alternative use	No No
Instance on Rooms 339, 345, 347, 354	Inspected
Power Panel Alternative use	No No
Instance on Rooms 440, 444	Inspected
Power Panel Alternative use	No No
<b>Lighting</b>	Inspected
Instance on Rooms 440, 444	Inspected
Instance on Rooms 339, 345, 347, 354	Inspected
Instance on Room 446	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Rooms 440, 444	Inspected
Instance on Rooms 339, 345, 347, 354	Inspected
Instance on Room 446	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Rooms 440, 444	Does not Exist
Instance on Rooms 339, 345, 347, 354	Does not Exist
Instance on Room 446	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on Rooms 440, 444	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	60
Quantity Uom	EACH

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Rooms 339, 345, 347, 354	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	120
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 446	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	
Instance on Rooms 440, 444	Does not Exist
Instance on Rooms 339, 345, 347, 354	Does not Exist
Instance on Room 446	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Rooms 440, 444	Does not Exist
Instance on Rooms 339, 345, 347, 354	Does not Exist
Instance on Room 446	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Rooms 440, 444	Inspected
Instance on Rooms 339, 345, 347, 354	Does not Exist
Instance on Room 446	Inspected
<b>Pendant Mounted</b>	
Instance on Rooms 440, 444	Does not Exist
Instance on Room 446	Does not Exist
<b>Surface Mounted</b>	
Instance on Rooms 440, 444	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	8

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
<b>Surface Mounted</b>	
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 446	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	
Instance on Rooms 440, 444	Does not Exist
Instance on Room 446	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Rooms 440, 444	Does not Exist
Instance on Rooms 339, 345, 347, 354	Does not Exist
Instance on Room 446	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Rooms 440, 444	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 339, 345, 347, 354	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 446	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Rooms 440, 444	Does not Exist
Instance on Rooms 339, 345, 347, 354	Does not Exist
Instance on Room 446	Does not Exist
<b>Power Supply</b>	
Instance on Rooms 440, 444	Inspected
Instance on Rooms 339, 345, 347, 354	Inspected
Instance on Room 446	Inspected
<b>Instructor Unit</b>	
Instance on Rooms 440, 444	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Power Supply</b>	
<b>Instructor Unit</b>	
Instance on Rooms 339, 345, 347, 354	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 446	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Meter Demonstration Unit</b>	
Instance on Rooms 440, 444	Does not Exist
Instance on Rooms 339, 345, 347, 354	Does not Exist
Instance on Room 446	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on Rooms 440, 444	Does not Exist
Instance on Rooms 339, 345, 347, 354	Does not Exist
Instance on Room 446	Does not Exist
<b>SCIENCE LAB</b>	
Instance on Rooms 341, 358	Inspected
Power Panel Alternative use	Yes No
Instance on Room 439	Inspected
Power Panel Alternative use	Yes No
Instance on Room 346	Inspected
Power Panel Alternative use	Yes No
Instance on Room 445	Inspected
Power Panel Alternative use	Yes No
<b>Lighting</b>	
Instance on Room 445	Inspected
Instance on Room 346	Inspected
Instance on Room 439	Inspected
Instance on Rooms 341, 358	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 445	Inspected
Instance on Room 346	Inspected
Instance on Room 439	Inspected
Instance on Rooms 341, 358	Inspected
<b>Pendant Mounted</b>	
Instance on Room 445	Does not Exist
Instance on Room 346	Does not Exist
Instance on Room 439	Does not Exist
Instance on Rooms 341, 358	Does not Exist
<b>Surface Mounted</b>	
Instance on Room 445	Inspected
Condition	3 - Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

Question	Response
<b>SCIENCE LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	39
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 346	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	33
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 439	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	35
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Rooms 341, 358	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	60
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 445	Does not Exist
Instance on Room 346	Does not Exist
Instance on Room 439	Does not Exist
Instance on Rooms 341, 358	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 445	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

Question	Response
<b>SCIENCE LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - HID</b>	
Instance on Room 346	Does not Exist
Instance on Room 439	Does not Exist
Instance on Rooms 341, 358	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 445	Inspected
Instance on Room 346	Does not Exist
Instance on Room 439	Inspected
Instance on Rooms 341, 358	Does not Exist
<b>Pendant Mounted</b>	
	Does not Exist
Instance on Room 445	Does not Exist
Instance on Room 439	Does not Exist
<b>Surface Mounted</b>	
	Inspected
Instance on Room 445	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 439	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	
	Does not Exist
Instance on Room 445	Does not Exist
Instance on Room 439	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 445	Does not Exist
Instance on Room 346	Does not Exist
Instance on Room 439	Does not Exist
Instance on Rooms 341, 358	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	
	Inspected
Instance on Room 445	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 346	Inspected
Condition	3 - Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K505**

<b>Question</b>	<b>Response</b>
<b>SCIENCE LAB</b>	
<b>Emergency Gas Shut-Off Valve</b>	
Deficiency	No deficiencies recorded
Instance on Room 439	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 341, 358	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Room 445	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 346	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 439	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 341, 358	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	
Instance on Room 445	Inspected
Instance on Room 346	Inspected
Instance on Room 439	Inspected
Instance on Rooms 341, 358	Inspected
<b>Instructor Unit</b>	
Instance on Room 445	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 346	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 439	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 341, 358	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Meter Demonstration Unit</b>	
Instance on Room 445	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 346	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 439	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 341, 358	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

Question	Response
<b>SCIENCE LAB</b>	
<b>Power Supply</b>	
<b>Meter Demonstration Unit</b>	
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Student Unit</b>	
Instance on Room 445	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 346	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 439	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 341, 358	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on Room 445	Does not Exist
Instance on Room 346	Does not Exist
Instance on Room 439	Does not Exist
Instance on Rooms 341, 358	Does not Exist
<b>SCIENCE PREP ROOM</b>	
Instance on Room 441	Inspected
Power Panel Alternative use	Yes No
Instance on Room 443	Inspected
Power Panel Alternative use	Yes No
Instance on Room 344	Inspected
Power Panel Alternative use	Yes No
<b>Lighting</b>	
Instance on Room 344	Inspected
Instance on Room 443	Inspected
Instance on Room 441	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 344	Inspected
Instance on Room 443	Inspected
Instance on Room 441	Inspected
<b>Pendant Mounted</b>	
Instance on Room 344	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

Question	Response
<b>SCIENCE PREP ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 443	Does not Exist
Instance on Room 441	Does not Exist
<b>Surface Mounted</b>	
Instance on Room 344	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	31
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 443	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 441	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	21
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	
Instance on Room 344	Does not Exist
Instance on Room 344	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

Question	Response
<b>SCIENCE PREP ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Recessed Mounted</b>	
Instance on Room 443	Does not Exist
Instance on Room 441	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 344	Does not Exist
Instance on Room 443	Does not Exist
Instance on Room 441	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 344	Does not Exist
Instance on Room 443	Does not Exist
Instance on Room 441	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 344	Does not Exist
Instance on Room 443	Does not Exist
Instance on Room 441	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	Inspected
Instance on Room 344	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 443	Does not Exist
Instance on Room 441	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	Does not Exist
Instance on Room 344	Does not Exist
Instance on Room 443	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 441	Does not Exist
<b>Power Supply</b>	Inspected
Instance on Room 344	Inspected
Instance on Room 443	Inspected
Instance on Room 441	Inspected
<b>Instructor Unit</b>	
Instance on Room 344	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 443	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 441	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>SWIMMING POOL</b>	Does not Exist
<b>TOILET ROOM - STAFF</b>	Inspected
<b>Lighting</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

Question	Response
<b>TOILET ROOM - STAFF</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	26
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Does not Exist
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	53
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Inspected
Replacement Quantity	287,000
Replacement Uom	S.F.



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K505**

<b>Question</b>	<b>Response</b>
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not Exist
<b>EMERGENCY GENERATOR SET</b>	Does not Exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Does not Exist
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	1st Floor - Gymnasium AB
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	1st Floor Corridor - By (Room 116, Gas Sprinkler Water Room), 1st Floor - Staircase A Vestibule, Cafeteria, Girls Locker Room, Library
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Non Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Does not Exist
<b>EXIT/EMERGENCY LIGHT</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>FIRE ALARM SYSTEM</b>	Inspected
Replacement Quantity	287,000
Replacement Uom	S.F.
<b>Bell/Horn</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Strobe</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Manual Pull Station</b>	Inspected
Condition	2 - Between Good and Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	
<b>Manual Pull Station</b>	Inspected
Deficiency	No deficiencies recorded
<b>Fan Shutdown Control</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Duct Smoke Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Area Smoke Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>CO Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Heat Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Elevator Recall</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Magnetic Door Holder/Contactor</b>	Does not Exist
<b>Fused Cutout Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Honeywell
Equipment	Central Station Fire Alarm
Installation Year	2013
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
<b>Main Panel</b>	Inspected
<b>Bell At Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	Fire Alarm Control Panel
Model	EST 2
Installation Year	2013
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Main Panel</b>	Inspected
<b>Fire Alarm Control Panel (Standard)</b>	Does not Exist
<b>Sub-Panel</b>	Does not Exist
<b>Remote Annunciator</b>	Inspected
<b>Display Monitor</b>	Does not Exist
<b>Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Printer</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Punch Register</b>	Does not Exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Tamper Flow Switch/Chain</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>GROUNDING SYSTEM</b>	Inspected
Condition	4 - Between Fair and Poor
Deficiency	DETACHED GROUND CONDUCTOR
Deficiency Location/Instance	1st Floor - Gas Sprinkler Water Main
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>INTERCOM SYSTEM</b>	Inspected
<b>Elevator</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Holding Area</b>	Does not Exist
<b>LAN</b>	Inspected
<b>Local Distribution Frame (I/LDF)</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	Does not Exist
<b>MOTOR CONTROLLER</b>	Inspected
<b>Motor Control Center</b>	Does not Exist
<b>Motor Starter/Contactor</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Variable Frequency Drive</b>	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K505**

<b>Question</b>	<b>Response</b>
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Mechanical Room 189A
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Room 189A, Boy's Locker Room Mechanical Room, Boiler Room
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Fused Toggle Switch Type</b>	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B19
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Corridors - by (Rooms 452A, 431, 415, 401, 352A, 336, 312, 302, 265, 247, 236, 211, 189A, 133, 102, B15, 1st Floor - Exit 12), Rooms (441, 439, 344, 321, 160, 141A, 139), Kitchen, Cafeteria, Gymnasiums, Boy's Locker Room, Boiler Room, Electrical Room B19
Deficiency Quantity	43
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	Corridors by Rooms (431, 236, 171, 151, 133, 102)

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K505**

<b>Question</b>	<b>Response</b>
<b>PANEL BOARD</b>	
<b>Molded Case Circuit Breaker Type</b>	
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Electrical Room B19, Electrical Closet 398
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	Electrical Room B19
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>PUBLIC ADDRESS SYSTEM</b>	Inspected
Replacement Quantity	287,000
Replacement Uom	S.F.
Instance	Room 103B
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	1965
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>SECURITY</b>	Inspected
<b>IPDVS/CCTV System</b>	Inspected
Replacement Quantity	287,000
Replacement Uom	S.F.
Installation Year	2013
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	CAMERA NOT OPERATIONAL
Deficiency Location/Instance	Main Entrance Lobby, 1st Floor Corridor - By Room 143
Deficiency Quantity	2
Quantity Uom	EACH

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

Question	Response
<b>SECURITY</b>	
<b>IPDVS/CCTV System</b>	
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Intrusion Alarm System</b>	
	Inspected
Replacement Quantity	287,000
Replacement Uom	S.F.
<b>Central Control Panel</b>	
	Inspected
Instance	Room 165
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	2000
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
<b>Infrared Sensor</b>	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	
	Inspected
Condition	3 - Fair
Deficiency	SIREN/STROBE NOT ACTIVE
Deficiency Location/Instance	Exterior Wall - facing 20th Avenue
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting - Security</b>	
	Inspected
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Exterior Wall - facing 20th Avenue
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 3

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

<b>Question</b>	<b>Response</b>
<b>SECURITY</b>	Inspected
<b>Lighting - Security</b>	
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>SERVICE SWITCH</b>	Inspected
Instance	Electrical Room B19
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Lexington
Equipment	Main Service 2500A. Fuse
Capacity/Size Quantity	2,500
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1965
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room B19
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Boltswitch
Equipment	N/A
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Electrical Room B19
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Lexington
Equipment	Main Switch For " S D B "
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1965
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>SWITCHBOARD</b>	Inspected
Number of Spares	9
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	Electrical Room B19
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Lexington

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

Question	Response
<b>SWITCHBOARD</b>	
<b>Fused Disconnect Switch Type</b>	
Equipment	N/A
Capacity/Size Quantity	2,500
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	5
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1965
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room B19
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	Section 1, 2
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	2010
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Electrical Closet by Room 116
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Lexington
Equipment	N/A
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1965
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Does not Exist
<b>TELEPHONE SYSTEM</b>	Inspected
<b>PBX/Intercom</b>	Inspected
Condition	3 - Fair
Deficiency	TELEPHONE MISSING
Deficiency Location/Instance	Boys Locker Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL TELEPHONE



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K505

Question	Response
<b>TELEPHONE SYSTEM</b>	
<b>PBX/Intercom</b>	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Standard</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>TRANSFORMER</b>	
Instance	Electrical Room B19
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Hammond Power Solutions
Equipment	N/A
Capacity/Size Quantity	330
Capacity/Size UOM	KVA
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded