# **Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection K541

Asset:	Asset: DEWEY AF - BROOKLYN, 50 AVENUE X, New York, 11223			
Inspection Id	Inspection Type	Time In	Last Edited	
SA : K541	Architectural - Senior	2024-04-15 8:17 AM	2024-04-24 4:10 PM	
AA : K541	Architectural - Associate	2024-04-15 8:40 AM	2024-06-11 11:48 AM	

sset Data				
Question		Answer		
Was the building fully accessible for inspection		Yes		
<b>Building Square Footage</b>		0		
Comments on the Area (for A Leased Spaces)	athletic Field, Playing Surfaces,	235,000 SF Total Site Area; 115,000 SF Playing Surfaces		
Comments on the Stories (Flo	oors) plus Basements	0 (No Field House)		
Comments on the Number of	Classrooms	0		
Comments on the Year Built		1969		
Student Population		2,216		
Staff Population		1		
Weather		Fair		
Principal(s) Information				
	Principal Name	Heather Adelle		
	Organization	John Dewey High School Athletic Field - Brooklyn		
	Did you meet with this Principal?	No		
	Did this Principal provide feedback?	Yes		
	Summary of Principal's Feedback	Assistant Principal Jon Messinger spoke on behalf of the Principal and had no comments regarding the physical condition of the athletic field at this time.		
Custodian		James Martinez		
Fireman		Fatmir Jasari		

Facade Photo



Football/Soccer Field - East view


Architectural Inspection K541

Main Entrance Photo



East Gate Entrance

Roof Photo



Football/Soccer Field - Northeast view

Have any Systems/Major Building Components been upgraded?

Have there been any Building Additions?

Yes Systems: Football/Soccer Field Artificial Turf replacement.

Year: Under Construction

Systems: Running Track, Tennis Courts - replacement

Year: 2004

No No

No

#### **Priority Condition**

Tandem Schools?

Leased Space?

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	PhotoImage
Yes	Tripping Hazard	Deteriorated and cracked asphalt playing surface is a potential tripping hazard.	ATHLETIC FIELDS   PLAYING SURFACE	Tennis Courts	James Martinez	Custodian	

# **Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection K541

Yes Tripping Hazard

Deteriorated and cracked athletic wearing surface is a potential tripping hazard. ATHLETIC FIELDS | PLAYING SURFACE

Running Track

James Martinez


Custodian



Structural Enginee	er Required					
Structural Condition Type	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	PhotoImage
No condition record	ed					
Programmatic Aco	cessibility					
No Accessibility s	status data recorded					
Physical Breakdo	own Structure		Exists	Required	Complies Deficiency	Assistive Fire Listening Alarn System Strob
PROGRAMMAT	ΓΙC ACCESSIBILI	TY				System Strop
Exterior Rou						
Exterior	Entrances & Exits					
Exterior	H/C Lifts					
Exterior	Ramps and Railing	gs				
Interior Rout	tes					
Corrido	r and Lobby H/C Li	ifts				
Interior	Corridor Doors and	d Hardware				
Interior	Corridors and Lobl	bies				
Interior	Elevators					
Interior	Lobby Doors and H	lardware				
Interior	Ramps					
Rooms & Spa	aces					
Art Room	ms					
Auditori	um					
Cafeteria	a					
Classroo	oms					
Compute	er Rooms					
Gymnas	ium					
Library						
Main Of	fice					
Multi-pu	irpose Room					
Nurse's	Room					
Pool						
Science 1	Lab					
Toilet Ro	ooms (Boys)					
Toilet Ro	ooms (Girls)					
Toilet Ro	ooms (Staff)					

Architectural Inspection K541


## **Building Template**



## Inspection

Roof Plan reference

Question	Response		
Architectural			
EXTERIOR	Does not Exist		
INTERIOR	Does not Exist		
ATHLETIC FIELDS	Inspected		
PLAYING SURFACE	Inspected		
Synthetic Turf Field exists? Year of Installation	Yes 2004		
Replacement Quantity	115,000		
Replacement Uom	S.F.		
Instance on Football/Soccer Field	Under Construction		
Instance Quantity	70,000		
Instance Quantity Uom	S.F.		
Instance on Running Track	Inspected		
Instance Condition	4 - Between Fair and Poor		
Instance Quantity	27,000		
Instance Quantity Uom	S.F.		
Deficiency	ATHLETIC WEARING SURFACE: DAMAGED/DETERIORATED		
Deficiency Location/Instance	Running Track		



Deficiency Quantity 500
Quantity Uom S.F.

Architectural Inspection K541

#### Question Response

#### ATHLETIC FIELDS

#### PLAYING SURFACE

Potential Action REPLACE
Urgency of Action PRIORITY 5
Purpose of Action LEVEL 6

Deficiency Photo1



Running Track

Violations No violations recorded.

Instance on Tennis Courts	Inspected
Instance Condition	4 - Between Fair and Poor
Instance Quantity	18,000
Instance Quantity Uom	S.F.


Deficiency
Deficiency Location/Instance

Roof Plan reference

Deficiency Photo1

### ASPHALT: DAMAGED/DETERIORATED

Tennis Courts



Deficiency Quantity 500
Quantity Uom S.F.
Potential Action REPLACE
Urgency of Action PRIORITY 5
Purpose of Action LEVEL 6



Tennis Courts

Violations No violations recorded.

FIXED EQUIPMENT	Inspected
Basketball Backboard	Does not Exist

# **Building Condition Assessment Survey 2023 - 2024**

chitectural Inspection	K541
Question	Response
ATHLETIC FIELDS	
FIXED EQUIPMENT	
Basketball Hoops	Does not Exist
Basketball Posts	Does not Exist
Football Goal Posts	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Tennis Net Posts	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SEATING	Inspected
Benches	Inspected
Concrete	Does not Exist
Metal/Wood/Plastic	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Bleachers	Does not Exist
SITE	Inspected
CONTAINERIZATION	Does not Exist
Drainage System for Asphalt	Inspected
Catch Basins/Manhole - Surrounded by asphalt	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Culverts - Asphalt Covering	Does not Exist
Drainage System for Concrete	Does not Exist
Drainage System for Soil	Inspected
Catch Basins/Manhole - Surrounded by Soil	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Culverts - Soil Covering	Does not Exist
DRINKING FOUNTAINS	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
FENCES	Inspected
Condition	3 - Fair
Deficiency	CONCRETE CURB: DAMAGED/DETERIORATED
Deficiency Location/Instance	Tennis Court, Running Track Area
Deficiency Quantity	200
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

#### **Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection K541

**Question** Response

SITE FENCES

Deficiency Photo1



Tennis Court

Violations No violations recorded.

Deficiency CHAIN LINK: DAMAGED/DETERIORATED

Deficiency Location/Instance Tennis Court, Running Track Area

Deficiency Quantity 200
Quantity Uom S.F.

Potential Action REPLACE

Urgency of Action PRIORITY 3

Purpose of Action LEVEL 2

Deficiency Photo1



Tennis Court

Violations No violations recorded.

Violations	To violations recorded.		
RRIGATION SYSTEM	Does not Exist		
AVING	Inspected		
Student Non-Use	Does not Exist		
Student Use	Inspected		
Gravel Exists?	No		
Asphalt	Inspected		
Condition	4 - Between Fair and Poor		
Deficiency	CRACKS - MAJOR		
Deficiency Location/Instance	Running Track Area		
Deficiency Quantity	500		
Quantity Uom	S.F.		
Potential Action	REPLACE		
Urgency of Action	PRIORITY 3		
Purpose of Action	LEVEL 2		

# **Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection K541

Question SITE Response

**PAVING** 

Student Use

Asphalt

Deficiency Photo1



Violations	Running Track Area  No violations recorded.
Violations	NO VIOIAHORS recorded.
Concrete	Does not Exist
Pavers	Does not Exist
Site Sidewalks & Walkways	Does not Exist
DOT Sidewalk	Does not Exist
PLAYGROUNDS	Does not Exist
RETAINING WALLS	Does not Exist
SEATING	Does not Exist
SITE WALLS (NOT RETAINING WALLS)	Does not Exist
STAIRS/RAMPS: EXTERIOR	Does not Exist
ARTWORK	Does not Exist