

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K600**

**Asset: CLARA BARTON HS - K, 901 CLASSON AVENUE, New York, 11225**

Inspection Id	Inspection Type	Time In	Last Edited
EE : K600	Electrical	2024-05-28 8:39 AM	2024-06-07 9:00 AM

**Asset Data**

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: IPDVS/CCTV System, Auditorium (Projection System), LED Lighting - Room 231, Partial Grounding System
	Years: 2024
	Systems: Auditorium (Theatre Lighting System)
	Years: 2022
	Systems: Security Lights, LAN
	Years: 2021
	Systems: Intrusion Alarm System (Central Control Panel, Remote Annunciator)
	Years: 2020
	Systems: Partial Emergency Lighting (Battery Pack)
	Years: 2019
	Systems: Telephone System
	Years: 2018
	Systems: Interior Lighting - Except (Incandescent Lighting, Science Lab - Rooms 333, 339, 350, 437, 449, 450, Science Prep Rooms), Most Emergency Lighting (Non Battery Pack), Exit Lights (Battery Pack)
	Years: 2017
	Systems: Gymnasium (Scoreboard)
	Years: 2016
	Systems: Intercom System (Elevator)
	Years: 2014
	Systems: Fire Alarm System (Manual Pull Station, Fan Shutdown Control, Duct Smoke Detector, Fused Cutout Panel, Main Panel, Remote Annunciator Panel, Printer)
	Years: 2011
	Systems: Science Lab - Rooms (333, 339, 350, 437, 449, 450), Science Prep Rooms
	Years: 2007
	Systems: Public Address System, Local Sound System
	Years: 2006
	Systems: Emergency Light/Exit Light Panel
	Years: 1995
	Systems: Molded Case Circuit Breaker Type Panel Board
	Years: 1988, 2001, 2007, 2017, 2022
	Systems: Fused Disconnect Switch Type Panel Board
	Years: 1988, 1995
	Systems: Service Switch
	Years: 1988
	Systems: Fire Alarm System, Partial Fused Toggle Switch Type Panel Board, Switchboard
	Years: 1988

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K600**

Are all dedicated intercoms operational?	No
Which rooms or areas have non-operational dedicated intercoms?	Rooms 223, 323, 423

**Priority Condition**

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Water Leaks onto Electrical Equipment	Sewage pipe leak	Panel Board	Electrical Room	Keith Bull	Custodian	Sent to DSF	
No	Intercom - Not Connected to Remote Monitoring Station	N/A	INTERCOM SYSTEM   Elevator	Elevator - Device ID: 3P3111	Keith Bull	Custodian	Sent to DSF	
Yes	Fire Alarm System - Components Not Operational	N/A	FIRE ALARM SYSTEM   Elevator Recall	Elevator - Device ID: 3P3111	Keith Bull	Custodian	Sent to DSF	
Yes	Emergency Lighting - Battery Not Operational	N/A	EMERGENCY LIGHTING   Battery Pack	Auditorium, Auditorium Balcony, Main Entrance Lobby, Boys Locker Room, Basement Staircase D, 1st Floor (Staircase I, by Room 169), 3rd Floor (Staircase C, by Rooms 363, 375A), 4th Floor Corridor by Rooms (414, 406)	Keith Bull	Custodian	Sent to DSF	
Yes	Fire Alarm System - Components Not Operational	N/A	FIRE ALARM SYSTEM   Magnetic Door Holder/Contacto r	Corridors - by Rooms (150, 254, 324)	Keith Bull	Custodian	Sent to DSF	
Yes	Fire Alarm System - Components Missing	N/A	FIRE ALARM SYSTEM   Magnetic Door Holder/Contacto r	Corridor - by Rooms (123, 150, 349, 424)	Keith Bull	Custodian	Sent to DSF	

**Inspection**

Question	Response
<b>Electrical</b>	
<b>AUDITORIUM</b>	Inspected
Instance on 1st Floor	Inspected
<b>House Lighting</b>	Inspected
Does a Chandelier exist?	Yes
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K600**

<b>Question</b>	<b>Response</b>
<b>AUDITORIUM</b>	
<b>House Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Local Sound System</b>	
Instance on 1st Floor	Inspected
Installation Year	2006
Source of Installation	Custodial Staff
Condition	4 - Between Fair and Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Projection System</b>	
Is the projector on a cart or installed on the ceiling?	Cart
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	
	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K600

Question	Response
<b>AUDITORIUM</b>	
<b>Theater Lighting System</b>	
Instance on 1st Floor	Inspected
<b>Dimming System</b>	
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Theater Lighting</b>	
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>CAFETERIA</b>	
Instance on Basement	Inspected
<b>Lighting</b>	
Instance on Basement	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement	Inspected
<b>Pendant Mounted</b>	
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Basement	Does not Exist
<b>Local Sound System</b>	
Instance on Basement	Inspected
Installation Year	2006
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on Basement	Does not Exist
<b>Theater Lighting System</b>	
Instance on Basement	Does not Exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	
Does a Chandelier exist?	Yes
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement	Inspected
<b>Pendant Mounted</b>	
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K600**

<b>Question</b>	<b>Response</b>
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
<b>COMPUTER LAB</b>	Inspected
Instance on Rooms 419, 420, 429	Inspected
Power Panel	Yes
<b>Lighting</b>	Inspected
Instance on Rooms 419, 420, 429	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Rooms 419, 420, 429	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Rooms 419, 420, 429	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on Rooms 419, 420, 429	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on Rooms 419, 420, 429	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Rooms 419, 420, 429	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Rooms 419, 420, 429	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Rooms 419, 420, 429	Does not Exist
<b>Raceway With Receptacles</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K600**

<b>Question</b>	<b>Response</b>
<b>COMPUTER LAB</b>	Inspected
<b>Raceway With Receptacles</b>	
Instance on Rooms 419, 420, 429	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>GYMNASIUM</b>	Inspected
Instance on 4th Floor	Inspected
<b>Lighting</b>	Inspected
Instance on 4th Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 4th Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 4th Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 4th Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 4th Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 4th Floor	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on 4th Floor	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on 4th Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Local Sound System</b>	Inspected
Instance on 4th Floor	Inspected
Installation Year	2006
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Does not Exist
Instance on 4th Floor	Does not Exist
<b>Scoreboard</b>	Inspected
Instance on 4th Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	Does not Exist
Instance on 4th Floor	Does not Exist
<b>KITCHEN</b>	Inspected
Instance on Basement	Inspected
<b>Lighting</b>	Inspected
Instance on Basement	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Basement	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on Basement	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K600

Question	Response
<b>KITCHEN</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Recessed Mounted</b>	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Basement	Does not Exist
<b>LIBRARY</b>	
Instance on Room 305	Inspected
<b>Lighting</b>	
Instance on Room 305	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 305	Inspected
<b>Pendant Mounted</b>	
Instance on Room 305	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 305	Does not Exist
<b>Recessed Mounted</b>	
Instance on Room 305	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 305	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 305	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 305	Does not Exist
<b>Raceway With Receptacles</b>	
Instance on Room 305	Does not Exist
<b>Projection System</b>	
Instance on Room 305	Does not Exist
<b>LOCKER ROOM</b>	
Instance on 3rd Floor - Boys, 3rd Floor - Girls	Inaccessible
<b>MULTIPURPOSE ROOM</b>	
	Does not Exist
<b>SCIENCE DEMO ROOM</b>	
Instance on Rooms 438, 443, 447	Inspected
Power Panel	No
Alternative use	No
Instance on Rooms 440, 445, 457	Inspected
Power Panel	Yes
Alternative use	No
<b>Lighting</b>	
Instance on Rooms 440, 445, 457	Inspected
Instance on Rooms 438, 443, 447	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K600

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
Instance on Rooms 440, 445, 457	Inspected
Instance on Rooms 438, 443, 447	Inspected
<b>Pendant Mounted</b>	
Instance on Rooms 440, 445, 457	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 438, 443, 447	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Rooms 440, 445, 457	Does not Exist
Instance on Rooms 438, 443, 447	Does not Exist
<b>Recessed Mounted</b>	
Instance on Rooms 440, 445, 457	Does not Exist
Instance on Rooms 438, 443, 447	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Rooms 440, 445, 457	Does not Exist
Instance on Rooms 438, 443, 447	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Rooms 440, 445, 457	Does not Exist
Instance on Rooms 438, 443, 447	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Rooms 440, 445, 457	Does not Exist
Instance on Rooms 438, 443, 447	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Rooms 440, 445, 457	Does not Exist
Instance on Rooms 438, 443, 447	Does not Exist
<b>Emergency Shut-Off Power</b>	
Instance on Rooms 440, 445, 457	Does not Exist
Instance on Rooms 438, 443, 447	Does not Exist
<b>Power Supply</b>	
Instance on Rooms 440, 445, 457	Inspected
Instance on Rooms 438, 443, 447	Inspected
<b>Instructor Unit</b>	
Instance on Rooms 440, 445, 457	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 438, 443, 447	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Meter Demonstration Unit</b>	
Instance on Rooms 440, 445, 457	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 438, 443, 447	Inspected
Condition	3 - Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K600**

<b>Question</b>	<b>Response</b>
<b>SCIENCE DEMO ROOM</b>	
<b>Power Supply</b>	Inspected
<b>Meter Demonstration Unit</b>	
Deficiency	No deficiencies recorded
<b>Projection System</b>	Does not Exist
Instance on Rooms 440, 445, 457	Does not Exist
Instance on Rooms 438, 443, 447	Does not Exist
<b>SCIENCE LAB</b>	Inspected
Instance on Room 150	Inspected
Power Panel	No
Alternative use	No
Instance on Rooms 333, 339, 350, 437, 449, 450	Inspected
Power Panel	Yes
Alternative use	No
<b>Lighting</b>	Inspected
Instance on Rooms 333, 339, 350, 437, 449, 450	Inspected
Instance on Room 150	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Rooms 333, 339, 350, 437, 449, 450	Inspected
Instance on Room 150	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Rooms 333, 339, 350, 437, 449, 450	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 150	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on Rooms 333, 339, 350, 437, 449, 450	Does not Exist
Instance on Room 150	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on Rooms 333, 339, 350, 437, 449, 450	Does not Exist
Instance on Room 150	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Rooms 333, 339, 350, 437, 449, 450	Does not Exist
Instance on Room 150	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Rooms 333, 339, 350, 437, 449, 450	Does not Exist
Instance on Room 150	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Rooms 333, 339, 350, 437, 449, 450	Does not Exist
Instance on Room 150	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	Inspected
Instance on Rooms 333, 339, 350, 437, 449, 450	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 150	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K600**

<b>Question</b>	<b>Response</b>
<b>SCIENCE LAB</b>	
<b>Emergency Shut-Off Power</b>	
Instance on Rooms 333, 339, 350, 437, 449, 450	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 150	Does not Exist
<b>Power Supply</b>	Inspected
Instance on Rooms 333, 339, 350, 437, 449, 450	Inspected
Instance on Room 150	Does not Exist
<b>Instructor Unit</b>	
Instance on Rooms 333, 339, 350, 437, 449, 450	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Meter Demonstration Unit</b>	
Instance on Rooms 333, 339, 350, 437, 449, 450	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Student Unit</b>	
Instance on Rooms 333, 339, 350, 437, 449, 450	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Does not Exist
Instance on Rooms 333, 339, 350, 437, 449, 450	Does not Exist
Instance on Room 150	Does not Exist
<b>SCIENCE PREP ROOM</b>	Inspected
Instance on Room 348	Inspected
Power Panel	Yes
Alternative use	No
Instance on Rooms 337, 448, 453	Inspected
Power Panel	No
Alternative use	No
Instance on Room 448A	Inspected
Power Panel	Yes
Alternative use	No
<b>Lighting</b>	Inspected
Instance on Room 448A	Inspected
Instance on Rooms 337, 448, 453	Inspected
Instance on Room 348	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 448A	Inspected
Instance on Rooms 337, 448, 453	Inspected
Instance on Room 348	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Room 448A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 337, 448, 453	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 348	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K600**

<b>Question</b>	<b>Response</b>
<b>SCIENCE PREP ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on Room 448A	Does not Exist
Instance on Rooms 337, 448, 453	Does not Exist
Instance on Room 348	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 448A	Does not Exist
Instance on Rooms 337, 448, 453	Does not Exist
Instance on Room 348	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 448A	Does not Exist
Instance on Rooms 337, 448, 453	Does not Exist
Instance on Room 348	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 448A	Does not Exist
Instance on Rooms 337, 448, 453	Does not Exist
Instance on Room 348	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 448A	Does not Exist
Instance on Rooms 337, 448, 453	Does not Exist
Instance on Room 348	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	Does not Exist
Instance on Room 448A	Does not Exist
Instance on Rooms 337, 448, 453	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 348	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	Does not Exist
Instance on Room 448A	Does not Exist
Instance on Rooms 337, 448, 453	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 348	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	Does not Exist
Instance on Room 448A	Does not Exist
Instance on Rooms 337, 448, 453	Does not Exist
Instance on Room 348	Does not Exist
<b>SWIMMING POOL</b>	Does not Exist
<b>TOILET ROOM - STAFF</b>	Inspected
<b>Lighting</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K600**

<b>Question</b>	<b>Response</b>
<b>TOILET ROOM - STAFF</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Inspected
Replacement Quantity	200,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not Exist
<b>EMERGENCY GENERATOR SET</b>	Does not Exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Auditorium, Auditorium Balcony, Main Entrance Lobby, Boys Locker Room, Basement Staircase D, 1st Floor (Staircase I, by Room 169), 3rd Floor (Staircase C, by Rooms 363, 375A), 4th Floor Corridor by Rooms (414, 406)
Deficiency Quantity	19
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K600**

<b>Question</b>	<b>Response</b>
<b>EMERGENCY LIGHTING</b>	
<b>Battery Pack</b>	Inspected
Violations	35674664L
<b>Non Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	
<b>Battery Pack</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Does not Exist
<b>EXIT/EMERGENCY LIGHT</b>	
	Does not Exist
<b>FIRE ALARM SYSTEM</b>	
	Inspected
Replacement Quantity	200,000
Replacement Uom	S.F.
<b>Bell/Horn</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Strobe</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Manual Pull Station</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fan Shutdown Control</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Duct Smoke Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Area Smoke Detector</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>CO Detector</b>	Does not Exist
<b>Heat Detector</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Elevator Recall</b>	Inspected
Condition	4 - Between Fair and Poor
Deficiency	SYSTEM NOT OPERATIONAL
Deficiency Location/Instance	Elevator - Device ID: 3P3111
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo 1	No photo recorded
Violations	No violations recorded.
<b>Magnetic Door Holder/Contactor</b>	Inspected
Condition	4 - Between Fair and Poor

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K600

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Magnetic Door Holder/Contactor</b>	
Deficiency	CONTACTOR NOT OPERATIONAL
Deficiency Location/Instance	Corridors - by Rooms (150, 254, 324)
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	CONTACTOR MISSING
Deficiency Location/Instance	Corridor - by Rooms (123, 150, 349, 424)
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	INSTALL CONTACTOR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Fused Cutout Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	Does not Exist
<b>Main Panel</b>	Inspected
<b>Bell At Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Gamewell
Equipment	N/A
Model	E3 Series
Installation Year	2011
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	Does not Exist
<b>Sub-Panel</b>	Does not Exist
<b>Remote Annunciator</b>	Inspected
<b>Display Monitor</b>	Does not Exist
<b>Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Printer</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K600**

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	
<b>Remote Annunciator</b>	Inspected
<b>Punch Register</b>	Does not Exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Tamper Flow Switch/Chain</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>GROUNDING SYSTEM</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>INTERCOM SYSTEM</b>	Inspected
<b>Elevator</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	NOT CONNECTED TO REMOTE MONITORING STATION
Deficiency Location/Instance	Elevator - Device ID: 3P3111
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo	No photo recorded
Violations	No violations recorded.
<b>Holding Area</b>	Does not Exist
<b>LAN</b>	Inspected
<b>Local Distribution Frame (LDF)</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	Does not Exist
<b>MOTOR CONTROLLER</b>	Inspected
<b>Motor Control Center</b>	Does not Exist
<b>Motor Starter/Contactor</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Variable Frequency Drive</b>	Does not Exist
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Fused Toggle Switch Type</b>	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Cafeteria
Deficiency Quantity	1

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K600**

<b>Question</b>	<b>Response</b>
<b>PANEL BOARD</b>	
<b>Fused Toggle Switch Type</b>	
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Molded Case Circuit Breaker Type</b>	
Condition	Inspected
Condition	3 - Fair
Deficiency	NO SPARE
Deficiency Location/Instance	Corridors - by Rooms (B50, 121, 218, 236, 254), Boiler Room Mechanical Room, Penthouse Fan Room #2
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>PUBLIC ADDRESS SYSTEM</b>	
Replacement Quantity	Inspected
Replacement Uom	200,000
Instance	S.F.
Instance Condition	General Office
Instance Quantity	3 - Fair
Instance Quantity Uom	1
Model	EACH
Installation Year	Rauland Telecenter
Source of Installation	2006
Deficiency	Custodial Staff
Deficiency Location/Instance	CLOCK NOT OPERATIONAL
Deficiency Quantity	Classrooms and Corridors
Quantity Uom	17
Potential Action	EACH
Urgency of Action	REPLACE
Purpose of Action	PRIORITY 3
Deficiency Photo1	LEVEL 2
Violations	No photo recorded
Violations	No violations recorded.
<b>SECURITY</b>	
<b>IPDVS/CCTV System</b>	
Replacement Quantity	Inspected
Replacement Uom	200,000
Installation Year	S.F.
Source of Installation	2024
Condition	Custodial Staff
Deficiency	1 - Good
Deficiency	No deficiencies recorded
<b>Intrusion Alarm System</b>	
Replacement Quantity	Inspected
Replacement Quantity	200,000

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K600

Question	Response
<b>SECURITY</b>	
<b>Intrusion Alarm System</b>	
Replacement Uom	S.F.
<b>Central Control Panel</b>	
Instance	Room 108
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista-128BPT
Installation Year	2020
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
<b>Infrared Sensor</b>	
Condition	Inspected
Deficiency	3 - Fair
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	
Condition	Inspected
Deficiency	3 - Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	
Condition	Inspected
Deficiency	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	
Condition	Inspected
Deficiency	3 - Fair
Deficiency	SIREN/STROBE NOT ACTIVE
Deficiency Location/Instance	Exterior Wall - facing Washington Avenue
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting - Security</b>	
Condition	Inspected
Replacement Uom	EACH
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>SERVICE SWITCH</b>	
Condition	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Gallagher
Equipment	Main Switch
Capacity/Size Quantity	3,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1988
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K600

Question	Response
<b>SWITCHBOARD</b>	Inspected
Number of Spares	2
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Gallagher Switchboard Co.
Equipment	N/A
Capacity/Size Quantity	3,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	7
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	1988
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Does not Exist
<b>TELEPHONE SYSTEM</b>	Inspected
<b>PBX/Intercom</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Standard</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>TRANSFORMER</b>	Does not Exist