Building Condition Assessment Survey 2023 - 2024

Inspection Id	Inspection T	ype				Time In	Last Edited
EE: K687	Electrical					2024-01-29 12:01 PM	2024-02-12 11:01 AN
Asset Data							
Question					Answer		
Type of Service					Below Gro	ound	
Does Interactive V	Whiteboard (IW	VB) Exist?			Yes		
Water Penetration					No		
Have any System	s/Major Buildir	ng Components	been upgraded?		Yes		
					Systems:	Fire Alarm System (CO Detect	tor)
					Years:	2021 All Other Electrical Systems as	nd Components
					Systems: Years:	2016	nd Components
DEDICATED IN	TERCOMS I	N FIRE RESC	UE AREAS		rears.	2010	
Question					Response		
Are there any Lif and/or Holding R			re Rescue Areas,		No		
riority Condition							
Priority Pri Condition Exist Ca Last Year?		Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title Status	PhotoImage
No condition recorde	d						
nspection							
Question					Respons	se	
Electrical							
AUDITORIUM					Does not	t Exist	
CAFETERIA					Does not	t Exist	
CLASSROOM/O	CORRIDOR/A	DMINISTRAT	TIVE SPACE		Inspecte	d	
Lighting					Inspecte	d	
Does a	Chandelier exi	ist?			No		
Lighting Fix	ture - Fluoreso	cent			Inspecte	d	
Pendant M	Iounted				Inspecte	d	
Conditio	n				2 - Betw	een Good and Fair	
Deficie	ency				No defic	iencies recorded	
Surface M	ounted				Inspecte	d	
Conditio						een Good and Fair	
Deficie						iencies recorded	
Recessed I					Inspecte		
Conditio						een Good and Fair	
Deficie						iencies recorded	
Lighting Fix					Does not		
	ture - Incande	escent			Does not		
Lighting Fix	ture - LED				Inspecte	d	
Pendant M	Iounted				Does not	t Exist	
Surface M	ounted				Inspecte	d	
Conditio						een Good and Fair	
Deficie						iencies recorded	
Recessed I	Mounted				Inspecte		
Conditio						een Good and Fair	

Building Condition Assessment Survey 2023 - 2024

uestion	Response	
COMPUTER LAB	Does not Exist	
GYMNASIUM	Does not Exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting	Inspected	
Instance on 1st Floor	Inspected	
-	търсски	
Lighting Fixture - Fluorescent Instance on 1st Floor	Inspected	
Pendant Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Surface Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Recessed Mounted	Inspected	
Instance on 1st Floor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	D	
Instance on 1st Floor	Does not Exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not Exist	
LIBRARY	Does not Exist	
LOCKER ROOM	Does not Exist	
MULTIPURPOSE ROOM	Inspected	
Instance on 1st Floor	Inspected	
Lighting	Inspected	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Surface Mounted	Inspected	
Instance on 1st Floor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Instance on 1st Floor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not Exist	
Local Sound System	Does not Exist	
Instance on 1st Floor	Does not Exist Does not Exist	
Instance on 13t 1 1001	Does not Exist	

Building Condition Assessment Survey 2023 - 2024

Electrical Inspection K687 Question

uestion	Response
MULTIPURPOSE ROOM	Inspected
Projection System	Does not Exist
Instance on 1st Floor	Does not Exist
Theater Lighting System	Does not Exist
Instance on 1st Floor	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	
Condition	Inspected 2 - Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	22,000
Replacement Uom	S.F.
Condition	2 - Between Good and Fair
Deficiency EMERGENCY DC STANDBY BATTERY POWER	No deficiencies recorded Does not Exist
EMERGENCY GENERATOR SET	
	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance Instance Condition	Room 101D 2 - Between Good and Fair
Instance Quantity	2 FACH
Instance Quantity Uom	EACH
Instance Manufacturer	Kohler Power Systems
Equipment	Transfer Switch 70
Capacity/Size Quantity	
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate

Building Condition Assessment Survey 2023 - 2024

Question		Response	
EMERG	ENCY GENERATOR SET		
Autom	natic Transfer Switch (ATS)	Inspected	
	Installation Year	2016	
	Source of Installation	Documented	
	Deficiency	No deficiencies recorded	
Battery	y Charger	Inspected	
	Instance	Room 101D	
	Instance Condition	2 - Between Good and Fair	
	Instance Quantity	1	
	Instance Quantity Uom	EACH	
	Instance Manufacturer	Kohler Power Systems	
	Equipment	Battery Charger	
	Capacity/Size Quantity	10	
	Capacity/Size UOM	AmpsDC	
	Capacity/Size2 Quantity	24	
	Capacity/Size2 UOM	VDC	
	Source of Capacity/Size	Nameplate	
	Installation Year	2016	
	Source of Installation	Documented	
	Deficiency	No deficiencies recorded	
Emerg	ency Distribution Board	Does not Exist	
Diesel	·,	Inspected	
Diesei	Instance	Playground - Outdoor Generator Enclosure	
	Instance Condition	2 - Between Good and Fair	
	Instance Quantity	1	
	Instance Quantity Uom	EACH	
	Instance Manufacturer	Kohler Power Systems	
	Equipment	Emergency Generator	
	Capacity/Size Quantity	19	
	Capacity/Size Quantity Capacity/Size UOM	KVA	
	Capacity/Size2 Quantity	15	
	Capacity/Size2 UOM	KW	
	Capacity/Size3Quantity	52	
	Capacity/Size3 UOM	Amps	
	Source of Capacity/Size	Nameplate	
	Installation Year	2016	
	Source of Installation	Documented	
	Deficiency	No deficiencies recorded	
Natura	al Gas	Does not Exist	
EMERG	ENCY LIGHT/EXIT LIGHT PANEL	Does not Exist	
EMERG	ENCY LIGHTING	Inspected	
Battery	y Pack	Does not Exist	
Non Ba	attery Pack	Inspected	
Cond	lition	2 - Between Good and Fair	
	Deficiency	No deficiencies recorded	
EXIT LI	GHT	Inspected	
Battery	y Pack	Inspected	
Cond	dition	2 - Between Good and Fair	
	Deficiency	No deficiencies recorded	
(D)	Dogo A	1 of 9 Print Data 6/25/2024	

Building Condition Assessment Survey 2023 - 2024

ilear inspection		1100
estion	Response	
XIT LIGHT	Inspected	
Non Battery Pack	Does not Exist	
XIT/EMERGENCY LIGHT	Does not Exist	
TRE ALARM SYSTEM	Inspected	
Replacement Quantity	22,000	
Replacement Uom	S.F.	
Bell/Horn	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control		
Condition	Inspected 2 - Between Good and Fair	
	No deficiencies recorded	
Deficiency Duct Smoke Detector		
	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Condition	1 - Good No deficiencies recorded	
Deficiency Heat Detector		
	Inspected	
Condition	2 - Between Good and Fair	
Deficiency Electric Parallel	No deficiencies recorded	
Elevator Recall	Does not Exist	
Magnetic Door Holder/Contactor	Does not Exist	
Fused Cutout Panel	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not Exist	
Main Panel	Inspected	
Bell At Panel	Does not Exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Edwards System Technology	
Equipment	Fire Alarm Control Panel	
Model	EST3X	
Installation Year	2016	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Deficiency	two deficiencies recorded	

Building Condition Assessment Survey 2023 - 2024

Question	Response
FIRE ALARM SYSTEM	Inspected
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Does not Exist
Main Equipment Rack (MDF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	22,000
Replacement Uom	S.F.
Instance	Room 101A
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
. ,	

Building Condition Assessment Survey 2023 - 2024

Question	Response
PUBLIC ADDRESS SYSTEM	
Model	Telecor XL
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Replacement Quantity	22,000
Replacement Uom	S.F.
Installation Year	2016
Source of Installation	Documented
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Replacement Quantity	22,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista-128BPT
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room 101
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	N/A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Pero 7 of 8 Priot Poto 6/05/2024

Building Condition Assessment Survey 2023 - 2024

Question	Response		
SERVICE SWITCH			
Source of Capacity/Size	Nameplate		
Installation Year	2016		
Source of Installation	Documented		
Deficiency	No deficiencies recorded		
SWITCHBOARD	Inspected		
Number of Spares	0		
Fused Disconnect Switch Type	Inspected		
Instance	Electrical Room 101		
Instance Condition	2 - Between Good and Fair		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Instance Manufacturer	All City Switchboard		
Equipment	MDP		
Capacity/Size Quantity	1,600		
Capacity/Size UOM	Amps Total		
Capacity/Size2 Quantity	1		
Capacity/Size2 UOM	Section(S)		
Source of Capacity/Size	Nameplate		
Installation Year	2016		
Source of Installation	Documented		
Deficiency	No deficiencies recorded		
Fused Knife Switch Type	Does not Exist		
Molded Case Circuit Breaker Type	Does not Exist		
TELEPHONE SYSTEM	Inspected		
PBX/Intercom	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
Standard	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
TRANSFORMER	Does not Exist		