#### **Building Condition Assessment Survey 2023 - 2024**

#### **Electrical Inspection**

#### Asset: PRE-K CENTER @ 1258 65TH STREET - BROOKLYN, 1258 65TH STREET, New York, 11219 Last Edited **Inspection Id** Time In Inspection Type EE: K695 Electrical 2024-04-18 11:12 AM 2024-04-29 4:12 PM Asset Data Question Answer Type of Service Below Ground Does Interactive Whiteboard (IWB) Exist? Yes Water Penetration in Electrical Room? Yes Have any Systems/Major Building Components been upgraded? Yes LAN Systems: Years: 2017 Most Molded Case Circuit Breaker Type Panel Board, All Systems: Other Electrical Systems and Components - Except (Motor Controller) 2015 Years: DEDICATED INTERCOMS IN FIRE RESCUE AREAS Question Response Are there any Life Rescue Assistance Areas, Fire Rescue Areas, No and/or Holding Rooms in your building? **Priority Condition** Priority Priority Condition Component Location Person(s) Person(s) Title Status **PhotoImage Condition Exist Category** Description Affected Description Notified Last Year? No Water N/A Electrical Electrical Room Francesco Cleaner Sent to DSF Penetration in Domicolo Equipment Electrical Room Inspection Question Response Electrical AUDITORIUM Does not Exist CAFETERIA Does not Exist CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE Inspected Lighting Inspected Does a Chandelier exist? No **Lighting Fixture - Fluorescent** Inspected Pendant Mounted Inspected Condition 2 - Between Good and Fair Deficiency No deficiencies recorded Surface Mounted Inspected Condition 2 - Between Good and Fair Deficiency No deficiencies recorded **Recessed Mounted** Inspected Condition 2 - Between Good and Fair Deficiency No deficiencies recorded Lighting Fixture - HID Does not Exist **Lighting Fixture - Incandescent** Does not Exist Lighting Fixture - LED Inspected Pendant Mounted Does not Exist Surface Mounted Inspected Condition 2 - Between Good and Fair

K695

uestion	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - LED		
Surface Mounted		
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
COMPUTER LAB	Does not Exist	
GYMNASIUM	Inspected	
Instance on 1st Floor	Inspected	
Lighting	Inspected	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Surface Mounted	Inspected	
Instance on 1st Floor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not Exist Does not Exist	
Surface Mounted	Inspected	
Instance on 1st Floor	Inspected	
Condition	2 - Between Good and Fair No deficiencies recorded	
Deficiency Recessed Mounted		
Instance on 1st Floor	Inspected	
	Inspected 2 - Between Good and Fair	
	2 - Between Good and Fair No deficiencies recorded	
Deficiency Local Sound System		
Instance on 1st Floor	Inspected	
Instance on 1st Floor Installation Year	Inspected 2015	
Source of Installation Condition	Documented           2 - Between Good and Fair	
Deficiency Projection System	No deficiencies recorded Does not Exist	
Projection System		
Instance on 1st Floor	Does not Exist	
<u> </u>		
Scoreboard Instance on 1st Floor	Inspected Inspected	

### **Building Condition Assessment Survey 2023 - 2024**

### Electrical Inspection

Violations

uestion	Response	
GYMNASIUM		
Scoreboard		
Deficiency	NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	

No violations recorded.

Theater Lighting System	Does not Exist
Instance on 1st Floor	Does not Exist
ITCHEN	Inspected
Instance on 3rd Floor	Inspected
Lighting	Inspected
Instance on 3rd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 3rd Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 3rd Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 3rd Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 3rd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 3rd Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 3rd Floor	Does not Exist
Lighting Fixture - LED	
Instance on 3rd Floor	Does not Exist
IBRARY	Does not Exist
OCKER ROOM	Inspected
Instance on Room 004	Inspected
Alternative use	Yes
Instance on Rooms 002, 017	Inaccessible
Lighting	Inspected
Instance on Room 004	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 004	Inspected
Pendant Mounted	Does not Exist
Instance on Room 004	Does not Exist
Surface Mounted	Does not Exist
Instance on Room 004	Does not Exist

K695

## **Building Condition Assessment Survey 2023 - 2024**

trical Inspection		]
uestion	Response	
LOCKER ROOM		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted	Inspected	
Instance on Room 004	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 004	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Room 004	Does not Exist	
Lighting Fixture - LED		
Instance on Room 004	Does not Exist	
MULTIPURPOSE ROOM	Inspected	
Instance on 1st Floor	Inspected	
Lighting	Inspected	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted	Inspected	
Instance on 1st Floor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Recessed Mounted	Inspected	
Instance on 1st Floor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Surface Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Recessed Mounted	Inspected	
Instance on 1st Floor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System	Inspected	
Instance on 1st Floor	Inspected	
Installation Year	2015	
Source of Installation	Documented	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Projection System	Does not Evist	

Does not Exist

uestion	Response	
MULTIPURPOSE ROOM	Inspected	
Projection System	Does not Exist	
Instance on 1st Floor	Does not Exist	
Theater Lighting System	Does not Exist	
Instance on 1st Floor	Does not Exist	
SCIENCE DEMO ROOM	Does not Exist	
SCIENCE LAB	Does not Exist	
SCIENCE PREP ROOM	Does not Exist	
SWIMMING POOL	Does not Exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not Exist	
Surface Mounted	Does not Exist	
Recessed Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Does not Exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not Exist	
Surface Mounted	Does not Exist	
Recessed Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Does not Exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Replacement Quantity	19,000	
Replacement Uom	S.F.	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist	
EMERGENCY GENERATOR SET	Does not Exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist	
EMERGENCY LIGHTING	Inspected	
	*	
Battery Pack Condition	Inspected 2 - Between Good and Fair	
Deficiency	BATTERY NOT OPERATIONAL	
Deficiency Deficiency Location/Instance	Gymnasium	
Deficiency Location/Instance	1	
Quantity Uom	EACH	
Potential Action	EACH REPLACE BATTERY	
Urgency of Action	PRIORITY 5	

# **Building Condition Assessment Survey 2023 - 2024**

iestion	Response	
EMERGENCY LIGHTING		
Battery Pack	Inspected	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Non Battery Pack	Does not Exist	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not Exist	
EXIT/EMERGENCY LIGHT	Does not Exist	
FIRE ALARM SYSTEM	Inspected	
Replacement Quantity	19,000	
Replacement Uom	S.F.	
Bell/Horn	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Does not Exist	
Magnetic Door Holder/Contactor	Does not Exist	
Fused Cutout Panel	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not Exist	
Main Panel	Inspected	
Bell At Panel	Does not Exist	
Fire Alarm Control Panel (Electronic)	Inspected	

(P)

uestion	Response	
FIRE ALARM SYSTEM		
Main Panel		
Fire Alarm Control Panel (Electronic)		
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Mircom	
Equipment	Fire Alarm Control	
Model	FX - 2000	
Installation Year	2015	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not Exist	
Sub-Panel	Does not Exist	
Remote Annunciator	Inspected	
Display Monitor	Does not Exist	
Panel	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not Exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Does not Exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Does not Exist	
Main Equipment Rack (MDF)	Inspected	
Condition	2 - Between Good and Fair	
	No deficiencies recorded	
Deficiency		
	Inspected	
LIGHTNING PROTECTION	Inspected	
LIGHTNING PROTECTION Condition Deficiency	Inspected 2 - Between Good and Fair	
LIGHTNING PROTECTION Condition Deficiency	Inspected 2 - Between Good and Fair No deficiencies recorded	
LIGHTNING PROTECTION Condition Deficiency MOTOR CONTROLLER	Inspected 2 - Between Good and Fair No deficiencies recorded Inspected	
LIGHTNING PROTECTION Condition Deficiency MOTOR CONTROLLER Motor Control Center	Inspected 2 - Between Good and Fair No deficiencies recorded Inspected Does not Exist	
LIGHTNING PROTECTION Condition Deficiency MOTOR CONTROLLER Motor Control Center Motor Starter/Contactor	Inspected         2 - Between Good and Fair         No deficiencies recorded         Inspected         Does not Exist         Inspected	
LIGHTNING PROTECTION Condition Deficiency MOTOR CONTROLLER Motor Control Center Motor Starter/Contactor Condition	Inspected         2 - Between Good and Fair         No deficiencies recorded         Inspected         Does not Exist         Inspected         3 - Fair	
LIGHTNING PROTECTION Condition Deficiency MOTOR CONTROLLER Motor Control Center Motor Starter/Contactor Condition Deficiency	Inspected         2 - Between Good and Fair         No deficiencies recorded         Inspected         Does not Exist         Inspected         3 - Fair         No deficiencies recorded	

uestion	Response	
PANEL BOARD		-
Fused Knife Switch Type	Does not Exist	
Fused Toggle Switch Type	Does not Exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	PANEL BOARD COVER IS MISSING	
Deficiency Location/Instance	Multipurpose Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE	
Deficiency Location/Instance	Boiler Room, Multipurpose Room	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
PUBLIC ADDRESS SYSTEM	Inspected	
Replacement Quantity	19,000	
Replacement Uom	S.F.	
Instance	MDF Room	
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Bogen Quantum Multicom IP	
Installation Year	2015	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	<u> </u>
SECURITY	Inspected	
IPDVS/CCTV System	Inspected	
Replacement Quantity	19,000	
Replacement Uom	S.F.	
Installation Year	2015	
Source of Installation	Documented	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Replacement Quantity	19,000	
Replacement Uom	S.F.	
Central Control Panel		
Instance	Inspected Custodian's Office	
Instance Instance	2 - Between Good and Fair	

uestion	Response	
SECURITY	Response	
Intrusion Alarm System		
Central Control Panel		
Instance Quantity Uom	EACH	
Model	Vista-128BPT	
Installation Year	2015	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Inspected	
Replacement Uom	EACH	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
SERVICE SWITCH	Inspected	
Instance	Electrical Room	
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Quantity com	Siemens	
Equipment	Service Disconnect	
Capacity/Size Quantity	2,000	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2015	
Source of Installation	Documented	
Deficiency SWITCHBOARD	No deficiencies recorded	
Number of Spares	Inspected 5	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room	
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Siemens	
Equipment	MDB	
Capacity/Size Quantity	2,000	
Capacity/Size UOM	Amps Total	

6	e e e e e e e e e e e e e e e e e e e	
ctrical Inspection		K6
Question	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Source of Capacity/Size	Nameplate	
Installation Year	2015	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not Exist	
Molded Case Circuit Breaker Type	Does not Exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not Exist	