

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K705**

**Asset: MIDWOOD HS ADDITION - BROOKLYN, 2886 BEDFORD AVENUE, New York, 11210**

Inspection Id	Inspection Type	Time In	Last Edited
EE : K705	Electrical	2024-01-02 8:07 AM	2024-02-12 2:50 PM

**Asset Data**

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Retrofitted LED Lighting, LAN
	Years: 2022
	Systems: IPDVS/CCTV System
	Years: 2020
	Systems: Intrusion Alarm System (Central Control Panel, Panic Switch)
	Years: 2016
	Systems: Security Lights
	Years: 2008, 2022
	Systems: Intrusion Alarm System (Remote Annunciator)
	Years: 2008, 2016
	Systems: Molded Case Circuit Breaker Type Panel Board
	Years: 2008, 2011
	Systems: All Other Electrical Systems and Components
	Years: 2008

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

**Priority Condition**

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
Yes	Water Leaks onto Electrical Equipment	Skylight Leak	Lighting Fixture	Room 100A (inside Library)	Michael Cutrone	Fireman	Sent to DSF	

**Inspection**

Question	Response
<b>Electrical</b>	
<b>AUDITORIUM</b>	Does not Exist
<b>CAFETERIA</b>	Does not Exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	Inspected
<b>Lighting</b>	Inspected
Does a Chandelier exist?	No
<b>Lighting Fixture - Fluorescent</b>	Does not Exist
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	2 - Between Good and Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K705**

<b>Question</b>	<b>Response</b>
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	
<b>Lighting Fixture - LED</b>	
<b>Pendant Mounted</b>	
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>COMPUTER LAB</b>	Does not Exist
<b>GYMNASIUM</b>	Does not Exist
<b>KITCHEN</b>	Does not Exist
<b>LIBRARY</b>	Inspected
Instance on Room 100-1A	Inspected
<b>Lighting</b>	Inspected
Instance on Room 100-1A	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 100-1A	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 100-1A	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 100-1A	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 100-1A	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Room 100-1A	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Instance on Room 100-1A	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Instance on Room 100-1A	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Raceway With Receptacles</b>	Does not Exist
Instance on Room 100-1A	Does not Exist
<b>Projection System</b>	Inspected
Instance on Room 100-1A	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>LOCKER ROOM</b>	Does not Exist
<b>MULTIPURPOSE ROOM</b>	Does not Exist
<b>SCIENCE DEMO ROOM</b>	Inspected
Instance on Rooms 115, 117, 119, 216, 314, 320	Inspected
Power Panel	No
Alternative use	No

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K705

Question	Response
<b>SCIENCE DEMO ROOM</b>	
Instance on Rooms 218, 220, 316, 318	Inspected
Power Panel	No
Alternative use	No
<b>Lighting</b>	Inspected
Instance on Rooms 218, 220, 316, 318	Inspected
Instance on Rooms 115, 117, 119, 216, 314, 320	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Rooms 218, 220, 316, 318	Does not Exist
Instance on Rooms 115, 117, 119, 216, 314, 320	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Rooms 218, 220, 316, 318	Does not Exist
Instance on Rooms 115, 117, 119, 216, 314, 320	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Rooms 218, 220, 316, 318	Inspected
Instance on Rooms 115, 117, 119, 216, 314, 320	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Rooms 218, 220, 316, 318	Does not Exist
Instance on Rooms 115, 117, 119, 216, 314, 320	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on Rooms 218, 220, 316, 318	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 115, 117, 119, 216, 314, 320	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
Instance on Rooms 218, 220, 316, 318	Does not Exist
Instance on Rooms 115, 117, 119, 216, 314, 320	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Rooms 218, 220, 316, 318	Inspected
Instance on Rooms 115, 117, 119, 216, 314, 320	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Rooms 218, 220, 316, 318	Does not Exist
Instance on Rooms 115, 117, 119, 216, 314, 320	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on Rooms 218, 220, 316, 318	Does not Exist
Instance on Rooms 115, 117, 119, 216, 314, 320	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on Rooms 218, 220, 316, 318	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 115, 117, 119, 216, 314, 320	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Emergency Gas Shut-Off Valve</b>	Inspected
Instance on Rooms 218, 220, 316, 318	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K705

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Emergency Gas Shut-Off Valve</b>	Inspected
Instance on Rooms 115, 117, 119, 216, 314, 320	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	Inspected
Instance on Rooms 218, 220, 316, 318	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 115, 117, 119, 216, 314, 320	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	Inspected
Instance on Rooms 218, 220, 316, 318	Inspected
Instance on Rooms 115, 117, 119, 216, 314, 320	Inspected
<b>Instructor Unit</b>	
Instance on Rooms 218, 220, 316, 318	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 115, 117, 119, 216, 314, 320	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Meter Demonstration Unit</b>	
Instance on Rooms 218, 220, 316, 318	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 115, 117, 119, 216, 314, 320	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Does not Exist
Instance on Rooms 218, 220, 316, 318	Does not Exist
Instance on Rooms 115, 117, 119, 216, 314, 320	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>SCIENCE LAB</b>	Inspected
Instance on Rooms 215, 219, 313, 319	Inspected
Power Panel	Yes
Alternative use	No
<b>Lighting</b>	Inspected
Instance on Rooms 215, 219, 313, 319	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Rooms 215, 219, 313, 319	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Rooms 215, 219, 313, 319	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Rooms 215, 219, 313, 319	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Rooms 215, 219, 313, 319	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on Rooms 215, 219, 313, 319	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K705

Question	Response
<b>SCIENCE LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
<b>Surface Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
Instance on Rooms 215, 219, 313, 319	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Rooms 215, 219, 313, 319	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Rooms 215, 219, 313, 319	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on Rooms 215, 219, 313, 319	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on Rooms 215, 219, 313, 319	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Emergency Gas Shut-Off Valve</b>	Inspected
Instance on Rooms 215, 219, 313, 319	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	Inspected
Instance on Rooms 215, 219, 313, 319	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	Inspected
Instance on Rooms 215, 219, 313, 319	Inspected
<b>Instructor Unit</b>	
Instance on Rooms 215, 219, 313, 319	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Meter Demonstration Unit</b>	
Instance on Rooms 215, 219, 313, 319	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Student Unit</b>	
Instance on Rooms 215, 219, 313, 319	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Inspected
Instance on Rooms 215, 219, 313, 319	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>SCIENCE PREP ROOM</b>	Inspected
Instance on Room 214	Inspected
Power Panel Alternative use	Yes No
Instance on Rooms 217, 317	Inspected
Power Panel Alternative use	Yes No

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K705

Question	Response
<b>SCIENCE PREP ROOM</b>	
<b>Lighting</b>	Inspected
Instance on Rooms 217, 317	Inspected
Instance on Room 214	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Rooms 217, 317	Does not Exist
Instance on Room 214	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Rooms 217, 317	Does not Exist
Instance on Room 214	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Rooms 217, 317	Does not Exist
Instance on Room 214	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Rooms 217, 317	Inspected
Instance on Room 214	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Rooms 217, 317	Does not Exist
Instance on Room 214	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on Rooms 217, 317	Does not Exist
Instance on Room 214	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on Rooms 217, 317	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 214	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Emergency Gas Shut-Off Valve</b>	Inspected
Instance on Rooms 217, 317	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 214	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	Inspected
Instance on Rooms 217, 317	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 214	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	Does not Exist
Instance on Rooms 217, 317	Does not Exist
Instance on Room 214	Inspected
<b>Instructor Unit</b>	
Instance on Room 214	Inspected
Condition	3 - Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K705**

<b>Question</b>	<b>Response</b>
<b>SCIENCE PREP ROOM</b>	Inspected
<b>Power Supply</b>	Does not Exist
<b>Instructor Unit</b>	
Deficiency	No deficiencies recorded
<b>SWIMMING POOL</b>	Does not Exist
<b>TOILET ROOM - STAFF</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Does not Exist
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Does not Exist
<b>Recessed Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Does not Exist
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Does not Exist
<b>Recessed Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Inspected
Replacement Quantity	36,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not Exist
<b>EMERGENCY GENERATOR SET</b>	Inspected
<b>Automatic Transfer Switch (ATS)</b>	Inspected
Instance	Electrical Room C14
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	GE Zenith Controls
Equipment	ATS #1 Fire Alarm System
Capacity/Size Quantity	40
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C14

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K705

Question	Response
<b>EMERGENCY GENERATOR SET</b>	
<b>Automatic Transfer Switch (ATS)</b>	
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	GE Zenith Controls
Equipment	ATS #2 1200A
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Fire Booster Room (By Electrical Room C12)
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Metron Inc
Equipment	ATS #3 Sprinkler Booster Pump
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Battery Charger</b>	Does not Exist
<b>Emergency Distribution Board</b>	Inspected
Number of Spares	4
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	Electrical Room C14
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	EDP SWBD
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Molded Case Circuit Breaker Type</b>	Does not Exist
<b>Diesel</b>	Inspected
Instance	Outdoor Generator Enclosure
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**K705**

<b>Question</b>	<b>Response</b>
<b>EMERGENCY GENERATOR SET</b>	
<b>Diesel</b>	
Instance Manufacturer	Generac
Equipment	Emergency Generator
Capacity/Size Quantity	344
Capacity/Size UOM	KVA
Capacity/Size2 Quantity	275
Capacity/Size2 UOM	KW
Capacity/Size3Quantity	954
Capacity/Size3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Natural Gas</b>	Does not Exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Does not Exist
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Battery Pack</b>	Does not Exist
<b>Non Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EXIT/EMERGENCY LIGHT</b>	Does not Exist
<b>FIRE ALARM SYSTEM</b>	Inspected
Replacement Quantity	36,000
Replacement Uom	S.F.
<b>Bell/Horn</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Strobe</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Manual Pull Station</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fan Shutdown Control</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Duct Smoke Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Area Smoke Detector</b>	Inspected
Condition	2 - Between Good and Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K705

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Area Smoke Detector</b>	Inspected
Deficiency	No deficiencies recorded
<b>CO Detector</b>	Does not Exist
<b>Heat Detector</b>	Does not Exist
<b>Elevator Recall</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Magnetic Door Holder/Contactor</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fused Cutout Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	Inspected
Instance	Telecom Room 109B
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Ademco
Equipment	Fire Alarm Communicator
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Main Panel</b>	Inspected
<b>Bell At Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	Fire Alarm Control Panel
Model	EST 2
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	Does not Exist
<b>Sub-Panel</b>	Does not Exist
<b>Remote Annunciator</b>	Inspected
<b>Display Monitor</b>	Does not Exist
<b>Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Printer</b>	Does not Exist
<b>Punch Register</b>	Does not Exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K705

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Tamper Flow Switch/Chain</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>GROUNDING SYSTEM</b>	
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>INTERCOM SYSTEM</b>	
<b>Elevator</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Holding Area</b>	Does not Exist
<b>LAN</b>	
<b>Local Distribution Frame (I/LDF)</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Does not Exist
<b>LIGHTNING PROTECTION</b>	
Does not Exist	
<b>MOTOR CONTROLLER</b>	
<b>Motor Control Center</b>	Does not Exist
<b>Motor Starter/Contactor</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Variable Frequency Drive</b>	Does not Exist
<b>PANEL BOARD</b>	
<b>Fused Disconnect Switch Type</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Fused Toggle Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>PUBLIC ADDRESS SYSTEM</b>	
Replacement Quantity	36,000
Replacement Uom	S.F.
Instance	Telecom Room 109B
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Telecor II
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>SECURITY</b>	
<b>IPDVS/CCTV System</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K705

Question	Response
<b>SECURITY</b>	
<b>IPDVS/CCTV System</b>	
Replacement Quantity	36,000
Replacement Uom	S.F.
Installation Year	2020
Source of Installation	Custodial Staff
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Intrusion Alarm System</b>	
	Inspected
Replacement Quantity	36,000
Replacement Uom	S.F.
<b>Central Control Panel</b>	
	Inspected
Instance	IDF Room 200C
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista-128BPT
Installation Year	2016
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
<b>Infrared Sensor</b>	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting - Security</b>	
	Inspected
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>SERVICE SWITCH</b>	
	Inspected
Instance	Electrical Room C12
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	Service Disconnect
Capacity/Size Quantity	3,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C12

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K705

Question	Response
<b>SERVICE SWITCH</b>	
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Eaton
Equipment	Service Disconnect for Fire Pump ATS Controller
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>SWITCHBOARD</b>	Inspected
Number of Spares	2
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	Electrical Room C12
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	MDP SWBD
Capacity/Size Quantity	3,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Does not Exist
<b>TELEPHONE SYSTEM</b>	Inspected
<b>PBX/Intercom</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Standard</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>TRANSFORMER</b>	Does not Exist