

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Mechanical Inspection

K705

Asset: MIDWOOD HS ADDITION - BROOKLYN, 2886 BEDFORD AVENUE, New York, 11210

Inspection Id	Inspection Type	Time In	Last Edited
ME : K705	Mechanical	2024-01-02 8:28 AM	2024-01-12 4:11 PM

Asset Data

Question	Answer
Are there fuel tanks?	Yes
Total # of above ground tanks	1
Total capacity of all above ground tanks in gal.	150
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0
Total # of water main service entries to the asset	2
MERs/Fan Rooms Locations	Basement Fire Booster Pump Assembly Room
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Emergency Stop Switches with Missing Hammers?	No
Are there any Painted/Obstructed Sprinkler Heads?	Yes
Location(s)	2nd Floor Corridor opposite to the elevators
Have any Systems/Major Building Components been upgraded?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
Yes	Other	Defective Eye Wash	SCIENCE DEMO ROOM Eye Wash	Room 115	Michael Cutrone	Fireman	Sent to DSF	
Yes	Other	Defective Eye Wash	SCIENCE LAB Eye Wash	Science Lab 319	Michael Cutrone	Fireman	Sent to DSF	

Inspection

Question	Response
Mechanical	
AIR CONDITIONING	Inspected
Chilled Water System	Does not Exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not Exist
Cooling Coil in Ductwork	Does not Exist
Cooling Tower	Does not Exist
DX Split System	Inspected
Indoor Unit	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Outdoor Unit	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Dry Cooler	Does not Exist
Packaged / Rooftop Unit	Inspected
Instance	Roof
Instance Condition	2 - Between Good and Fair
Instance Quantity	2
Instance Quantity Uom	EACH
Source of Heating	Gas
Refrigerant Type	R-22
Instance Manufacturer	Seasons4
Equipment	RTU-3, RTU-4

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Mechanical Inspection

K705

Question	Response
AIR CONDITIONING	
Packaged / Rooftop Unit	
Capacity/Size Quantity	25
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Roof
Instance Condition	2 - Between Good and Fair
Instance Quantity	2
Instance Quantity Uom	EACH
Source of Heating	Gas
Refrigerant Type	R-22
Instance Manufacturer	Seasons4
Equipment	RTU-1, RTU-2
Capacity/Size Quantity	50
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
Packaged Terminal A/C	Does not Exist
Refrigerant Leak Detection System	Does not Exist
Refrigerant Piping	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Return Fan	Does not Exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CLIMATE CONTROL SYSTEM	Inspected
BMS	Inspected
Instance	Throughout
Instance Condition	5 - Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	0-20%
Installation Year	2008
Source of Installation	Documented
Deficiency	DEFECTIVE SYSTEM
Deficiency Location/Instance	Throughout
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Mechanical Inspection

K705

Question	Response
CLIMATE CONTROL SYSTEM	Inspected
Pneumatic System	Does not Exist
Hybrid System	Does not Exist
Electric System	Does not Exist
COMPACTOR	Does not Exist
CONVEYING	Inspected
Dumbwaiter	Does not Exist
Elevator	Inspected
Are all the existing elevators operable?	Yes
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Escalator	Does not Exist
Non-auditorium Handicap Lift - Vertical	Does not Exist
Non-auditorium Handicap Lift - Stair	Does not Exist
Ash Hoist	Does not Exist
Sidewalk Elevator	Does not Exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not Exist
Pressure Booster System	Inspected
Electric Pressure Booster System	Inspected
Instance	Basement Fire Booster Pump Assembly Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Liquitrol
Equipment	N/A
Capacity/Size Quantity	2
Capacity/Size UOM	Total # Pumps
Capacity/Size2 Quantity	6
Capacity/Size2 UOM	Total Pumps HP
Source of Capacity/Size	Documented
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
Hydraulic/Pneumatic Booster System	Does not Exist
Water Service	Inspected
Instance	Basement Fire Booster Pump Assembly Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	2
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Domestic Water Heat Exchanger	Does not Exist
Electric Domestic Water Heater	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Mechanical Inspection

K705

Question	Response
DOMESTIC WATER SYSTEM	
Domestic Hot Water System	
Heat Pump Domestic Water Heater	Does not Exist
Gas Fired Domestic Water Heater	Inspected
Instance	Penthouse Room 403
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Lochinvar
Equipment	N/A
Capacity/Size Quantity	180
Capacity/Size UOM	MBH Input
Capacity/Size2 Quantity	0
Capacity/Size2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Penthouse Room 403
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Lochinvar
Equipment	N/A
Capacity/Size Quantity	315
Capacity/Size UOM	MBH Input
Capacity/Size2 Quantity	0
Capacity/Size2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
Oil Fired Domestic Water Heater	Does not Exist
Domestic Water Distribution Piping	Inspected
Condition	2 - Between Good and Fair
Deficiency	DEFECTIVE BACKFLOW PREVENTER
Deficiency Location/Instance	Basement Fire Booster Pump Assembly Room / Science Rooms Service
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo	No photo recorded
Violations	No violations recorded.
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Mechanical Inspection

K705

Question	Response
DRAIN/WASTE/VENT AND STORM SYSTEM	
Sewage/Waste/Vent Piping	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Sump Pump	Does not Exist
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not Exist
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Urinal	Does not Exist
Student	Inspected
Drinking Fountain	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Locker Room Shower	Does not Exist
Sink And Fountain Combo Unit	Does not Exist
Toilet	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GAS FIRED FURNACE	Does not Exist
GAS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Does not Exist
Gas Meter Room Vent	Does not Exist
Gas Pressure Booster	Does not Exist
CO/Gas Leak Detection	Inspected
Instance	Penthouse Room 403
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Mechanical Inspection

K705

Question	Response
GAS SERVICE	Inspected
CO/Gas Leak Detection	
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
HEATING	Inspected
Heating Coil In Ductwork	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Hydronic Heating	Does not Exist
Radiator/Convactor/Fin Tube	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Steam Heating	Does not Exist
Steam supplied by External Sources	Does not Exist
Unit Heater/Cabinet Heater	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
HEATING PLANT	Does not Exist
Enclosed IDF Room	Inspected
Instance on Room 109B	Inspected
Instance on Rooms 200C, 300C	Inspected
Dedicated A/C Equipment	Inspected
Instance on Rooms 200C, 300C	Inspected
Condition	4 - Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Rooms 200C, 300C
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 109B	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
KITCHEN	Does not Exist
MDF Room	Does not Exist
SCIENCE DEMO ROOM	Inspected
Instance on Room 115	Inspected
Alternative use	No
Instance on Rooms 117, 119, 216, 218, 220, 314, 316, 318, 320	Inspected
Alternative use	No
Acid Waste Neutralizing Tank	Does not Exist
Instance on Rooms 117, 119, 216, 218, 220, 314, 316, 318, 320	Does not Exist
Instance on Room 115	Does not Exist
CO Detector	Inspected
Instance on Rooms 117, 119, 216, 218, 220, 314, 316, 318, 320	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Mechanical Inspection

K705

Question	Response
SCIENCE DEMO ROOM	
CO Detector	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 115	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shower	
Instance on Rooms 117, 119, 216, 218, 220, 314, 316, 318, 320	Does not Exist
Instance on Room 115	Does not Exist
Eye Wash	
Instance on Rooms 117, 119, 216, 218, 220, 314, 316, 318, 320	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 115	Inspected
Condition	4 - Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Room 115
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Hood Exhaust Ductwork	
Instance on Rooms 117, 119, 216, 218, 220, 314, 316, 318, 320	Does not Exist
Instance on Room 115	Does not Exist
Hood Exhaust Fan	
Instance on Rooms 117, 119, 216, 218, 220, 314, 316, 318, 320	Does not Exist
Instance on Room 115	Does not Exist
Fixed Laboratory Hood	
Instance on Rooms 117, 119, 216, 218, 220, 314, 316, 318, 320	Does not Exist
Instance on Room 115	Does not Exist
Laboratory Sink	
Instance on Rooms 117, 119, 216, 218, 220, 314, 316, 318, 320	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 115	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Make-up Air Unit	
Instance on Rooms 117, 119, 216, 218, 220, 314, 316, 318, 320	Does not Exist
Instance on Room 115	Does not Exist
SCIENCE LAB	
Instance on Rooms 215, 219, 313	Inspected
Alternative use	No
Instance on Room 319	Inspected
Alternative use	No

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Mechanical Inspection

K705

Question	Response
SCIENCE LAB	
Acid Waste Neutralizing Tank	Does not Exist
Instance on Room 319	Does not Exist
Instance on Rooms 215, 219, 313	Does not Exist
CO Detector	Inspected
Instance on Room 319	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 215, 219, 313	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shower	Inspected
Instance on Room 319	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 215, 219, 313	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Eye Wash	Inspected
Instance on Room 319	Inspected
Condition	4 - Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Room 319
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Rooms 215, 219, 313	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	Inspected
Instance on Room 319	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 215, 219, 313	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Hood Exhaust Fan	Inspected
Instance on Room 319	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 215, 219, 313	Does not Exist
Fixed Laboratory Hood	Inspected
Instance on Room 319	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 215, 219, 313	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Mechanical Inspection

K705

Question	Response
SCIENCE LAB	
Fixed Laboratory Hood	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Laboratory Sink	Inspected
Instance on Room 319	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 215, 219, 313	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Make-up Air Unit	Does not Exist
Instance on Room 319	Does not Exist
Instance on Rooms 215, 219, 313	Does not Exist
SCIENCE PREP ROOM	
Instance on Rooms 214, 217, 317	Inspected
Alternative use	No
Acid Waste Neutralizing Tank	Does not Exist
Instance on Rooms 214, 217, 317	Does not Exist
CO Detector	Inspected
Instance on Rooms 214, 217, 317	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shower	Inspected
Instance on Rooms 214, 217, 317	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Eye Wash	Inspected
Instance on Rooms 214, 217, 317	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	Inspected
Instance on Rooms 214, 217, 317	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Hood Exhaust Fan	Does not Exist
Instance on Rooms 214, 217, 317	Does not Exist
Fixed Laboratory Hood	Inspected
Instance on Rooms 214, 217, 317	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Laboratory Sink	Inspected
Instance on Rooms 214, 217, 317	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Make-up Air Unit	Does not Exist
Instance on Rooms 214, 217, 317	Does not Exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	
Dry Sprinkler Alarm Valve Assembly	Does not Exist
Wet Sprinkler Alarm Valve Assembly	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Mechanical Inspection

K705

Question	Response
SPRINKLERS, STANDPIPE, FIRE SYSTEM	
Fire Booster Pump Assembly	Inspected
Condition	3 - Fair
Deficiency	DEFECTIVE FIRE BOOSTER PUMP
Deficiency Location/Instance	Fire Booster Pump Assembly Room / Leaks
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Roof Tank	Does not Exist
Siamese Connection	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Sprinkler Head	Inspected
Condition	3 - Fair
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	2nd Floor Corridor opposite to the elevators
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Sprinkler Piping	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Standpipe System	Does not Exist
Water Gong	Does not Exist
SWIMMING POOL	Does not Exist
VENTILATION	Inspected
Is the building mechanically ventilated?	Yes
Exhaust Fan	Inspected
Approximate Total # of Fans	1-25
Condition	3 - Fair
Deficiency	No deficiencies recorded
Heating And Ventilating Unit	Does not Exist
Metal Ductwork	Inspected
Are there any uninsulated ductwork by design in Mechanical Rooms?	No
Are there chain operated dampers?	No
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Supply Fan	Does not Exist
Unit Ventilator	Does not Exist