Building Condition Assessment Survey 2023 - 2024

Inspection Id	Inspection '	Туре				Time In	Last Edited
EE : K749	Electrical					2023-12-07 7:40 AM	2023-12-20 11:51 AN
sset Data							
Question					Answer		
Type of Service					Below Gro	ound	
Does Interactive	Whiteboard (I	WB) Exist?			Yes		
Water Penetration	n in Electrical	Room?			No		
Have any System	s/Major Build	ling Components	been upgraded?		Yes		
					Systems:	Multipurpose Room (Incandesce	nt Lighting)
					Years:	2022	
					Systems:	All Other Electrical Systems and	Components
DEDICATED II	WEED COME	IN FIDE DEGG	HE ADEAG		Years:	2015	
DEDICATED II Question	NTERCOMS	IN FIRE RESC	UE AREAS		Response		
	fe Rescue Ass	istance Areas, Fir	e Rescue Areas.		No		
and/or Holding I	Rooms in your						
riority Condition							
Priority Pr Condition Exist Ca Last Year?	iority itegory	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title Status	PhotoImage
No condition recorde	ed						
nspection							
Question					Respon	se	
Electrical							
AUDITORIUM					Does no	t Exist	
CAFETERIA					Does no	t Exist	
CLASSROOM/	CORRIDOR	ADMINISTRAT	TIVE SPACE		Inspecte	ed	
Lighting					Inspecte	ed	
Does a	Chandelier e	xist?			No		
Lighting Fix	ture - Fluore	escent			Inspecte	ed	
Pendant N	Jounted				Inspecte	ed	
Condition	on				2 - Betw	veen Good and Fair	
Defici	ency				No defic	ciencies recorded	
Surface M	Iounted				Inspecte	ed	
Condition	on				2 - Betw	veen Good and Fair	
Defici	ency				No defic	ciencies recorded	
Recessed	Mounted				Inspecte	ed	
Condition	on				2 - Betw	veen Good and Fair	
Defici						ciencies recorded	
Lighting Fix	ture - HID				Does no	t Exist	
Lighting Fix	ture - Incand	lescent			Does no	t Exist	
Lighting Fix	ture - LED				Inspecte	ed	
Pendant N	Mounted				Inspecte	ed	
Condition	on				2 - Betw	veen Good and Fair	
Defici	ency				No defic	ciencies recorded	
Surface M	Iounted				Does no	t Exist	
Recessed	Mounted				Does no	t Exist	
COMPUTER L	AB				Does no	t Exist	
					Does no	t Evict	

Building Condition Assessment Survey 2023 - 2024

trical Inspection	K
nestion	Response
KITCHEN	Inspected
Instance on Basement	Inspected
Lighting	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	Does not Exist
Instance on Basement	Does not Exist
Surface Mounted	Does not Exist
Instance on Basement	Does not Exist
Recessed Mounted	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
LIBRARY	Does not Exist
LOCKER ROOM	Does not Exist
MULTIPURPOSE ROOM	
Instance on 3rd Floor	Inspected Inspected
Lighting Instance on 3rd Floor	Inspected
	Inspected
Lighting Fixture - Fluorescent	T 1
Instance on 3rd Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 3rd Floor	Does not Exist
Surface Mounted	Inspected
Instance on 3rd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 3rd Floor	Does not Exist
Lighting Fixture - HID	
Instance on 3rd Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 3rd Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 3rd Floor	Does not Exist
Surface Mounted	Inspected
Instance on 3rd Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
	Does not Exist

Building Condition Assessment Survey 2023 - 2024

Question	Response
MULTIPURPOSE ROOM	
Lighting	Inspected
Lighting Fixture - LED	
Instance on 3rd Floor	Does not Exist
Local Sound System	Does not Exist
Instance on 3rd Floor	Does not Exist
Projection System	Does not Exist
Instance on 3rd Floor	Does not Exist
Theater Lighting System	Does not Exist
Instance on 3rd Floor	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	
Condition	Inspected 2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	30,000
Replacement Uom	S.F.
-	

Building Condition Assessment Survey 2023 - 2024

uestion	Response
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Multipurpose Room, Custodian's Office
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	Does not Exist
EXIT LIGHT	Inspected
	•
Battery Pack Condition	Inspected
	2 - Between Good and Fair No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Does not Exist
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	30,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Does not Exist
Duct Smoke Detector	Does not Exist
Area Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency H. (D. (1)	No deficiencies recorded
Heat Detector	Inspected
Condition Deficiency	2 - Between Good and Fair No deficiencies recorded

Building Condition Assessment Survey 2023 - 2024

icai inspection	
estion	Response
IRE ALARM SYSTEM	
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Does not Exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Mircom
Equipment	Fire Alarm Control
Model	FX - 2000
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Does not Exist
Tamper Flow Switch/Chain	Does not Exist
ROUNDING SYSTEM	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
NTERCOM SYSTEM	Does not Exist
AN	Inspected
Local Distribution Frame (I/LDF)	Does not Exist
Main Equipment Rack (MDF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
IGHTNING PROTECTION	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
IOTOR CONTROLLER	Does not Exist
ANEL BOARD	Inspected
ANEL BOARD Fused Disconnect Switch Type	Inspected Does not Exist
	•

Building Condition Assessment Survey 2023 - 2024

estion	Response		
ANEL BOARD	Inspected		
Molded Case Circuit Breaker Type	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
UBLIC ADDRESS SYSTEM	Inspected		
Replacement Quantity	30,000		
Replacement Uom	S.F.		
Instance	MDF Room 108		
Instance Condition	2 - Between Good and Fair		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Model	Telecor XL		
Installation Year	2015		
Source of Installation	Documented		
Deficiency	No deficiencies recorded		
ECURITY	Inspected		
IPDVS/CCTV System	Inspected		
Replacement Quantity	30,000		
Replacement Uom	S.F.		
Installation Year	2015		
Source of Installation	Documented		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
Intrusion Alarm System	Inspected		
Replacement Quantity	30,000		
Replacement Uom	S.F.		
Central Control Panel	Inspected		
Instance	Custodian's Office		
Instance Condition	2 - Between Good and Fair		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Model	Vista-128BPT		
Installation Year	2015		
Source of Installation	Documented		
Deficiency	No deficiencies recorded		
Infrared Sensor	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	SENSOR NOT OPERATIONAL		
Deficiency Location/Instance	Custodian's Office		
Deficiency Quantity	1		
Quantity Uom	EACH		
Potential Action	REPLACE		
Urgency of Action	PRIORITY 4		
Purpose of Action	LEVEL 3		
Deficiency Photo1	No photo recorded		
Violations	No violations recorded.		
Panic Switch	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		

Building Condition Assessment Survey 2023 - 2024

Question	Response
SECURITY	
Intrusion Alarm System	
Remote Annunciator	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	SIREN/STROBE NOT ACTIVE
Deficiency Location/Instance	Exterior Wall - facing 25th Street
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting - Security	Inspected
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room 010
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Quantity Conf	All City Switchboard
Equipment	Service Switch #1
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size Installation Year	Nameplate
	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD Number of Sparce	Inspected
Number of Spares	2
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room 010
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	MDP
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	2015
Source of Installation	Documented

Building Condition Assessment Survey 2023 - 2024

Question	Response	
SWITCHBOARD	Inspected	
Fused Disconnect Switch Type	Inspected	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not Exist	
Molded Case Circuit Breaker Type	Does not Exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not Exist	