# **Building Condition Assessment Survey 2023 - 2024**

Inspection Id	Inspection Type				Time In	Last Edited
EE: K751	Electrical				2023-12-05 12:03 PM	2023-12-27 8:55 AM
Asset Data						
Question				Answer		
Type of Service				Below Gro	ound	
Does Interactive	Whiteboard (IWB) Exist?			Yes		
Water Penetration	n in Electrical Room?			No		
Have any System	s/Major Building Component	ts been upgraded?		Yes		
				Systems:	All Electrical Systems and Com Switch)	ponents - Except (Service
				Years:	2016	
	NTERCOMS IN FIRE RES	CUE AREAS				
Question	fe Rescue Assistance Areas, I	Fire Descue Areas		Response No		
	Rooms in your building?	rife Rescue Afeas,		NO		
riority Condition						
Priority Pr Condition Exist Ca Last Year?	iority Condition htegory Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title Status	PhotoImage
No condition recorde	ed					
nspection						
Question				Respon	se	
Electrical						
AUDITORIUM				Does no	t Exist	
CAFETERIA				Does no	t Exist	
CLASSROOM/	CORRIDOR/ADMINISTRA	ATIVE SPACE		Inspecte	ed	
Lighting				Inspecte	ed	
Does a	Chandelier exist?			No		
Lighting Fix	xture - Fluorescent			Inspecte	ed	
Pendant N	Mounted			Inspecte		
Condition				*	veen Good and Fair	
Defici	ency			No defic	ciencies recorded	
Surface M				Inspecte	ed .	
Condition	on			2 - Betw	veen Good and Fair	
Defici	ency			No defic	ciencies recorded	
Recessed 1	Mounted			Inspecte	ed	
Condition	on			2 - Betw	veen Good and Fair	
Defici	ency			No defic	ciencies recorded	
Lighting Fix	kture - HID			Does no	t Exist	
Lighting Fix	xture - Incandescent			Does no	t Exist	
Lighting Fix	kture - LED			Inspecte	ed	
Pendant N	Mounted			Does no	t Exist	
Surface M	Iounted			Does no	et Exist	
Recessed				Inspecte		
Condition					veen Good and Fair	
Defici					ciencies recorded	
	-			Does no		
COMPUTER L.	AD					
COMPUTER LA GYMNASIUM	AD			Does no	nt Exist	

# **Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection	K/51	
1		

Question	Response
LIBRARY	Does not Exist
LOCKER ROOM	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	4,000
Replacement Uom	S.F.
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Inspected

# **Building Condition Assessment Survey 2023 - 2024**

estion	Response
EXIT/EMERGENCY LIGHT	
Condition	2 - Between Good and Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Basement - by Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	4,000
Replacement Uom	S.F.
Bell/Horn	
Condition	Inspected  2 - Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	
	Inspected  2 - Between Good and Fair
Condition	
Deficiency Fan Shutdown Control	No deficiencies recorded
Condition	Inspected  2 - Between Good and Fair
	No deficiencies recorded
Deficiency Duct Smoke Detector	
Condition	Inspected  2 - Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	
Condition	Inspected  2 - Between Good and Fair
	No deficiencies recorded
Deficiency  CO Detector	
Condition	Inspected  2 - Between Good and Fair
	No deficiencies recorded
Deficiency Heat Detector	
Condition	Inspected  2 - Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Does not Exist
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel  Rell At Panel	Inspected  December Fruit
Bell At Panel	Does not Exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1

## **Building Condition Assessment Survey 2023 - 2024**

Question	Response	
FIRE ALARM SYSTEM		
Main Panel		
Fire Alarm Control Panel (Electronic)		
Instance Quantity Uom	EACH	
Instance Manufacturer	Edwards System Technology	
Equipment	Fire Alarm Control Panel	
Model	EST	
Installation Year	2016	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not Exist	
Sub-Panel	Does not Exist	
Remote Annunciator	Inspected	
Display Monitor	Does not Exist	
Panel	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not Exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Does not Exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Does not Exist	
Main Equipment Rack (MDF)	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not Exist	
MOTOR CONTROLLER	Inspected	
Motor Control Center	Does not Exist	
Motor Starter/Contactor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Does not Exist	
Fused Knife Switch Type	Does not Exist	
Fused Toggle Switch Type	Does not Exist	

# **Building Condition Assessment Survey 2023 - 2024**

stion	Response	
NEL BOARD	Inspected	
Molded Case Circuit Breaker Type	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
JBLIC ADDRESS SYSTEM	Inspected	
Replacement Quantity	4,000	
Replacement Uom	S.F.	
Instance	MDF Room (Inside Room 101)	
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Telecor XL	
Installation Year	2016	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
CCURITY	Inspected	
IPDVS/CCTV System	Inspected	
Replacement Quantity	4,000	
Replacement Uom	S.F.	
Installation Year	2016	
Source of Installation	Documented	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Replacement Quantity	4,000	
Replacement Uom	S.F.	
Central Control Panel	Inspected  Custodian's Office - Outside Boiler Room	
Instance Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista-128BPT	
Installation Year	2016	
Source of Installation	Documented	
Deficiency	PANEL NOT CONNECTED TO DOE CENTRAL STATION	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	INSTALL CONNECTION	
Urgency of Action	PRIORITY 4	
Purpose of Action	LEVEL 3	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Infrared Sensor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	

# **Building Condition Assessment Survey 2023 - 2024**

estion	Response		
ECURITY			
Intrusion Alarm System			
Remote Annunciator	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
Siren/Strobe	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
Lighting - Security	Inspected		
Replacement Uom	EACH		
Condition	2 - Between Good and Fair		
Deficiency	TIME CLOCK NOT OPERATIONAL		
Deficiency Location/Instance	Room 101		
Deficiency Quantity	1		
Quantity Uom	EACH		
Potential Action	REPLACE		
Urgency of Action	PRIORITY 3		
Purpose of Action	LEVEL 3		
Deficiency Photo1	No photo recorded		
Violations	No violations recorded.		
SERVICE SWITCH	Inspected		
Instance	Cellar		
Instance Condition	3 - Fair		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Instance Manufacturer	Cutler Hammer		
Equipment	Main Switch		
Capacity/Size Quantity	200		
Capacity/Size UOM	Amps		
Source of Capacity/Size	Nameplate		
Installation Year	1960		
Source of Installation	Inspector Estimate		
Deficiency	No deficiencies recorded		
SWITCHBOARD	Inspected		
Number of Spares	2		
Fused Disconnect Switch Type	Inspected		
Instance	Cellar		
Instance Condition	2 - Between Good and Fair		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Instance Manufacturer	Eaton		
Equipment	DP - 1		
Capacity/Size Quantity	250		
Capacity/Size UOM	Amps Total		
Capacity/Size2 Quantity	1		
Capacity/Size2 UOM	Section(S)		
Source of Capacity/Size	Nameplate		
Installation Year	2016		
Source of Installation	Documented		

# **Building Condition Assessment Survey 2023 - 2024**

Question	Response	
SWITCHBOARD	Inspected	
Fused Disconnect Switch Type	Inspected	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not Exist	
<b>Molded Case Circuit Breaker Type</b>	Does not Exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not Exist	