

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Asset: EL PUENTE HS - BROOKLYN, 250 HOOPER STREET, New York, 11211

Inspection Id	Inspection Type	Time In	Last Edited
SA : K778	Architectural - Senior	2023-12-22 8:12 AM	2024-01-19 2:47 PM
AA : K778	Architectural - Associate	2023-12-22 7:30 AM	2024-01-03 5:51 PM

Asset Data

Question	Answer
Was the building fully accessible for inspection	Yes
Building Square Footage	27,000
Comments on the Area (for Athletic Field, Playing Surfaces, Leased Spaces)	Entire Building Leased
Comments on the Stories (Floors) plus Basements	4+B
Comments on the Number of Classrooms	11
Comments on the Year Built	1908
Student Population	185
Staff Population	20
Weather	Fair
Principal(s) Information	
Principal Name	Tina Lee
Organization	El Puente Academy for Peace and Justice - Brooklyn
Did you meet with this Principal?	Yes
Did this Principal provide feedback?	Yes
Summary of Principal's Feedback	The Principal's comment is as follows: There is water leak through foundation wall in the Cafeteria.
Custodian	Ralthie Llorens
Fireman	Was not present
Facade Photo	



Corner of Hooper Street and Marcy Avenue
- Northeast View

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Main Entrance Photo



Facade A - Hooper Street

Roof Photo



Roof 1 - Southeast View

Have any Systems/Major Building Components been upgraded?

Yes
 Systems: Chimney Cap, Bulkhead Door, Foundation Walls - Repairs
 Year: 2023
 Systems: Roofing, Parapets, Coping, Roof Drains, Roof Barrier, Exterior Guards, Window Lintels, Windows (All Facades except Multipurpose Room) - replacement; Chimney, Bulkhead, Exterior Walls - repairs
 Year: 2019
 Systems: Exterior Stair Cheek/Flank Walls - repairs
 Year: 2018
 Systems: Steel Stairs - repairs
 Year: 2014
 Systems: Exterior Doors - repairs; Steel Stairs, Windows (Multipurpose Room) - replacement
 Year: 2008

Have there been any Building Additions?

No

Tandem Schools?

No

Leased Space?

Yes

Year Leased

2008

Inspection



Full Inspection

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

K778

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	PhotoImage
No	Protruding Elements	Severely damaged fences with protruding metallic element is a potential safety hazard.	SITE FENCES	Schoolyard	Ralthie Llorens	Custodian	
Yes	Tripping Hazard	Severely broken tread edge is a potential safety hazard.	INTERIOR STAIRS/RAMP S: INTERIOR Stairs and Landings	Room 102	Ralthie Llorens	Custodian	

Structural Engineer Required

Structural Condition Type	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	PhotoImage
No condition recorded						

Programmatic Accessibility

Programmatic Accessibility Status Question	Response
Is the primary or secondary entrance on an accessible route?	No

Physical Breakdown Structure	Exists	Required	Complies	Deficiency	Assistive Listening System	Fire Alarm Strobe
------------------------------	--------	----------	----------	------------	----------------------------	-------------------

PROGRAMMATIC ACCESSIBILITY

Exterior Routes

Exterior Entrances & Exits			No	Saddle height > 1/2"		
Exterior H/C Lifts	No	No				
Exterior Ramps and Railings	No	Yes				

Interior Routes

Corridor and Lobby H/C Lifts	No	No				
Interior Corridor Doors and Hardware	Yes		Yes			
Interior Corridors and Lobbies			Yes			
Interior Elevators	No					
Interior Lobby Doors and Hardware			Yes			
Interior Ramps	No					

Rooms & Spaces

Art Rooms	Room 301	Yes	No	Not on Accessible Route		
Auditorium		No				
Cafeteria	Basement	Yes	No	Not on Accessible Route	FM System	Yes
Classrooms	None on Accessible Route	Yes	No	Not on Accessible Route		
Computer Rooms		No				
Gymnasium		No				
Library	Room 303	Yes	No	Not on Accessible Route		


NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

K778

Physical Breakdown Structure	Exists	Required	Complies	Deficiency	Assistive Listening System	Fire Alarm Strobe
Rooms & Spaces						
Main Office	Room 207	Yes	No	Not on Accessible Route		
Multi-purpose Room	1st Floor	Yes	No	Not on Accessible Route	FM System	Yes
Nurse's Room	Room 409	Yes	No	Not on Accessible Route		
Pool		No				
Science Lab	Room 401/402	Yes	No	Not on Accessible Route		
Toilet Rooms (Boys)	None on Accessible Route	Yes	No	Not on Accessible Route		
Toilet Rooms (Girls)	None on Accessible Route	Yes	No	Not on Accessible Route		
Toilet Rooms (Staff)	None on Accessible Route	Yes	No	Not on Accessible Route		

Building Template



Inspection

Question	Response
Architectural	
EXTERIOR	Inspected
AREAWAY	Inspected
Instance on AW1 - AW3	Inspected
Instance Condition	4 - Between Fair and Poor
Instance Quantity	3
Instance Quantity Uom	EACH
Deficiency	AREAWAY DRAINS: DETERIORATED

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

K778


Question

Response

EXTERIOR

AREAWAY

Roof Plan reference



Deficiency Quantity
 Quantity Uom
 Potential Action
 Urgency of Action
 Purpose of Action
 Deficiency Photo1

1
 EACH
 REPLACE
 PRIORITY 4
 LEVEL 2




AW3
 No violations recorded.

Violations

Deficiency

AREAWAY STAIRS: DETERIORATED
 TREADS/RISERS/NOSINGS

Roof Plan reference



Deficiency Quantity
 Quantity Uom
 Potential Action
 Urgency of Action
 Purpose of Action

20
 S.F.
 REPLACE
 PRIORITY 4
 LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Question

Response

EXTERIOR

AREAWAY

Deficiency Photo1



AW2

Violations


No violations recorded.

Deficiency

AREAWAY WALLS: CRACKS AND SPALLING

Roof Plan reference

K778



Hooper Street

Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

REPAIR

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



AW3

Violations

No violations recorded.

Deficiency

AREAWAY WALLS: DETERIORATED JOINTS

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778


Question

Response

EXTERIOR

AREAWAY

Roof Plan reference



Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action
Deficiency Photo1

20
S.F.
REPAIR
PRIORITY 3
LEVEL 2




AW1
No violations recorded.

Violations

Deficiency

AREAWAY WALLS: DETERIORATED COPING STONE

Roof Plan reference



Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action

20
S.F.
REPLACE
PRIORITY 4
LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Question	Response
----------	----------

EXTERIOR

AREAWAY

Deficiency Photo1



AW1
No violations recorded.

Violations

AWNINGS AND CANOPIES

Does not Exist

CHIMNEY

Inspected

Material Type(s)

Masonry

Condition


3 - Fair

Deficiency

BRICK: DETERIORATED JOINTS

Roof Plan reference

K778



Hooper Street

Deficiency Quantity

50

Quantity Uom

S.F.

Potential Action

REPOINT


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



CH
No violations recorded.

Violations

Deficiency

BRICK: MINOR CRACKS AND SPALLING

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

K778


Question

Response

EXTERIOR


CHIMNEY

Roof Plan reference



Deficiency Quantity
 Quantity Uom
 Potential Action
 Urgency of Action
 Purpose of Action
 Deficiency Photo1

K778
 30
 S.F.
 RESTITCH
 PRIORITY 3
 LEVEL 2




Violations

CH
 No violations recorded.

Deficiency

BRICK: MAJOR / THRU CRACKS

Roof Plan reference






Deficiency Quantity
 Quantity Uom
 Potential Action
 Urgency of Action
 Purpose of Action

K778
 20
 S.F.
 REMOVE AND REBUILD
 PRIORITY 4
 LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Question	Response
EXTERIOR	
CHIMNEY	
Deficiency Photo1	
Violations	CH No violations recorded.
COPING	
Condition	Inspected 2 - Between Good and Fair
Deficiency	CAST STONE: DETERIORATED TRANSVERSE JOINTS
Roof Plan reference	K778
	
	Hooper Street
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Roof 1 No violations recorded.
CORNICE	
Condition	Inspected 2 - Between Good and Fair
Deficiency	No deficiencies recorded
DOORS	
Condition	Inspected 2 - Between Good and Fair
Deficiency	No deficiencies recorded
DOOR HARDWARE	
Condition	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Question	Response
----------	----------

EXTERIOR

DOORS

DOOR HARDWARE

Inspected

Condition

2 - Between Good and Fair

Deficiency

No deficiencies recorded

LINTELS

Inspected

Condition

2 - Between Good and Fair

Deficiency

No deficiencies recorded

TRANSOM/SIDE LIGHT

Inspected

Condition

2 - Between Good and Fair

Deficiency

No deficiencies recorded

EXTERIOR WALLS

Inspected

Material Type(s)

Masonry

Replacement Quantity

18,000

Replacement Uom

S.F.

Instance on All Facades

Inspected

Instance Condition

4 - Between Fair and Poor

Instance Quantity

18,000

Instance Quantity Uom


S.F.

Deficiency

BRICK: DETERIORATED JOINTS

Roof Plan reference

K778



Hooper Street



Elevation

Deficiency Quantity

50

Quantity Uom

S.F.

Potential Action

REPOINT

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Question

Response

EXTERIOR

EXTERIOR WALLS

Deficiency Photo1



Facade B

No violations recorded.


Violations

Deficiency

BRICK: MINOR CRACKS AND SPALLING

Roof Plan reference

K778



Elevation

Hooper Street



10

S.F.

RESTITCH

PRIORITY 3

LEVEL 2

Deficiency Quantity


Quantity Uom

Potential Action

Urgency of Action

Purpose of Action

Deficiency Photo1



Facade C

No violations recorded.

Violations

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Question

Response

EXTERIOR


EXTERIOR WALLS

Deficiency

BRICK: CRACKS/DISPLACED/SPALLED BRICK AT BUILDING CORNERS


Roof Plan reference

K778



Elevation

Hooper Street



Deficiency Quantity

30

Quantity Uom

S.F.

Potential Action

REMOVE AND REBUILD


Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade D

Violations


No violations recorded.

Deficiency

BRICK: DETERIORATED MASONRY SILLS - MAJOR

Roof Plan reference

K778



Hooper Street

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778


Question

Response

EXTERIOR

EXTERIOR WALLS

Elevation



Deficiency Quantity

10

Quantity Uom

L.F.

Potential Action

REMOVE AND REPLACE

Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade D

No violations recorded.


Violations

Deficiency

BRICK: WATER INFILTRATION IN INSTRUCTIONAL SPACE

Roof Plan reference

K778



Hooper Street

Elevation



Deficiency Quantity

300

Quantity Uom

S.F.

Potential Action

REPAIR

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Question	Response
----------	----------

EXTERIOR

EXTERIOR WALLS

Urgency of Action
Purpose of Action
Deficiency Photo1

PRIORITY 5
LEVEL 2



Facade B - Room 105 (shown), Multipurpose Room, Stair B/3
No violations recorded.

Violations

EXTERIOR SOFFITS

Does not Exist

LOADING DOCK

Does not Exist

LOUVER

Inspected

Condition


3 - Fair

Deficiency

BROKEN/ DENTED BLADES


Roof Plan reference

K778



Elevation

Hooper Street





Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action

30
S.F.
REPLACE
PRIORITY 4
LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



K778

Question	Response
EXTERIOR	
LOUVER	
Deficiency Photo1	
Violations	Facade D No violations recorded.
PARAPETS	Inspected
Material Type(s)	Masonry
Replacement Quantity	2,000
Replacement Uom	C.F.
Instance on All Facades	Inspected
Instance Condition	3 - Fair
Instance Quantity	2,000
Instance Quantity Uom	C.F.
Deficiency	BRICK: EFFLORESCENCE
Roof Plan reference	K778
	
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PLAZA DECK	Does not Exist
ROOF	Inspected
Roofing	Inspected
Replacement Quantity	6,000
Replacement Uom	S.F.
ROOF HATCH/SMOKE HATCH	Does not Exist
LEADERS, GUTTERS, DOWNSPOUTS, SCUPPERS	Does not Exist
ROOF BARRIER/FENCE	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection




K778

Question	Response
EXTERIOR	
ROOF	
Roofing	
ROOF CAGE	Does not Exist
ROOFING	Inspected
Instance on Modified Bitumen: Roof 1	Inspected
Instance Condition	1 - Good
Instance Photo	
	Roof 1
Instance Quantity	6,000
Instance Quantity Uom	S.F.
Does the roof have major mechanical equipment sitting on Dunnage Steel less than 18" above the Roofing?	No
Does this roof instance have a Sustainable Roof System?	Yes
Sustainable Roof Type	White Roof
Sustainable Roof Location (Roof Number)	Roof 1
Do solar panels exist on these roofs?	No
Is/Are the roof(s) suitable for Solar Panel installation?	No
Installation Year	2019
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
ROOFING DRAINS	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Specialties	Inspected
BULKHEAD/PENTHOUSE	Inspected
Condition	3 - Fair
Deficiency	BULKHEAD/PENTHOUSE WALLS/INTERIOR: PLASTER CRACKS/SPALLING
Roof Plan reference	K778 
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Question	Response
EXTERIOR	
ROOF	
Specialties	
BULKHEAD/PENTHOUSE	
Deficiency Photo1	
Violations	BH1 No violations recorded.
Deficiency	BULKHEAD/PENTHOUSE DOORS: DETERIORATED DOOR AND FRAME
Roof Plan reference	K778 
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE DOOR AND FRAME
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	BH2 No violations recorded.
CUPOLA/ SPIRES/ TOWERS	Does not Exist
DORMER	Does not Exist
DUNNAGE STEEL	Does not Exist
SKYLIGHT/ROOF VENT	Does not Exist
ROOF/GRAVITY TANK	Does not Exist
STAIRS/RAMPS: EXTERIOR	Inspected
BUILDING CHEEK/FLANK WALLS	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Question	Response
----------	----------

EXTERIOR

STAIRS/RAMPS: EXTERIOR

BUILDING CHEEK/FLANK WALLS

Inspected

Condition

2 - Between Good and Fair

Deficiency

No deficiencies recorded

RAILINGS

Inspected

Condition


4 - Between Fair and Poor

Deficiency

RUST - MAJOR

Roof Plan reference

K778



Deficiency Quantity

20

Quantity Uom

L.F.

Potential Action

REPLACE

Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade A

Violations


No violations recorded.

Deficiency

BROKEN BRACKET

Roof Plan reference

K778



Deficiency Quantity

2

Quantity Uom

EACH

Potential Action

REPLACE

Urgency of Action

PRIORITY 4




Purpose of Action

LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Question	Response
EXTERIOR	
STAIRS/RAMPS: EXTERIOR	
RAILINGS	Inspected
Deficiency Photo1	
Violations	AW3 No violations recorded.
STAIRS/RAMPS	
Condition	Inspected 2 - Between Good and Fair
Deficiency	CONCRETE: CRACKS/SPALLING - MINOR
Roof Plan reference	K778
	
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Facade A No violations recorded.
WINDOWS	
Replacement Quantity	Inspected 6,000
Replacement Uom	S.F.
EXTERIOR GUARDS	
Condition	Inspected 2 - Between Good and Fair
Deficiency	No deficiencies recorded
LINTELS	
	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

K778

Question	Response
----------	----------

EXTERIOR


WINDOWS

LINTELS

Condition	3 - Fair
-----------	----------

Deficiency	STEEL: MAJOR RUSTING
------------	----------------------

Roof Plan reference	K778
---------------------	------



Elevation	Hooper Street
-----------	---------------



Deficiency Quantity	10
---------------------	----

Quantity Uom	L.F.
--------------	------

Potential Action	REPLACE
------------------	---------

Urgency of Action	PRIORITY 4
-------------------	------------

Purpose of Action	LEVEL 2
-------------------	---------

Deficiency Photo1	
-------------------	--



Facade B

Violations	No violations recorded.
------------	-------------------------

WINDOWS	Inspected
----------------	-----------

Material Type(s)	Aluminum
------------------	----------

Instance on Aluminum - Double Hung: All Facades except Multipurpose Room	Inspected
--	-----------

Instance Condition	2 - Between Good and Fair
--------------------	---------------------------

Instance Quantity	5,500
-------------------	-------

Instance Quantity Uom	S.F.
-----------------------	------

Are these windows insulated	No
-----------------------------	----

Installation Year	2019
-------------------	------

Source of Installation	Custodial Staff
------------------------	-----------------

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



K778

Question	Response
EXTERIOR	
WINDOWS	
WINDOWS	
Deficiency	ALUMINUM - DOUBLE HUNG: BROKEN PANE
Roof Plan reference	K778
Elevation	<p align="center">Hooper Street</p>
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Facade A - Room 205 No violations recorded.
Instance on Aluminum - Double Hung: Multipurpose Room	Inspected
Instance Condition	2 - Between Good and Fair
Instance Quantity	500
Instance Quantity Uom	S.F.
Are these windows insulated	Yes
Installation Year	2008
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
INTERIOR	Inspected
POOLS	Does not Exist
STRUCTURAL	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection



K778

Question	Response
INTERIOR	
STRUCTURAL	
COLUMNS/BEAMS/BEARING WALLS	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
FLOOR STRUCTURE	Inspected
Condition	3 - Fair
Deficiency	CINDER CONCRETE ARCH: METAL PAN DETERIORATED, SPALLED
Deficiency Location/Instance	Basement - Boiler Room
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPAIR
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 5
Deficiency Photo1	
Violations	Basement - Boiler Room No violations recorded.
Deficiency	CONCRETE SLAB ON GRADE: THRU CRACKS
Deficiency Location/Instance	Basement - Boiler Room
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 5
Deficiency Photo1	
Violations	Basement - Boiler Room No violations recorded.
FOUNDATION WALLS	Inspected
Material Type(s)	Concrete, Masonry
Condition	4 - Between Fair and Poor
Deficiency	BRICK: WATER INFILTRATION IN INSTRUCTIONAL SPACE
Deficiency Location/Instance	Basement - Cafeteria, Cafeteria Exit Vestibule
Deficiency Quantity	200

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

K778

Question	Response
INTERIOR	
STRUCTURAL	
FOUNDATION WALLS	
Quantity Uom	S.F.
Potential Action	INSTALL WATERPROOFING
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 5
Deficiency Photo1	
Violations	Cafeteria Exit Vestibule No violations recorded.
Deficiency	BRICK: CRACKED/SPALLED
Deficiency Location/Instance	Basement - Boiler Room, Meter Room
Deficiency Quantity	70
Quantity Uom	S.F.
Potential Action	RESTITCH
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 5
Deficiency Photo1	
Violations	Basement - Boiler Room, Meter Room, Room 002A No violations recorded.
ROOF STRUCTURE	
Condition	Inspected
Deficiency	2 - Between Good and Fair
VAULTS-BUNKERS	
Condition	No deficiencies recorded
AUDITORIUM	
Condition	Does not Exist
CAFETERIA	
Instance on Basement	Does not Exist
Ceiling	
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	GYPSUM BOARD: DAMAGED/DETERIORATED
Deficiency Location/Instance	Room 009, near Servery
Deficiency Quantity	20
Quantity Uom	S.F.

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



K778

Question	Response
INTERIOR	
CAFETERIA	
Ceiling	
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Room 009
Violations	No violations recorded.
Deficiency	ACOUSTIC TILES: DAMAGED/MISSING
Deficiency Location/Instance	Near Rooms 002A, 004, By Stair A/Basement, Exit Vestibule near Cafeteria
Deficiency Quantity	120
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Near Room 004
Violations	No violations recorded.
Door(s)	
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fixed Equipment	
Instance on Basement	Does not Exist
Floor Finish	
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	VINYL TILES: BROKEN/DETERIORATED/MISSING TILES
Deficiency Location/Instance	Near Room 004, 005, by Exit - Vestibule, Right Side
Deficiency Quantity	60
Quantity Uom	S.F.
Potential Action	REPLACE

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Question	Response
INTERIOR	
CAFETERIA	
Floor Finish	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near Room 004 No violations recorded.
Sliding-folding Partition	
Instance on Basement	Does not Exist
Stage	
Instance on Basement	Does not Exist
Walls	
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	BRICK: CRACKS/SPALLING
Deficiency Location/Instance	Exit - Vestibule
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Exit - Vestibule No violations recorded.
Deficiency	GYP SUM BOARD: DETERIORATED
Deficiency Location/Instance	Near Windows
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Question	Response
INTERIOR	
CAFETERIA	
Walls	
Deficiency Photo1	
Violations	Near Windows No violations recorded.
Deficiency	BRICK: CRACKS/SPALLING - ACTIVE LEAK
Deficiency Location/Instance	Exit - Vestibule
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Exit - Vestibule No violations recorded.
Deficiency	GYPSUM BOARD: DETERIORATED - ACTIVE LEAK
Deficiency Location/Instance	Exit - Vestibule
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Exit - Vestibule No violations recorded.

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

K778

Question	Response
INTERIOR	
CAFETERIA	
Walls	
Deficiency	CERAMIC TILE: BROKEN/ MISSING
Deficiency Location/Instance	Near Servery, By Rooms 003, 004, 006, close to Stair A/Basement and others
Deficiency Quantity	60
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Near Servery
Violations	No violations recorded.
Window Curtains/Shades/Blinds	
Instance on Basement	Does not Exist
CLASSROOMS/CORRIDORS/ADMIN SPACES	
Ceiling	
Condition	2 - Between Good and Fair
Deficiency	GYPSON BOARD: DAMAGED/DETERIORATED
Deficiency Location/Instance	Room 407
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Room 407
Violations	No violations recorded.
Deficiency	PLASTER: CRACKS/SPALLING
Deficiency Location/Instance	Main Entrance - Vestibule
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Question	Response
----------	----------


INTERIOR

CLASSROOMS/CORRIDORS/ADMIN SPACES

Ceiling

Urgency of Action
Purpose of Action
Deficiency Photo1

PRIORITY 3
LEVEL 2



Main Entrance - Vestibule
No violations recorded.


Violations

Door(s)	Inspected
----------------	-----------

Condition	5 - Poor
-----------	----------

Deficiency
Deficiency Location/Instance
Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action
Deficiency Photo1

WOOD: DETERIORATED DOOR
Rooms 206, 401, 403, 405
4
EACH
MAINTENANCE
PRIORITY 3
LEVEL 2



Room 401
No violations recorded.

Violations

Floor Finish	Inspected
---------------------	-----------

Condition	2 - Between Good and Fair
-----------	---------------------------

Deficiency
Deficiency Location/Instance
Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action

WOOD: DAMAGED/DETERIORATED
Rooms 403, 302
30
S.F.
REPLACE
PRIORITY 3
LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778


Question	Response
----------	----------

INTERIOR

CLASSROOMS/CORRIDORS/ADMIN SPACES

Floor Finish

Deficiency Photo1



Room 403

Violations

No violations recorded.

Deficiency

VINYL TILES: DETERIORATED SUBSTRATE

Deficiency Location/Instance

Rooms 405, 404, 401, 301, Main Entrance Lobby

Deficiency Quantity

200

Quantity Uom

S.F.

Potential Action

REPLACE


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Room 401

Violations

No violations recorded.

Deficiency

TERRAZZO: CRACKS

Deficiency Location/Instance

Main Entrance - Vestibule, Corridor near Stair A/1, By Rooms 403, 411, 412 and others

Deficiency Quantity

180

Quantity Uom

S.F.

Potential Action

REPLACE


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1





Corridor near Stair A/1

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection


K778

Question	Response
INTERIOR	
CLASSROOMS/CORRIDORS/ADMIN SPACES	
Floor Finish	Inspected
Violations	No violations recorded.
Walls	Inspected
Condition	2 - Between Good and Fair
Deficiency	GYPSUM BOARD: DETERIORATED
Deficiency Location/Instance	Corridor near Room 311
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Corridor near Room 311 No violations recorded.
Deficiency	PLASTER: CRACKS/SPALLING
Deficiency Location/Instance	Main Entrance - Vestibule, Corridor near Rooms 309, 308
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Main Entrance - Vestibule No violations recorded.
Specialties	Inspected
Classroom Locker(s)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fixed Seating	Does not Exist
GYMNASIUM	Does not Exist
INTERIOR DOOR HARDWARE	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Question	Response
INTERIOR	
INTERIOR DOOR HARDWARE	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERIOR GUARDS	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
KITCHEN	Inspected
Instance on Basement	Inspected
Ceiling	
Instance on Basement	Not Required
Door(s)	
Instance on Basement	Does not Exist
Floor Finish	
Instance on Basement	Not Required
Walls	
Instance on Basement	Not Required
LIBRARY	Inspected
Instance on Room 303	Inspected
Built-in Furnishing	
Instance on Room 303	Does not Exist
Ceiling	
Instance on Room 303	Inspected
Condition	2 - Between Good and Fair
Deficiency	ACOUSTIC TILES: DAMAGED/MISSING
Deficiency Location/Instance	Near Windows
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near Windows No violations recorded.
Door(s)	
Instance on Room 303	Inspected
Condition	3 - Fair
Deficiency	WOOD: DETERIORATED DOOR
Deficiency Location/Instance	Main Entrance
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Question	Response
INTERIOR	
LIBRARY	
Door(s)	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Main Entrance
Violations	No violations recorded.
Floor Finish	
Instance on Room 303	Inspected
Condition	3 - Fair
Deficiency	CARPET: WORN/DETERIORATED
Deficiency Location/Instance	Near Main Entrance, Main Entrance, Center
Deficiency Quantity	40
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Near Main Entrance
Violations	No violations recorded.
Walls	
Instance on Room 303	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
LOCKER ROOM	
	Does not Exist
MULTI-PURPOSE ROOM	
Instance on 1st Floor	Inspected
Ceiling	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	GYPSUM BOARD: DAMAGED/DETERIORATED
Deficiency Location/Instance	Near Right Side Windows, near Room 101
Deficiency Quantity	30

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



K778

Question	Response
INTERIOR	
MULTI-PURPOSE ROOM	
Ceiling	
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Near Right Side Windows
Violations	No violations recorded.
Door(s)	
Instance on 1st Floor	Inspected
Condition	5 - Poor
Deficiency	METAL: DAMAGED LOUVER
Deficiency Location/Instance	Room 105
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Room 105
Violations	No violations recorded.
Deficiency	WOOD: DETERIORATED DOOR
Deficiency Location/Instance	Rooms 101, 102
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Question	Response
INTERIOR	
MULTI-PURPOSE ROOM	
Door(s)	
Deficiency Photo1	
Violations	Room 101 No violations recorded.
Fixed Equipment	
Instance on 1st Floor	Does not Exist
Floor Finish	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	CERAMIC TILE: BROKEN/MISSING TILES
Deficiency Location/Instance	Room 101
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 101 No violations recorded.
Deficiency	VINYL TILES: BROKEN/DETERIORATED/MISSING TILES
Deficiency Location/Instance	Near Room 106
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



K778

Question	Response
INTERIOR	
MULTI-PURPOSE ROOM	
Floor Finish	
Deficiency Photo1	
Violations	Near Room 106 No violations recorded.
Deficiency	WOOD: DAMAGED/DETERIORATED
Deficiency Location/Instance	Near Main Entrance, By Room 106, Close to Stair B/1, next to Drinking Fountain, Front Stage and others
Deficiency Quantity	80
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near Main Entrance No violations recorded.
Sliding-folding Partition	
Instance on 1st Floor	Does not Exist
Stage	Inspected
Instance on 1st Floor	Inspected
Stage	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	DAMAGED FLOOR
Deficiency Location/Instance	Back Center
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Question	Response
INTERIOR	
MULTI-PURPOSE ROOM	
Stage	
Stage	
Deficiency Photo1	
Violations	Back Center No violations recorded.
Stage Curtain Rigging	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Stage Curtains	Inspected
Instance on 1st Floor	Inspected
Condition	4 - Between Fair and Poor
Deficiency	WORN/DETERIORATED
Deficiency Location/Instance	Right and Left Side, Back Curtain
Deficiency Quantity	900
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Left Side No violations recorded.
Walls	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	GYPSON BOARD: DETERIORATED
Deficiency Location/Instance	Right Side
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Question

Response

INTERIOR

MULTI-PURPOSE ROOM

Walls

Deficiency Photo1



Right Side

Violations

No violations recorded.

Deficiency

PLASTER: CRACKS/SPALLING - ACTIVE LEAK

Deficiency Location/Instance

Right Side near Windows

Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

REPLACE


Urgency of Action

PRIORITY 5

Purpose of Action

LEVEL 2

Deficiency Photo1



Right Side near Windows

Violations

No violations recorded.

Deficiency

PLASTER: CRACKS/SPALLING

Deficiency Location/Instance

Near Stair B/1, By Right Side Windows

Deficiency Quantity

20

Quantity Uom

S.F.

Potential Action

REPLACE


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Near Stair B/1

Violations

No violations recorded.

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Question	Response
INTERIOR	
MULTI-PURPOSE ROOM	
Walls	
Deficiency	WOOD PANELING: DETERIORATED
Deficiency Location/Instance	Near Windows
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near Windows No violations recorded.
Deficiency	WALL PADDING: DETERIORATED
Deficiency Location/Instance	Near Windows, By Drinking Fountain, Front Stage
Deficiency Quantity	80
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near Windows No violations recorded.
Window Curtains/Shades/Blinds	
Instance on 1st Floor	Inspected
Condition	4 - Between Fair and Poor
Deficiency	WORN/DAMAGED CURTAINS
Deficiency Location/Instance	Right and Left Side
Deficiency Quantity	900
Quantity Uom	S.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



K778

Question	Response
INTERIOR	
MULTI-PURPOSE ROOM	
Window Curtains/Shades/Blinds	
Deficiency Photo1	
	Right Side
Violations	No violations recorded.
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Inspected
Instance on Room 401/402	Inspected
Alternative use	No
Fixed Equipment	
Instance on Room 401/402	Inspected
Condition	3 - Fair
Deficiency	CABINETRY: MISSING/DAMAGED
Deficiency Location/Instance	Room 401/402
Deficiency Quantity	12
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Room 401
Violations	No violations recorded.
SCIENCE PREP ROOM	Inspected
Instance on Room 409	Inspected
Alternative use	Yes
Fixed Equipment	
Instance on Room 409	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SHOWER ROOM	Does not Exist
STAIRS/RAMPS: INTERIOR	Inspected
Do Letter Stair Signs Exist?	Yes
Ceiling	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection



K778

Question	Response
INTERIOR	
STAIRS/RAMPS: INTERIOR	
Ceiling	
Condition	2 - Between Good and Fair
Deficiency	PLASTER: CRACKS/SPALLING
Deficiency Location/Instance	Stairs B/2, 1
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Stair B/1 No violations recorded.
Door(s)	
Condition	Inspected
Condition	3 - Fair
Deficiency	METAL: DETERIORATED DOOR
Deficiency Location/Instance	Stair A/4
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Stair A/4 No violations recorded.
Partition	Does not Exist
Railings	
Condition	Inspected
Condition	3 - Fair
Deficiency	METAL: BROKEN BRACKET
Deficiency Location/Instance	Stair B/1
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



K778

Question	Response
INTERIOR	
STAIRS/RAMPS: INTERIOR	
Railings	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Stair B/1 No violations recorded.
Stairs and Landings	
Condition	Inspected 3 - Fair
Deficiency	WOOD: BROKEN/DETERIORATED
Deficiency Location/Instance	Room 102
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	
Violations	Room 102 No violations recorded.
Deficiency	TERRAZZO: CRACKS
Deficiency Location/Instance	Stairs A/1, B/1, Exit 2 - Vestibule
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Question	Response
INTERIOR	
STAIRS/RAMPS: INTERIOR	
Stairs and Landings	
Deficiency Photo1 Violations	 Stair B/1 No violations recorded.
Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations	STONE: WORN-OUT TREAD/NOSINGS Stairs A/Basement, 1, 2 120 S.F. REPLACE PRIORITY 3 LEVEL 2  Stair A/1 No violations recorded.
Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations	STONE: BROKEN/MISSING Stairs A/1, Bulkhead, B/Basement, 1, Bulkhead 100 S.F. REPLACE PRIORITY 3 LEVEL 2  Stair B/Basement No violations recorded.

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Question	Response
INTERIOR	
STAIRS/RAMPS: INTERIOR	
Walls	Inspected
Condition	2 - Between Good and Fair
Deficiency	PLASTER: CRACKS/SPALLING
Deficiency Location/Instance	Stair B/2
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Stair B/2 No violations recorded.
Deficiency	PLASTER: CRACKS/SPALLING - ACTIVE LEAK
Deficiency Location/Instance	Stairs B/3
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Stair B/3 No violations recorded.
TOILET ROOMS - STAFF	
Ceiling	Inspected
Condition	5 - Poor
Deficiency	GYPSUM BOARD: DAMAGED/DETERIORATED
Deficiency Location/Instance	Room 309
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Question	Response
INTERIOR	
TOILET ROOMS - STAFF	
Ceiling	
Deficiency Photo1	
Violations	Room 309 No violations recorded.
Door(s)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Floor Finish	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Stalls	Does not Exist
Walls	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOMS - STUDENTS	
Ceiling	Inspected
Condition	3 - Fair
Deficiency	GYPSUM BOARD: DAMAGED/DETERIORATED
Deficiency Location/Instance	Rooms 003, 306, 308
Deficiency Quantity	60
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 306 No violations recorded.
Door(s)	Inspected
Condition	5 - Poor
Deficiency	WOOD: DETERIORATED DOOR
Deficiency Location/Instance	Rooms 410, 004
Deficiency Quantity	2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



K778

Question	Response
INTERIOR	
TOILET ROOMS - STUDENTS	
Door(s)	
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Room 004
Violations	No violations recorded.
Deficiency	WOOD: DAMAGED LOUVER
Deficiency Location/Instance	Rooms 003, 004, 306
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Room 003
Violations	No violations recorded.
Floor Finish	Inspected
Condition	2 - Between Good and Fair
Deficiency	CERAMIC TILE: BROKEN/MISSING TILES
Deficiency Location/Instance	Room 004
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Question	Response
INTERIOR	
TOILET ROOMS - STUDENTS	
Floor Finish	
Deficiency Photo1	
	Room 004
Violations	No violations recorded.
Stalls	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Walls	Inspected
Condition	2 - Between Good and Fair
Deficiency	CERAMIC TILE: BROKEN/ MISSING
Deficiency Location/Instance	Room 306
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Room 306
Violations	No violations recorded.
LIFE SAFETY	Inspected
F.D. HOLDING AREA	Does not Exist
STEEL STAIRS	Inspected
Condition	4 - Between Fair and Poor
Deficiency	MAJOR RUSTING
Deficiency Location/Instance	Facade B
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Question	Response
LIFE SAFETY	
STEEL STAIRS	
Deficiency Photo1	
Violations	Facade B No violations recorded.
SITE	Inspected
CONTAINERIZATION	Does not Exist
Drainage System for Asphalt	Does not Exist
Drainage System for Concrete	Inspected
Catch Basins/Manhole - Surrounded by concrete	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Culverts - Concrete Covering	Does not Exist
Drainage System for Soil	Does not Exist
DRINKING FOUNTAINS	Does not Exist
FENCES	Inspected
Condition	4 - Between Fair and Poor
Deficiency	CHAIN LINK: DAMAGED/DETERIORATED
Deficiency Location/Instance	Schoolyard
Deficiency Quantity	100
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	
Violations	Schoolyard No violations recorded.
Deficiency	CHAIN LINK: RUST - MAJOR
Deficiency Location/Instance	Schoolyard
Deficiency Quantity	750
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Question	Response
SITE	
FENCES	
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Schoolyard
Violations	No violations recorded.
Deficiency	CHAIN LINK: DAMAGED/DETERIORATED
Deficiency Location/Instance	Hooper Street
Deficiency Quantity	450
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Schoolyard
Violations	No violations recorded.
Deficiency	WROUGHT IRON: RUST - MAJOR
Deficiency Location/Instance	Hooper Street
Deficiency Quantity	240
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Hooper Street
Violations	No violations recorded.

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



K778

Question	Response
SITE	
FENCES	
Deficiency	CONCRETE CURB: DAMAGED/DETERIORATED
Deficiency Location/Instance	Hooper Street, Schoolyard
Deficiency Quantity	70
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Hooper Street No violations recorded.
IRRIGATION SYSTEM	
	Does not Exist
PAVING	
	Inspected
Student Non-Use	
Gravel Exists?	Inspected No
Asphalt	
	Does not Exist
Concrete	
Condition	Inspected 2 - Between Good and Fair
Deficiency	DAMAGED/DETERIORATED/MISSING SECTIONS
Deficiency Location/Instance	Hooper Street
Deficiency Quantity	25
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Hooper Street No violations recorded.
Pavers	
	Does not Exist
Student Use	
Gravel Exists?	Inspected No
Asphalt	
	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



K778

Question	Response
SITE	
PAVING	
Student Use	
Concrete	Inspected
Condition	4 - Between Fair and Poor
Deficiency	DAMAGED/DETERIORATED/MISSING SECTIONS
Deficiency Location/Instance	Schoolyard
Deficiency Quantity	600
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Schoolyard No violations recorded.
Pavers	Does not Exist
Site Sidewalks & Walkways	Inspected
Asphalt	Does not Exist
Concrete	Inspected
Condition	3 - Fair
Deficiency	DAMAGED/DETERIORATED/MISSING SECTIONS
Deficiency Location/Instance	Near Exit 3, Hopper Street
Deficiency Quantity	300
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near Exit 3 No violations recorded.
Pavers	Does not Exist
DOT Sidewalk	Inspected
Asphalt	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Question	Response
SITE	
PAVING	
DOT Sidewalk	
Concrete	Inspected
Condition	4 - Between Fair and Poor
Deficiency	DAMAGED/DETERIORATED/MISSING SECTIONS
Deficiency Location/Instance	Hooper Street
Deficiency Quantity	450
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Hooper Street No violations recorded.
Deficiency	DAMAGED CURBS
Deficiency Location/Instance	Hooper Street
Deficiency Quantity	50
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Hooper Street No violations recorded.
Pavers	Does not Exist
PLAYGROUNDS	Does not Exist
PLAYING SURFACE	Does not Exist
RETAINING WALLS	Does not Exist
SEATING	Does not Exist
SITE WALLS (NOT RETAINING WALLS)	Inspected
Condition	3 - Fair
Deficiency	CAST IN PLACE CONCRETE: CRACKS/SPALLING - MAJOR

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K778

Question	Response
SITE	
SITE WALLS (NOT RETAINING WALLS)	
Deficiency Location/Instance	Schoolyard
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Schoolyard No violations recorded.
STAIRS/RAMPS: EXTERIOR	
	Does not Exist
ARTWORK	
	Does not Exist