Asset: DIV. COMPUTER INFO-DATA CENTER-K. 2 M	ETROTECH CENTER, New York, 11211	
Inspection Id Inspection Type	Time In	Last Edited
ME: K831 Mechanical	2024-02-13 1:08 PM	2024-02-20 2:28 PI
Asset Data	2021 02 10 1100 111	202. 02 20 2.20 1
Question	Answer	
Are there fuel tanks?	No	
Total # of water main service entries to the asset	0	
MERs/Fan Rooms Locations	3rd Floor MER	
Are there any spaces with Missing or Defective CO Detectors?	No	
Are there any Emergency Stop Switches with Missing Hammers?	No	
Are there any Painted/Obstructed Sprinkler Heads?	Yes	
Location(s)	Room 328, 3rd Floor Corridor adjacent to ME	ER.
Have any Systems/Major Building Components been upgraded?	Yes	
	Systems: Electric Domestic Water Heater	(1 of 2)
	Years: 2018	
Priority Condition		
Priority Priority Condition Component Location Condition Exist Category Description Affected Description Last Year?	* /	PhotoImage
No condition recorded		
nspection		
Question	Response	
Mechanical		
AIR CONDITIONING	Inspected	
Chilled Water System	Inspected	
Absorption Chiller	Does not Exist	
Air Cooled Chiller	Does not Exist	
Air Cooled Condenser	Does not Exist	
Chilled Water Distribution: Piping, Pumps and Auxiliaries	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Backflow Preventer	Does not Exist	
Central Station Air Handler	Inspected	
Instance	3rd Floor MER	
Instance Condition	3 - Fair	
Instance Quantity	2	
Instance Quantity Uom	EACH	
Instance Manufacturer	McQuay	
Equipment	AC 3-1, AC 3-2	
Capacity/Size Quantity	27,000	
Capacity/Size UOM	CFM	
Source of Capacity/Size	Documented	
Installation Year	1990	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Fan Coil Unit	Does not Exist	
Packaged Air Cooled Chiller	Does not Exist	
	Does not Exist	
Water Cooled Chiller	DOES HOLEXIST	
Water Cooled Chiller Condenser Water Distribution: Piping, Pumps and Auxiliaries	Inspected	

hanical Inspection		K83
estion	Response	
AIR CONDITIONING		
Condenser Water Distribution: Piping, Pumps and Auxiliaries		
Deficiency	No deficiencies recorded	
Cooling Coil in Ductwork	Does not Exist	
Cooling Tower	Inspected	
Instance	Main Roof	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Baltimore Air Coil (BAC)	
Equipment	CT-5A	
Capacity/Size Quantity	350	
Capacity/Size UOM	Tons	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1988	
Source of Installation	Documented	
Deficiency	151 - 350 TONS: FAN DEFECTIVE	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Instance	Main Roof	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Baltimore Air Coil (BAC)	
Equipment	CT-5B	
Capacity/Size Quantity	350	
Capacity/Size UOM	Tons	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1988	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
DX Split System	Does not Exist	
Dry Cooler	Does not Exist	
Packaged / Rooftop Unit	Does not Exist	
Packaged Terminal A/C	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Refrigerant Leak Detection System	Does not Exist	
Refrigerant Piping	Does not Exist	
Return Fan	Does not Exist	
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not Exist	
CLIMATE CONTROL SYSTEM	Does not Exist	
COMPACTOR	Does not Exist	
CONVEYING	Does not Exist	

echanical Inspection		K831
Question	Response	
CONVEYING	Does not Exist	
DOMESTIC WATER SYSTEM	Inspected	
Domestic Cold Water System	Does not Exist	
Domestic Hot Water System	Inspected	
Domestic Hot Water Remote Storage Tank	Does not Exist	
Domestic Water Heat Exchanger	Does not Exist	
Electric Domestic Water Heater	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Gas Fired Domestic Water Heater	Does not Exist	
Heat Pump Domestic Water Heater	Does not Exist	
Oil Fired Domestic Water Heater	Does not Exist	
Domestic Water Distribution Piping	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Sewage/Waste/Vent Piping	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Does not Exist	
Sump Pump	Does not Exist	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not Exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Urinal 	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Student	Does not Exist	
GAS FIRED FURNACE	Does not Exist	
GAS SERVICE	Does not Exist	
HEATING	Inspected	
Heating Coil In Ductwork	Does not Exist	
Hydronic Heating	Inspected	
Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	

Response	
Inspected	
Does not Exist	
Does not Exist	
Inspected	
3 - Fair	
No deficiencies recorded	
Does not Exist	
Inspected	
3 - Fair	
No deficiencies recorded	
Does not Exist	
Does not Exist	
Does not Exist	
Inspected	
Inspected	
3 - Fair	
No deficiencies recorded	
Does not Exist	
Inspected	
3 - Fair	
DEFECTIVE/DETERIORATED	
Room 328, 3rd Floor Corridor adjacent to MER	
2	
EACH	
REPLACE	
No violations recorded.	
Inspected	
3 - Fair	
No deficiencies recorded	
Inspected	
Inspected	
3 - Fair No deficiencies recorded	
	Does not Exist Inspected 3 - Fair No deficiencies recorded Does not Exist Inspected Inspected Inspected Inspected Inspected Does not Exist Does not Exist Does not Exist Inspected Inspected Inspected Inspected Inspected Inspected Inspected Does not Exist Does not Exist Does not Exist Does not Exist Inspected Inspected Inspected Inspected 3 - Fair No deficiencies recorded Does not Exist Inspected Joes not Exist Does not Exist Linspected 3 - Fair DEFECTIVE/DETERIORATED Room 328, 3rd Floor Corridor adjacent to MER 2 EACH REPLACE PRIORITY 5 LEVEL 6 No photo recorded No violations recorded. Inspected Inspected Inspected Inspected Inspected

chanical Inspection		K83
uestion	Response	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Standpipe System	Inspected	
Piping		
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Water Gong	Does not Exist	
SWIMMING POOL	Does not Exist	
VENTILATION	Inspected	
Is the building mechanically ventilated?	Yes	
Exhaust Fan	Does not Exist	
Heating And Ventilating Unit	Does not Exist	
Metal Ductwork	Inspected	
Are there any uninsulated ductwork by design in Mechanical Rooms? Are there chain operated dampers?	No No	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Supply Fan	Does not Exist	
Unit Ventilator	Does not Exist	