

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

K854

Asset: P.S. 178 AX (BED STUY ECC 1)-K, 1784 PARK PLACE, New York, 11212

Inspection Id	Inspection Type	Time In	Last Edited
SA : K854	Architectural - Senior	2023-11-09 7:30 AM	2023-11-16 4:31 PM
AA : K854	Architectural - Associate	2023-11-09 1:07 PM	2023-11-13 11:50 AM

Asset Data

Question	Answer
Was the building fully accessible for inspection	Yes
Building Square Footage	10,000
Comments on the Area (for Athletic Field, Playing Surfaces, Leased Spaces)	None
Comments on the Stories (Floors) plus Basements	1 (No Basement)
Comments on the Number of Classrooms	6
Comments on the Year Built	1969
Student Population	0
Staff Population	30
Weather	Fair
Principal(s) Information	
Principal Name	Khalek Kirkland (Superintendent)
Organization	CSD 23 District Office and Parent Resource Center - Brooklyn
Did you meet with this Principal?	Yes
Did this Principal provide feedback?	Yes
Summary of Principal's Feedback	Superintendent Khalek Kirkland comments are as follows: 1. The playground equipment is not in use and should be removed. 2. The wifi bandwidth is poor. 3. The clocks are not working properly. 4. The toilet room exhaust is dysfunctional.
Custodian	Ronald Ziemak
Fireman	Anthony Guastella
Facade Photo	



Park Place - South View

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K854

Main Entrance Photo



Facade A - Park Place

Roof Photo



Roof 1 - West View

Have any Systems/Major Building Components been upgraded?

Yes

Systems: Staff Toilet Room HC compliance (Room 1) - upgrade

Year: 2018

Systems: Roofing, Windows - replacement

Year: 1998

Have there been any Building Additions?

No


Tandem Schools?

No

Leased Space?

No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	PhotoImage
No	Protruding Elements	Severely heaving and separated safety surface is a potential tripping hazard.	SITE PLAYGROUN DS Safety Surfacing	Schoolyard	Anthony Gaustella	Fireman	

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

K854

No	Tripping Hazard	Missing pavers is a potential tripping hazard.	SITE PLAYGROUN DS Pavement	Schoolyard	Anthony Gaustella	Fireman
----	-----------------	--	--------------------------------	------------	-------------------	---------



Structural Engineer Required

Structural Condition Type	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	PhotoImage
---------------------------	-----------------------	--------------------	----------------------	--------------------	-----------------	------------

No condition recorded

Programmatic Accessibility

Programmatic Accessibility Status Question	Response
Is the primary or secondary entrance on an accessible route?	Yes
Is the building a multi-story building?	No
Do any of the following spaces exist? Classroom, Art Room, Auditorium, Cafeteria, Computer, Gymnasiums, Library, Multipurpose Room, Science Labs	Yes
For the spaces that do exist, are they ALL accessible?	Yes
Is there at least one Boys and Girls or Unisex toilet accessible in the building	Yes

Physical Breakdown Structure	Exists	Required	Complies	Deficiency	Assistive Fire Listening Alarm System	Strobe
------------------------------	--------	----------	----------	------------	---------------------------------------	--------

PROGRAMMATIC ACCESSIBILITY

Exterior Routes

Exterior Entrances & Exits			Yes		
Exterior H/C Lifts	No	No			
Exterior Ramps and Railings	No	No			

Interior Routes

Corridor and Lobby H/C Lifts	No	No			
Interior Corridor Doors and Hardware	Yes		Yes		
Interior Corridors and Lobbies			Yes		
Interior Elevators	No				
Interior Lobby Doors and Hardware			Yes		
Interior Ramps	No				

Rooms & Spaces

Art Rooms	No
Auditorium	No
Cafeteria	No
Classrooms	No
Computer Rooms	No
Gymnasium	No
Library	No
Main Office	No
Multi-purpose Room	No
Nurse's Room	No
Pool	No
Science Lab	No


NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

K854

Physical Breakdown Structure	Exists	Required	Complies	Deficiency	Assistive Listening System	Fire Alarm Strobe
Rooms & Spaces						
Toilet Rooms (Boys)	No					
Toilet Rooms (Girls)	No					
Toilet Rooms (Staff)	Yes		Yes			

Building Template




Inspection

Question	Response
Architectural	
EXTERIOR	Inspected
AREAWAY	Does not Exist
AWNINGS AND CANOPIES	Does not Exist
CHIMNEY	Does not Exist
COPING	Inspected
Condition	4 - Between Fair and Poor

Deficiency CAST STONE: DETERIORATED BED JOINT

Roof Plan reference



Deficiency Quantity

40

Quantity Uom

L.F.

Potential Action

REPOINT

Urgency of Action

PRIORITY 3

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K854

Question

Response

EXTERIOR

COPING

Purpose of Action
Deficiency Photo1

LEVEL 2



Roof 1

No violations recorded.


Violations

Deficiency

Roof Plan reference

CAST STONE: DISINTEGRATING / FREEZE THAW

K854



Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action
Deficiency Photo1


100

L.F.

REPLACE-IN-KIND

PRIORITY 4

LEVEL 4



Roof 1

35674658P

Violations

Deficiency

CAST STONE: DETERIORATED TRANSVERSE JOINTS

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K854


Question

Response

EXTERIOR

COPING

Roof Plan reference



Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action
Deficiency Photo1

100
L.F.
MAINTENANCE
PRIORITY 3
LEVEL 2




Roof 1
No violations recorded.

Violations

Deficiency

CAST STONE: CRACKED/BROKEN PIECES

Roof Plan reference





Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action


50
L.F.
REPLACE-IN-KIND
PRIORITY 4
LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K854

Question	Response
EXTERIOR	
COPING	
Deficiency Photo1	
Violations	Roof 1 No violations recorded.
CORNICE	Does not Exist
DOORS	Inspected
DOORS AND FRAMES	Inspected
Condition	3 - Fair
Deficiency	METAL: DETERIORATED DOOR - MINOR DETERIORATION
Roof Plan reference	K854
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Facade A No violations recorded.
DOOR HARDWARE	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
LINTELS	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded



**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K854

Question	Response
----------	----------

EXTERIOR

DOORS	Inspected
--------------	-----------

TRANSOM/SIDE LIGHT	Inspected
---------------------------	-----------

Condition	2 - Between Good and Fair
-----------	---------------------------

Deficiency	No deficiencies recorded
------------	--------------------------

EXTERIOR WALLS	Inspected
-----------------------	-----------

Material Type(s)	Masonry
------------------	---------

Replacement Quantity	6,000
----------------------	-------

Replacement Uom	S.F.
-----------------	------

Instance on All Facades	Inspected
-------------------------	-----------


Instance Condition	4 - Between Fair and Poor
--------------------	---------------------------

Instance Quantity	6,000
-------------------	-------

Instance Quantity Uom	S.F.
-----------------------	------

Deficiency	CONCRETE MASONRY UNIT: MASONRY SILLS - DETERIORATED JOINTS
------------	--

Roof Plan reference



Elevation



Deficiency Quantity

10

Quantity Uom

L.F.

Potential Action

REPOINT

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade A

No violations recorded.

Violations

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K854

Question

Response

EXTERIOR

EXTERIOR WALLS


Deficiency

Roof Plan reference


Inspected

CONCRETE MASONRY UNIT: DETERIORATED JOINTS

K854



Elevation



Deficiency Quantity

35

Quantity Uom

S.F.

Potential Action

REPOINT


Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 4

Deficiency Photo1



Facade E

35674658P


Violations

Deficiency

Roof Plan reference

CONCRETE MASONRY UNIT: MAJOR / THRU CRACKS

K854



**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K854

Question

Response

EXTERIOR

EXTERIOR WALLS

Elevation



Deficiency Quantity

30

Quantity Uom

S.F.

Potential Action

REMOVE AND REBUILD

Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade F


No violations recorded.

Violations

Deficiency

CONCRETE MASONRY UNIT: DETERIORATED CONTROL/EXPANSION JOINTS

Roof Plan reference



Elevation



Deficiency Quantity

40

Quantity Uom

L.F.

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K854

Question


Response

EXTERIOR

EXTERIOR WALLS

Potential Action
Urgency of Action
Purpose of Action
Deficiency Photo1

MAINTENANCE
PRIORITY 3
LEVEL 2



Facade F


No violations recorded.

Violations


Deficiency

CONCRETE MASONRY UNIT: MINOR CRACKS AND SPALLING

Roof Plan reference




Elevation



Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action
Deficiency Photo1




50
S.F.
RESTITCH
PRIORITY 3
LEVEL 4



**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



K854

Question	Response
EXTERIOR	
EXTERIOR WALLS	Inspected
Violations	Facade F 35674658P
EXTERIOR SOFFITS	Does not Exist
LOADING DOCK	Does not Exist
LOUVER	Inspected
Condition	3 - Fair
Deficiency	BROKEN/ DENTED BLADES
Roof Plan reference	K854 
Elevation	
Deficiency Quantity	60
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Facade B No violations recorded.
PARAPETS	Inspected
Material Type(s)	Masonry
Replacement Quantity	500
Replacement Uom	C.F.
Instance on Roof 1	Inspected
Instance Condition	2 - Between Good and Fair

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection




K854

Question	Response
EXTERIOR	
PARAPETS	Inspected
Instance Quantity	500
Instance Quantity Uom	C.F.
Deficiency	No deficiencies recorded
PLAZA DECK	Does not Exist
ROOF	Inspected
Roofing	Inspected
Replacement Quantity	10,900
Replacement Uom	S.F.
ROOF HATCH/SMOKE HATCH	Does not Exist
LEADERS, GUTTERS, DOWNSPOUTS, SCUPPERS	Does not Exist
ROOF BARRIER/FENCE	Inspected
Condition	3 - Fair
Deficiency	BEAR CLAW/METAL BAR: DETERIORATED, MAJOR RUSTING
Roof Plan reference	<p>K854</p> 
Deficiency Quantity	40
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Roof 1 No violations recorded.
ROOF CAGE	Does not Exist
ROOFING	Inspected
Instance on Built-Up: Roof 1	Inspected
Instance Condition	3 - Fair

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K854

Question	Response
EXTERIOR	
ROOF	
Roofing	
ROOFING	
Instance Photo	
	Roof 1
Instance Quantity	10,900
Instance Quantity Uom	S.F.
Does the roof have major mechanical equipment sitting on Dunnage Steel less than 18" above the Roofing?	No
Does this roof instance have a Sustainable Roof System?	No
Do solar panels exist on these roofs?	No
Is/Are the roof(s) suitable for Solar Panel installation?	Yes
Installation Year	1998
Source of Installation	Custodial Staff
Deficiency	BUILT-UP: ROOFING: LOSS OF GRAVEL
Roof Plan reference	K854 
Deficiency Quantity	80
Quantity Uom	S.F.
Potential Action	INSTALL NEW GRAVEL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Roof 1
Violations	No violations recorded.
ROOFING DRAINS	
Condition	Inspected
Deficiency	3 - Fair DETERIORATED

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

K854

Question	Response
----------	----------

EXTERIOR


ROOF

Roofing

ROOFING DRAINS

Roof Plan reference

Deficiency Quantity
 Quantity Uom
 Potential Action
 Urgency of Action
 Purpose of Action
 Deficiency Photo1



1
 EACH
 REPLACE
 PRIORITY 4
 LEVEL 2



Roof 1
 No violations recorded.

Violations

Specialties

Does not Exist

STAIRS/RAMPS: EXTERIOR

Inspected

BUILDING CHEEK/FLANK WALLS

Does not Exist

RAILINGS

Inspected

Condition

2 - Between Good and Fair

Deficiency

No deficiencies recorded

STAIRS/RAMPS

Inspected


Condition

3 - Fair

Deficiency

CONCRETE: CRACKS/SPALLING - MAJOR

Roof Plan reference



Deficiency Quantity

15

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection



K854

Question	Response
EXTERIOR	
STAIRS/RAMPS: EXTERIOR	
STAIRS/RAMPS	
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Facade B No violations recorded.
WINDOWS	
	Inspected
Replacement Quantity	1,000
Replacement Uom	S.F.
EXTERIOR GUARDS	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
LINTELS	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
WINDOWS	
	Inspected
Material Type(s)	Aluminum
Instance on Aluminum - Other: Facades A, B, H	Inspected
Instance Condition	3 - Fair
Instance Quantity	1,000
Instance Quantity Uom	S.F.
Are these windows insulated	Yes
Installation Year	1998
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
INTERIOR	
	Inspected
POOLS	
	Does not Exist
STRUCTURAL	
	Inspected
COLUMNS/BEAMS/BEARING WALLS	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
FLOOR STRUCTURE	
	Inspected
Condition	3 - Fair
Deficiency	CONCRETE SLAB ON GRADE: THRU CRACKS
Deficiency Location/Instance	1st Floor
Deficiency Quantity	15
Quantity Uom	S.F.

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K854

Question	Response
INTERIOR	
STRUCTURAL	
FLOOR STRUCTURE	
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 5
Deficiency Photo1	
	Room 7
Violations	No violations recorded.
Deficiency	CONCRETE SLAB ON GRADE: THRU CRACKS
Deficiency Location/Instance	1st Floor
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 5
Deficiency Photo1	
	Room 7
Violations	No violations recorded.
FOUNDATION WALLS	
Material Type(s)	Inspected Concrete
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
ROOF STRUCTURE	
Condition	Inspected 3 - Fair
Deficiency	CONCRETE: CRACKED/SPALLED/REINFORCEMENT EXPOSED
Deficiency Location/Instance	Facade A
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPAIR
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 5

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K854

Question	Response
INTERIOR	
STRUCTURAL	
ROOF STRUCTURE	
Deficiency Photo1	
Violations	Facade A No violations recorded.
VAULTS-BUNKERS	Does not Exist
AUDITORIUM	Does not Exist
CAFETERIA	Does not Exist
CLASSROOMS/CORRIDORS/ADMIN SPACES	Inspected
Ceiling	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Door(s)	Inspected
Condition	5 - Poor
Deficiency	WOOD: DETERIORATED DOOR
Deficiency Location/Instance	Room 16
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 16 No violations recorded.
Floor Finish	Inspected
Condition	2 - Between Good and Fair
Deficiency	VINYL TILES: BROKEN/DETERIORATED/MISSING TILES
Deficiency Location/Instance	Room 8, 16, Corridor near Room 12
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection


K854

Question	Response
INTERIOR	
CLASSROOMS/CORRIDORS/ADMIN SPACES	
Floor Finish	
Deficiency Photo1	
Violations	Room 16 No violations recorded.
Walls	Inspected
Condition	2 - Between Good and Fair
Deficiency	GYP SUM BOARD: DETERIORATED
Deficiency Location/Instance	Room 16
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 16 No violations recorded.
Specialties	Does not Exist
GYMNASIUM	Does not Exist
INTERIOR DOOR HARDWARE	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
INTERIOR GUARDS	Does not Exist
KITCHEN	Does not Exist
LIBRARY	Does not Exist
LOCKER ROOM	Does not Exist
MULTI-PURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SHOWER ROOM	Does not Exist
STAIRS/RAMPS: INTERIOR	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K854

Question	Response
INTERIOR	
TOILET ROOMS - STAFF	Inspected
Ceiling	Does not Exist
Door(s)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Floor Finish	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Stalls	Inspected
Condition	5 - Poor
Deficiency	RUST - MAJOR
Deficiency Location/Instance	Room 12, 10
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 12 No violations recorded.
Walls	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOMS - STUDENTS	Does not Exist
LIFE SAFETY	Inspected
F.D. HOLDING AREA	Does not Exist
STEEL STAIRS	Does not Exist
SITE	Inspected
CONTAINERIZATION	Does not Exist
Drainage System for Asphalt	Inspected
Catch Basins/Manhole - Surrounded by asphalt	Inspected
Condition	2 - Between Good and Fair
Deficiency	DAMAGED COVER
Deficiency Location/Instance	Playground
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K854

Question	Response
SITE	
Drainage System for Asphalt	
Catch Basins/Manhole - Surrounded by asphalt	
Deficiency Photo1	
Violations	No violations recorded.
Culverts - Asphalt Covering	Does not Exist
Drainage System for Concrete	Inspected
Catch Basins/Manhole - Surrounded by concrete	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Culverts - Concrete Covering	Does not Exist
Drainage System for Soil	Inspected
Catch Basins/Manhole - Surrounded by Soil	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Culverts - Soil Covering	Does not Exist
DRINKING FOUNTAINS	Does not Exist
FENCES	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
IRRIGATION SYSTEM	Does not Exist
PAVING	Inspected
Student Non-Use	Does not Exist
Student Use	Does not Exist
Site Sidewalks & Walkways	Does not Exist
DOT Sidewalk	Inspected
Asphalt	Does not Exist
Concrete	Inspected
Condition	4 - Between Fair and Poor
Deficiency	DAMAGED CURBS
Deficiency Location/Instance	Along Park Place
Deficiency Quantity	60
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K854

Question	Response
SITE	
PAVING	
DOT Sidewalk	
Concrete	
Deficiency Photo1	
Violations	Along Park Place No violations recorded.
Deficiency	DAMAGED/DETERIORATED/MISSING SECTIONS
Deficiency Location/Instance	Along Park Place
Deficiency Quantity	500
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Along Park Place No violations recorded.
Pavers	Does not Exist
PLAYGROUNDS	Inspected
Instance on Park place	Inspected
Benches	
Instance on Park place	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fence	
Instance on Park place	Does not Exist
Pavement	
Instance on Park place	Inspected
Condition	3 - Fair
Deficiency	PAVERS: DAMAGED/MISSING
Deficiency Location/Instance	Schoolyard
Deficiency Quantity	60
Quantity Uom	S.F.
Potential Action	REPLACE

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



K854

Question	Response
SITE	
PLAYGROUNDS	
Pavement	
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	
	Schoolyard
Violations	No violations recorded.
Play Equipment	
Instance on Park place	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Safety Surfacing	
Instance on Park place	Inspected
Condition	3 - Fair
Deficiency	DETERIORATED/MISSING
Deficiency Location/Instance	Schoolyard
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	
	Schoolyard
Violations	No violations recorded.
Unpaved Area	
Instance on Park place	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
PLAYING SURFACE	
	Does not Exist
RETAINING WALLS	
Are there any Retaining Walls 6' OR higher facing public street/sidewalk?	No
Condition	2 - Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K854

Question	Response
SITE	
RETAINING WALLS	
Deficiency	CAST IN PLACE CONCRETE: DETERIORATED CONTROL/EXPANSION JOINT
Deficiency Location/Instance	Along Park Place
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Along Park Place No violations recorded.
SEATING	Does not Exist
SITE WALLS (NOT RETAINING WALLS)	Inspected
Condition	2 - Between Good and Fair
Deficiency	CAST IN PLACE CONCRETE: CRACKS/SPALLING - MAJOR
Deficiency Location/Instance	Along Park Place
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Along Park Place No violations recorded.
STAIRS/RAMPS: EXTERIOR	Does not Exist
ARTWORK	Does not Exist