Building Condition Assessment Survey 2023 - 2024

Inspection Id Inspection Type		Time In	Last Edited
EE: K892 Electrical		2024-01-30 8:27 AM	2024-02-12 1:37 PM
sset Data			
Question	Answer		
Type of Service	Below Groun	d	
Does Interactive Whiteboard (IWB) Exist?	Yes		
Water Penetration in Electrical Room?	No		
Have any Systems/Major Building Components been upgraded?	Yes		
	•	Partial Molded Case Circuit Brea	aker Type Panel Board
		2023	
		Fire Alarm System	
		2017	
		Interior Fluorescent Lighting	
		2013 Samulton Limban	
		Security Lights 2006	
		Public Address System	
		2000	
DEDICATED INTERCOMS IN FIRE RESCUE AREAS	Tours	2000	
Question	Response		
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No		
riority Condition			
No condition recorded aspection			
Question	Response		
Electrical			
AUDITORIUM	Does not E	xist	
CAFETERIA	Does not E	xist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected		
Lighting	Inspected		
Does a Chandelier exist?	No		
Lighting Fixture - Fluorescent	Inspected		
Pendant Mounted	Inspected		
Condition	2 - Between	n Good and Fair	
Deficiency	No deficien	ncies recorded	
Surface Mounted	Inspected		
Condition	2 - Between	n Good and Fair	
Deficiency		ncies recorded	
Recessed Mounted	Does not E	xist	
Lighting Fixture - HID	Does not E	xist	
Lighting Fixture - Incandescent	Does not E	xist	
Lighting Fixture - LED	Does not E	xist	
		vist	
COMPUTER LAB	Does not E	Alst	
COMPUTER LAB GYMNASIUM	Does not E		
-		xist	
GYMNASIUM	Does not E	xist	

Building Condition Assessment Survey 2023 - 2024

uestion	Response		
LIBRARY	Response		
LOCKER ROOM	Does not Exist		
MULTIPURPOSE ROOM			
	Does not Exist		
SCIENCE DEMO ROOM	Does not Exist		
SCIENCE LAB	Does not Exist		
SCIENCE PREP ROOM	Does not Exist		
SWIMMING POOL	Does not Exist		
TOILET ROOM - STAFF	Inspected		
Lighting	Inspected		
Lighting Fixture - Fluorescent	Inspected		
Pendant Mounted	Does not Exist		
Surface Mounted	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
Recessed Mounted	Does not Exist		
Lighting Fixture - HID	Does not Exist		
Lighting Fixture - Incandescent	Does not Exist		
Lighting Fixture - LED	Does not Exist		
TOILET ROOM - STUDENT	Inspected		
Lighting	Inspected		
Lighting Fixture - Fluorescent	Inspected		
Pendant Mounted	Does not Exist		
Surface Mounted	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
Recessed Mounted	Does not Exist		
Lighting Fixture - HID	Does not Exist		
Lighting Fixture - Incandescent	Does not Exist		
Lighting Fixture - LED	Does not Exist		
AUXILIARY SIGNAL/BELL SYSTEM	Inspected		
Replacement Quantity	9,000		
Replacement Uom	S.F.		
Condition	3 - Fair		
Deficiency	No deficiencies recorded		
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist		
EMERGENCY GENERATOR SET	Does not Exist		
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist		
EMERGENCY LIGHTING	Inspected		
Battery Pack	Inspected		
Condition	3 - Fair		
Deficiency	No deficiencies recorded		
Non Battery Pack	Does not Exist		
EXIT LIGHT	Inspected		
Battery Pack	Inspected		
Condition	3 - Fair		
Deficiency	No deficiencies recorded		
Non Battery Pack	Does not Exist		
EXIT/EMERGENCY LIGHT	Does not Exist		

Building Condition Assessment Survey 2023 - 2024

estion	Response		
XIT/EMERGENCY LIGHT	Does not Exist		
TRE ALARM SYSTEM	Inspected		
Replacement Quantity	9,000	9,000	
Replacement Uom	S.F.	S.F.	
Bell/Horn	Inspected	Inspected	
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
Strobe	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
Manual Pull Station	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
Fan Shutdown Control	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
Duct Smoke Detector	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
Area Smoke Detector	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
CO Detector	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
Heat Detector	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
Elevator Recall	Does not Exist		
Magnetic Door Holder/Contactor	Does not Exist		
Fused Cutout Panel	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
Fire Alarm Digital Communicator	Does not Exist		
Main Panel	Inspected		
Bell At Panel	Does not Exist		
Fire Alarm Control Panel (Electronic)	Inspected		
Instance	Main Entrance Lobby		
Instance Condition	2 - Between Good and Fair		
Instance Quantity	1		
Instance Quantity Uom	EACH	EACH	
Instance Manufacturer	Edwards System Technology		
Equipment	Main Building Fire Alarm Contro	l Panel	
Model	EST3X		
Installation Year	2017		
Source of Installation	Custodial Staff		
Deficiency	No deficiencies recorded		
Fire Alarm Control Panel (Standard)	Does not Exist		
Sub-Panel	Does not Exist		
Remote Annunciator	Inspected		

Building Condition Assessment Survey 2023 - 2024

Question	Response
FIRE ALARM SYSTEM	Inspected
Remote Annunciator	
Display Monitor	Does not Exist
Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Does not Exist
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Does not Exist
Tamper Flow Switch/Chain	Does not Exist
GROUNDING SYSTEM	Does not Exist
INTERCOM SYSTEM	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Does not Exist
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Does not Exist
PANEL BOARD	
	Inspected
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Room 008
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	9,000
Replacement Uom	S.F.
Instance	Connected to Main Asset K221
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	2000
Source of Installation	Inspector Estimate
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	10
Quantity Uom	EACH
Quantity Uom	EACH

Building Condition Assessment Survey 2023 - 2024

ctrical Inspection		K8	
euestion	Response		
PUBLIC ADDRESS SYSTEM			
Potential Action	REPLACE		
Urgency of Action	PRIORITY 3		
Purpose of Action	LEVEL 2		
Deficiency Photo1	No photo recorded		
Violations	No violations recorded.	No violations recorded.	
SECURITY	Inspected		
IPDVS/CCTV System	Does not Exist		
Intrusion Alarm System	Inspected		
Replacement Quantity	9,000		
Replacement Uom	S.F.		
Central Control Panel	Inspected		
Instance	Room 001		
Instance Condition	3 - Fair		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Model	Vista-128B		
Installation Year	1996		
Source of Installation	Inspector Estimate		
Deficiency	No deficiencies recorded		
Infrared Sensor	Inspected		
Condition	3 - Fair		
Deficiency	No deficiencies recorded		
Panic Switch	Inspected		
Condition	3 - Fair		
Deficiency	No deficiencies recorded		
Remote Annunciator	Inspected		
Condition	3 - Fair		
Deficiency	No deficiencies recorded		
Siren/Strobe	Inspected		
Condition	3 - Fair	*	
Deficiency	No deficiencies recorded		
Lighting - Security	Inspected		
Replacement Uom	EACH		
Condition	3 - Fair		
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE		
Deficiency Location/Instance	Exterior Wall facing Main Asset K221		
Deficiency Quantity	2		
Quantity Uom	EACH		
Potential Action	REPLACE BALLAST		
Urgency of Action	PRIORITY 2		
Purpose of Action	LEVEL 3		
Deficiency Photo1	No photo recorded		
Violations	No violations recorded.		
SERVICE SWITCH	Does not Exist		
SWITCHBOARD	Does not Exist		
TELEPHONE SYSTEM	Inspected		
PBX/Intercom	Inspected		
Condition	3 - Fair	3 - Fair	

Building Condition Assessment Survey 2023 - 2024

uestion	Response	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
FRANSFORMER	Does not Exist	