Building Condition Assessment Survey 2023 - 2024

Mechanical Inspection

Inspection Id Inspection Type		Time In	Last Edited
ME : K905 Mechanical		2023-12-19 12:28 PM	2023-12-29 3:33 PM
set Data			
Question	Answer		
Are there fuel tanks?	Yes		
Total # of above ground tanks	1		
Total capacity of all above ground tanks in gal.	275		
Total # of below ground tanks	0		
Total capacity of all below ground tanks in gal.	0		
Total # of water main service entries to the asset	1		
MERs/Fan Rooms Locations	MER 007		
Are there any spaces with Missing or Defective CO Detectors?	No		
Are there any Emergency Stop Switches with Missing Hammers?	No		
Are there any Painted/Obstructed Sprinkler Heads?	No		
Have any Systems/Major Building Components been upgraded?	Yes		
	Systems:	Enclosed IDF Room - Dedicated Split System); Fixtures - Student	
	Years:	2022	
	Systems:	Gas Fired Domestic Water Heate Drinking Fountains	r; Fixtures - Student:
	Years:	2018	
	Systems:	Electric Pressure Booster System	L
	Years:	2013	
	Systems:	Gas Fired Furnaces	
	Years:	2012	

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
Yes	Defective CO/Gas Leak Detection	Control Panel in Fault Mode	GAS SERVICE CO/Gas Leak Detection	MER 007	Vincent Bianco	Handyman	Sent to DSF	

spection		
Question	Response	
Mechanical		
AIR CONDITIONING	Inspected	
Chilled Water System	Does not Exist	
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not Exist	
Cooling Coil in Ductwork	Does not Exist	
Cooling Tower	Does not Exist	
DX Split System	Does not Exist	
Dry Cooler	Does not Exist	
Packaged / Rooftop Unit	Inspected	
Instance	Building Addition Roof	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Source of Heating Refrigerant Type	Gas R-22	
Instance Manufacturer	Trane	

estion	Response	
IR CONDITIONING	Каронас	
Packaged / Rooftop Unit		
Equipment	AC-3	
Capacity/Size Quantity	2	
Capacity/Size UOM	Tons	
Source of Capacity/Size	Inspector Estimate	
Installation Year	2002	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Instance	Building Addition Roof	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Source of Heating	Gas	
Refrigerant Type	R-22	
Instance Manufacturer	Trane	
Equipment	AC-4	
Capacity/Size Quantity	6	
Capacity/Size UOM	Tons	
Source of Capacity/Size	Inspector Estimate	
Installation Year	2002	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Instance	Building Addition Roof	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Source of Heating Refrigerant Type	Gas R-22	
Instance Manufacturer	Trane	
Equipment	AC-5	
Capacity/Size Quantity	4	
Capacity/Size UOM	Tons	
Source of Capacity/Size	Inspector Estimate	
Installation Year	2002	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Instance	MER 007	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Source of Heating	N/A	
Refrigerant Type	R-22	
Instance Manufacturer	KOLDWAVE.	
Equipment	AC-1	
Capacity/Size Quantity	10	
Capacity/Size UOM	Tons	
Source of Capacity/Size	Custodial Staff	
Installation Year	1997	
Source of Installation	Documented	

uestion	Response
AIR CONDITIONING	•
Packaged / Rooftop Unit	
Deficiency	No deficiencies recorded
Instance	MER 007
Instance Condition	4 - Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Source of Heating Refrigerant Type	N/A R-22
Instance Manufacturer	KOLDWAVE.
Equipment	AC-2
Capacity/Size Quantity	15
Capacity/Size UOM	Tons
Source of Capacity/Size	Custodial Staff
Installation Year	1997
Source of Installation	Documented
Deficiency	UP TO 20 TONS: DEFECTIVE CONTROLS
Deficiency Location/Instance	MER 007 / AC-2 (defective volume damper actuator)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	UP TO 20 TONS: DEFECTIVE COMPRESSOR
Deficiency Location/Instance	MER 007
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Packaged Terminal A/C	Does not Exist
Refrigerant Leak Detection System	Does not Exist
Refrigerant Piping	Does not Exist
Return Fan	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not Exist
CLIMATE CONTROL SYSTEM	Does not Exist
COMPACTOR	Does not Exist
CONVEYING	Does not Exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not Exist
Pressure Booster System	Inspected
Electric Pressure Booster System	Inspected

stion	Response	
OMESTIC WATER SYSTEM		
Domestic Cold Water System		
Pressure Booster System		
Electric Pressure Booster System		
Instance	Room 007B	
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	A. O. Smith	
Equipment	N/A	
Capacity/Size Quantity	1	
Capacity/Size UOM	Total # Pumps	
Capacity/Size2 Quantity	1	
Capacity/Size2 UOM	Total Pumps HP	
Source of Capacity/Size	Documented	
Installation Year	2013	
Source of Installation	Inspector Estimate	
Deficiency	No deficiencies recorded	
Hydraulic/Pneumatic Booster System	Does not Exist	
Water Service	Inspected	
Instance	Room 007B	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Deficiency	No deficiencies recorded	
Domestic Hot Water System	Inspected	
Domestic Hot Water Remote Storage Tank	Does not Exist	
Domestic Water Heat Exchanger	Does not Exist	
Electric Domestic Water Heater	Does not Exist	
Heat Pump Domestic Water Heater	Does not Exist	
Gas Fired Domestic Water Heater	Inspected	
Instance	MER 007	
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	A.O. Smith	
Equipment	N/A	
Capacity/Size Quantity	75	
Capacity/Size UOM	MBH Input	
Capacity/Size2 Quantity	98	
Capacity/Size2 UOM	Gallons	
Source of Capacity/Size	Documented	
Installation Year	2018	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Oil Fired Domestic Water Heater	Does not Exist	
Domestic Water Distribution Piping	Inspected	
Condition	2 - Between Good and Fair	

Building Condition Assessment Survey 2023 - 2024

Mechanical Inspection

iestion	Desponse
	Response
DOMESTIC WATER SYSTEM	
Domestic Water Distribution Piping	MED 007
Deficiency Location/Instance	MER 007 10
Deficiency Quantity	
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3 LEVEL 2
Purpose of Action	
Deficiency Photo1 Violations	No photo recorded No violations recorded.
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	2 - Between Good and Fair
Deficiency	INTERIOR FLOOR DRAIN: DEFECTIVE
Deficiency Location/Instance	1st Floor Tank Maintenance Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	SEWAGE/WASTE PIPING: DEFECTIVE/LEAKS
Deficiency Location/Instance	1st Floor Tank Maintenance Room
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Sewage Ejector Pump	Does not Exist
Sump Pump	Does not Exist
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT VATER)	Does not Exist
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

uestion	Response
FIXTURES	
Staff And Other	Inspected
Urinal	Does not Exist
Student	Inspected
Drinking Fountain	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3 - Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ET
Deficiency Location/Instance	Boys Toilet Room 008
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Locker Room Shower	Does not Exist
Sink And Fountain Combo Unit	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	4 - Between Fair and Poor
Deficiency	CRACKED/PHYSICAL DAMAGE
Deficiency Location/Instance	Girls Toilet Room 009
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Urinal	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
GAS FIRED FURNACE	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
GAS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Does not Exist
Gas Meter Room Vent	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Gas Pressure Booster	Does not Exist

uestion	Response	
GAS SERVICE	-	
CO/Gas Leak Detection		
Instance	MER 007, Gas Service Room 108	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Installation Year	2009	
Source of Installation	Inspector Estimate	
Deficiency	DEFECTIVE CONTROL PANEL	
Deficiency Location/Instance	MER 007	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
HEATING	Inspected	
Heating Coil In Ductwork	Does not Exist	
Hydronic Heating	Does not Exist	
Radiator/Convector/Fin Tube	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Steam Heating	Does not Exist	
Steam supplied by External Sources	Does not Exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
HEATING PLANT	Does not Exist	
Enclosed IDF Room	Inspected	
Instance on Closet inside General Office	Inspected	
Dedicated A/C Equipment	Inspected	
Instance on Closet inside General Office	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
KITCHEN	Does not Exist	
MDF Room	Does not Exist	
SCIENCE DEMO ROOM	Inspected	
Instance on Rooms 001, 002	Inspected	
Alternative use	No	
Acid Waste Neutralizing Tank	Does not Exist	
Instance on Rooms 001, 002	Does not Exist	
CO Detector	Not Required	
Instance on Rooms 001, 002	Not Required	
Emergency Shower	Does not Exist	
Instance on Rooms 001, 002	Does not Exist	
Eye Wash	Does not Exist	
Instance on Rooms 001, 002	Does not Exist	
Hood Exhaust Ductwork	Does not Exist	

iestion	Response	
SCIENCE DEMO ROOM		
Hood Exhaust Ductwork	Does not Exist	
Instance on Rooms 001, 002	Does not Exist	
Hood Exhaust Fan	Does not Exist	
Instance on Rooms 001, 002	Does not Exist	
Fixed Laboratory Hood	Does not Exist	
Instance on Rooms 001, 002	Does not Exist	
Laboratory Sink	Inspected	
Instance on Rooms 001, 002	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Make-up Air Unit	Does not Exist	
Instance on Rooms 001, 002	Does not Exist	
SCIENCE LAB	Does not Exist	
SCIENCE PREP ROOM	Does not Exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Does not Exist	
SWIMMING POOL	Does not Exist	
VENTILATION	Inspected	
Is the building mechanically ventilated?	Yes	
Exhaust Fan	Inspected	
Approximate Total # of Fans	1-25	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Does not Exist	
Metal Ductwork	Inspected	
Are there any uninsulated ductwork by design in Mechanical	V	
Rooms? Are there chain operated dampers?	Yes No	
Condition	3 - Fair	
Deficiency	DEFECTIVE REGISTER/DIFFUSER	
Deficiency Location/Instance	Student's Toilet Room 103	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Deficiency	DAMAGED/MISSING INSULATION	
Deficiency Location/Instance	MER 007	
Deficiency Quantity	10	
Quantity Uom	L.F.	
Potential Action	L.F. MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	LEVEL 2 No photo recorded	
Violations	No violations recorded.	
v iolauolis	no violations recorded.	