

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K907

Asset: BROWNSVILLE DIPLOMA PLUS HS - K, 1150 EAST NEW YORK AVE, New York, 11212

Inspection Id	Inspection Type	Time In	Last Edited
EE : K907	Electrical	2024-02-02 8:22 AM	2024-06-20 1:59 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Intercom System (Elevator)
	Years: 2023
	Systems: Most Exit Lights (Battery Pack)
	Years: 2021
	Systems: Intrusion Alarm System - Except (Panic Switch, Siren/Strobe)
	Years: 2019
	Systems: Fire Alarm System (Heat Detector), LAN, Telephone System
	Years: 2016
	Systems: Public Address System - Except (Clocks)
	Years: 2013
	Systems: IPDVS/CCTV System
	Years: 2011
	Systems: Fire Alarm System (Main Panel, Remote Annunciator Panel, Printer)
	Years: 2009
	Systems: Security Lights
	Years: 1994, 2016
	Systems: Molded Case Circuit Breaker Type Panel Board
	Years: 1994, 2009, 2016, 2019
	Systems: All Other Electrical Systems and Components
	Years: 1994

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
Yes	Fire Alarm System - Components Not Operational	N/A	FIRE ALARM SYSTEM Fire Alarm Digital Communicator	Telephone Room 109	Jose Garcia	Custodian	Sent to DSF	

Inspection

Question	Response
Electrical	
AUDITORIUM	Does not Exist
CAFETERIA	Inspected
Instance on Basement - Staff	Inspected
Instance on Basement - Students	Inspected
Lighting	Inspected
Instance on Basement - Students	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K907

Question	Response
CAFETERIA	
Lighting	
Instance on Basement - Staff	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement - Students	Inspected
Instance on Basement - Staff	Inspected
Pendant Mounted	
Instance on Basement - Students	Does not Exist
Instance on Basement - Staff	Does not Exist
Surface Mounted	
Instance on Basement - Students	Does not Exist
Instance on Basement - Staff	Does not Exist
Recessed Mounted	
Instance on Basement - Students	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	70
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Basement - Staff	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	
Instance on Basement - Students	Does not Exist
Instance on Basement - Staff	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement - Students	Does not Exist
Instance on Basement - Staff	Does not Exist
Lighting Fixture - LED	
Instance on Basement - Students	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K907

Question	Response
CAFETERIA	
Lighting	Inspected
Lighting Fixture - LED	
Instance on Basement - Staff	Does not Exist
Local Sound System	Does not Exist
Instance on Basement - Students	Does not Exist
Instance on Basement - Staff	Does not Exist
Projection System	Does not Exist
Instance on Basement - Students	Does not Exist
Instance on Basement - Staff	Does not Exist
Theater Lighting System	Does not Exist
Instance on Basement - Students	Does not Exist
Instance on Basement - Staff	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	58
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	38
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	747

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K907

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
COMPUTER LAB	
	Inspected
Instance on Room 209	Inspected
Power Panel	No
Lighting	Inspected
Instance on Room 209	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 209	Inspected
Pendant Mounted	
Instance on Room 209	Does not Exist
Surface Mounted	
Instance on Room 209	Does not Exist
Recessed Mounted	
Instance on Room 209	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	11
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	
Instance on Room 209	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 209	Does not Exist
Lighting Fixture - LED	
Instance on Room 209	Does not Exist
Raceway With Receptacles	
Instance on Room 209	Does not Exist
GYMNASIUM	
	Does not Exist
KITCHEN	
	Inspected
Instance on Basement	Inspected
Lighting	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K907

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not Exist
Surface Mounted	
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	31
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	
Instance on Basement	Does not Exist
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
LIBRARY	
Instance on Room 300	Inspected
Lighting	
Instance on Room 300	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 300	Inspected
Pendant Mounted	
Instance on Room 300	Does not Exist
Surface Mounted	
Instance on Room 300	Does not Exist
Recessed Mounted	
Instance on Room 300	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	9
Quantity Uom	EACH

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K907

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	100
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	
Instance on Room 300	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 300	Does not Exist
Lighting Fixture - LED	
Instance on Room 300	Does not Exist
Raceway With Receptacles	
Instance on Room 300	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 300	Does not Exist
LOCKER ROOM	
Instance on 1st Floor	Inspected
Alternative use	Yes
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not Exist
Surface Mounted	
Instance on 1st Floor	Does not Exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K907

Question	Response
LOCKER ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	13
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Inspected
Instance on Room 302	Inspected
Power Panel	No
Alternative use	No
Lighting	Inspected
Instance on Room 302	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 302	Inspected
Pendant Mounted	
Instance on Room 302	Does not Exist
Surface Mounted	
Instance on Room 302	Does not Exist
Recessed Mounted	
Instance on Room 302	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K907

Question	Response
SCIENCE DEMO ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	
Instance on Room 302	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 302	Does not Exist
Lighting Fixture - LED	
Instance on Room 302	Does not Exist
Emergency Gas Shut-Off Valve	
Instance on Room 302	Does not Exist
Emergency Shut-Off Power	
Instance on Room 302	Does not Exist
Power Supply	
Instance on Room 302	Inspected
Instructor Unit	
Instance on Room 302	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 302	Does not Exist
Projection System	
Instance on Room 302	Does not Exist
SCIENCE LAB	
Instance on Room 201	Inspected
Power Panel	Yes
Alternative use	No
Lighting	
Instance on Room 201	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 201	Inspected
Pendant Mounted	
Instance on Room 201	Does not Exist
Surface Mounted	
Instance on Room 201	Does not Exist
Recessed Mounted	
Instance on Room 201	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K907

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	18
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	
Instance on Room 201	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 201	Does not Exist
Lighting Fixture - LED	
Instance on Room 201	Does not Exist
Emergency Gas Shut-Off Valve	
Instance on Room 201	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 201	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 201	Inspected
Instructor Unit	
Instance on Room 201	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 201	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Room 201	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 201	Does not Exist
SCIENCE PREP ROOM	
Instance on Room 201A	Inspected
Power Panel	No
Alternative use	No
Lighting	
Instance on Room 201A	Inspected
Lighting Fixture - Fluorescent	

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K907

Question	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Room 201A	Inspected
Pendant Mounted	Does not Exist
Instance on Room 201A	Does not Exist
Surface Mounted	Does not Exist
Instance on Room 201A	Does not Exist
Recessed Mounted	Inspected
Instance on Room 201A	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	
Instance on Room 201A	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 201A	Does not Exist
Lighting Fixture - LED	
Instance on Room 201A	Does not Exist
Emergency Gas Shut-Off Valve	Does not Exist
Instance on Room 201A	Does not Exist
Emergency Shut-Off Power	Does not Exist
Instance on Room 201A	Does not Exist
Power Supply	Does not Exist
Instance on Room 201A	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	13
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

K907

Question	Response
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	36
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	68,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Kohler Power Systems
Equipment	Emergency Transfer Switch
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1994

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K907

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Kohler Power Systems
Equipment	Fire Alarm Transfer Switch
Capacity/Size Quantity	150
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1994
Source of Installation	Documented
Deficiency	No deficiencies recorded
Battery Charger	Does not Exist
Emergency Distribution Board	Inspected
Number of Spares	0
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	N/A
Capacity/Size Quantity	400
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	1994
Source of Installation	Documented
Deficiency	No deficiencies recorded
Molded Case Circuit Breaker Type	Does not Exist
Diesel	Does not Exist
Natural Gas	Inspected
Instance	Roof - Outdoor Generator Enclosure
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Kohler Power Systems
Equipment	Emergency Generator
Capacity/Size Quantity	100
Capacity/Size UOM	KVA
Capacity/Size2 Quantity	80
Capacity/Size2 UOM	KW
Capacity/Size3Quantity	278
Capacity/Size3 UOM	Amps

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K907

Question	Response
EMERGENCY GENERATOR SET	
Natural Gas	
Source of Capacity/Size	Nameplate
Installation Year	1994
Source of Installation	Documented
Deficiency	No deficiencies recorded
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Does not Exist
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Locker Room, Basement - Stair 4
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
EXIT/EMERGENCY LIGHT	Does not Exist
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	68,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
CO Detector	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K907

Question	Response
FIRE ALARM SYSTEM	
Heat Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Inspected
Instance	Telephone Room 109
Instance Condition	4 - Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Radionics
Equipment	Fire Control Panel
Installation Year	1994
Source of Installation	Documented
Deficiency	COMMUNICATOR NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	N/A
Model	EST 3
Installation Year	2009
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	2 - Between Good and Fair

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K907

Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	
Panel	Inspected
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	5 - Poor
Deficiency	PRINTER NOT OPERATIONAL
Deficiency Location/Instance	Telephone Room 109
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	
Elevator	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Holding Area	Does not Exist
LAN	
Local Distribution Frame (I/LDF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not Exist
PANEL BOARD	
Fused Disconnect Switch Type	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K907

Question	Response
PANEL BOARD	
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	3 - Fair
Deficiency	NO SPARE
Deficiency Location/Instance	Cafeteria, Corridor by Rooms (109, 201, 401)
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	
	Inspected
Replacement Quantity	68,000
Replacement Uom	S.F.
Instance	Room 106
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Bogen Quantum Multicom IP
Installation Year	2013
Source of Installation	Custodial Staff
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	14
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SECURITY	
	Inspected
IPDVS/CCTV System	
	Inspected
Replacement Quantity	68,000
Replacement Uom	S.F.
Installation Year	2011
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
Intrusion Alarm System	
	Inspected
Replacement Quantity	68,000
Replacement Uom	S.F.
Central Control Panel	
	Inspected
Instance	Principal's Office (Inside Closet)
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K907

Question	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	Inspected
Installation Year	2019
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Stroke	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Replacement Uom	EACH
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Main Entrance Canopy
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SERVICE SWITCH	
	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	RPB2
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1994
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	Floor Panels
Capacity/Size Quantity	1,200

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K907

Question	Response
SERVICE SWITCH	
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1994
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	Kitchen
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1994
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	Emergency
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1994
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	PPBR
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1994
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	RPB1
Capacity/Size Quantity	800

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K907

Question	Response
SERVICE SWITCH	
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1994
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	0
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	N/A
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	1994
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist