NYC Department of Education

Building Condition Assessment Survey 2023 - 2024

| Asset: P.S. 209 TRANSPORTABLE - K, 2609 EAST 7TH ST, New York, 11215 | | | | | | |
|--|--------------------------|-----------------------|---------------------------|-------------------------------|-------------------------------|-------------------|
| Inspection Id Inspection | 1 Туре | | | | Time In | Last Edited |
| ME: K941 Mechanica | al | | | | 2023-11-01 8:08 AM | 2023-11-06 4:27 P |
| set Data | | | | | | |
| Question | | | | Answer | | |
| Are there fuel tanks? | | | | No | | |
| Total # of water main service entries to the asset | | | | 0 | | |
| MERs/Fan Rooms Locations | | | | None | | |
| Are there any spaces with Missing or Defective CO Detectors? | | | | No | | |
| Are there any Emergency Stop Switches with Missing Hammers? Are there any Painted/Obstructed Sprinkler Heads? | | | | No No | | |
| Have any Systems/Major Building Components been upgraded? | | | | Yes | | |
| There any bysicins/Major Building components been apgraded. | | | Systems: | Electric Domestic Water Heate | er for T-1. T-2 | |
| | | | Years: | 2021 | | |
| | | | | Systems: | Electric Domestic Water Heate | er for T-3, T-4 |
| | | | | Years: | 2019 | |
| ority Condition | | | | | | |
| Priority Priority Condition Exist Category Last Year? | Condition Description | Component Affected | Location Description | Person(s) Notified | Person(s) Title Status | PhotoImage |
| No condition recorded | | | | | | |
| spection | | | | | | |
| Question | | | | Response | | |
| Mechanical | | | | | | |
| AIR CONDITIONING | | | | Inspected | | |
| Packaged Terminal A/C | | | | Inspected | | |
| Condition | | | | 3 - Fair | | |
| Deficiency | | | No deficiencies recorded | | | |
| Refrigerant Leak Detection System | | | Does not Exist | | | |
| DOMESTIC WATER SYSTEM | | | Inspected | | | |
| Domestic Hot Water System | | | | Inspected | | |
| Electric Domestic Water Heater | | | | Inspected | | |
| Condition | | | | 1 - Good | | |
| Deficiency | | | | No deficiencies recorded | | |
| Domestic Water Distribution Piping | | | | Inspected | | |
| Condition | | | | 2 - Between Good and Fair | | |
| Deficiency | | | | | riencies recorded | |
| DRAIN/WASTE/VENT AND STORM SYSTEM | | | | Inspecte | | |
| Sewage/Waste/Vent Piping | | | | Inspected | | |
| Condition | | | 2 - Between Good and Fair | | | |
| Deficiency | | | No deficiencies recorded | | | |
| Sewage Ejector Pump | | | Does not Exist | | | |
| FIXTURES | | | Inspected | | | |
| Staff And Other | | | | Does no | t Exist | |
| Student | | | Inspected | | | |
| Drinking Fountain | | | Does not Exist | | | |
| Lavatory/Sink | | | Inspected | | | |
| Lavatory/Sink | | | | | | |
| Lavatory/Sink Condition | | | | 3 - Fair | | |

NYC Department of Education

Building Condition Assessment Survey 2023 - 2024

K941 Mechanical Inspection Question Response **FIXTURES** Student Toilet Inspected Condition 3 - Fair Deficiency No deficiencies recorded Urinal Does not Exist HEATING Does not Exist **Enclosed IDF Room** Does not Exist VENTILATION Inspected Is the building mechanically ventilated? Yes **Exhaust Fan** Inspected Approximate Total # of Fans 1-25 Condition 3 - Fair Deficiency DEFECTIVE Deficiency Location/Instance Toilet Rooms in T-2, T-3, T-4 Deficiency Quantity **EACH** Quantity Uom Potential Action MAINTENANCE PRIORITY 3 Urgency of Action Purpose of Action LEVEL 2 Deficiency Photo1 No photo recorded Violations No violations recorded. **Metal Ductwork** Inspected Are there any uninsulated ductwork by design in Mechanical No Rooms? Are there chain operated dampers? No 3 - Fair Condition Deficiency DEFECTIVE REGISTER/DIFFUSER Deficiency Location/Instance Room T-2 **Deficiency Quantity** 1 Quantity Uom **EACH** Potential Action MAINTENANCE Urgency of Action PRIORITY 3 LEVEL 2 Purpose of Action Deficiency Photo1 No photo recorded Violations No violations recorded.