

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K982

Asset: P.S. 261 TRANSPORTABLE - K, 314 PACIFIC STREET, New York, 11210

Inspection Id	Inspection Type	Time In	Last Edited
EE : K982	Electrical	2024-02-08 8:36 AM	2024-03-18 9:52 AM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	No
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Intrusion Alarm System (Remote Annunciator)
	Years: 2015
	Systems: All Other Electrical Systems and Components
	Years: 1999

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
Yes	Emergency Lighting - Fixture Not Operational	N/A	EMERGENCY LIGHTING Battery Pack	T-1, T-2	Reinaldo Hernandez	Handyman	Sent to DSF	

Inspection

Question	Response
Electrical	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - LED	Does not Exist
COMPUTER LAB	Does not Exist
TOILET ROOM - STAFF	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K982

Question	Response
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	5 - Poor
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	T-1, T-2
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	35632042L, 35650883P
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Does not Exist
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	1,300
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Does not Exist
Duct Smoke Detector	Does not Exist
Area Smoke Detector	Does not Exist
CO Detector	Does not Exist
Fused Cutout Panel	Does not Exist
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	T-1
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards System Technology
Equipment	Fire Alarm System
Model	EST 2
Installation Year	1999
Source of Installation	Documented

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K982

Question	Response
FIRE ALARM SYSTEM	Inspected
Main Panel	Inspected
Fire Alarm Control Panel (Electronic)	
Deficiency	No deficiencies recorded
Remote Annunciator	Does not Exist
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
LAN	Does not Exist
PANEL BOARD	Inspected
Molded Case Circuit Breaker Type	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	1,300
Replacement Uom	S.F.
Instance	Connected to Main Asset K261
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	1999
Source of Installation	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	T-2
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SECURITY	Inspected
IPDVS/CCTV System	Does not Exist
Intrusion Alarm System	Inspected
Replacement Quantity	1,300
Replacement Uom	S.F.
Central Control Panel	Does not Exist
Infrared Sensor	Does not Exist
Panic Switch	Does not Exist
Remote Annunciator	Inspected
Condition	4 - Between Fair and Poor
Deficiency	ANNUNCIATOR NOT OPERATIONAL
Deficiency Location/Instance	T-2
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K982

Question	Response
SECURITY	
Intrusion Alarm System	
Remote Annunciator	Inspected
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Siren/Strobe	
Condition	Inspected
Deficiency	3 - Fair
Deficiency	No deficiencies recorded
Lighting - Security	
Replacement Uom	Inspected
Condition	EACH
Condition	4 - Between Fair and Poor
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Building Perimeter
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SERVICE SWITCH	
	Does not Exist
SWITCHBOARD	
Number of Spares	Inspected
	2
Fused Disconnect Switch Type	
Instance	Inspected
Instance Condition	Outdoor Electrical Enclosure
Instance Quantity	3 - Fair
Instance Quantity Uom	1
Instance Manufacturer	EACH
Equipment	Siemens
Capacity/Size Quantity	N/A
Capacity/Size UOM	400
Capacity/Size2 Quantity	Amps Total
Capacity/Size2 UOM	1
Source of Capacity/Size	Section(S)
Installation Year	Switchboard Mains Size
Source of Installation	1999
Deficiency	Documented
	No deficiencies recorded
Molded Case Circuit Breaker Type	
	Does not Exist
TELEPHONE SYSTEM	
	Inspected
PBX/Intercom	
Condition	Inspected
Condition	3 - Fair
Deficiency	TELEPHONE MISSING
Deficiency Location/Instance	T-1
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL TELEPHONE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

K982

Question	Response
TELEPHONE SYSTEM	
PBX/Intercom	Inspected
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Standard	Does not Exist