# **Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection K995

Asset:	LEARNING SUPPORT CENTER - BROOKLYN, 5613 FLATLANDS AVE, New York,
	11234

Inspection Id	Inspection Type		Time In	Last Edited
EE : K995	Electrical		2023-12-13 8:01 AM	2024-01-02 11:11 AM
sset Data				
Question		Answer		
Type of Service		Below Gro	und	
Does Interactive	Whiteboard (IWB) Exist?	No		
Water Penetration	n in Electrical Room?	No		
Have any System	s/Major Building Components been upgraded?	Yes		
		Systems:	Computer Lab (Raceway With R Alarm System (Panic Switch)	deceptacles), Intrusion
		Years:	2017	
		Systems:	Fire Alarm System	
		Years:	2016	
		Systems:	All Other Electrical Systems and	Components
		Years:	2003	

#### DEDICATED INTERCOMS IN FIRE RESCUE AREAS

DEDICATED INTERCOMS IN FIRE RESCUE AREAS			
Question	Response		
Are there any Life Rescue Assistance Areas, Fire Rescue Areas,	No		
and/or Holding Rooms in your building?			

#### Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
Yes	Water Leaks onto Electrical Equipment	N/A	Electrical Outlet, Lighting Fixture	Basement - Waiting Room B	Jason Ortiz	Fireman	Sent to DSF	

# Inspection

uestion	Response		
lectrical			
AUDITORIUM	Does not Exist		
CAFETERIA	Does not Exist		
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected		
Lighting	Inspected		
Does a Chandelier exist?	No		
Lighting Fixture - Fluorescent	Inspected		
Pendant Mounted	Does not Exist		
Surface Mounted	Inspected		
Condition	3 - Fair		
Deficiency	No deficiencies recorded		
Recessed Mounted	Inspected		
Condition	3 - Fair		
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE		
Deficiency Quantity	5		
Quantity Uom	EACH		
Potential Action	REPLACE BALLAST		
Urgency of Action	PRIORITY 3		
Purpose of Action	LEVEL 2		
Deficiency Photo1	No photo recorded		
Violations	No violations recorded.		

# **Building Condition Assessment Survey 2023 - 2024**

urear inspection		
nestion	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - HID	Does not Exist	
<b>Lighting Fixture - Incandescent</b>	Does not Exist	
Lighting Fixture - LED	Does not Exist	
COMPUTER LAB	Inspected	
Instance on Room 003	Inspected	
Power Panel	No	
Lighting	Inspected	
Instance on Room 003	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 003	Inspected	
Pendant Mounted	Does not Exist	
Instance on Room 003	Does not Exist	
Surface Mounted	Does not Exist	
Instance on Room 003	Does not Exist	
Recessed Mounted	Inspected	
Instance on Room 003	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 003	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Room 003	Does not Exist	
Lighting Fixture - LED		
Instance on Room 003	Does not Exist	
Raceway With Receptacles	Inspected	
Instance on Room 003	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
GYMNASIUM	Does not Exist	
KITCHEN	Does not Exist	
JBRARY	Does not Exist	
LOCKER ROOM	Does not Exist	
MULTIPURPOSE ROOM	Does not Exist	
CIENCE DEMO ROOM	Does not Exist	
CIENCE LAB	Does not Exist	
SCIENCE PREP ROOM	Does not Exist	
SWIMMING POOL	Does not Exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not Exist	
Surface Mounted	Does not Exist	
Recessed Mounted	Inspected	
Condition	3 - Fair	
Deficiency Lighting Fixture - HID	No deficiencies recorded	

# **Building Condition Assessment Survey 2023 - 2024**

uestion	Response
TOILET ROOM - STAFF	Inspected
Lighting	•
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Does not Exist
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	
	Does not Exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Does not Exist
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	24,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected  2 - Between Good and Fair
Condition Deficiency	No deficiencies recorded
CO Detector	Does not Exist
Heat Detector  Condition	Inspected  2 - Between Good and Fair
	2 - Between Good and Fair  No deficiencies recorded
Deficiency Elevator Recall	
Condition	Inspected  2 - Between Good and Fair
Deficiency	2 - Between Good and Fair  No deficiencies recorded
Magnetic Door Holder/Contactor	Does not Exist

# **Building Condition Assessment Survey 2023 - 2024**

inear hispection	II.
nestion	Response
FIRE ALARM SYSTEM	
Fused Cutout Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Does not Exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Basement - Electrical & Sprinkler Control Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards System Technology
Equipment	Fire Alarm Control Panel
Model	EST
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Does not Exist
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Holding Area	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Does not Exist
Main Equipment Rack (MDF)	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
	The deliteration recorded
LIGHTNING PROTECTION	Does not Exist
LIGHTNING PROTECTION MOTOR CONTROLLER	Does not Exist  Does not Exist

# **Building Condition Assessment Survey 2023 - 2024**

Question	Response
PANEL BOARD	
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Does not Exist
SECURITY	Inspected
IPDVS/CCTV System	Does not Exist
Intrusion Alarm System	Inspected
Replacement Quantity	24,000
Replacement Uom	S.F.
Central Control Panel	Inspected The Paris of the Pari
Instance	Telecommunication Room (Next to Room 137)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3 - Fair
Deficiency Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	2 - Between Good and Fair
Deficiency Remote Annunciator	No deficiencies recorded
Condition	Inspected 3 - Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Replacement Uom	EACH
Condition	4 - Between Fair and Poor
Deficiency	LIGHTING FIXTURE PHOTOCELL NOT OPERATIONAL
Deficiency Location/Instance	Exterior Walls facing parking lot
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SERVICE SWITCH	Does not Exist
SWITCHBOARD	Inspected
Simonius	Inspected

# **Building Condition Assessment Survey 2023 - 2024**

nestion	Response	
SWITCHBOARD		
Fused Disconnect Switch Type	Inspected	
Instance	Basement - Electrical & Sprinkler Control Room	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	All City Switchboard	
Equipment	N/A	
Capacity/Size Quantity	1,200	
Capacity/Size UOM	Amps Total	
Capacity/Size2 Quantity	1	
Capacity/Size2 UOM	Section(S)	
Source of Capacity/Size	Inspector Estimate	
Installation Year	2003	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not Exist	
Molded Case Circuit Breaker Type	Does not Exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
FRANSFORMER	Does not Exist	