Building Condition Assessment Survey 2023-2024

Electrical Inspection

Asset:	P.S. 2 - MANI	HATTAN, 122 HENRY ST	REET, MANHATTA	AN, NY, 10002			
Inspection Id	Inspection Type	2			Time In		Last Edited
208	1 ELECTRICAL				2024-01-03	08:57AM	2024-01-23 02:01PM
sset Data							
Question				Answer			
Have any Systems/Major Building Components been upgraded?			?	Systems:	Gymnasium (LED I (Partial Battery Pack) Non Battery Pack), Panic Switch)	x), Emergen	cy Lighting (Partial
				Years:	2023		
				Systems:	Most Lighting - Sec	urity	
				Years:	2016, 2008		
				Systems:	LAN (MDF)		
				Years:	2014		
				Systems:	Alarm System Exce Switch)		xcept Kitchen), Fire r Flow/Air Pressure
				Years:	2011		
				Systems:	Molded Case Circui	t Breaker Pa	anel Board
				Years:	2008, 2002, 1995		
				Systems:	Service Switch, Swi	tchboard	
				Years:	2008		
				Systems:	Kitchen (Surface Flu	uorescent Li	ighting)
				Years:	2007	T 10	10
				Systems:	Public Address Syst 2004	em, Local S	ound System
				Years:		tam	
				Systems: Years:	2001	tem	
				Systems:	Emergency Light/Ex	rit Light Pa	nel
				Years:	1990	the English I al	
Type of Servi	ce			Below G			
	ive Whiteboard (IW	B) Exist?		Yes			
	tion In Electrical R	· · · · · · · · · · · · · · · · · · ·		No			
DEDICATE	D INTERCOMS	S IN FIRE RESCUE AREA	AS				
Question					Response		
your buildir	ng?	istance Areas, Fire Rescue Area	as, and/or Holding Roon	ms in	No		
riority Condu		Condition	C +	Lost	Domo(-) P	aan(-) •	Dhata
	•iority ategory	Condition Description	Component Affected	Location Description	Person(s) Person Notified Title	()	Photo Image
No condition				2 comption	The first second	- •	
nspection							
Question				Response			
Electrical				Kesponse	~		
	C FIFI D			Does not	exist		
ATHLETIC FIELD AUDITORIUM				Inspected			
-	IUM Instance on Baseme	ent		Inspected			
House Li		-111		mspected	•		
	gnung Instance on Baseme	ent		Inspected			
	Does a Chandelier I			No			
	g Fixture - Fluores			-			
-	Instance on Baseme			Inspected	l		
Penda	ant Mounted			-			
-	Instance on Baseme	ent		Does not	exist		

Surface Mounted

Building Condition Assessment Survey 2023-2024

estion	Response	
UDITORIUM		
House Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement	Does not exist	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Inspected	
Pendant Mounted	inspected	
Instance on Basement	Does not exist	
	Does not exist	
Surface Mounted Instance on Basement	Dass not avist	
	Does not exist	
Recessed Mounted	Y . 1	
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	36 FACH	
Quantity Uom	EACH REPLACE-UPGRADE	
Potential Action	PRIORITY 1	
Urgency of Action Purpose of Action	LEVEL 2	
Violations	LEVEL 2 No violations recorded	
	No violations recorded	
Lighting Fixture - LED Instance on Basement	Does not exist	
	Does not exist	
Local Sound System Instance on Basement	Inspected	
Instance Condition	3- Fair	
Installation Year	2004	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Is the projector on a cart or installed on the ceiling?	Cart	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on Basement	Inspected	
Dimming System		
Instance on Basement	Does not exist	
Theater Lighting		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	24	
Quantity Uom	24 EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
AFETERIA	Inspected	

Building Condition Assessment Survey 2023-2024

	D	
uestion	Response	
CAFETERIA	T 1	
Instance on Basement	Inspected	
Lighting	T (1	
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement	Does not exist	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Does not exist	
Local Sound System		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Installation Year	2004	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Basement	Does not exist	
	Does not exist	
Theater Lighting System Instance on Basement	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Inspected	
Instance on Room 207		
	Inspected	
Power Panel?	Yes	
Lighting	·	
Instance on Room 207	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 207	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

ical Inspection		MUU
uestion	Response	
COMPUTER LAB		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Instance on Room 207	Does not exist	
Surface Mounted		
Instance on Room 207	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 207	Does not exist	
Lighting Fixture - HID		
Instance on Room 207	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 207	Does not exist	
Lighting Fixture - LED		
Instance on Room 207	Does not exist	
Raceway With Receptacles		
Instance on Room 207	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
GYMNASIUM	Inspected	
Instance on Basement	Inspected	
Lighting		
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement	Does not exist	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Basement	Does not exist	
Recessed Mounted		
Instance on Basement	Does not exist	
Local Sound System		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Installation Year	2004	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Basement	Does not exist	
Scoreboard		
Instance on Basement	Does not exist	
Theater Lighting System		
Instance on Basement	Does not exist	
KITCHEN	Inspected	

Building Condition Assessment Survey 2023-2024

uestion	Response	
	Kesponse	
KITCHEN	In sector 1	
Instance on Basement	Inspected	
Lighting Instance on Basement	Inspected	
Lighting Fixture - Fluorescent	nispected	
Instance on Basement	Inspected	
Pendant Mounted	nispected	
Instance on Basement	Does not exist	
	Does not exist	
Surface Mounted	In sec. et al.	
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement	Does not exist	
Lightin <u>g</u> Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Does not exist	
LIBRARY	Inspected	
Instance on Room 222	Inspected	
Lighting	mperce	
Instance on Room 222	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 222	Inspected	
Pendant Mounted	hispeeted	
Instance on Room 222	Does not exist	
Surface Mounted	Does not exist	
Instance on Room 222	Increased	
	Inspected 3- Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 222	Does not exist	
Lighting Fixture - HID		
Instance on Room 222	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 222	Does not exist	
Lighting Fixture - LED		
Instance on Room 222	Does not exist	
Raceway With Receptacles		
Instance on Room 222	Does not exist	
Projection System		
Instance on Room 222	Does not exist	
LOCKER ROOM	Inspected	
Instance on 1st Floor - Girls	Inspected	
Alternative Use	Yes	
Instance on Basement - Boys	Inaccessible	
	maccession	
Lighting Instance on 1st Floor - Girls	Inspected	
	Inspected	
Lighting Fixture - Fluorescent	T 1	
Instance on 1st Floor - Girls	Inspected	
Pendant Mounted Instance on 1st Floor - Girls	Does not exist	

Building Condition Assessment Survey 2023-2024

uestion	Response
LOCKER ROOM	A A A A A A A A A A A A A A A A A A A
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on 1st Floor - Girls	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor - Girls	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor - Girls	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Girls	Inspected
Pendant Mounted	1
Instance on 1st Floor - Girls	Does not exist
Surface Mounted	
Instance on 1st Floor - Girls	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on 1st Floor - Girls	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor - Girls	Does not exist
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
FOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected Does not exist
Pendant Mounted	
Surface Mounted	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

Building Condition Assessment Survey 2023-2024

Electrical Inspection

rical Inspection	M00
Question	Response
TOILET ROOM - STAFF	
Lighting	
Lighting Fixture - Incandescent	
Recessed Mounted	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	ALARM INDICATOR AT THE INDICATOR PANEL NOT
	OPERATIONAL
Deficiency Location/Instance	Room C1
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Electrical Room C8
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance Deficiency Quantity	Electrical Room C8
Quantity Uom	EACH
Potential Action	MAINTENANCE

Building Condition Assessment Survey 2023-2024

M002

-	
uestion	Response
EMERGENCY LIGHT/EXIT LIGHT PANEL	
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	By Stair E/Basement
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	Inspected
Area Smoke Detector Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
	Does not exist
Heat Detector	Does not exist
Elevator Recall Magnetic Deer Helder/Contactor	Does not exist
Magnetic Door Holder/Contactor Fused Cutout Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Inspected
Instance	Room C10
Instance Condition	2- Between Good and Fair

Building Condition Assessment Survey 2023-2024

Electrical Inspection

icui Inspection		IVIUU.
uestion	Response	
FIRE ALARM SYSTEM		
Fire Alarm Digital Communicator		
Instance Quantity Uom	EACH	
Manufacturer	Ademco	
EquipmentId	Sprinkler System DACT	
Installation Year	2011	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	General Electric	
Model	EST 2	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2011	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
ROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
NTERCOM SYSTEM	Does not exist	
AN	Inspected	
	Inspected	
Local Distribution Frame (I/LDF) Condition	3- Fair	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
JGHTNING PROTECTION	Does not exist	
AOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Does not exist	

NYC Department of Education Building Condition Assessment Survey 2023-2024

M002

ricai Inspeciion	MIOO
uestion	Response
MOTOR CONTROLLER	
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 122
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland TC2100
Installation Year	2004
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room B11
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	2001
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inaccessible
SERVICE SWITCH	Inspected
Instance	Electrical Room C8
Instance Instance Condition	2- Between Good and Fair
Instance Condition	
	L EACH
Instance Quantity Uom	
Manufacturer	Boltswitch Main Service Switch 2000 Amp
EquipmentId Capacity/Size Quantity	2000

NYC Department of Education Building Condition Assessment Survey 2023-2024

Electrical Inspection

D	
Response	
Amps	
Fuse Size	
2008	
Documented	
No deficiencies recorded	
Inspected	
4	
Inspected	
Electrical Room C8	
2- Between Good and Fair	
1	
EACH	
Siemens	
Section 4, Section 5	
2000	
Amps Total	
2	
Section(s)	
Service Switch Fuse Size	
2008	
Documented	
No deficiencies recorded	
Does not exist	
Does not exist	
Inspected	
Inspected	
3- Fair	
No deficiencies recorded	
Inspected	
3- Fair	
No deficiencies recorded	
Does not exist	
	Fuse Size 2008 Documented No deficiencies recorded Inspected 4 Inspected Electrical Room C8 2- Between Good and Fair 1 EACH Siemens Section 4, Section 5 2000 Amps Total 2 Section(s) Service Switch Fuse Size 2008 Documented No deficiencies recorded Does not exist Does not exist Inspected Inspected Inspected Ja- Fair No deficiencies recorded Inspected Ja- Fair No deficiencies recorded