Building Condition Assessment Survey 2023-2024

Flactrical Inspaction

Asset:	P.S. 3 - MANHATTAN, 490 HUDSON STREET, MAN	NHATTAN, NY, 10014		
Inspection Id	Inspection Type		Time In	Last Edited
2050	ELECTRICAL		2024-01-02 08:53AM	2024-01-23 01:57PM
et Data				
Question		Answer		
Have any Systems/Major Building Components been upgraded?		Systems:	Most Emergency Light - Battery lighting)	Pack, Kitchen (LED
		Years:	2022	
		Systems:	Security Lighting	
		Years:	2021	
		Systems:	Exit Lights (Battery Pack)	
		Years:	2019	
		Systems:	Public Address System (Partial S	peakers)
		Years:	2017	
		Systems:	Molded Case Circuit Breaker Par	nel Boards
		Years:	2013, 2002, 2000, 1984	
		Systems:	Fire Alarm System, Cafeteria (Lo Exit/Emergency Lighting	cal Sound System),
		Years:	2013	
		Systems:	Science Lab Room 510 (Except I Multipurpose Room	Fluorescent Lighting),
		Years:	2008	
		Systems:	Interior Fluorescent Lighting (Ex Room, Kitchen)	cept Multipurpose
		Years:	2004	
		Systems:	Service Switch, Switchboard	
		Years:	2003,1984	
		Systems:	Emergency Light/Exit Panel	
		Years:	2003	
		Systems:	Intrusion Alarm System	
		Years:	2001	
Type of Service		Below Gr	ound	

Does Interactive Whiteboard (IWB) Exist? Water Penetration In Electrical Room?

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question

Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Water Leaks onto Electrical Equipment	Plaza Deck Leak, Pipe Leak	Lighting Fixture	Corridor near Stair G/1, Room 410	Robinson Reyes	Custodian	No Photo Taken
No	Emergency Lighting - Not Operational	12 Batteries are Not Operational Throughout the Building, All Batteries are not Operational in Auditorium	Emergency Lighting	Throughout the Building	Robinson Reyes	Custodian	No Photo Taken

Yes

No

Response

No

Question	Response	
Clectrical		
ATHLETIC FIELD	Does not exist	
AUDITORIUM	Does not exist	
CAFETERIA	Inspected	
Instance on 1st Floor	Inspected	

Building Condition Assessment Survey 2023-2024

uestion	Response	
CAFETERIA	Response	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted	miljoudu	
Instance on 1st Floor	Does not exist	
Surface Mounted	Does not exist	
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2013	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	15	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Does not exist	
GYMNASIUM	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting	IIIspecieu	

Building Condition Assessment Survey 2023-2024

uestion	Response	
KITCHEN		
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
IBRARY	Inspected	
Instance on Room 311	Inspected	
Lighting		
Instance on Room 311	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 311	Inspected	
Pendant Mounted		
Instance on Room 311	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 311	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 311	Does not exist	
Lighting Fixture - HID		
Instance on Room 311	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 311	Does not exist	
Lighting Fixture - LED		
Instance on Room 311	Does not exist	
	DOGS HOL CALST	
Raceway With Receptacles Instance on Room 311	Does not exist	
	DOGS HOL CAISI	
Projection System Instance on Room 311	Does not exist	
OCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Inspected	
Instance on 1st Floor	Inspected	

Building Condition Assessment Survey 2023-2024

lestion	Response	
AULTIPURPOSE ROOM	Response	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	inspected	
Instance on 1st Floor	Inspected	
Pendant Mounted	hispected	
Instance on 1st Floor	Does not exist	
Surface Mounted	Doos not exist	
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL	
Deficiency Quantity	35	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
	No violations recorded	
Lighting Fixture - HID	Does not exist	
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent	D	
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System	D	
Instance on 1st Floor	Does not exist	
Theater Lighting System	T / 1	
Instance on 1st Floor	Inspected	
Dimming System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
CIENCE DEMO ROOM	Does not exist	
CIENCE LAB	Inspected	
Instance on Room 510	Inspected	
Power Panel?	Yes	
Alternative Use	Yes	
	105	
Lighting Instance on Room 510	Inspected	
Lighting Fixture - Fluorescent	Inspected	

Building Condition Assessment Survey 2023-2024

uestion	Response	
SCIENCE LAB	······································	
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Instance on Room 510	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 510	Does not exist	
Recessed Mounted		
Instance on Room 510	Does not exist	
Lighting Fixture - HID		
Instance on Room 510	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 510	Inspected	
Pendant Mounted	inspected	
Instance on Room 510	Does not exist	
Surface Mounted	Does not exist	
Instance on Room 510	To average d	
	Inspected 3- Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 510	Does not exist	
Lighting Fixture - LED		
Instance on Room 510	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 510	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 510	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Room 510	Inspected	
Instructor Unit		
Instance on Room 510	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Room 510	Does not exist	
Student Unit		
Instance on Room 510	Does not exist	
Projection System		
Instance on Room 510	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
CIENCE PREP ROOM	Inspected	
Instance on Room 304	Inspected	
Power Panel?	No	
Alternative Use	Yes	
Lighting	105	
Instance on Room 304	Inspected	
Lighting Fixture - Fluorescent	inspecied	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

in tear inspection		111000
Question	Response	
SCIENCE PREP ROOM		
Lighting		
Lighting Fixture - Fluorescent		
Instance on Room 304	Inspected	
Pendant Mounted		
Instance on Room 304	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 304	Does not exist	
Recessed Mounted		
Instance on Room 304	Does not exist	
Lighting Fixture - HID		
Instance on Room 304	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 304	Does not exist	
Lighting Fixture - LED		
Instance on Room 304	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 304	Does not exist	
Emergency Shut-Off Power		
Instance on Room 304	Does not exist	
Power Supply		
Instance on Room 304	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Lighting Fixture - HID	Does not exist	
Eighting Fixture - IIID	Does not exist Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - Incandescent Lighting Fixture - LED	Does not exist Does not exist Does not exist	
Lighting Fixture - Incandescent	Does not exist Does not exist	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
•		
EMERGENCY LIGHTING	Inspected	
Battery Pack Condition	Inspected 3- Fair	
Deficiency	BATTERY NOT OPERATIONAL	
Deficiency Location/Instance	Throughout the Building	
Deficiency Quantity	12	
Quantity Uom	EACH	
Potential Action	REPLACE BATTERY	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Inspected	
Condition	4- Between Fair and Poor	
Deficiency	FIXTURE NOT OPERATIONAL	
Deficiency Location/Instance	By Exit 6	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

	11100
Response	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Does not exist	
Does not exist	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Does not exist	
Inspected	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
Main Entrance Lobby	
2- Between Good and Fair	
1	
EACH	
Edwards System Technology	
EST3X	
Fire Alarm Control Panel	
2013	
Documented	
No deficiencies recorded	
Does not exist	
Does not exist	
Inspected	
Does not exist	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Does not exist	
Does not exist	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
Does not exist	
Does not exist	
Inspected	
Inspected Inspected	
Inspected Inspected 3- Fair	
Inspected Inspected 3- Fair No deficiencies recorded	
Inspected Inspected 3- Fair	
	2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Does not exist Inspected 2- Between Good and Fair No deficiencies recorded Does not exist Inspected 2- Between Good and Fair No deficiencies recorded Does not exist Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected Main Entrance Lobby 2- Between Good and Fair 1 EACH Edwards System Technology EST3X Fire Alarm Control Panel 2013 Documented No deficiencies recorded Does not exist Inspected 2- Between Good and Fair No deficiencies recorded Does not exist Inspected 2- Between Good and Fair No deficiencies recorded

Building Condition Assessment Survey 2023-2024

Electrical Inspection

Response Does not exist Inspected Does not exist Inspected 3- Fair No deficiencies recorded Does not exist Inspected Does not exist Inspected Does not exist Inspected Does not exist Does not exist Data not exist
Inspected Does not exist Inspected 3- Fair No deficiencies recorded Does not exist Inspected Does not exist Does not exist Inspected
Does not exist Inspected 3- Fair No deficiencies recorded Does not exist Inspected Does not exist Does not exist Inspected Inspected Inspected
Inspected 3- Fair No deficiencies recorded Does not exist Inspected Does not exist Does not exist Inspected
3- Fair No deficiencies recorded Does not exist Inspected Does not exist Does not exist Inspected
No deficiencies recorded Does not exist Inspected Does not exist Does not exist Inspected
Does not exist Inspected Does not exist Does not exist Inspected Inspected
Inspected Does not exist Does not exist Inspected
Does not exist Does not exist Inspected
Does not exist Inspected
Inspected
3- Fair
PANEL BOARD BEYOND USEFUL LIFE
Boiler Room
1
EACH
REPLACE-UPGRADE
PRIORITY 1
LEVEL 2
No violations recorded
Inspected
3- Fair
PANEL BOARD COVER IS MISSING
Room 101A, Boiler Room
1
EACH
MAINTENANCE
PRIORITY 2
LEVEL 2
No violations recorded
PANEL BOARD DOOR LOCK IS MISSING
Boiler Room
2
EACH
MAINTENANCE
PRIORITY 2
LEVEL 2
No violations recorded
PANEL BOARD DOOR LOCK IS MISSING
Corridor near Room 409
1
EACH
MAINTENANCE
PRIORITY 3
LEVEL 2
No violations recorded
PANEL BOARD COVER IS MISSING
Corridor near Room 509
1
EACH
MAINTENANCE
MAINTENANCE PRIORITY 3
MAINTENANCE PRIORITY 3 LEVEL 2
MAINTENANCE PRIORITY 3

Building Condition Assessment Survey 2023-2024

Electrical Inspection

1	
uestion	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 201
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland Telecenter IV
Installation Year	1985
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	General Office - Room 201
Deficiency Quantity	101,000
Quantity Uom	S.F.
Potential Action	S.F. REPLACE
	PRIORITY 1
Urgency of Action Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Storage Room By Custodian's Office
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	2001
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Does not exist
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected

Building Condition Assessment Survey 2023-2024

Electrical Inspection

rical Inspection	MU
uestion	Response
SECURITY	
Lighting - Security	
Condition	1- Good
Deficiency	LIGHTING FIXTURE PHOTOCELL NOT OPERATIONAL
Deficiency Location/Instance	By Exits 1, 2, 5
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	N/A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	I.T.E.
EquipmentId	N/A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1984
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	10
Fused Disconnect Switch Type	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	MDP-1
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	
Capacity/Size 2 UOM Source of Capacity/Size	Section(s)
	Nameplate 2003
Installation Year Source of Installation Year	2003 Documented
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Instance Quantity Uom	EACH	
Manufacturer	I.T.E. Imperial Corp.	-
EquipmentId	N/A	
Capacity/Size Quantity	800	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	1984	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
FELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
FRANSFORMER	Does not exist	

BCAS Partners Version 2.0 (P)