Building Condition Assessment Survey 2023-2024

Asset:	P.S. 9 - MANHA	TTAN, 100 WEST 84 ST	REET, MANHAT	TAN, NY, 10024	<u> </u>		
Inspection	Id Inspection Type				Time	In	Last Edited
1:	584 ELECTRICAL				2023-	12-11 09:11AN	И 2024-06-03 01:47F
sset Data							
Question				Answer			
Have any Systems/Major Building Components been upgraded?				Systems:	Cafeteria and	Gymnasium Lo	cal Sound Systems
·				Years:	2024		
				Systems:	Intrusion Alar	m System (Rem	note Annunciator)
				Years:	2023, 2020		
				Systems:	Intrusion Alar Infrared Senso	•	tral Control Panel, Partial
				Years:	2023		
				Systems:	Exit Lights (B	attery Pack), Li	ighting - Security
				Years:	2022		
				Systems:	Fluorescent in	ED Lighting (Ex Auditorium and	ccept Gymnasium, Pendan d Library)
				Years:	2021	a a: :: b	
				Systems:			reaker Panel Board
				Years:		007, 2001, 1990	
				Systems:	Emergency Li System, LAN		on Battery Pack), Partial Pack), Library, Telephone
				Years:	2018		
				Systems:		LED Lighting)	
				Years:	2016	_	
				Systems:		s System (Exce	pt Clocks)
				Years:	2015		
				Systems: Years:	Science Lab - 2012	Room 326	
				Systems: Years:	,	Local Sound System), IPDVS/C	
				Systems:		Theater Lighting	System)
				Years:	2007	inewer Eighting	, 2, 5, 5, 5, 5, 5, 5, 5, 5, 5, 5, 5, 5, 5,
				Systems:		endant Fluoresc	ent Lighting
				Years:	2001	ondani i raorese	ont Digitting
					Intrusion Alar	m System	
				Years:	1999		
				Systems:		ght/Exit Light I	Panel
				Years:	1994	8	
Type of Ser	vice			Below G	round		
	ctive Whiteboard (IWB)	Exist?		Yes			
Water Pene	tration In Electrical Room	n?		No			
DEDICA	TED INTERCOMS I	N FIRE RESCUE AREAS	S				
Question					Response		
Are there your buil	•	nce Areas, Fire Rescue Areas,	, and/or Holding Room	ms in	No		
riority Con	dition						
	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
	Emergency Lighting - Not Operational	30 Batteries are Not Operational	Emergency Lighting	Throughout the Building	Antonio Otero	Fireman	No Photo Taken
nspection							
Question				Response	e		
Electrical							

Building Condition Assessment Survey 2023-2024

ical Inspection		M
uestion	Response	
AUDITORIUM	Inspected	
Instance on 1st Floor	Inspected	
House Lighting		
Instance on 1st Floor	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2010	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Inspected	
Dimming System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
CA PETERNA	Inchested	

CAFETERIA

Instance on 1st Floor

Inspected

Inspected

Electrical Inspection	M009
Question	Response

Question	Response			
CAFETERIA				
Lighting				
Instance on 1st Floor	Inspected			
Lighting Fixture - Fluorescent				
Instance on 1st Floor	Does not exist			
Lighting Fixture - HID				
Instance on 1st Floor	Does not exist			
Lighting Fixture - Incandescent				
Instance on 1st Floor	Does not exist			
Lighting Fixture - LED				
Instance on 1st Floor	Inspected			
Pendant Mounted				
Instance on 1st Floor	Does not exist			
Surface Mounted				
Instance on 1st Floor	Inspected			
Instance Condition	2- Between Good and Fair			
Deficiency	No deficiencies recorded			
Recessed Mounted				
Instance on 1st Floor	Does not exist			
Local Sound System				
Instance on 1st Floor	Inspected			
Instance Condition	1- Good			
Installation Year	2024			
Source of Installation Year	Custodial Staff			
Deficiency	No deficiencies recorded			
Projection System				
Instance on 1st Floor	Does not exist			
Theater Lighting System				
Instance on 1st Floor	Does not exist			
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected			
Lighting	Inspected			
Does a Chandelier Exist?	No Does not exist			
Lighting Fixture - Fluorescent	Does not exist Does not exist			
Lighting Fixture - HID	Does not exist Does not exist			
Lighting Fixture - Incandescent	Inspected			
Lighting Fixture - LED	Inspected			
Pendant Mounted Condition	2- Between Good and Fair			
Deficiency	No deficiencies recorded			
	Inspected			
Surface Mounted Condition	2- Between Good and Fair			
Deficiency	No deficiencies recorded			
Recessed Mounted	Inspected			
Condition	2- Between Good and Fair			
	No deficiencies recorded			
Deficiency				
COMPUTER LAB	Inspected			
Instance on Room 226	Inspected			
Power Panel?	Yes			
Instance on Room 317	Inspected			
Power Panel?	Yes			
Lighting				
Instance on Room 226	Inspected			
Instance on Room 317	Inspected			
Lighting Fixture - Fluorescent				

Duestion	Response	
COMPUTER LAB		
Lighting		
Lighting Fixture - Fluorescent		
Instance on Room 317	Does not exist	
Instance on Room 226	Does not exist	
Lighting Fixture - HID		
Instance on Room 317	Does not exist	
Instance on Room 226	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 317	Does not exist	
Instance on Room 226	Does not exist	
Lighting Fixture - LED		
Instance on Room 317	Inspected	
Instance on Room 226	Inspected	
Pendant Mounted	*	
Instance on Room 226	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 317	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 226	Does not exist	
Instance on Room 317	Does not exist	
Recessed Mounted	2000 1000 01100	
Instance on Room 226	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 317	Does not exist	
Raceway With Receptacles	DOES NOT CAIST	
Instance on Room 226	Inspected	
Instance Condition	3- Fair	
Deficiency	RECEPTACLES NOT OPERATIONAL	
Deficiency Quantity	4	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance on Room 317	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
GYMNASIUM	Inspected	
Instance on 2nd Floor	Inspected	
Lighting	пърсски	
Instance on 2nd Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - HID	D 000 HOL ONDI	
Instance on 2nd Floor	Does not exist	
	DOGS HOL CAISU	
Lighting Fixture - Incandescent Instance on 2nd Floor	Does not exist	
mstance on 2nd floor	Does not exist	

Question	Response	
GYMNASIUM		
Lighting		
Lighting Fixture - LED		
Pendant Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 2nd Floor	Does not exist	
Recessed Mounted		
Instance on 2nd Floor	Does not exist	
Local Sound System		
Instance on 2nd Floor	Inspected	
Instance Condition	1- Good	
Installation Year	2024	
Source of Installation Year	Custodial Staff	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 2nd Floor	Does not exist	
Scoreboard		
Instance on 2nd Floor	Does not exist	
Theater Lighting System		
Instance on 2nd Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID	2 040 100 0.110	
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED	DOES HOL CAISE	
Instance on 1st Floor	Inspected	
Pendant Mounted	nispected	
Instance on 1st Floor	Does not exist	
	Does not exist	
Surface Mounted	Y	
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 217	Inspected	
Lighting		
Instance on Room 217	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 217	Does not exist	
Lighting Fixture - HID		
Instance on Room 217	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 217	Does not exist	
Lighting Fixture - LED	DOG HOLOMBU	

Duestion	Response	
LIBRARY	response	
Lighting		
Lighting Fixture - LED		
Instance on Room 217	Inspected	
Pendant Mounted	тырессей	
Instance on Room 217	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 217	Does not exist	
Recessed Mounted		
Instance on Room 217	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Raceway With Receptacles		
Instance on Room 217	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 217	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
	Inspected	
SCIENCE LAB		
Instance on Room 326	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting		
Instance on Room 326	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 326	Does not exist	
Lighting Fixture - HID		
Instance on Room 326	Inspected	
Pendant Mounted		
Instance on Room 326	Does not exist	
Surface Mounted		
Instance on Room 326	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 326	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 326	Does not exist	
Lighting Fixture - LED		
Instance on Room 326	Inspected	
Pendant Mounted	may court	
Instance on Room 326	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	ino deficiencies recorded	
Surface Mounted	D	
Instance on Room 326	Does not exist	

Building Condition Assessment Survey 2023-2024

icui Inspection		11100
uestion	Response	
SCIENCE LAB		
Emergency Gas Shut-Off Valve		
Instance on Room 326	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 326	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Room 326	Inspected	
Instructor Unit		
Instance on Room 326	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Room 326	Does not exist	
Student Unit		
Instance on Room 326	Does not exist	
Projection System		
Instance on Room 326	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected Does not exist	
Lighting Fixture - Fluorescent	Does not exist Does not exist	
Lighting Fixture - HID		
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected Does not exist	
Pendant Mounted		
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	

Building Condition Assessment Survey 2023-2024

исан інѕреспон	Mul
uestion	Response
EMERGENCY LIGHT/EXIT LIGHT PANEL	
Condition	3- Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	4- Between Fair and Poor
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Non Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Does not exist
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Does not exist
Duct Smoke Detector	Does not exist
Area Smoke Detector	Does not exist
CO Detector	Under construction
Heat Detector	Does not exist
Elevator Recall	Does not exist
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not exist
THE MATHECOND TAILET (ETECTIONIC)	Inspected

Question	Response	
FIRE ALARM SYSTEM		
Main Panel		
Fire Alarm Control Panel (Standard)		
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	ACME	
EquipmentId	Fire Alarm	
Installation Year	1965	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	88,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Sub-Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Under construction	
Fire Alarm Control Panel (Standard)	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	ACME	
EquipmentId	Sprinkler Alarm	
Installation Year	1965	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	88,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Remote Annunciator	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	1- Good	

Building Condition Assessment Survey 2023-2024

ricai inspection	MU
uestion	Response
LAN	
Local Distribution Frame (I/LDF)	
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Under construction
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Room 301, Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout The Building
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
	-
Instance	General Office - Room 140
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Bogen Quantum Multicom IP
Installation Year	2015
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL

Building Condition Assessment Survey 2023-2024

Question	Response
PUBLIC ADDRESS SYSTEM	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	3- Fair
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 142
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2023
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room
	3- Fair
Instance Condition	
Instance Quantity	1 FACH
Instance Quantity Uom	EACH
Manufacturer	Metropolitan
EquipmentId	N/A
Capacity/Size Quantity	1600 Amas
Capacity/Size UOM Source of Capacity/Size	Amps Nameplate
Installation Year	1965
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
E Pautuaus Vausiau 2.0 (P)	Page 11 of 12 Print Data 9/9/2024

Duestion	Response	
SERVICE SWITCH	ж	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity		
	1 EACH	
Instance Quantity Uom		
Manufacturer	Metropolitan	
EquipmentId Capacity/Size Quantity	Heating Equipment P.P.S.W 200	
Capacity/Size Quantity Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1965	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SWITCHBOARD	Inspected	
Number of Spares	0	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Metropolitan Electric	
EquipmentId	N/A	
Capacity/Size Quantity	1600	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	3	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Service Switch Size	
Installation Year	1965	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Electrical Inspection M009

QuestionResponseTRANSFORMERDoes not exist