Building Condition Assessment Survey 2023-2024

	P.S. 15 - MA	ANHATTAN, 333 EAST 4 STRE	EI, MANHALI	AN, NY, 10009			
Inspection	n Id Inspection Ty	уре			Time	In	Last Edited
	1650 MECHANIC	AL			2023-	12-13 11:48AN	M 2024-06-20 12:08PM
sset Data							
Question				Answer			
Have any	Systems/Major Build	ding Components been upgraded?		Systems:	Domestic Hot Condensate R Climate Contr Boiler Room;	Water Remote eturn Pumping rol System; Sun	nestic Water Heater; Storage Tank; Steam System; Gas Service; ap Pumps (2 of 4) in binet Heaters in Boiler
				Vaara	Room 2023		
				Years: Systems:		ic Booster Syste	em - Compressor
				Years:	2022	ic boosici sysii	in - Compressor
				Systems:		Thermostatic T	rans
				Years:	2021	Thermostatic 1	таръ
				Systems:	F&T/Steam D	rip Traps (~90% m - Pressure Bo	%); Hyd/Pneumatic
				Years:	2018	iii Tressure B	rester r unips
				Systems:	Split System): - Toilets, Urin	Student Fixtur	Equipment (1 of 2, DX es - Toilets; Staff Fixtures
				Years:	2015		
				Systems:	MDF Room - Window A/C)		Equipment (1 of 2,
				Years:	2014		
Are there	fuel tanks?			No			
Total # of	water main service	entries to the asset		2			
	n Rooms Locations				- Hydraulic/Pn	eumatic Booste	Room; MER 214
		sing or Defective CO Detectors?		No Yes			
Location(ted Sprinkler Heads?			- Paint Room K	itchen Storage	Room (5 painted)
`		Switches with Missing Hammers?		No compo		inchen Storage	rtoom (5 paintea)
riority Co				7.7.75			
			~ .	Location	Person(s)	Person(s)	Photo
Exist Last Year?	Priority Category	Condition Description	Component Affected	Description	Notified	Title	Image
Last Year?	•		-		Notified	Title	Image
Last Year? No condit	Category tion recorded		-		Notified	Title	Image
No condit	Category tion recorded		-	Description		Title	Image
No condit Inspection Question	Category tion recorded		-			Title	Image
No condit Inspection Question Mechanic	Category tion recorded		-	Description Response	:	Title	Image
No condit Inspection Question Mechanic	Category tion recorded cal ONDITIONING		-	Description Response		Title	Image
No condit Inspection Question Mechanic AIR CO	Category tion recorded cal ONDITIONING ed Water System	Description	Affected	Description Response	exist	Title	Image
No condit Inspection Question Mechanic AIR CO Chille	Category tion recorded cal ONDITIONING ed Water System enser Water Distrib	Description ution: Piping, Pumps and Auxiliarie	Affected	Response Inspected Does not	exist exist	Title	Image
No condit Inspection Question Mechanic AIR CC Chille Condit	Category tion recorded cal ONDITIONING ed Water System	Description ution: Piping, Pumps and Auxiliarie	Affected	Response Inspected Does not Does not	exist exist exist	Title	Image
No condit Inspection Question Mechanic AIR CC Chille Condo Coolin	cal ONDITIONING ed Water System enser Water Distrib ng Coil in Ductworl	Description ution: Piping, Pumps and Auxiliarie	Affected	Response Inspected Does not Does not Does not	exist exist exist exist	Title	Image
No condit Inspection Question Mechanic AIR CC Chille Condit Coolin Coolin DX S	cal CONDITIONING ed Water System enser Water Distrib ng Coil in Ductworl	Description ution: Piping, Pumps and Auxiliarie	Affected	Response Inspected Does not Does not Does not Does not	exist exist exist exist	Title	Image
No condit Inspection Question Mechanic AIR CC Chille Condo Coolin Coolin DX S Inde	Category tion recorded Cal ONDITIONING ed Water System enser Water Distrib ng Coil in Ductworl ng Tower plit System	Description ution: Piping, Pumps and Auxiliarie	Affected	Response Inspected Does not Does not Does not Inspected Inspected Inspected	exist exist exist exist		Image
No condit Inspection Question Mechanic AIR CC Chille Condo Coolin Coolin DX S Inde	Category tion recorded cal ONDITIONING ed Water System enser Water Distrib ng Coil in Ductworl ng Tower plit System oor Unit	Description ution: Piping, Pumps and Auxiliarie	Affected	Inspected Does not Does not Does not Inspected Linspected Linspected Linspected Linspected Linspected No deficit	exist exist exist exist exist en Good and Fai		Image
No condit Inspection Question Mechanic Chille Condo Coolin Coolin DX S Indo Co Out	cal CONDITIONING Ed Water System enser Water Distrib ng Coil in Ductworl ng Tower plit System oor Unit condition Deficiency idoor Unit	Description ution: Piping, Pumps and Auxiliarie	Affected	Inspected Does not Does not Does not Inspected Linspected Linspect	exist exist exist exist exist en Good and Fai		Image
No condit Inspection Question Mechanic Chille Condo Coolin Coolin DX S Indo Co Out	cal ONDITIONING ed Water System enser Water Distrib ng Coil in Ductworl ng Tower plit System oor Unit ondition Deficiency	Description ution: Piping, Pumps and Auxiliarie	Affected	Response Inspected Does not Does not Does not Inspected Inspected Inspected Inspected Inspected Inspected Inspected Inspected	exist exist exist exist exist en Good and Fai	r	Image
No condit Inspection Question Mechanic Chille Condo Coolin Coolin DX S Indo Co Out	cal CONDITIONING Ed Water System enser Water Distrib ng Coil in Ductworl ng Tower plit System oor Unit condition Deficiency idoor Unit	Description ution: Piping, Pumps and Auxiliarie	Affected	Response Inspected Does not Does not Does not Inspected Inspected Inspected 2- Betwee No deficit Inspected 2- Betwee Proceed	exist exist exist exist en Good and Fai	r	Image
No condit Inspection Question Mechanic AIR CC Chille Condit Coolin DX Sy Index Cc Out Cc Dry C	cal Condition recorded C	Description ution: Piping, Pumps and Auxiliarie	Affected	Inspected Does not Does not Does not Inspected Inspected Inspected 2- Betwee No defici Inspected 2- Betwee No defici	exist exist exist exist en Good and Fai encies recorded en Good and Fai encies recorded	r	Image
No condit Inspection Question Mechanic AIR CC Chille Condit Coolin DX Sj Inde Cc Out Cc Dry C Packa	cal ONDITIONING ed Water System enser Water Distrib ng Coil in Ductworl ng Tower plit System oor Unit ondition Deficiency tdoor Unit ondition Deficiency	Description ution: Piping, Pumps and Auxiliarie	Affected	Inspected Does not Does not Does not Inspected Inspected Inspected 2- Betwee Vo defici	exist exist exist exist en Good and Fai encies recorded en Good and Fai encies recorded exist	r	Image

Building Condition Assessment Survey 2023-2024

estion	Response
IR CONDITIONING	
Refrigerant Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Return Fan	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Inspected
BMS	Does not exist
Pneumatic System	Does not exist
Hybrid System	Does not exist
Electric System	Inspected
Instance	Throughout except Auditorium, Gymnasium
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	No deficiencies recorded
COMPACTOR	Does not exist
CONVEYING	Does not exist
OMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Inspected
Electric Pressure Booster System	Does not exist
Hydraulic/Pneumatic Booster System	Inspected
· · · · · · · · · · · · · · · · · · ·	Inspected
Water Pressure Booster - Compressor Condition	1- Good
Deficiency	No deficiencies recorded
	Inspected
Pressure Booster Pump	2- Between Good and Fair
Condition	No deficiencies recorded
Deficiency	
Domestic Cold Water Tank	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Water Service	Inspected
Instance	Basement - Sprinkler/Water Meter Room (near Boiler Room
Instance Condition	Entrance/Exit 1), Near Electric Meter Room 3- Fair
Instance Condition	
Instance Quantity	EACH
Instance Quantity Uom	
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION
Definion ov I coation/Instance	DEVICE Pagement Sprinkler/Water Meter Pagers (non Pailer Pagers
Deficiency Location/Instance	Basement - Sprinkler/Water Meter Room (near Boiler Room Entrance/Exit 1), Near Electric Meter Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
	Inspected
Domestic Hot Water Remote Storage Tank	

Building Condition Assessment Survey 2023-2024

nunicui Inspection	MINIS
Question	Response
DOMESTIC WATER SYSTEM	
Domestic Hot Water System	
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Inspected
Instance	Boiler Room
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Laars
EquipmentId	Hot Water Heater
Capacity/Size Quantity	199
Capacity/Size UOM	MBH Input
Capacity/Size 2 Quantity	0
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2023
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	INTERIOR FLOOR DRAIN:DEFECTIVE
Deficiency Location/Instance	2nd Floor Boys Toilet Room
Deficiency Quantity	1 FACH
Quantity Uom	EACH MAINTENANCE
Potential Action Urgency of Action	MAINTENANCE PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sewage Ejector Pump	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sump Pump	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	Does not exist
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	2- Between Good and Fair

Building Condition Assessment Survey 2023-2024

nanicai Inspection		MIUIS
Question	Response	
FIXTURES		
Staff And Other		
Toilet		
Deficiency	No deficiencies recorded	
Urinal	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Student	Inspected	
Drinking Fountain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Locker Room Shower	Inspected	
Instance on 3rd Floor Inside Gymnasium	Inaccessible	
Instance on Room 417 - Girls	Inaccessible	
Sink And Fountain Combo Unit	Inspected	
Condition Combo Unit	3- Fair	
	-	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
U <u>rinal</u>	Inspected	
Condition	2- Between Good and Fair	
Deficiency	CRACKED/PHYSICAL DAMAGE	
Deficiency Location/Instance	Boys Toilet Rooms 113B, 411	
Deficiency Quantity	3	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
GAS FIRED FURNACE	Does not exist	
GAS SERVICE	Inspected	
Gas Distribution Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Gas Meter Room Exhaust Fan	Does not exist	
Gas Meter Room Vent	Does not exist	
Gas Pressure Booster	Inspected	
Instance	Boiler Room	
Instance Condition	1- Good	
Instance Quantity	2	
Instance Quantity Uom	EACH	
Manufacturer	Etter	
EquipmentId	N/A	
Capacity/Size Quantity	1	
Capacity/Size UOM	НР	
Source of Capacity/Size	Documented	
Installation Year	2023	
Source of Installation Year	Custodial Staff	
Deficiency	No deficiencies recorded	
CO/Gas Leak Detection	Inspected	
	<u> </u>	

Building Condition Assessment Survey 2023-2024

•	
estion	Response
GAS SERVICE	
CO/Gas Leak Detection	
Instance	Boiler Room
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Installation Year	2023
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
EATING	Inspected
Heating Coil In Ductwork	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	RADIATOR/CONVECTOR: DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Room 103
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected
Condition	3- Fair
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	MER 214
Deficiency Location/Instance Deficiency Quantity	MER 214 80
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Piping	Inspected
Condition Condensate Return Figure	3- Fair
	No deficiencies recorded
Deficiency	
Steam Condensate Return Pumping System	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Steam Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Terminal Unit Thermostatic Trap	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Steam supplied by External Sources	Does not exist
Unit Heater/Cabinet Heater	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

Mechanical Inspection	M015
-----------------------	------

		1/1//
estion	Response	
EATING PLANT	Inspected	
Instance on Basement	Inspected	
Is there a water meter on the boiler make-up water piping?	Yes	
Observed Operational?	Yes	
Burner Manufacturer	Weishaupt	
Burner Model	G30/2 - A, ZM - NR	
Burner Type	Gas	
Heating Plant Oil Number	N/A	
Boiler Auxiliaries		
Instance on Basement	Inspected	
Boiler Auxiliary Piping		
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Emergency Stop Switch		
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Feedwater System		
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
	No deficiencies recorded	
Boiler Feedwater Treatment(Automatic)	Towns and d	
Instance on Basement	Inspected 1- Good	
Instance Condition		
Deficiency	No deficiencies recorded	
Boiler Flue Exhaust		
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Make-up Water Backflow Preventer		
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Room Steam And Condensate Piping		
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Safety Valve		
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler System	No deficiencies recorded	
Instance on Basement	Inspected	
Coal-fired Boiler	nispected	
	Door not arrist	
Instance on Basement	Does not exist	
Hot Water Boiler	B	
Instance on Basement	Does not exist	
Modular Boiler		
Instance on Basement	Does not exist	
Steam Boiler		
Instance on Basement	Inspected	
Instance on Basement	Inspected	
Instance	Boiler Room	

Building Condition Assessment Survey 2023-2024

	Inspection		M0
uestion		Response	
HEATIN	G PLANT		
Boiler S	•		
Stean	Boiler		
	Instance Condition	1- Good	
	Instance Quantity	4,075	
	Instance Quantity Uom	MBH NET	
	Cast Iron Boiler?	No	
	Manufacturer	Burnham	
	EquipmentId	10000209289N111	
	Capacity/Size Quantity	5248	
	Capacity/Size UOM	MBH Gross	
	Source of Capacity/Size	Documented	
	Installation Year	2023	
	Source of Installation Year	Custodial Staff	
	Deficiency	No deficiencies recorded	
	Instance	Boiler Room	
	Instance Condition	1- Good	
	Instance Quantity	4,075	
	Instance Quantity Uom	MBH NET	
	Cast Iron Boiler?	No	
	Manufacturer	Burnham	
	EquipmentId	10000209290N1111	
	Capacity/Size Quantity	5248	
	Capacity/Size UOM	MBH Gross	
	Source of Capacity/Size	Documented	
	Installation Year	2023	
	Source of Installation Year	Custodial Staff	
	Deficiency	No deficiencies recorded	
Fuel Sy			
	Instance on Basement	Inspected	
Boile	r Fresh Air Louver/Damper		
	Instance on Basement	Inspected	
	Instance Condition	1- Good	
	Type	Automatic	
	Deficiency	No deficiencies recorded	
Burn	er/Burner Control Panel		
	Instance on Basement	Inspected	
	Instance Condition	1- Good	
	Deficiency	No deficiencies recorded	
Fuel	Oil Storage/Supply System		
	Instance on Basement	Does not exist	
Gas T	Trains And Vent At The Boiler		
	Instance on Basement	Inspected	
	Instance Condition	1- Good	
	Deficiency	No deficiencies recorded	
Enclosed	IDF Room	Does not exist	
		Inspected	
KITCHE			
~-	Instance on 1st Floor	Inspected	
CO De	tector	N 1	

Not required

Does not exist

Does not exist

Instance on 1st Floor

Instance on 1st Floor

Instance on 1st Floor

Gas System

Grease Trap

Hood

Building Condition Assessment Survey 2023-2024

anicai Inspection	MIU
nestion	Response
ATCHEN	
Hood	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Fan	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Fire Suppression System	
Instance on 1st Floor	Does not exist
Hot Water Temperature Booster	
Instance on 1st Floor	Does not exist
Kitchen Sink	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
IDF Room	Inspected
Instance on Building Addition - Room 216	Inspected
Dedicated A/C Equipment	
Instance on Building Addition - Room 216	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CIENCE DEMO ROOM	Does not exist
CIENCE LAB	Does not exist
CIENCE PREP ROOM	Does not exist
PRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist
Wet Sprinkler Alarm Valve Assembly	Does not exist
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Does not exist
Sprinkler Head	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Basement- Paint Room, Kitchen Storage Room (painted, 5)
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Sprinkler Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standpipe System	Does not exist
Water Gong	Does not exist
SWIMMING POOL	Does not exist
/ENTILATION	Inspected
Is the building Mechanically ventilated?	Partial

Building Condition Assessment Survey 2023-2024

estion	Response	
ENTILATION		
Exhaust Fan	Inspected	
Condition	3- Fair	
Approximate Total # of Fans	1-25	
Deficiency	DEFECTIVE MOTOR	
Deficiency Location/Instance	Lower Roof-3 West	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Heating And Ventilating Unit	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Metal Ductwork	Inspected	
Condition	3- Fair	
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes	
Are there chain operated dampers?	No	
Deficiency	DAMAGED FLEXIBLE CONNECTION	
Deficiency Location/Instance	MER 214 @ Gym Blower, Auditorium Blower	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Supply Fan	Inspected	
Condition	3- Fair	
Approximate Total # of Fans	1-5	
Deficiency	DEFECTIVE CONTROLS	
Deficiency Location/Instance	MER 214 @ Auditorium Blower, Gym Blower	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Unit Ventilator	Does not exist	