#### **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

Asset:	P.S. 19 -	MANHATTAN, 185 1ST AVE	NUE, MANHALIAN, N	11,10003		
Inspection	-				Time In	Last Edited
	915 ELECTRI	ICAL			2023-11-10 08:56AM	2023-11-13 09:52AM
sset Data						
Question				Answer		
Have any	Systems/Major E	Building Components been upgrade	d?	Systems:		
				Years:	2022	
				Systems:	Intrusion Alarm System (Remo	te Annunciator)
				Years:	2021	
				Systems:	Partial Molded Case Circuit Br	eaker Panel Board
				Years:	2020, 2008, 2002, 1995, 1985	
				Systems:	Security Lights	
				Years:	2020, 2008	
				Systems:	Most Emergency Lighting (Nor	n Battery Pack)
				Years:	2017, 2013	
				Systems: Years:	Interior Fluorescent Lighting (F LED Lighting (Main Entrance 1 (Battery Pack) 2017	
				Systems:	Public Address System	
				Years:	2014	
				Systems:	Gymnasium (LED Lighting), A	uditorium (UID and
				Systems.	LED Lighting, Partial Theater I System)	
				Years:	2013	
				Systems:	Telephone System	
				Years:	2012	
				Systems:	Science Lab - Room 221	
				Years:	2008	
				Systems:	Service Switch, Partial Switchb	oard
				Years:	2006	
				Systems:	Emergency Light/Exit Light Pa	nel
				Years:	2002	
				Systems:	Intrusion Alarm System (Excep	t Remote Annunciator)
				Years:	2000	
Type of S	ervice			Below Gr	ound	
Does Inte	ractive Whiteboa	rd (IWB) Exist?		Yes		
Water Per	netration In Electr	rical Room?		No		
DEDICA	ATED INTERC	COMS IN FIRE RESCUE ARE	EAS			
Question					Response	
your bu	ilding?	ie Assistance Areas, Fire Rescue Ar	eas, and/or Holding Rooms	in 1	No	
Priority Co						
Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description		Photo Image
No condit	tion recorded					
Inspection	!					
Question				Response		
Electrica	1					
ATHLI	ETIC FIELD			Does not	exist	
AUDIT	ORIUM			Inspected		
	Instance on B	Basement		Inspected		
House	e Lighting					
	Instance on D			Increated		

Instance on Basement Does a Chandelier Exist? Inspected

No

#### **Building Condition Assessment Survey 2023-2024**

estion	Response	
UDITORIUM		
House Lighting		
Lighting Fixture - Fluorescent		
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement	Does not exist	
Lighting Fixture - HID		
Instance on Basement	Inspected	
Pendant Mounted	A.	
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Inspected	
Pendant Mounted	Å	
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Does not exist	
Recessed Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on Basement	Inspected	
Instance Condition	5- Poor	
Installation Year	1956	
Source of Installation Year	Documented	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on Basement	Inspected	

#### **Building Condition Assessment Survey 2023-2024**

iestion	Response
AUDITORIUM	
Theater Lighting System	
Dimming System	
Instance on Basement	Does not exist
Theater Lighting	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	32
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
CAFETERIA	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	inspected
Instance on 1st Floor	Inspected
	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	· · · · ·
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Installation Year	1956
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded

#### **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

		MUI
Question	Response	
CAFETERIA		
Projection System		
Instance on 1st Floor	Does not exist	
Theater Lighting System Instance on 1st Floor	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting Does a Chandelier Exist?	Inspected No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
· · · · · · · · · · · · · · · · · · ·	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
COMPUTER LAB	Inspected	
Instance on Room 219	Inspected	
Power Panel?	Yes	
Lighting	Y 1	
Instance on Room 219	Inspected	
Lighting Fixture - Fluorescent	Y 1	
Instance on Room 219	Inspected	
Pendant Mounted	Y	
Instance on Room 219	Inspected 2- Between Good and Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 219	Does not exist	
Recessed Mounted		
Instance on Room 219	Does not exist	
Lighting Fixture - HID		
Instance on Room 219	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 219	Does not exist	
Lighting Fixture - LED		
Instance on Room 219	Does not exist	
Raceway With Receptacles	Turner etc. 1	
Instance on Room 219	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
GYMNASIUM	Inspected	
Instance on Basement Lighting	Inspected	

#### **Building Condition Assessment Survey 2023-2024**

estion	Response	
GYMNASIUM	response	
Lighting		
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent	x x	
Instance on Basement	Does not exist	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Inspected	
Pendant Mounted	I	
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement	Does not exist	
Local Sound System	Does not exist	
Instance on Basement	Inspected	
Instance Condition	5- Poor	
Installation Year	1956	
Source of Installation Year	Documented	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on Basement	Does not exist	
Scoreboard		
Instance on Basement	Does not exist	
Theater Lighting System		
Instance on Basement	Does not exist	
ATCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	

#### **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

rical Inspection	MU
Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LIBRARY	Inspected
Instance on Room 209	Inspected
Lighting	
Instance on Room 209	Inspected
Lighting Fixture - Fluorescent	<b>^</b>
Instance on Room 209	Inspected
Pendant Mounted	
Instance on Room 209	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 209	Does not exist
Recessed Mounted	
Instance on Room 209	Does not exist
Lighting Fixture - HID	
Instance on Room 209	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 209	Does not exist
Lighting Fixture - LED	
Instance on Room 209	Does not exist
Raceway With Receptacles	
Instance on Room 209	Does not exist
Projection System	
Instance on Room 209	Does not exist
LOCKER ROOM	Inspected
Instance on Basement - Boys	Inspected
Alternative Use	Yes
Lighting	
Instance on Basement - Boys	Inspected
Lighting Fixture - Fluorescent	1
Instance on Basement - Boys	Inspected
Pendant Mounted	
Instance on Basement - Boys	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement - Boys	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	No deficicies recorded
Recessed Mounted	Does not exist
Instance on Basement - Boys	ראואנ
Lighting Fixture - HID	Doos not avist
Instance on Basement - Boys	Does not exist
Lighting Fixture - Incandescent	Doos not wist
Instance on Basement - Boys	Does not exist
Lighting Fixture - LED	Description in the second seco
Instance on Basement - Boys	Does not exist

## NYC Department of Education Building Condition Assessment Survey 2023-2024

ical Inspection	M01
uestion	Response
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Inspected
Instance on Room 221	Inspected
Power Panel?	Yes
Alternative Use	Yes
Lighting	
Instance on Room 221	Inspected
Lighting Fixture - Fluorescent	1
Instance on Room 221	Inspected
Pendant Mounted	X
Instance on Room 221	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 221	Does not exist
Recessed Mounted	
Instance on Room 221	Does not exist
Lighting Fixture - HID	
Instance on Room 221	Inspected
Pendant Mounted	Inspected
Instance on Room 221	Does not exist
Surface Mounted	
Instance on Room 221	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 221	Does not exist
Lighting Fixture - Incandescent Instance on Room 221	Does not exist
Lighting Fixture - LED	Does not exist
Instance on Room 221	Does not exist
Emergency Gas Shut-Off Valve	Does not exist
Instance on Room 221	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 221	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 221	Inspected
Instructor Unit	Inspected
Instance on Room 221	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	Daga not avist
Instance on Room 221	Does not exist
Student Unit	Descustorist
Instance on Room 221	Does not exist
Projection System	Insuranted
Instance on Room 221	Inspected

## NYC Department of Education Building Condition Assessment Survey 2023-2024

#### Electrical Inspection

ricui Inspeciion	
uestion	Response
SCIENCE LAB	
Projection System	
Deficiency	No deficiencies recorded
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
FOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Boiler Room, Auditorium (Stage - Right Side), Gymnasium (by
,	Staircase A ), 1st Floor by Staircases (A, C, D)
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Violations	35657950H
Non Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded Inspected

## **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

	1	VIUI
lestion	Response	
EXIT LIGHT		
Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Strobe	Does not exist	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Does not exist	
Duct Smoke Detector	Does not exist	
Area Smoke Detector	Does not exist	
CO Detector	Does not exist	
Heat Detector	Does not exist	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	-
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Does not exist	
Fire Alarm Control Panel (Standard)	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity		
	L EACH	
Instance Quantity Uom		
Manufacturer	ACME	
EquipmentId	Fire Alarm 1956	
Installation Year Source of Installation Year	Documented	
	BEYOND USEFUL LIFE	
Deficiency Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	84,000	
Quantity Uom	84,000 S.F.	
Potential Action	S.F. REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Sub-Panel	Inspected	
Sub-ranel Bell At Panel	Inspected	
Condition		
	3-Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Does not exist	
	×	
Fire Alarm Control Panel (Standard)	Inspected Boiler Room	

## **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

	IVIU .
uestion	Response
FIRE ALARM SYSTEM	
Sub-Panel	
Fire Alarm Control Panel (Standard)	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	Sprinkler Alarm
Installation Year	1956
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	84,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Remote Annunciator	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
	No deficiencies recorded
Deficiency	
NTERCOM SYSTEM	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
	Does not exist
MOTOR CONTROL CENTER MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Does not exist
Variable Frequency Drive	
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Quantity Uom Potential Action	REPLACE-UPGRADE
Quantity Uom Potential Action Urgency of Action	REPLACE-UPGRADE PRIORITY 1
Quantity Uom Potential Action Urgency of Action Purpose of Action	REPLACE-UPGRADE PRIORITY 1 LEVEL 2
Quantity Uom Potential Action Urgency of Action	REPLACE-UPGRADE PRIORITY 1

## **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

stion	Response
NEL BOARD	
used Knife Switch Type	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
used Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room, By Room B33
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	By Room B33
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Iolded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	By Room 105
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Auditorium, Gymnasium, By Rooms (105, 117, 125, 245)
Deficiency Quantity	6
	EACH
Quantity Uom Potential Action	EACH REPLACE-UPGRADE
	PRIORITY 1
Urgency of Action	LEVEL 2
Purpose of Action Violations	LEVEL 2 No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	Auditorium, Cafeteria, By Staircase A (Basement, 1st Floor), By Rooms (223, 233)
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded

## **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

		1101
uestion	Response	
PUBLIC ADDRESS SYSTEM		
Instance	Principal's Office - Room 11	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Bogen Quantum Multicom IP	
Installation Year	2014	
Source of Installation Year	Documented	
Deficiency	CLOCK NOT OPERATIONAL	
Deficiency Location/Instance	Classrooms and Corridors	
Deficiency Quantity	11	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Does not exist	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	Custodian's Office - Room 115	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista - 128B	
Installation Year	2000	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3- Fair	
Deficiency	SIREN/STROBE NOT ACTIVE	
Deficiency Location/Instance	Exterior Wall - Facing 1st Avenue	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 4	
Purpose of Action	LEVEL 3	
Violations	No violations recorded	
Lighting - Security	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
SERVICE SWITCH	Inspected	
Instance	Electrical Room B13	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	

## **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

	IVI
uestion	Response
SERVICE SWITCH	
Instance Quantity Uom	EACH
Manufacturer	Delta Metal Product
EquipmentId	N/A
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
WITCHBOARD	Inspected
Number of Spares	0
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room B13
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Delta Metal Product
EquipmentId	N/A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Inspected
Instance	Electrical Room B13
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Standard Switchboard
EquipmentId	N/A
Capacity/Size Quantity	400
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	- Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	1956
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B13
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Does not exist
ELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair

## Building Condition Assessment Survey 2023-2024

trical Inspection		M019
Question	Response	
TELEPHONE SYSTEM		
Standard		
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	