Building Condition Assessment Survey 2023-2024

Electrical Inspection M033

Asset:	P.S. 33 - MANHATTAN, 281 9TH AVENUE, MANHATTAN, NY, 10001		
Inspection Id	Inspection Type	Time In	Last Edited
4965	ELECTRICAL	2024-04-26 09:29AM	2024-05-23 12:41PM

4965 ELECTRICAL	2024-04-26 09:29AM 2024-05-23 12:41I		
sset Data			
Question	Answer		
Have any Systems/Major Building Components been upgraded?	Systems: LED Lighting (Gymnasium, Rooms 242, 117), Emergency Light (Battery Pack), Fire Alarm System (Printer)		
	Years: 2022		
	Systems: Interior Lighting, Emergency Lighting (Non Battery Pack), LAN, Telephone System		
	Years: 2015		
	Systems: Auditorium (Projection System)		
	Years: 2012		
	Systems: Fire Alarm System (Except Printer)		
	Years: 2010		
	Systems: Intercom System, Most Motor Starters		
	Years: 2009		
	Systems: Public Address System, Local Sound System, Emergency Light/Exit Light Panel, Most Molded Case Circuit Breaker Type Panel Boards		
	Years: 2008		
	Systems: Service Switch, Switchboard Years: 2007		
	Systems: Intrusion Alarm System		
Th	Years: 2006 Below Ground		
Type of Service			
Does Interactive Whiteboard (IWB) Exist?	Yes		
Water Penetration In Electrical Room?	Yes		

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

QuestionResponseAre there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?No

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Exposed Electrical Wires	N/A	Electrical outlet	Room 145	Edzert Pierre	Fireman	
No	Water Leaks onto Electrical Equipment	Foundation Wall Leak affecting a Lighting fixture.	Lighting Fixture	Boiler Room	Edzert Pierre	Fireman	
Yes	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electrical Room	Edzert Pierre	Fireman	

Inspection

Building Condition Assessment Survey 2023-2024

rical Inspection	n	M
Question	Response	
lectrical		
ATHLETIC FIELD	Does not exist	
AUDITORIUM	Inspected	
Instance on 1st Floor	Inspected	
House Lighting		
Instance on 1st Floor	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on 1st Floor	Inspected	
	mspected	
Pendant Mounted	Description of the second of t	
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	4- Between Fair and Poor	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Inspected	

Instance on 1st Floor

Instance on 1st Floor

Instance on 1st Floor

Dimming System

Theater Lighting

Inspected

Inspected

Does not exist

Building Condition Assessment Survey 2023-2024

	11105
Response	
3- Fair	
LIGHTING FIXTURE BEYOND USEFUL LIFE	
44	
EACH	
REPLACE-UPGRADE	
PRIORITY 1	
LEVEL 2	
No violations recorded	
Inspected	
Inspected	
1	
Inspected	
Inspected	
-	
LEVEL 2	
No violations recorded	
Does not exist	
Does not exist	
Does not exist	
	-
Does not exist	
2 040 100 0.1100	
Does not exist	
Does not exist	
Inspected	
NO VIOIATIONS recorded	
De construire	
Does not exist	
Does not exist Inspected	
	3- Fair LIGHTING FIXTURE BEYOND USEFUL LIFE 44 EACH REPLACE-UPGRADE PRIORITY 1 LEVEL 2 No violations recorded Inspected Inspected Inspected Inspected Inspected LIGHTING FIXTURE BALLAST DEFECTIVE 1 EACH REPLACE BALLAST PRIORITY 3 LEVEL 2 No violations recorded Does not exist

Building Condition Assessment Survey 2023-2024

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted Condition	Inspected 1- Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
COMPUTER LAB	Does not exist
GYMNASIUM	Inspected
Instance on 1st Floor	Inspected
Lighting Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	inspected
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	Does not exist
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	4- Between Fair and Poor
Installation Year Source of Installation Year	2008 Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 2

Building Condition Assessment Survey 2023-2024

icui Inspection		14103
uestion	Response	
GYMNASIUM		
Local Sound System		
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Scoreboard		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
KITCHEN	Inspected	
Instance on Basement	Inspected	
Lighting	·	
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent	-	
Instance on Basement	Inspected	
Pendant Mounted	•	
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	1 to deficiencies recorded	
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	ivo deficieles recorded	
Instance on Basement	Does not exist	
	DOCS HOT CAIST	
Lighting Fixture - Incandescent Instance on Basement	Does not exist	
	Does not exist	
Lighting Fixture - LED	Dona and societ	
Instance on Basement	Does not exist	
LIBRARY	Does not exist	
LOCKER ROOM	Inspected	
Instance on 1st Floor - Boys, 1st Floor - Girls	Inaccessible	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
	2- Between Good and Fair	
Condition		
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID Lighting Fixture - Incandescent	Does not exist	
Laghting Universe Incondessont	Does not exist	

Building Condition Assessment Survey 2023-2024

iricai Inspection	1/1033
Question	Response
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	Inspected
EXIT LIGHT	
Battery Pack Condition	Inspected 3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	FIXTURE LENS MISSING
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH DISTALL LENG
Potential Action	INSTALL LENS
Urgency of Action	PRIORITY 5 LEVEL 2
Purpose of Action Violations	
	No violations recorded
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH PERMACE
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	1st Floor (By Exit 3, Auditorium Stage-Left Side, Auditorium - Stage)
Deficiency Quantity	4

Building Condition Assessment Survey 2023-2024

nestion	Response
EXIT LIGHT	
Non Battery Pack	
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Violations	E552799
XIT/EMERGENCY LIGHT	Does not exist
IRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Heat Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards System Technology
Model	EST 2
EquipmentId	Fire Alarm Control Panel
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

aricai inspection	W1055
Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
	Inspected
Elevator Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area Condition	Inspected 3- Fair
Deficiency	No deficiencies recorded
i	
LAN	Inspected
Local Distribution Frame (I/LDF) Condition	Inspected 2- Between Good and Fair
	No deficiencies recorded
Deficiency	
Main Equipment Rack (MDF)	Inspected 2- Between Good and Fair
Condition	No deficiencies recorded
Deficiency	
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Cafeteria
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE

Building Condition Assessment Survey 2023-2024

nestion	Response
PANEL BOARD	•
Molded Case Circuit Breaker Type	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Cafeteria, Mechanical Room 208
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 101
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Telecor II
Installation Year	2008
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Boiler Room, by Auditorium, General Office - Room 101
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room B3
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
•	Vista - 128B
Model	Vista - 128B 2006
Installation Year Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
	No deficiencies recorded
Deficiency	
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inaccessible

Building Condition Assessment Survey 2023-2024

uestion	Response
SERVICE SWITCH	Inspected
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electric Switchboard
EquipmentId	1600 Amp Switch
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2007
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	6
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	MDB Section 1, 2, 3
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2007
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist