Building Condition Assessment Survey 2023-2024

		Dunuing (Condition Assessm	ent Survey 2	U2J-2U2 4	
lectrical Ins	-					M0
Asset:		NHATTAN, 730 EAST 12	STREET, MANHAT	FAN, NY, 10009		
Inspection Id					Time In	Last Edited
142	9 ELECTRICAL				2023-12-04 11:59AM	2023-12-04 01:41PM
sset Data						
Question				Answer		
Have any Sys	stems/Major Buildi	ng Components been upgrade	d?	Systems:	Sound System)	ED Lighting, Local
				Years:	2023	
				Systems:	Public Address System (Most Cl	ocks, Partial Speakers)
				Years:	2020	
				Systems:	Public Address System (Amplific	er)
				Years:	2017	
				Systems:	Intrusion Alarm System (Central	Control Panel)
				Years:	2016	
				Systems:	Telephone System	
				Years:	2014	
				Systems:	Interior Lighting (Except Library Emergency Lighting (Non Batter	
				Years:	2013	
				Systems:	Gymnasium (Scoreboard)	
				Years:	2012	
				Systems:	IPDVS/CCTV System, Local So (Gymnasium)	und System
				Years:	2011	
				Systems:	Science Lab	
				Years:	2009	
				Systems:	Library	
				Years:	2007	
				Systems:	Lighting - Security	
				Years:	2003	
				Systems:	Intrusion Alarm System	
				Years:	2002	
Type of Servi				Below Gr	ound	
	tive Whiteboard (IV	,		Yes		
	ation In Electrical I		D + C	No		
	EDINTERCOM	IS IN FIRE RESCUE ARI	EAS	7	D	
Question Are there a	nv Life Rescue Ass	sistance Areas, Fire Rescue Ar	eas, and/or Holding Roon		Response No	
your buildi	ng?					
riority Cond	ition					
	riority	Condition	Component	Location		hoto
Last Year? C No condition	ategory	Description	Affected	Description	Notified Title II	nage
<i>no condition</i> (nspection	recorded					
Question				Response	<u> </u>	
Electrical				response	•	
ATHLETI	C FIELD			Does not	exist	
				Inspected		
AUDITOR	Instance on 1st Flo					
		001		Inspected		
House Li	ignting					

Inspected

Inspected

No

Instance on 1st Floor

Instance on 1st Floor

Lighting Fixture - Fluorescent

Pendant Mounted

Does a Chandelier Exist?

Question	Response
	кезрине
AUDITORIUM H. Linki	
House Lighting	
Lighting Fixture - Fluorescent Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	DOCS HOL CAISE
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
	No deficiencies recorded
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	

urtners Version 2.0 (P)	Page 2 of 10	Print Date: 8/8/2024
Instance on 1st Floor		Inspected
CAFETERIA		Inspected
Violations		No violations recorded
Purpose of Action		LEVEL 2
Urgency of Action		PRIORITY 1
Potential Action		REPLACE-UPGRADE
Quantity Uom		EACH
Deficiency Quantity		32
Deficiency		LIGHTING FIXTURE BEYOND USEFUL LIFE
Instance Condition		3- Fair
Instance on 1st Floor		Inspected
Theater Lighting		
Instance on 1st Floor		Does not exist
Dimming System		
Instance on 1st Floor		Inspected
Theater Lighting System		
Instance on 1st Floor		Does not exist
Projection System		
Deficiency		No deficiencies recorded
Source of Installation Year		Custodial Staff
Installation Year		2023
Instance Condition		1- Good
Instance on 1st Floor		Inspected
Local Sound System		2000 Hot Dates
Instance on 1st Floor		Does not exist
Recessed Mounted		
Violations		No violations recorded
Purpose of Action		LEVEL 2
Urgency of Action		PRIORITY 3
Quantity Uom Potential Action		EACH REPAIR
		1 EACH
Deficiency Deficiency Quantity		LIGHTING FIXTURE NOT OPERATIONAL
Instance Condition		2- Between Good and Fair
Instance on 1st Floor		Inspected
Surface Mounted		
Instance on 1st Floor		Does not exist
Pendant Mounted		
Instance on 1st Floor		Inspected
Lighting Fixture - LED		· · · · ·
Instance on 1st Floor		Does not exist
Lighting Fixture - Incandescent		
Instance on 1st Floor		Does not exist
Lighting Fixture - HID		
Instance on 1st Floor		Does not exist
Recessed Mounted		

Building Condition Assessment Survey 2023-2024

Response	
Inchaotad	
nispected	
Inconceted	
inspected	
Turanosta d	
No deficiencies recorded	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Inspected	
-	
No violations recorded	
Door not aviet	
Does not exist	
Door not aviet	
•	
LEVEL 2 No violations recorded	
	Inspected Inspected 2- Between Good and Fair No deficiencies recorded Does not exist Does not exist Does not exist Does not exist Inspected 3- Fair 1995 Custodial Staff BEYOND USEFUL LIFE Cafeteria-1st Floor 1 EACH REPLACE PRIORITY 1 LEVEL 2 No violations recorded Does not exist Does not exist Linspected Inspected

Does not exist

Does not exist

Lighting Fixture - HID

Lighting Fixture - Incandescent

Building Condition Assessment Survey 2023-2024

Electrical Inspection M034

		11105
uestion	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Does not exist	
GYMNASIUM	Inspected	
Instance on 1st Floor	Inspected	
Lighting	Inspected	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID	Does not exist	
Instance on 1st Floor	Does not exist	
	DOCS HOT CAIST	
Lighting Fixture - Incandescent Instance on 1st Floor	Does not exist	
	Does not exist	
Lighting Fixture - LED Instance on 1st Floor	Insuranted	
	Inspected	
Pendant Mounted	Y 1	
Instance on 1st Floor	Inspected 3- Fair	
Instance Condition		
Deficiency Deficiency Quantity	LIGHTING FIXTURE NOT OPERATIONAL	
	11 FACH	
Quantity Uom	EACH	
Potential Action	REPAIR PRIORITY 2	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2011	
Source of Installation Year	Custodial Staff	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Scoreboard		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	

Electrical Inspection	M034

ieur inspection		
estion	Response	
KITCHEN		
Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 217	Inspected	
Lighting	nispected	
Instance on Room 217	Inspected	
Lighting Fixture - Fluorescent	nispected	
Instance on Room 217	Inspected	
Pendant Mounted	nispected	
Instance on Room 217	Does not exist	
Surface Mounted	Does not exist	
Instance on Room 217	Lucusottad	
	Inspected 3- Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Recessed Mounted	Y 1	
Instance on Room 217	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 217	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 217	Inspected	
Pendant Mounted		
Instance on Room 217	Does not exist	
Surface Mounted		
Instance on Room 217	Does not exist	
Recessed Mounted		
Instance on Room 217	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - LED		
Instance on Room 217	Does not exist	
Raceway With Receptacles		
Instance on Room 217	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 217	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	

Electrical Inspection	N1034

cirical Inspection		141054
Question	Response	
LOCKER ROOM	Inspected	
Instance on 1st Floor - Boys	Inaccessible	
Instance on 2nd Floor - Girls	Inspected	
Alternative Use	Yes	
Lighting		
Instance on 2nd Floor - Girls	Inspected	
Lighting Fixture - Fluorescent	•	
Instance on 2nd Floor - Girls	Inspected	
Pendant Mounted		
Instance on 2nd Floor - Girls	Does not exist	
Surface Mounted		
Instance on 2nd Floor - Girls	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 2nd Floor - Girls	Does not exist	
Lighting Fixture - HID		
Instance on 2nd Floor - Girls	Does not exist	
Lighting Fixture - Incandescent		
Instance on 2nd Floor - Girls	Does not exist	
Lighting Fixture - LED		
Instance on 2nd Floor - Girls	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 318	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting	140	
Instance on Room 318	Inspected	
Lighting Fixture - Fluorescent	- Indipersor	
Instance on Room 318	Inspected	
Pendant Mounted		
Instance on Room 318	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	110 4011010101010	
Instance on Room 318	Does not exist	
Recessed Mounted		
Instance on Room 318	Does not exist	
Lighting Fixture - HID		
Instance on Room 318	Inspected	
Pendant Mounted	1	
Instance on Room 318	Does not exist	
Surface Mounted		
Instance on Room 318	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 318	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 318	Does not exist	
Lighting Fixture - LED		
<u> </u>		

Electrical Inspection	N1034

uestion	Response	
SCIENCE LAB		
Lighting		
Lighting Fixture - LED		
Instance on Room 318	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 318	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 318	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Room 318	Inspected	
Instructor Unit		
Instance on Room 318	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Room 318	Does not exist	
Student Unit		
Instance on Room 318	Does not exist	
Projection System		
Instance on Room 318	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency		

Electrical Inspection	N1034

Question	Response
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Under construction
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Boiler Room, By Exit 7
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Does not exist
	Under construction
FIRE ALARM SYSTEM	
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Does not exist
Variable Frequency Drive	
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected 3- Fair
Condition	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance Deficiency Quantity	Boiler Room 1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
	LEVEL 2
Purpose of Action Violations	
	No violations recorded
Fused Knife Switch Type	Inspected

Building Condition Assessment Survey 2023-2024

Electrical Inspection M034

uestion	Response
PANEL BOARD	
Fused Knife Switch Type	
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Rooms, Boiler Room
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Under construction
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 101
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
Model	Biamp 301
Installation Year	1995
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	3- Fair
Installation Year	2011
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 124
Instance Condition	3- Fair
Instance Quantity	1
mistance Quantity	EACH
<u> </u>	
Instance Quantity Uom	
Instance Quantity Uom Model	Vista 128BPT
Instance Quantity Uom Model Installation Year	Vista 128BPT 2016
Instance Quantity Uom Model	Vista 128BPT

Building Condition Assessment Survey 2023-2024

Electrical Inspection M034

Question	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Quantity Uom	EACH
Potential Action	REPAIR SYSTEM
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inaccessible
SERVICE SWITCH	Under construction
SWITCHBOARD	Under construction
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist