Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Asset:	P.S. 41 - MANHATTAN, 116 WEST 11 STREET, MANHATTAN, NY, 10011		
Inspection Id	Inspection Type	Time In	Last Edited
2186	MECHANICAL	2024-01-05 08:39AM	2024-03-02 03:19PM
sset Data			

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Electric Domestic Water Heater for Kitchen; Sump
· · · · · · · · · ·	Pump
	Years: 2023
	Systems: Kitchen - Grease Traps
	Years: 2021
	Systems: Staff Fixtures - Toilets; Student Fixtures - Drinking
	Fountains, Lavatory/Sinks, Toilets; Boiler Make-up
	Water Backflow Preventer
	Years: 2019
	Systems: MDF Room - Dedicated A/C Equipment (DX Split
	System); Terminal Unit Thermostatic Traps
	Years: 2018
	Systems: Boiler Safety Valves
	Years: 2015
Are there fuel tanks?	Yes
Total # of above ground tanks	1
Total capacity of all above ground tanks in gal.	10,000
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0
Total # of water main service entries to the asset	1
MERs/Fan Rooms Locations	MER B10; 1st Floor - Fan Room
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Painted/Obstructed Sprinkler Heads?	Yes
Location(s)	Room B9 (painted, 2)
Are there any Emergency Stop Switches with Missing Hammers?	No components

Priority Condition

1 1101 119 00	mannon						
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No	Defective Boiler Safety Auxiliary	(1)	Boiler Safety Valve	Boiler Room @ Boiler #2	Basilio Espinal	Fireman	

	HI
	1
the second	

spection		
Question	Response	
Mechanical		
AIR CONDITIONING	Inspected	
Chilled Water System	Does not exist	
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Cooling Coil in Ductwork	Does not exist	-
Cooling Tower	Does not exist	
DX Split System	Does not exist	
Dry Cooler	Inspected	
Instance	Lower Roof	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Heatcraft	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

action		
estion		Response
IR CO	NDITIONING	
Dry Co	oler	
	EquipmentId	DC-1
	Capacity/Size Quantity	20
	Capacity/Size UOM	Tons
	Source of Capacity/Size	Inspector Estimate
	Installation Year	2008
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
	Instance	Lower Roof
	Instance Condition	2- Between Good and Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Heatcraft
	EquipmentId	DC-2
	Capacity/Size Quantity	15
	Capacity/Size UOM	Tons
	Source of Capacity/Size	Inspector Estimate
	Installation Year	2008
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
D 1		Does not exist
	ed / Rooftop Unit	
	ed Terminal A/C	Inspected 3- Fair
Condi		
	Deficiency	No deficiencies recorded
	erant Leak Detection System	Does not exist
	erant Piping	Does not exist
Return		Inspected
Condi	ition	3- Fair
	Deficiency	No deficiencies recorded
ENTR	AL ACID WASTE NEUTRALIZING TANK	Does not exist
LIMAT	TE CONTROL SYSTEM	Inspected
BMS		Inspected
	Instance	Throughout except Gymnasium and Auditorium (WPT System)
	Instance Condition	4- Between Fair and Poor
	Instance Quantity	1
	Instance Quantity	
	Instance Quantity Uom	EACH
	Instance Quantity Uom Building Area Covered by Operational System	EACH 0-20%
	Instance Quantity Uom Building Area Covered by Operational System Installation Year	EACH 0-20% 2010
	Instance Quantity Uom Building Area Covered by Operational System Installation Year Source of Installation Year	EACH 0-20% 2010 Custodial Staff
	Instance Quantity Uom Building Area Covered by Operational System Installation Year Source of Installation Year Deficiency	EACH 0-20% 2010 Custodial Staff DEFECTIVE SYSTEM
	Instance Quantity Uom Building Area Covered by Operational System Installation Year Source of Installation Year Deficiency Deficiency Location/Instance	EACH 0-20% 2010 Custodial Staff DEFECTIVE SYSTEM Throughout except Gymnasium and Auditorium
	Instance Quantity Uom Building Area Covered by Operational System Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity	EACH 0-20% 2010 Custodial Staff DEFECTIVE SYSTEM Throughout except Gymnasium and Auditorium 1
	Instance Quantity Uom Building Area Covered by Operational System Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom	EACH 0-20% 2010 Custodial Staff DEFECTIVE SYSTEM Throughout except Gymnasium and Auditorium 1 EACH
	Instance Quantity Uom Building Area Covered by Operational System Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action	EACH 0-20% 2010 Custodial Staff DEFECTIVE SYSTEM Throughout except Gymnasium and Auditorium 1 EACH REPAIR
	Instance Quantity Uom Building Area Covered by Operational System Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action	EACH 0-20% 2010 Custodial Staff DEFECTIVE SYSTEM Throughout except Gymnasium and Auditorium 1 EACH REPAIR PRIORITY 3
	Instance Quantity Uom Building Area Covered by Operational System Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action	EACH 0-20% 2010 Custodial Staff DEFECTIVE SYSTEM Throughout except Gymnasium and Auditorium 1 EACH REPAIR
	Instance Quantity Uom Building Area Covered by Operational System Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action	EACH 0-20% 2010 Custodial Staff DEFECTIVE SYSTEM Throughout except Gymnasium and Auditorium 1 EACH REPAIR PRIORITY 3
Pneuma	Instance Quantity Uom Building Area Covered by Operational System Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action	EACH 0-20% 2010 Custodial Staff DEFECTIVE SYSTEM Throughout except Gymnasium and Auditorium 1 EACH REPAIR PRIORITY 3 LEVEL 2
Pneuma	Instance Quantity Uom Building Area Covered by Operational System Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Violations	EACH 0-20% 2010 Custodial Staff DEFECTIVE SYSTEM Throughout except Gymnasium and Auditorium 1 EACH REPAIR PRIORITY 3 LEVEL 2 No violations recorded
Pneuma	Instance Quantity Uom Building Area Covered by Operational System Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Violations atic System	EACH 0-20% 2010 Custodial Staff DEFECTIVE SYSTEM Throughout except Gymnasium and Auditorium 1 EACH REPAIR PRIORITY 3 LEVEL 2 No violations recorded Inspected
Pneuma	Instance Quantity Uom Building Area Covered by Operational System Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Violations atic System Instance Instance Condition	EACH 0-20% 2010 Custodial Staff DEFECTIVE SYSTEM Throughout except Gymnasium and Auditorium 1 EACH REPAIR PRIORITY 3 LEVEL 2 No violations recorded Inspected Auditorium & Gymnasium 4- Between Fair and Poor
Pneuma	Instance Quantity Uom Building Area Covered by Operational System Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Violations atic System Instance Instance Quantity	EACH 0-20% 2010 Custodial Staff DEFECTIVE SYSTEM Throughout except Gymnasium and Auditorium 1 EACH REPAIR PRIORITY 3 LEVEL 2 No violations recorded Inspected Auditorium & Gymnasium 4- Between Fair and Poor 1
Pneuma	Instance Quantity Uom Building Area Covered by Operational System Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Violations atic System Instance Condition Instance Quantity Instance Quantity Instance Quantity	EACH 0-20% 2010 Custodial Staff DEFECTIVE SYSTEM Throughout except Gymnasium and Auditorium 1 EACH REPAIR PRIORITY 3 LEVEL 2 No violations recorded Inspected Auditorium & Gymnasium 4- Between Fair and Poor 1 EACH
Pneuma	Instance Quantity Uom Building Area Covered by Operational System Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Violations atic System Instance Instance Quantity	EACH 0-20% 2010 Custodial Staff DEFECTIVE SYSTEM Throughout except Gymnasium and Auditorium 1 EACH REPAIR PRIORITY 3 LEVEL 2 No violations recorded Inspected Auditorium & Gymnasium 4- Between Fair and Poor 1

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

A	
estion	Response
LIMATE CONTROL SYSTEM	
Pneumatic System	
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE TEMPERATURE CONTROL ZONE VALVE
Deficiency Location/Instance	MER B10 @ Gymnasium Bl
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hybrid System	Does not exist
Electric System	Does not exist
OMPACTOR	Does not exist
ONVEYING	Does not exist
OMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Does not exist
Water Service	Inspected
Instance	Water/Gas Meter Room B4
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION
Denciency	DEVICE
Deficiency Location/Instance	Water/Gas Meter Room B4
Deficiency Quantity	
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Inspected
Condition	3- Fair
Deficiency	Flange Leaks
Deficiency Location/Instance	MER B10
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
	Inspected
Electric Domestic Water Heater	
Electric Domestic Water Heater Condition	1- Good
Condition	
	1- Good No deficiencies recorded Inspected

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

	IVIU
uestion	Response
DOMESTIC WATER SYSTEM	
Domestic Hot Water System	
Gas Fired Domestic Water Heater	
Instance Condition	5- Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Laars
EquipmentId	46383-3
Capacity/Size Quantity	625
Capacity/Size UOM	MBH Input
Capacity/Size 2 Quantity	0
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	1995
Source of Installation Year	Documented
Deficiency	DEFECTIVE UNIT
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
RAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sump Pump	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
TXTURES	Inspected
	Inspected
Staff And Other Janitor Sink	Inspected
Condition	
	3- Fair
Deficiency	
	No deficiencies recorded
Lavatory/Sink	Inspected
Lavatory/Sink	Inspected
Lavatory/Sink Condition	Inspected 3- Fair
Lavatory/Sink Condition Deficiency	Inspected 3- Fair No deficiencies recorded
Lavatory/Sink Condition Deficiency Toilet Condition	Inspected 3- Fair No deficiencies recorded Inspected 1- Good
Lavatory/Sink Condition Deficiency Toilet	Inspected 3- Fair No deficiencies recorded Inspected

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

iestion	Response
FIXTURES	
Staff And Other	
Urinal	
Deficiency	No deficiencies recorded
Student	Inspected
Drinking Fountain	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Locker Room Shower	Inspected
Instance on 2nd Floor - Boys	Inaccessible
Instance on 3rd Floor - Girls	Inaccessible
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	3- Fair
	-
Deficiency	No deficiencies recorded
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Does not exist
Gas Meter Room Vent	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Pressure Booster	Does not exist Does not exist
CO/Gas Leak Detection	
HEATING	Inspected
Heating Coil In Ductwork Condition	Inspected 3- Fair
Deficiency	
Deficiency Location/Instance	DEFECTIVE MER B10 @ Gymnasium Bl 11
Deficiency Quantity	
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	AUXILIARY (VALVE, VENT): DEFECTIVE
Deficiency Location/Instance	Various Locations
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

estion	Response	
EATING	response	
Radiator/Convector/Fin Tube		
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Steam Heating	Inspected	
F&T/Steam Drip Trap	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
MER Steam and Condensate Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Condensate Return Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Condensate Return Pumping System	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Piping	Inspected	
Condition	3- Fair	
Deficiency	DEFECTIVE/LEAKS	
Deficiency Location/Instance	Boy's Toilet Rooms 314, 220	
Deficiency Quantity	20	
Quantity Uom	L.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Terminal Unit Thermostatic Trap	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Steam supplied by External Sources Unit Heater/Cabinet Heater	Inspected	
	3- Fair	
Deficiency	No deficiencies recorded	
EATING PLANT	Inspected	
Instance on Basement	Inspected	
Is there a water meter on the boiler make-up water piping?	Yes	
Observed Operational?	Yes	
Burner Manufacturer Burner Model	Industrial Combustion	
	6N184TTDR8020BE L	
Burner Type Heating Plant Oil Number	Oil 2	
Boiler Auxiliaries	2	
Instance on Basement	Inspected	
	inspected	
Boiler Auxiliary Piping	Increased	
Instance on Basement	Inspected 3- Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Boiler Emergency Stop Switch		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
	No deficiencies recorded	
Deficiency	110 deficicles recorded	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

-	
estion	Response
EATING PLANT	
Boiler Auxiliaries	
Boiler Feedwater System	
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Feedwater Treatment(Automatic)	
Instance on Basement	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Boiler Flue Exhaust	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Make-up Water Backflow Preventer	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Boiler Room Steam And Condensate Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Safety Valve	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Boiler Room @ Boiler #2 (1 of 4)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Boiler System	
Instance on Basement	Inspected
Coal-fired Boiler	
Instance on Basement	Does not exist
Hot Water Boiler	
Instance on Basement	Does not exist
Modular Boiler	
Instance on Basement	Does not exist
Steam Boiler	
Instance on Basement	Inspected
Instance on Basement	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	5,346
Instance Quantity Uom	MBH NET

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

······r····		111
stion	Response	
EATING PLANT		
Boiler System		
Steam Boiler		
Cast Iron Boiler?	No	
Manufacturer	Fitzgibbons Boiler Company	
EquipmentId	46383-1	
Capacity/Size Quantity	5346	
Capacity/Size UOM	MBH Net	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1957	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	5,346	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	No	
Manufacturer	Fitzgibbons Boiler Company	
EquipmentId	46383-2	
Capacity/Size Quantity	5346	
Capacity/Size UOM	MBH Net	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1957	
Source of Installation Year	Documented	
Deficiency	DAMAGED/MISSING INSULATION	
Deficiency Quantity	10	
Quantity Uom	S.F.	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fuel System	In constant	
Instance on Basement	Inspected	
Boiler Fresh Air Louver/Damper	т 1	
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Type	Automatic	
Deficiency	No deficiencies recorded	
Burner/Burner Control Panel		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fuel Oil Storage/Supply System		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Gas Trains And Vent At The Boiler		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	NOT IN USE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	2	
Quantity Uom	2 EACH	
	NO ACTION	
Potential Action Urgency of Action	NO ACTION PRIORITY 1	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

uestion	Inspection	Response	
		Response	
	G PLANT		
Fuel Sys	stem rains And Vent At The Boiler		
Gas II	Violations	No violations recorded	
	IDF Room	Does not exist	
KITCHE		Inspected	
	Instance on 1st Floor	Inspected	
CO Det		·	
	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Gas Sys		·	
	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Grease		T / 1	
	Instance on 1st Floor	Inspected 1- Good	
	Instance Condition		
	Deficiency	No deficiencies recorded	
Hood	T	т., 1	
	Instance on 1st Floor	Inspected 3- Fair	
	Instance Condition		
	Deficiency	No deficiencies recorded	
Hood E	xhaust Ductwork	·	
	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Hood E	xhaust Fan		
	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	No deficiencies recorded	
Hood Fi	re Suppression System		
	Instance on 1st Floor	Does not exist	
Hot Wa	ter Temperature Booster		
	Instance on 1st Floor	Does not exist	
Kitchen		Y . 1	
	Instance on 1st Floor	Inspected	
	Instance Condition	3- Fair	
	Deficiency	Missing Air Gap	
	Deficiency Location/Instance Deficiency Quantity	Kitchen (1 of 2) 1	
	Quantity Uom	EACH	
	Potential Action	MAINTENANCE	
	Urgency of Action	PRIORITY 3	
	Purpose of Action	LEVEL 4	
	Violations	SF103187	
MDF Roo		Inspected	
	Instance on Room 226	Inspected	
Dedicat	ed A/C Equipment	пъресеч	
Duntati	Instance on Room 226	Inspected	
	Instance Condition	2- Between Good and Fair	
	Deficiency	No deficiencies recorded	
OFFICE		Does not exist	
SCIENCE	E DEMO ROOM	Does not exist	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

Response
Does not exist
Inspected
Does not exist
Inspected
3- Fair
DEFECTIVE/DETERIORATED
Room B9 (painted, 2)
2
EACH
REPLACE
PRIORITY 5
LEVEL 6
No violations recorded
Inspected
3- Fair
No deficiencies recorded
Does not exist
Does not exist
Does not exist
Inspected
Partial
Inspected
3- Fair
1-25
No deficiencies recorded
Inspected
4- Between Fair and Poor
DEFECTIVE HEATING COIL
Kitchen Office (1 of 1)
1
EACH
REPLACE PRIORITY 3
LEVEL 2
No violations recorded
Inspected
3- Fair
Yes
Yes
No deficiencies recorded
Inspected 3. Fair
3- Fair
-