Building Condition Assessment Survey 2023-2024

----And a set T.

ectrical Inspe	ection			M0
Asset:	I.S. 44 - MANHATTAN, 100 WEST 77 STREET, MA	NHATTAN, NY, 10024	4	
Inspection Id	Inspection Type		Time In	Last Edited
2266	ELECTRICAL		2024-01-08 10:21AM	2024-01-30 09:49AM
set Data				
Question		Answer		
Have any Syste	ms/Major Building Components been upgraded?	Systems:	Intrusion Alarm System (Partial I	Remote Annunciator)
		Years:	2023	
		Systems:	LAN	
		Years:	2022	
		Systems:	Most Exit Lights (Battery Pack)	
		Years:	2020	
		Systems:	Partial Emergency Lighting (Bat	tery Pack)
		Years:	2017	
		Systems: Years:	Fire Alarm System, Public Addre Sound System (Cafeteria and Gy Motor Starters, Variable Frequen Lighting (Except Library, Studen Partial Emergency Lighting (Nor 2015	mnasium), Most cy Drive, Interior nt Toilet Rooms),
		Systems:	Auditorium (Except House Light (Scoreboard)	ting), Gymnasium
		Years:	2012	
		Systems:	Library	
		Years:	2011	
		Systems:	Telephone System	
		Years:	2010	
		Systems:	Students Toilet Rooms (Fluoresc	ent Lighting)
		Years:	2009	
		Systems:	IPDVS/CCTV System	
		Years:	2008	
		Systems:	Partial Molded Case Circuit Brea	aker Type Panel Board
		Years:	2006, 1995	
		Systems:	Intrusion Alarm System	
		Years:	1999	
		Systems:	Security Lighting, Emergency Li Fused Disconnect Switch Type P	
		Years:	1995	

Does Interactive Whiteboard (IWB) Exist? Water Penetration In Electrical Room?

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question

Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in No your building?

Priority Condition

Type of Service

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No	Public Address System - Speakers Not Operational	Eighteen Speakers in Cafeteria and Two speakers in the Auditorium are Not Operational	Public Address System	Auditorium, Cafeteria	Ilean Ramos	Fireman	

Below Ground

Response

Yes

No

Building Condition Assessment Survey 2023-2024

0	Water Leaks onto Electrical Equipment	Steam Pipe Leak affecting an Electrical Motor	Electrical Motor	Boiler Room	Ilean Ramos	Fireman	
	1.1						
)	Other	Not Operational	LAN (MDF)	MDF Room 227	Ilean Ramos	Fireman	No Photo Taken
specti	on						
Questi	ion			Response			
Electr	ical						
ATH	ILETIC FIELD			Does not	exist		
AUD	DITORIUM			Inspected			
	Instance on 1st Floor			Inspected			
Ho	ouse Lighting						
	Instance on 1st Floor			Inspected			
_	Does a Chandelier Exi	ist?		No			
I	ighting Fixture - Fluoresce	nt					
	Instance on 1st Floor			Inspected			
	Pendant Mounted						
	Instance on 1st Floor			Does not	exist		
	Surface Mounted						
	Instance on 1st Floor			Inspected			
	Instance Condition			2- Betwee	en Good and F	air	
	Deficiency			No deficie	encies recorde	d	
	Recessed Mounted						
_	Instance on 1st Floor			Does not	exist		
I	ighting Fixture - HID						
	Instance on 1st Floor			Does not	exist		
I	ighting Fixture - Incandesc	ent					
_	Instance on 1st Floor			Does not	exist		
I	ighting Fixture - LED						
	Instance on 1st Floor			Inspected			
	Pendant Mounted						
	Instance on 1st Floor			Does not	exist		
	Surface Mounted						
	Instance on 1st Floor			Inspected			
	Instance Condition			2- Betwee	n Good and F	air	
	Deficiency			LIGHTIN	G FIXTURE	BALLAST DE	FECTIVE
	Deficiency Quantity	7		2			
	Quantity Uom			EACH			
	Potential Action				E BALLAST		
	Urgency of Action			PRIORIT			
	Purpose of Action			LEVEL 2			
	Violations				ons recorded		
	Deficiency				G FIXTURE	NOT OPERAT	IONAL
	Deficiency Quantity	7		7			
	Quantity Uom			EACH			
	Potential Action			REPAIR	V 2		
	Urgency of Action			PRIORIT LEVEL 2			
	Purpose of Action Violations				ons recorded		
					ons recorded		
	Recessed Mounted Instance on 1st Floor			Does not			

Building Condition Assessment Survey 2023-2024

Response

Electrical Inspection

Question

lestion	Response	
UDITORIUM		_
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2012	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Inspected	
Dimming System		-
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CAFETERIA	Inspected	
Instance on Basement	Inspected	
Lighting Instance on Basement	Inspected	
	hispected	
Lighting Fixture - Fluorescent		
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Does not exist	
Recessed Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Does not exist	
Local Sound System		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2015	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Basement	Does not exist	
Theater Lighting System		
	Does not exist	
Instance on Basement	Does not exist	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

icui Inspeciion	IVIL
uestion	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
COMPUTER LAB	Inspected
Instance on Room 305	Inspected
Power Panel?	
	No
Lighting	
Instance on Room 305	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 305	Inspected
Pendant Mounted	
Instance on Room 305	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 305	Does not exist
Recessed Mounted	
Instance on Room 305	Does not exist
Lighting Fixture - HID	
Instance on Room 305	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 305	Does not exist
Lighting Fixture - LED	
Instance on Room 305	Does not exist
Raceway With Receptacles	
Instance on Room 305	Inspected
Instance Condition	3- Fair
	No deficiencies recorded
Deficiency	no acticiencies recorded

NYC Department of Education Building Condition Assessment Survey 2023-2024

Electrical Inspection

M044

ical Inspection	M0
lestion	Response
GYMNASIUM	Inspected
Instance on 2nd Floor	Inspected
Lighting	
Instance on 2nd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Does not exist
Surface Mounted	
Instance on 2nd Floor	Does not exist
Recessed Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 2nd Floor	Does not exist
Scoreboard	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 2nd Floor	Does not exist
ITCHEN	Inspected
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not exist
Surface Mounted	
Instance on Basement	Does not exist
Recessed Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Engineering Flatter - LED	

NYC Department of Education Building Condition Assessment Survey 2023-2024

Electrical Inspection

trical Inspection	M
Question	Response
LIBRARY	Inspected
Instance on Room 139	Inspected
Lighting	
Instance on Room 139	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 139	Inspected
Pendant Mounted	1
Instance on Room 139	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 139	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 139	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID Instance on Room 139	Does not exist
	Does not exist
Lighting Fixture - Incandescent Instance on Room 139	Descent mid
	Does not exist
Lighting Fixture - LED	
Instance on Room 139	Does not exist
Raceway With Receptacles	Dece not avist
Instance on Room 139	Does not exist
Projection System Instance on Room 139	Does not exist
LOCKER ROOM	Does not exist
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Inspected
Instance on Room 215	Inspected
Power Panel?	Yes
Alternative Use	No
Lighting	
Instance on Room 215	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 215	Inspected
Pendant Mounted	
Instance on Room 215	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 215	Does not exist
Recessed Mounted	
Instance on Room 215	Does not exist
Lighting Fixture - HID	
Instance on Room 215	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 215	Inspected
	IIIspecied
Pendant Mounted	Descent anid
Instance on Room 215	Does not exist

Building Condition Assessment Survey 2023-2024

Electrical Inspection

		IV1044
uestion	Response	
SCIENCE LAB		
Lighting		
Lighting Fixture - Incandescent		
Surface Mounted		
Instance on Room 215	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 215	Does not exist	
Lighting Fixture - LED		
Instance on Room 215	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 215	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 215	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Room 215	Inspected	
Instructor Unit	Å	
Instance on Room 215	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Room 215	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Student Unit	No deficiencies recorded	
Instance on Room 215	Does not exist	
-	Does not exist	
Projection System Instance on Room 215	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 214	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting		
Instance on Room 214	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 214	Inspected	
Pendant Mounted		
Instance on Room 214	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 214	Does not exist	
Recessed Mounted		
Instance on Room 214	Does not exist	
Lighting Fixture - HID		
Instance on Room 214	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 214	Does not exist	
Lighting Fixture - LED		

Building Condition Assessment Survey 2023-2024

Electrical Inspection

Duestion	Besnonso
	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - LED Instance on Room 214	Does not exist
	Dues not exist
Emergency Gas Shut-Off Valve Instance on Room 214	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
	No denciencies recorded
Emergency Shut-Off Power Instance on Room 214	Inspected
Instance On Room 214	3- Fair
	No deficiencies recorded
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 214	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	DOOR PUSH BUTTON NOT OPERATIONAL
Deficiency Location/Instance	Exterior Wall by Main Entrance
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Electric Meter Room Switchboard
Deficiency Quantity	1

Building Condition Assessment Survey 2023-2024

Electrical Inspection

Question	Response
<u></u>	Kesponse
EMERGENCY LIGHT/EXIT LIGHT PANEL	
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action Purpose of Action	PRIORITY 5
Violations	LEVEL 2
	No violations recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected 2- Between Good and Fair
Condition	
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance Deficiency Quantity	By Custodian's Office - Room 101 1
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack Condition	Inspected 1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Auditorium - Projection Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	Inspected
CO Detector	пърсиси

Building Condition Assessment Survey 2023-2024

Electrical Inspection

cui inspection		19104
estion	Response	
IRE ALARM SYSTEM		
CO Detector		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Siemens	
Model	FireFinder XLS	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2015	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
ROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
NTERCOM SYSTEM	Inspected	
Elevator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Holding Area	Does not exist	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

	14104
uestion	Response
LAN	
Local Distribution Frame (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	4- Between Fair and Poor
Deficiency	NOT OPERATIONAL
Deficiency Location/Instance	MDF Room 227
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Penthouse - Mechanical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Basement Corridor by Stair E, 1st Floor Corridor by Room 103
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Basement (Boiler Room - Mechanical Room, Boiler Room, Electric Meter Room Switchboard), 1st Floor (by Room 103, Custodian's Office - Room 101)
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	MAINTENANCE

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	22
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	Basement By (Stair E, Room G4)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Closet Between Rooms 102 and 103
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland TC2100
Installation Year	2015
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	By Rooms (319, 322)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SPEAKER NOT OPERATIONAL
Deficiency Location/Instance	Auditorium, Cafeteria
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	3- Fair
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 101
Instance Condition	4- Between Fair and Poor
Instance Quantity	1

Building Condition Assessment Survey 2023-2024

Electrical Inspection

ical Inspection	M04
uestion	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	1999
Source of Installation Year	Documented
Deficiency	PANEL NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	4- Between Fair and Poor
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Roof and Exterior Walls - Building Perimeter
Deficiency Quantity	16
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
ERVICE SWITCH	Inspected
Instance	Electric Meter Room Switchboard
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Royal Switchboard Co.
EquipmentId	Main Switch Service A
Capacity/Size Quantity	750
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1957
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electric Meter Room Switchboard
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

Building Condition Assessment Survey 2023-2024

Electrical Inspection

icui Inspeciion		
uestion	Response	
SERVICE SWITCH		
Violations	No violations recorded	
Instance	Electric Meter Room Switchboard	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Royal Switchboard Co.	
EquipmentId	Main Switch Service B	
Capacity/Size Quantity	750	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Fuse Size	
Installation Year	1957	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electric Meter Room Switchboard	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SWITCHBOARD	Inspected	
Number of Spares	2	
Fused Disconnect Switch Type	Does not exist	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Inspected	
Instance	Electric Meter Room Switchboard	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Royal Switchboard Co.	
EquipmentId	Main Switchboard Sec A	
Capacity/Size Quantity	750	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Service Switch Fuse Size	
Installation Year	1957	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electric Meter Room Switchboard	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electric Meter Room Switchboard	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Royal Switchboard Co.	
Manufacturer EquipmentId	Main Switchboard Co.	
Equipmentid Capacity/Size Quantity	750	
Capacity/Size UOM	Amps Total	
Capacity/Size UOW	Anips Iotai	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response
SWITCHBOARD	
Molded Case Circuit Breaker Type	
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1957
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electric Meter Room Switchboard
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
FELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	SYSTEM NOT OPERATIONAL
Deficiency Location/Instance	MDF Room 227
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
FRANSFORMER	Does not exist