Building Condition Assessment Survey 2023-2024

Electrical Inspection

Asset:		I.S. 45 - MANHATTAN, 2351 1ST AVENUE, MANHATTAN, NY, 10035				
	Inspection Id	Inspection Type	Time In	Last Edited		
	2393	ELECTRICAL	2024-01-09 08:44AM	2024-06-17 09:06AM		
4 55	et Data					

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Most Security Lighting Retrofitted
	Years: 2023
	Systems: Retrofitted LED Lighting (Auditorium, Gymnasium, Stairs and Corridors)
	Years: 2022
	Systems: Fire Alarm System (Sprinkler Flow Switch, Tamper
	Flow Switch/Chain)
	Years: 2018
	Systems: Computer Lab - Room 139
	Years: 2017
	Systems: Telephone System
	Years: 2016, 2009
	Systems: Interior Fluorescent Lighting (Except Science Room 249, HID Lighting in Swimming Pool, Auditorium), Most Emergency Lighting (Non Battery Pack)
	Years: 2015
	Systems: Swimming Pool (HID Lighting), Auditorium (Fluorescent Lighting, Theater Lighting System)
	Years: 2013
	Systems: IPDVS/CCTV System
	Years: 2011
	Systems: Partial Switchboard, Panel Boards, Emergency Light/Exit Light Panel, Fire Alarm System, Public Address System, Local Sound System
	Years: 2006
	Systems: Science Lab Room 249
	Years: 2004
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

 Question
 Response

 Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?
 No

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Water Leaks onto Electrical Equipment	Roof Leak affecting an Emergency Lighting (Non Battery Pack) in the Gymnasium and a Lighting Fixture (House Lighting) in the Auditorium.	Emergency Lighting (Non Battery Pack) and Lighting Fixture (House Lighting)	Gymnasium, Auditorium	Gennaro Bonomo	Fireman	
No	Fire Alarm System - Components Not Operational	N/A	Fire Alarm System - Magnetic Door Holder/Contac tor	By Rooms (134, 212, 232, 249)	Gennaro Bonomo	Fireman	
Inspection	ı						
Question	l			Response	,		

Building Condition Assessment Survey 2023-2024

M045

rical Inspection	M
uestion	Response
lectrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	^
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	1
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CAFETERIA	Inspected
Instance on Basement - Students	Inspected
Instance on Basement - Staff	Inspected
instance on Dasement - Stall	mspecteu

Building Condition Assessment Survey 2023-2024

estion	Response	
CAFETERIA	Response	
Lighting		
Instance on Basement - Students	Inspected	
Instance on Basement - Staff	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement - Students	Inspected	
Instance on Basement - Staff	Inspected	
Pendant Mounted	1	
Instance on Basement - Students	Does not exist	
Instance on Basement - Staff	Does not exist	
Surface Mounted		
Instance on Basement - Students	Does not exist	
Instance on Basement - Staff	Does not exist	
Recessed Mounted		
Instance on Basement - Students	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Basement - Staff	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	No deficicles recorded	
Instance on Basement - Students	Does not exist	
Instance on Basement - Staff	Does not exist	
Lighting Fixture - Incandescent Instance on Basement - Students	Does not exist	
Instance on Basement - Staff	Does not exist	
	Does not exist	
Lighting Fixture - LED Instance on Basement - Students	Does not exist	
Instance on Basement - Staff		
	Does not exist	
Local Sound System Instance on Basement - Students	Inspected	
Instance Condition	3- Fair	
Installation Year	2006	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance on Basement - Staff	Does not exist	
Projection System	Does not exist	
Instance on Basement - Students	Does not exist	
Instance on Basement - Staff	Does not exist	
Theater Lighting System	Does not exist	
Instance on Basement - Students	Does not exist	
Instance on Basement - Staff	Does not exist	
LASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
	Inspected	
Lighting Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

i i i i i i i i i i i i i i i i i i i		
Question	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
COMPUTER LAB	Inspected	
Instance on Room 139	Inspected	
Power Panel?	Yes	
Instance on Room 153	Inspected	
Power Panel?	No	
Lighting		
Instance on Room 139	Inspected	
Instance on Room 153	Inspected	
Lighting Fixture - Fluorescent	^	
Instance on Room 139	Inspected	
Instance on Room 153	Inspected	
Pendant Mounted	X	
Instance on Room 139	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 153	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 139	Does not exist	
Instance on Room 153	Does not exist	
Recessed Mounted		
Instance on Room 139	Does not exist	
Instance on Room 153	Does not exist	
Lighting Fixture - HID		
Instance on Room 139	Does not exist	
Instance on Room 153	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 139	Does not exist	
Instance on Room 153	Does not exist	
Lighting Fixture - LED		
Instance on Room 139	Does not exist	
Instance on Room 153	Does not exist	
Raceway With Receptacles		
Instance on Room 139		
	Inspected	
Instance Condition	Inspected 2- Between Good and Fair	
	-	

Building Condition Assessment Survey 2023-2024

M045
111043

-

Building Condition Assessment Survey 2023-2024

Electrical Inspection

		M043
Question	Response	
KITCHEN		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Does not exist	
LIBRARY	Inspected	
Instance on Room 323	Inspected	
Lighting	1	
Instance on Room 323	Inspected	
Lighting Fixture - Fluorescent	A.	
Instance on Room 323	Inspected	
Pendant Mounted	* *	
Instance on Room 323	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 323	Does not exist	
Recessed Mounted		
Instance on Room 323	Does not exist	
Lighting Fixture - HID		
Instance on Room 323	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 323	Does not exist	
Lighting Fixture - LED		
Instance on Room 323	Does not exist	
Raceway With Receptacles		
Instance on Room 323	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 323	Does not exist	
LOCKER ROOM	Inspected	
Instance on Basement - Boys, Basement - Girls, Room 246A	Inspected	
Alternative Use	Yes	
Lighting	105	
Instance on Basement - Boys, Basement - Girls, Room 246A	Inspected	
Lighting Fixture - Fluorescent	inspected	
Instance on Basement - Boys, Basement - Girls, Room 246A	Inspected	
Pendant Mounted	inspected	
Instance on Basement - Boys, Basement - Girls, Room 246A	Does not exist	
Surface Mounted	Does not exist	
Instance on Basement - Boys, Basement - Girls, Room 246A	Inspected	
Instance on Basement - Boys, Basement - Giris, Room 246A	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	No deficiencies recorded	
Recessed Mounted	Doos not avist	
Instance on Basement - Boys, Basement - Girls, Room 246A Lighting Fixture - HID	Does not exist	

Building Condition Assessment Survey 2023-2024

vical Inspection	Response	
LOCKER ROOM	Response	
Lighting		
Lighting Fixture - HID		
Instance on Basement - Boys, Basement - Girls, Room 246A	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement - Boys, Basement - Girls, Room 246A	Does not exist	
Lighting Fixture - LED		
Instance on Basement - Boys, Basement - Girls, Room 246A	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Inspected	
Instance on Room 147/149	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting	INO	
Instance on Room 147/149	Inspected	
Lighting Fixture - Fluorescent	mspected	
Instance on Room 147/149	Inspected	
Pendant Mounted	inspected	
Instance on Room 147/149	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	No deficiencies recorded	
Instance on Room 147/149	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	No deficicles recorded	
Instance on Room 147/149	Does not exist	
Lighting Fixture - HID	Does not exist	
Instance on Room 147/149	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on Room 147/149	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on Room 147/149	Does not exist	
Emergency Gas Shut-Off Valve	Does not exist	
Instance on Room 147/149	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 147/149	Does not exist	
Power Supply		
Instance on Room 147/149	Does not exist	
Projection System		
Instance on Room 147/149	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 249	Inspected	
Power Panel?	Yes	
Alternative Use	Yes	
Instance on Room 427	Inspected	
Power Panel?	No	
Alternative Use	No	
	110	
Lighting Instance on Room 249	Inspected	
Instance on Room 427	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

cui Inspection		IVIU
estion	Response	
CIENCE LAB		
Lighting		
Lighting Fixture - Fluorescent		
Instance on Room 249	Inspected	
Instance on Room 427	Inspected	
Pendant Mounted		
Instance on Room 249	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 427	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 249	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 427	Does not exist	
Recessed Mounted		
Instance on Room 249	Does not exist	
Instance on Room 427	Does not exist	
Lighting Fixture - HID		
Instance on Room 249	Inspected	
Instance on Room 427	Does not exist	
Pendant Mounted		
Instance on Room 249	Does not exist	
Surface Mounted		
Instance on Room 249	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 249	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 249	Does not exist	
Instance on Room 427	Does not exist	
Lighting Fixture - LED		
Instance on Room 249	Does not exist	
Instance on Room 427	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 249	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 427	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 249	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 427	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Room 249	Inspected	
Instance on Room 427	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

		W1045
Question	Response	
SCIENCE LAB		
Power Supply		
Instructor Unit		
Instance on Room 249	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 427	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Room 249	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 427	Does not exist	
Student Unit		
Instance on Room 249	Does not exist	
Instance on Room 427	Does not exist	
Projection System		
Instance on Room 249	Does not exist	
Instance on Room 217	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 147/149A Power Panel?	Inspected	
	No	
Alternative Use	No	
Lighting		
Instance on Room 147/149A	Inspected	
Lighting Fixture - Fluorescent	Y	
Instance on Room 147/149A	Inspected	
Pendant Mounted	Description	
Instance on Room 147/149A	Does not exist	
Surface Mounted		
Instance on Room 147/149A	Does not exist	
Recessed Mounted		
Instance on Room 147/149A	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 147/149A	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 147/149A	Does not exist	
Lighting Fixture - LED		
Instance on Room 147/149A	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 147/149A	Does not exist	
Emergency Shut-Off Power		
Instance on Room 147/149A	Does not exist	
Power Supply		
Instance on Room 147/149A	Does not exist	
SWIMMING POOL	Inspected	
Instance on Basement	Inspected	
Lighting		
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement	Inspected	

Building Condition Assessment Survey 2023-2024

uestion	Response	
SWIMMING POOL	*	
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Does not exist	
Recessed Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Basement	Inspected	
Pendant Mounted	I I I I I I I I I I I I I I I I I I I	
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Does not exist	
Local Sound System	Does not exist	
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Installation Year	2006	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Scoreboard		
Instance on Basement	Does not exist	
COILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
FOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

M045	
------	--

rical Inspection	M043
uestion	Response
TOILET ROOM - STUDENT	
Lighting	
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2- Between Good and Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Electrical Room B11
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Inspected
Strobe Condition	3- Fair
Condition	
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	PULL STATION COVER IS MISSING
Deficiency Location/Instance Deficiency Quantity	Basement (Swimming Pool, Locker Room Boys, by Room B1), 3

Building Condition Assessment Survey 2023-2024

Electrical Inspection

	1120
estion	Response
IRE ALARM SYSTEM	
Manual Pull Station	
Quantity Uom	EACH
Potential Action	INSTALL COVER
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fan Shutdown Control	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Heat Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Elevator Recall	Does not exist
Magnetic Door Holder/Contactor	Inspected
Condition	3- Fair
Deficiency	CONTACTOR NOT OPERATIONAL
Deficiency Location/Instance	By Rooms (134, 212, 232, 249)
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Fused Cutout Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards System Technology
Model	EST 2
EquipmentId	Fire Alarm Control Panel
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist

Building Condition Assessment Survey 2023-2024

uestion	Response
FIRE ALARM SYSTEM	
Remote Annunciator	
Panel	
Condition	3- Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Inspected
Instance	Mechanical Room B49
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	N/A
EquipmentId	Roof FAN CONT PP
Capacity/Size Quantity	50
Capacity/Size UOM	Amps
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	1958
Source of Installation Year	Documented
Deficiency Deficiency Quantity	MCC PUSH BUTTON NOT OPERATIONAL
	2
Quantity Uom Potential Action	EACH MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Room B49
Deficiency Quantity	
Quantity Uom	EACH

Building Condition Assessment Survey 2023-2024

Electrical Inspection

ricui Inspection	N104
uestion	Response
MOTOR CONTROLLER	
MOTOR CONTROL CENTER	
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Molded Case Circuit Breaker Type Condition	2- Between Good and Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance Deficiency Quantity	Electrical Closet (314,
Quantity Uom Potential Action	EACH MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance Deficiency Quantity	Boiler Room, by Room 150
Quantity Uom	EACH
Potential Action Urgency of Action	INSTALL NEW PANEL BOARD PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 117
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Biamp MPA250
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	3- Fair
Installation Year	2011
Source of Installation Year	Documented
Deficiency	CAMERA NOT OPERATIONAL
Deficiency Location/Instance	Staircases (1st Floor - L, 2nd Floor - G)
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4

Building Condition Assessment Survey 2023-2024

ical Inspection	IV1045
uestion	Response
SECURITY	
IPDVS/CCTV System	
Violations	No violations recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Closet by Main Entrance Lobby
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1990
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Closet by Main Entrance Lobby
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	SENSOR NOT OPERATIONAL
Deficiency Location/Instance	Principal's Office - Zone 33
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
	No deficiencies recorded
Deficiency	
Lighting - Security	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room B11
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Royal Switchboard Co.
EquipmentId	Service SW A
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1958
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE

Building Condition Assessment Survey 2023-2024

Electrical Inspection

Question	Response	
SERVICE SWITCH		
Deficiency Location/Instance	Electrical Room B11	
Deficiency Quantity		
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
	Electrical Room B11	
Instance Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Royal Switchboard Co.	
EquipmentId	Service SW B	
Capacity/Size Quantity	2000	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Fuse Size	
Installation Year	1958	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room B11	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room B11	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Royal Switchboard Co.	
EquipmentId	Main Safety SW	
Capacity/Size Quantity	1200	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Fuse Size	
Installation Year	1958	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room B11	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SWITCHBOARD	Inspected	
Number of Spares	10	
Fused Disconnect Switch Type	Does not exist	
Fused Knife Switch Type	Inspected	
Instance	Electrical Room B11	
Instance Condition	3- Fair	
Instance Quantity	1	
	EACH	
Instance Quantity Uom		
Manufacturer	Royal Switchboard	
EquipmentId	REC Wing Dis Panel	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

ncui inspeci		111
Question		Response
SWITCHBOAH	D	
Fused Knife S	witch Type	
	ity/Size Quantity	1200
	ity/Size UOM	Amps Total
-	ity/Size 2 Quantity	1
Capa	ity/Size 2 UOM	Section(s)
Source	e of Capacity/Size	Service Switch Fuse Size
Instal	ation Year	1958
Source	e of Installation Year	Documented
Defic	ency	BEYOND USEFUL LIFE
	iciency Location/Instance	Electrical Room B11
De	iciency Quantity	1
Qu	ntity Uom	EACH
Pot	ential Action	REPLACE
Urg	ency of Action	PRIORITY 1
Pur	pose of Action	LEVEL 2
Vic	lations	No violations recorded
Molded Case	Circuit Breaker Type	Inspected
Insta	ce	Electrical Room B11
Insta	ce Condition	2- Between Good and Fair
Insta	ce Quantity	1
Insta	ce Quantity Uom	EACH
	facturer	Siemens
	mentId	MSB 1A, 2A
	ity/Size Quantity	1200
	ity/Size UOM	Amps Total
	ity/Size 2 Quantity	2
	ity/Size 2 UOM	- Section(s)
-	e of Capacity/Size	Nameplate
	ation Year	2006
Source	e of Installation Year	Documented
Defic	ency	No deficiencies recorded
Insta	ce	Mechanical Equipment Room B49
Insta	ce Condition	2- Between Good and Fair
Insta	ce Quantity	1
Insta	ce Quantity Uom	EACH
	facturer	Siemens
	mentId	MSB 2A, 2B
	ity/Size Quantity	800
	ity/Size UOM	Amps Total
	ity/Size 2 Quantity	2
-	ity/Size 2 UOM	Section(s)
Source	of Capacity/Size	Nameplate
Instal	ation Year	2006
Source	e of Installation Year	Documented
Defic	ency	No deficiencies recorded
TELEPHONE S	YSTEM	Inspected
PBX/Intercon		Inspected
Condition		3- Fair
Defic	ency	TELEPHONE NOT OPERATIONAL
	iciency Location/Instance	Penthouse - Mechanical Room, Cafeteria
	iciency Quantity	2
	ntity Uom	EACH
	ential Action	REPLACE TELEPHONE
	ency of Action	PRIORITY 3
	pose of Action	LEVEL 2
	lations	No violations recorded

NYC Department of Education Building Condition Assessment Survey 2023-2024

Electrical Inspection M045 Question Response TELEPHONE SYSTEM Inspected Standard Inspected Condition 3- Fair Deficiency No deficiencies recorded TRANSFORMER Does not exist