### **Building Condition Assessment Survey 2023-2024**

#### Mechanical Inspection

Asset: RICHARD R GREEN HS OF TEACHING - MANHATTAN, 421 EAST 88 STREET, MANHATTAN, NY, 10128				, 10128	
Inspection Id	Inspection Type		Time In	Last Edited	
2268	MECHANICAL		2024-01-08 07:37AM	2024-02-16 08:19AN	
sset Data					
Question		Answer			
Have any Systems/Major Building Components been upgraded?		Systems:	s: Fixtures - Drinking Fountains (~80%)		
		Years:	2023		
		Systems:	Fixtures - Toilets (~90%), Urinal	s	
		Years:	2022		
		Systems:	Climate Control System - Pneum	atic System -	
			Refrigerated Air Dryer, PRV Stat	tion	
		Years:	2020		
		Systems:	Kitchen - Grease Trap		
		Years:	2019		
		Systems:	MDF Room - Dedicated A/C Equ Split System)	upment (1 of 2, DX	
		Years:	2015		
		Systems:	Student Fixtures - Lavatory/Sink	s (~50%)	
		Years:	2013		
Are there fuel t	anks?	Yes			
Total # of a	bove ground tanks	1			

Are there fuel tanks?	ies
Total # of above ground tanks	1
Total capacity of all above ground tanks in gal.	7,500
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0
Total # of water main service entries to the asset	2
MERs/Fan Rooms Locations	Boiler Room Mechanical Area
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Painted/Obstructed Sprinkler Heads?	Yes
Location(s)	Basement Storage Room; 1st Floor - East Lobby Storage
	Room, West Lobby Storage Room, Closet within Custodian's
	Office (painted, 9)
Are there any Emergency Stop Switches with Missing Hammers?	No components

#### **Priority Condition**

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Other	Defective	Gas Meter Room Exhaust Fan	Gas Meter Room	Steven Lane	Fireman	
Yes	Defective Boiler Safety Auxiliary	(3)	Boiler Safety Valve	Boiler Room @ Boilers #1, #2	Steven Lane	Fireman	
No	Defective Boiler Safety Auxiliary	Defective Secondary Low Water Cut-off	Steam Boiler	Boiler Room / Boiler #3	Steven Lane	Fireman	

# Inspection Question Response Mechanical

## **Building Condition Assessment Survey 2023-2024**

M066
IVIUUU

unical Inspection	M0
estion	Response
IR CONDITIONING	Inspected
Chilled Water System	Inspected
Absorption Chiller	Does not exist
Air Cooled Chiller	Does not exist
Air Cooled Condenser	Does not exist
Chilled Water Distribution: Piping, Pumps and Auxiliaries	Inspected
Condition	3- Fair
Deficiency	PIPING:DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Roof
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Backflow Preventer	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Central Station Air Handler	Inspected
Instance	Boiler Room Mechanical Area
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
	Trane
Manufacturer	AC-1
EquipmentId Capacity/Size Quantity	8
Capacity/Size Quantity Capacity/Size UOM	Fan Motor HP
Source of Capacity/Size	Documented
Installation Year	1995
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
Fan Coil Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Inspected
Packaged Air Cooled Chiller Instance	Roof
	3- Fair
Instance Condition	
Instance Quantity	
Instance Quantity Uom	EACH
Manufacturer	Trane
EquipmentId	N/A
Capacity/Size Quantity	200
Capacity/Size UOM Source of Capacity/Size	Tons Increastor Estimate
Installation Year	Inspector Estimate 1995
Source of Installation Year	Inspector Estimate
Refrigerant Type	R-22
Deficiency	No deficiencies recorded
Water Cooled Chiller	Does not exist
	Does not exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist
Cooling Coil in Ductwork Cooling Tower	Does not exist
DX Split System	Does not exist
	Does not exist
Dry Cooler	Does not exist

## **Building Condition Assessment Survey 2023-2024**

anical Inspection	MUG
uestion	Response
AIR CONDITIONING	
Packaged Terminal A/C	Does not exist
Refrigerant Leak Detection System	Does not exist
Refrigerant Piping	Does not exist
Return Fan	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Inspected
BMS	Does not exist
Pneumatic System	Inspected
Instance	Throughout
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
Building Area Covered by Operational System	81-100%
Deficiency	No deficiencies recorded
Hybrid System	Does not exist
Electric System	Does not exist
COMPACTOR	Does not exist
CONVEYING	Inspected
Dumbwaiter	Does not exist
Elevator	Does not exist
Escalator	Does not exist
Non-auditorium Handicap Lift - Vertical	Does not exist
Non-auditorium Handicap Lift - Stair	Inspected
Condition	2- Between Good and Fair
Are all the existing non-auditorium handicap stair lifts operable?	Yes
Deficiency	No deficiencies recorded
Ash Hoist	Does not exist
Sidewalk Elevator	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Does not exist
Water Service	Inspected
Instance	Boiler Room; Boiler Room near Gas Meter Room
Instance Condition	2- Between Good and Fair
Instance Quantity	2
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Inspected
Instance	Boiler Room Mechanical Area
Instance Condition	4- Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	PVI
EquipmentId	N/A
Capacity/Size Quantity	1000

## **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

	<b>D</b>	
uestion	Response	
DOMESTIC WATER SYSTEM		
Domestic Hot Water System		
Gas Fired Domestic Water Heater		
Capacity/Size 2 Quantity	250	
Capacity/Size 2 UOM	Gallons	
Source of Capacity/Size	Documented 1995	
Installation Year		
Source of Installation Year	Inspector Estimate	
Deficiency	TANK RUSTY/LEAKS	
Deficiency Location/Instance	Boiler Room Mechanical Area	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Oil Fired Domestic Water Heater	Does not exist	
Heat Pump Domestic Water Heater	Does not exist	
Domestic Water Distribution Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping	Inspected	
Condition	3- Fair	
Deficiency	DEFECTIVE/LEAKS	
Deficiency Location/Instance	Boiler Room	
Deficiency Location/Instance	10	
Quantity Uom	L.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Sewage/Waste/Vent Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Does not exist	
Sump Pump	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
Student	Inspected	
	1	
Drinking Fountain	Inspected	

### **Building Condition Assessment Survey 2023-2024**

Response

#### **Mechanical Inspection**

Question

Question	Response
FIXTURES	
Student	
Drinking Fountain	
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Locker Room Shower	Does not exist
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	Inspected
	1- Good
Deficiency	No deficiencies recorded
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Gas Meter Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5 LEVEL 6
Purpose of Action Violations	LEVEL 6 No violations recorded
Gas Meter Room Vent Condition	Inspected 3- Fair
Deficiency	No deficiencies recorded
· · ·	
Gas Pressure Booster	Does not exist Inspected
CO/Gas Leak Detection	Boiler Room; Basement near Gas Meter Room
Instance Condition	3- Fair
Instance Condition	
	l EACH
Instance Quantity Uom	
Installation Year Source of Installation Year	2011 Custodial Staff
	No deficiencies recorded
Deficiency	
HEATING	Inspected
Heating Coil In Ductwork	Does not exist
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition Deficiency	3- Fair No deficiencies recorded

## **Building Condition Assessment Survey 2023-2024**

#### Mechanical Inspection

Response	
Inspected	
3- Fair	
No deficiencies recorded	
Inspected	
L.F.	
REPLACE	
PRIORITY 3	
LEVEL 2	
No violations recorded	
Inspected	
Does not exist	
Inspected	
3- Fair	
No deficiencies recorded	
Inspected	
Inspected	
No	
N/A	
Gordon Paitt	
Dual Fuel (Gas/Oil)	
2	
Inspected	
Inspected	
3- Fair	
No deficiencies recorded	
Inspected	
Inspected 3 Foir	
3- Fair	
3- Fair FEEDWATER PUMP:DEFECTIVE	
3- Fair FEEDWATER PUMP:DEFECTIVE Boiler Room	
3- Fair FEEDWATER PUMP:DEFECTIVE Boiler Room 1	
3- Fair FEEDWATER PUMP:DEFECTIVE Boiler Room 1 EACH	
3- Fair FEEDWATER PUMP:DEFECTIVE Boiler Room 1	
	Inspected 3 - Fair No deficiencies recorded Inspected 3 - Fair DEFECTIVE/LEAKS Boiler Room 10 L.F. REPLACE PRIORITY 3 LEVEL 2 No violations recorded Inspected 3 - Fair No deficiencies recorded Inspected 1 Inspe

## **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

······································		
stion	Response	
EATING PLANT		
Boiler Auxiliaries		
Boiler Feedwater System		
Violations	No violations recorded	
Boiler Feedwater Treatment(Automatic)		
Instance on Basement	Does not exist	
Boiler Flue Exhaust		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Make-up Water Backflow Preventer		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Room Steam And Condensate Piping		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Safety Valve		
Instance on Basement	Inspected	
Instance Condition	4- Between Fair and Poor	
	DEFECTIVE	
Deficiency Deficiency Location/Instance	Boiler Room @ Boilers #1, #2	
Deficiency Quantity	3	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Boiler System		
Instance on Basement	Inspected	
Coal-fired Boiler		
Instance on Basement	Does not exist	
Hot Water Boiler		
Instance on Basement	Does not exist	
Modular Boiler		
Instance on Basement	Does not exist	
Steam Boiler		
Instance on Basement	Inspected	
Instance on Basement	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	3,441	
Instance Quantity Uom	MBH NET	
	No	
Cast Iron Boiler? Manufacturer	A. L. Eastmond & Sons Inc.	
	7169-1	
EquipmentId Capacity/Size Quantity	3441	
Capacity/Size UOM	MBH Net	
Source of Capacity/Size	Documented	
Installation Year	1994	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Boiler Room	

## **Building Condition Assessment Survey 2023-2024**

#### Mechanical Inspection

3,441
MBH NET
No
A. L. Eastmond & Sons Inc.
7169-2
3441
MBH Net
Documented 1994
Documented
No deficiencies recorded
Boiler Room
3- Fair
-
3,441
MBH NET
No
A. L. Eastmond & Sons Inc. 7169-3
3441
MBH Net
Documented
1994
Documented
DEFECTIVE SAFETY AUXILIARY: LOW-WATER CUT-OFF, WATER COLUMN ASSEMBLY
1
EACH
MAINTENANCE
PRIORITY 5
LEVEL 6
No violations recorded
Inspected
<b>A</b>
Inspected
3- Fair
Automatic
No deficiencies recorded
Inspected
3- Fair
No deficiencies recorded
Turne et al
Inspected 3- Fair
-
FUEL OIL PIPING:DEFECTIVE/LEAKS
Boiler Room by Fuel oil Pumps
1
EACH
MAINTENANCE
PRIORITY 3
LEVEL 2

## **Building Condition Assessment Survey 2023-2024**

3.40	"
MU	00

anical Inspection		M06
uestion	Response	
HEATING PLANT		
Fuel System		
Gas Trains And Vent At The Boiler		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Enclosed IDF Room	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
CO Detector	inspected (	
Instance on 1st Floor	Not required	
Gas System	1	
Instance on 1st Floor	Does not exist	
Grease Trap		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Hood		
Instance on 1st Floor	Does not exist	
Hood Exhaust Ductwork		
Instance on 1st Floor	Does not exist	
Hood Exhaust Fan		
Instance on 1st Floor	Does not exist	
Hood Fire Suppression System		
Instance on 1st Floor	Does not exist	
Hot Water Temperature Booster		
Instance on 1st Floor	Does not exist	
Kitchen Sink		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	Missing Air Gap	
Deficiency Location/Instance	Kitchen	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 4	
Violations	SF103050	
MDF Room	Inspected	
Instance on Room 306A	Inspected	
Dedicated A/C Equipment		
Instance on Room 306A	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 401	Inspected	
Alternative Use	Yes	
Acid Waste Neutralizing Tank		
Instance on Room 401	Does not exist	
CO Detector		
Instance on Room 401	Not required	
Emergency Shower	•	

## **Building Condition Assessment Survey 2023-2024**

uestion	Response
	Response
SCIENCE LAB	
Emergency Shower	2 5-1-
Instance Condition	3-Fair
Deficiency	No deficiencies recorded
Eye Wash	
Instance on Room 401	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	
Instance on Room 401	Does not exist
Hood Exhaust Fan	
Instance on Room 401	Does not exist
Fixed Laboratory Hood	
Instance on Room 401	Does not exist
Laboratory Sink	
Instance on Room 401	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Make-up Air Unit	
Instance on Room 401	Does not exist
SCIENCE PREP ROOM	Inspected
Instance on Room 402	Inspected
Alternative Use	Yes
Acid Waste Neutralizing Tank	103
Instance on Room 402	Does not exist
CO Detector	
Instance on Room 402	Not required
Emergency Shower	norregunou
Instance on Room 402	Does not exist
Eve Wash	
Instance on Room 402	Does not exist
Hood Exhaust Ductwork	
Instance on Room 402	Does not exist
Hood Exhaust Fan	Does not exist
Instance on Room 402	Does not exist
Fixed Laboratory Hood Instance on Room 402	Does not exist
	Does not exist
Laboratory Sink	T (1
Instance on Room 402	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Make-up Air Unit	
Instance on Room 402	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist
Wet Sprinkler Alarm Valve Assembly	Does not exist
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Does not exist
Sprinkler Head	Inspected
Condition	5- Poor
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Basement Storage Room; 1st Floor - East Lobby Storage Room, West Lobby Storage Room, Closet within Custodian's Office (painted, 9)

## **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

uestion	Response
SPRINKLERS, STANDPIPE, FIRE SYSTEM	
Sprinkler Head	
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Sprinkler Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standpipe System	Does not exist
Water Gong	Does not exist
SWIMMING POOL	Does not exist
VENTILATION	Inspected
Is the building Mechanically ventilated?	Yes
Exhaust Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-25
Deficiency	DEFECTIVE MOTOR
Deficiency Location/Instance	Kitchen Storage Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Heating And Ventilating Unit	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Kitchen Office (1 of 1)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Metal Ductwork	Inspected
Condition	3- Fair
Are there any uninsulated ductwork by design in Mechanical rooms?	No
Are there chain operated dampers?	No
Deficiency	No deficiencies recorded
Supply Fan	Does not exist
Unit Ventilator	Does not exist