#### **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

Asset:	P.S. 72 - MANHATTAN, 131 EAST 104 STREET, MA	NHATTAN, NY, 1002	.9	
Inspection Id	Inspection Type		Time In	Last Edited
1157	ELECTRICAL		2023-11-21 09:20AM	2023-12-11 02:20PM
et Data				
Question		Answer		
Have any Syste	ms/Major Building Components been upgraded?	Systems:	LED Lighting (6th Floor Soccer	Field)
		Years:	2022	
		Systems:	Exit Lights (Battery Pack)	
		Years:	2020, 2017	
		Systems:	Exit/Emergency Lights	
		Years:	2020	
		Systems:	Partial Molded Case Circuit Brea	ker Panel Board
		Years:	2017, 2011, 1999	
		Systems: Years:	Auditorium (Local Sound Systen Theater Lighting System), Scienc Cafeteria (Local Sound System) 2017	
		Systems:	Lighting - Security	
		Years:	2016	
		Systems:	Interior Lighting, Partial Emerge Battery Pack)	ncy Lighting (Non
		Years:	2015	
		Systems:	Partial Service Switch	
		Years:	2010	

	Systems: Public Address System
	Years: 2000
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	Yes
DEDICATED INTERCOMS IN FIRE RESCUE AREAS	

Systems: Fire Alarm System 2007

2001

Response

No

Systems: Emergency Light/Exit Light Panel

Years:

Years:

#### Question

Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?

#### **Priority Condition**

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
	Category	Description	Antettu	Description	Rotifica	The	
Yes	Water Penetration in	N/A	Electrical	Basement	David	Custodian	No Photo Taken
	Electrical Room		Equipment	Electrical	Correa		
				Meter Room			
				inside			
				Mechanical			
				Room			
Yes	Water Leaks onto	Roof Leak, Pipe Leak	Lighting	Library,	David	Custodian	No Photo Taken
	Electrical Equipment		Fixture	Rooms 508,	Correa		
				511, 4th Floor			
				Staff Toilet			
				Room			
Inspection	!						
Question				Response			
Electrica	1						
ATHLI	ETIC FIELD			Does not e	xist		
AUDIT	ORIUM			Inspected			

# **Building Condition Assessment Survey 2023-2024**

uestion	Response	
AUDITORIUM		
Instance on 1st Floor	Inspected	
House Lighting	inspected	
Instance on 1st Floor	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	No deficicies recorded	
Surface Mounted	<b>D</b>	
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Local Sound System Instance on 1st Floor	Inspected	
	2- Between Good and Fair	
Instance Condition	2017	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
	No deficicies recorded	
Projection System Instance on 1st Floor	Inspected	
	2- Between Good and Fair	
Instance Condition		
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System	x 1	
Instance on 1st Floor	Inspected	
Dimming System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CAFETERIA	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	

# **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

	Γ	VIU/2
Question	Response	
CAFETERIA		
Lighting		
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on 1st Floor	Does not exist	
Local Sound System Instance on 1st Floor	Inspected	
	2- Between Good and Fair	
Installation Year	2017	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
	Inspected	
Lighting Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Recessed Mounted		
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL	
Deficiency Quantity	5	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Recessed Mounted	Does not exist	
COMPUTER LAB	Inspected	

# NYC Department of Education **Building Condition Assessment Survey 2023-2024**

uestion	Response	
COMPUTER LAB	*	
Instance on Room 410	Inspected	
Power Panel?	No	
Lighting	10	
Instance on Room 410	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 410	Inspected	
Pendant Mounted	inspected	
Instance on Room 410	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	No deficiencies recorded	
Surface Mounted	De como est estist	
Instance on Room 410	Does not exist	
Recessed Mounted		
Instance on Room 410	Does not exist	
Lighting Fixture - HID		
Instance on Room 410	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 410	Does not exist	
Lighting Fixture - LED		
Instance on Room 410	Does not exist	
Raceway With Receptacles		
Instance on Room 410	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	RECEPTACLES NOT OPERATIONAL	
Deficiency Quantity	6	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
GYMNASIUM	Inspected	
Instance on 2nd Floor	Inspected	
Lighting	*	
Instance on 2nd Floor	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on 2nd Floor	Inspected	
Pendant Mounted		
Instance on 2nd Floor	Does not exist	
Surface Mounted		
Instance on 2nd Floor	Inspected	
	2- Between Good and Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - HID		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 2nd Floor	Does not exist	
Local Sound System		
Instance on 2nd Floor	Does not exist	

# **Building Condition Assessment Survey 2023-2024**

uestion	Response	
	Kesponse	
GYMNASIUM		
Projection System Instance on 2nd Floor	Does not exist	
Scoreboard		
Instance on 2nd Floor	Does not exist	
Theater Lighting System		
Instance on 2nd Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
	Inspected	
Lighting Instance on 1st Floor	Inspected	
	Inspected	
Lighting Fixture - Fluorescent Instance on 1st Floor	Inspected	
Pendant Mounted	Inspected	
Instance on 1st Floor	Does not exist	
	Does not exist	
Surface Mounted	T (1	
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 511/512	Inspected	
Lighting		
Instance on Room 511/512	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 511/512	Inspected	
Pendant Mounted		
Instance on Room 511/512	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 511/512	Does not exist	
Recessed Mounted		
Instance on Room 511/512	Does not exist	
Lighting Fixture - HID		
Instance on Room 511/512	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 511/512	Does not exist	
	Does not exist	
Lighting Fixture - LED Instance on Room 511/512	Does not exist	
	בסבצ ווטו באואו	
Raceway With Receptacles Instance on Room 511/512	Does not exist	
	Does not exist	
Projection System Instance on Room 511/512	Doos not aviat	
	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Does not exist	

# NYC Department of Education Building Condition Assessment Survey 2023-2024

N	A	77
IVI	v	14

rical Inspection	MU
Question	Response
SCIENCE DEMO ROOM	Inspected
Instance on Room 407	Inspected
Power Panel?	No
Alternative Use	No
Lighting	
Instance on Room 407	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 407	Inspected
Pendant Mounted	
Instance on Room 407	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 407	Does not exist
Recessed Mounted	
Instance on Room 407	Does not exist
Lighting Fixture - HID	
Instance on Room 407	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 407	Does not exist
Lighting Fixture - LED	
Instance on Room 407	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 407	Does not exist
Emergency Shut-Off Power	
Instance on Room 407	Does not exist
Power Supply	
Instance on Room 407	Does not exist
Projection System	
Instance on Room 407	Does not exist
SCIENCE LAB	Inspected
Instance on Room 507	Turner et al.
	Inspected
Power Panel?	No
Power Panel? Alternative Use	No
Alternative Use	
	No No
Alternative Use Lighting Instance on Room 507	No
Alternative Use Lighting Instance on Room 507 Lighting Fixture - Fluorescent	No No Inspected
Alternative Use Lighting Instance on Room 507	No No
Alternative Use         Lighting         Instance on Room 507         Lighting Fixture - Fluorescent         Instance on Room 507	No No Inspected Inspected
Alternative Use         Lighting         Instance on Room 507         Lighting Fixture - Fluorescent         Instance on Room 507         Pendant Mounted	No No Inspected
Alternative Use         Lighting         Instance on Room 507         Lighting Fixture - Fluorescent         Instance on Room 507         Pendant Mounted         Instance on Room 507	No No Inspected Inspected Inspected Inspected
Alternative Use         Lighting         Instance on Room 507         Lighting Fixture - Fluorescent         Instance on Room 507         Pendant Mounted         Instance on Room 507         Instance on Room 507         Deficiency	No         No         Inspected         Inspected         Inspected         2- Between Good and Fair
Alternative Use         Lighting         Instance on Room 507         Lighting Fixture - Fluorescent         Instance on Room 507         Pendant Mounted         Instance on Room 507         Instance Condition         Deficiency         Surface Mounted	No         No         Inspected         Inspected         2- Between Good and Fair         No deficiencies recorded
Alternative Use         Lighting         Instance on Room 507         Lighting Fixture - Fluorescent         Instance on Room 507         Pendant Mounted         Instance on Room 507         Instance on Room 507         Deficiency         Surface Mounted         Instance on Room 507	No         No         Inspected         Inspected         Inspected         2- Between Good and Fair
Alternative Use         Lighting         Instance on Room 507         Lighting Fixture - Fluorescent         Instance on Room 507         Pendant Mounted         Instance on Room 507         Instance on Room 507         Instance on Room 507         Surface Mounted         Instance on Room 507         Recessed Mounted	No         No         Inspected         Inspected         2- Between Good and Fair         No deficiencies recorded         Does not exist
Alternative Use         Lighting         Instance on Room 507         Lighting Fixture - Fluorescent         Instance on Room 507         Pendant Mounted         Instance on Room 507         Instance on Room 507         Instance Condition         Deficiency         Surface Mounted         Instance on Room 507         Recessed Mounted         Instance on Room 507	No         No         Inspected         Inspected         2- Between Good and Fair         No deficiencies recorded
Alternative Use         Lighting         Instance on Room 507         Lighting Fixture - Fluorescent         Instance on Room 507         Pendant Mounted         Instance on Room 507         Instance Condition         Deficiency         Surface Mounted         Instance on Room 507         Recessed Mounted         Instance on Room 507         Lighting Fixture - HID	No         No         Inspected         Inspected         2- Between Good and Fair         No deficiencies recorded         Does not exist         Does not exist
Alternative Use         Lighting         Instance on Room 507         Lighting Fixture - Fluorescent         Instance on Room 507         Pendant Mounted         Instance on Room 507         Instance on Room 507         Instance Condition         Deficiency         Surface Mounted         Instance on Room 507         Recessed Mounted         Instance on Room 507         Lighting Fixture - HID         Instance on Room 507	No         No         Inspected         Inspected         2- Between Good and Fair         No deficiencies recorded         Does not exist
Alternative Use         Lighting         Instance on Room 507         Lighting Fixture - Fluorescent         Instance on Room 507         Pendant Mounted         Instance on Room 507         Instance on Room 507         Instance Ondition         Deficiency         Surface Mounted         Instance on Room 507         Recessed Mounted         Instance on Room 507         Lighting Fixture - HID         Instance on Room 507         Lighting Fixture - Incandescent	No         No         Inspected         Inspected         2- Between Good and Fair         No deficiencies recorded         Does not exist         Does not exist         Does not exist
Alternative Use         Lighting         Instance on Room 507         Lighting Fixture - Fluorescent         Instance on Room 507         Pendant Mounted         Instance on Room 507         Instance on Room 507         Instance on Room 507         Instance on Room 507         Instance Ondition         Deficiency         Surface Mounted         Instance on Room 507         Recessed Mounted         Instance on Room 507         Lighting Fixture - HID         Instance on Room 507         Lighting Fixture - HID         Instance on Room 507         Lighting Fixture - Incandescent         Instance on Room 507	No         No         Inspected         Inspected         2- Between Good and Fair         No deficiencies recorded         Does not exist         Does not exist
Alternative Use         Lighting         Instance on Room 507         Lighting Fixture - Fluorescent         Instance on Room 507         Pendant Mounted         Instance on Room 507         Instance Condition         Deficiency         Surface Mounted         Instance on Room 507         Recessed Mounted         Instance on Room 507         Lighting Fixture - HID         Instance on Room 507         Lighting Fixture - Incandescent         Instance on Room 507	No         No         Inspected         Inspected         Inspected         2- Between Good and Fair         No deficiencies recorded         Does not exist         Does not exist
Alternative Use         Lighting         Instance on Room 507         Lighting Fixture - Fluorescent         Instance on Room 507         Pendant Mounted         Instance on Room 507         Instance on Room 507         Instance Condition         Deficiency         Surface Mounted         Instance on Room 507         Recessed Mounted         Instance on Room 507         Lighting Fixture - HID         Instance on Room 507         Lighting Fixture - Incandescent         Instance on Room 507	No         No         Inspected         Inspected         2- Between Good and Fair         No deficiencies recorded         Does not exist         Does not exist         Does not exist

# **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

		NIU / 2
Question	Response	
SCIENCE LAB		
Lighting		
Lighting Fixture - LED		
Surface Mounted		
Instance on Room 507	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 507	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 507	Does not exist	
Emergency Shut-Off Power		
Instance on Room 507	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Room 507	Inspected	
Instructor Unit		
Instance on Room 507	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Room 507	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Student Unit		
Instance on Room 507	Does not exist	
Projection System		
Instance on Room 507	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 508	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting		
Instance on Room 508	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 508	Inspected	
Pendant Mounted		
Instance on Room 508	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 508	Does not exist	
Recessed Mounted		
Instance on Room 508	Does not exist	
Lighting Fixture - HID		
Instance on Room 508	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 508	Does not exist	
Lighting Fixture - LED		
Instance on Room 508	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 508	Does not exist	
Emergency Shut-Off Power		

# NYC Department of Education Building Condition Assessment Survey 2023-2024

#### Electrical Inspection

rical Inspection	M072
Question	Response
SCIENCE PREP ROOM	
Emergency Shut-Off Power	
Instance on Room 508	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 508	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	INDICATOR PANEL NOT OPERATIONAL
Deficiency Location/Instance Deficiency Quantity	Custodian's Office 1
Quantity Uom	I EACH
Potential Action	REPLACE PANEL
Urgency of Action	PRIORITY 3
	LEVEL 2
Purpose of Action Violations	
	No violations recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Auditorium

# **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

	MO
iestion	Response
EMERGENCY LIGHTING	
Battery Pack	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected 1- Good
Condition	
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Inspected
Condition	2- Between Good and Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	6th Floor Soccer Field
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
	2- Between Good and Fair
Condition	
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Heat Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Does not exist
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

# **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

# **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

estion	Response
ANEL BOARD	
Fused Toggle Switch Type	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Basement Pump Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	NO SPARE
Deficiency Location/Instance	Kitchen, Corridor near Rooms 41a, 302, 211
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
UBLIC ADDRESS SYSTEM	Inspected
	1st Floor General Office
Instance Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland Telecenter System 21
	2000
Installation Year	2000
Source of Installation Year	Documented
Source of Installation Year Deficiency	Documented CLOCK NOT OPERATIONAL
Source of Installation Year Deficiency Deficiency Location/Instance	Documented CLOCK NOT OPERATIONAL Classrooms and Corridors
Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity	Documented CLOCK NOT OPERATIONAL Classrooms and Corridors 20
Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom	Documented CLOCK NOT OPERATIONAL Classrooms and Corridors 20 EACH
Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action	Documented CLOCK NOT OPERATIONAL Classrooms and Corridors 20 EACH REPLACE
Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action	Documented CLOCK NOT OPERATIONAL Classrooms and Corridors 20 EACH REPLACE PRIORITY 3
Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action	Documented         CLOCK NOT OPERATIONAL         Classrooms and Corridors         20         EACH         REPLACE
Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action	Documented         CLOCK NOT OPERATIONAL         Classrooms and Corridors         20         EACH         REPLACE         PRIORITY 3
Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action	DocumentedCLOCK NOT OPERATIONALClassrooms and Corridors20EACHREPLACEPRIORITY 3LEVEL 2
Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Violations	DocumentedCLOCK NOT OPERATIONALClassrooms and Corridors20EACHREPLACEPRIORITY 3LEVEL 2No violations recorded
Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Violations ECURITY IPDVS/CCTV System	DocumentedCLOCK NOT OPERATIONALClassrooms and Corridors20EACHREPLACEPRIORITY 3LEVEL 2No violations recordedInspected
Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Violations ECURITY	DocumentedCLOCK NOT OPERATIONALClassrooms and Corridors20EACHREPLACEPRIORITY 3LEVEL 2No violations recordedInspectedUnder construction
Source of Installation Year         Deficiency         Deficiency Location/Instance         Deficiency Quantity         Quantity Uom         Potential Action         Urgency of Action         Purpose of Action         Violations	DocumentedCLOCK NOT OPERATIONALClassrooms and Corridors20EACHREPLACEPRIORITY 3LEVEL 2No violations recordedInspectedUnder constructionInspected
Source of Installation Year         Deficiency         Deficiency Location/Instance         Deficiency Quantity         Quantity Uom         Potential Action         Urgency of Action         Purpose of Action         Violations         ECURITY         IPDVS/CCTV System         Intrusion Alarm System         Central Control Panel         Instance	DocumentedCLOCK NOT OPERATIONALClassrooms and Corridors20EACHREPLACEPRIORITY 3LEVEL 2No violations recordedInspectedInspectedInspectedInspectedInspectedInspected
Source of Installation Year         Deficiency         Deficiency Location/Instance         Deficiency Quantity         Quantity Uom         Potential Action         Urgency of Action         Purpose of Action         Violations         ECURITY         IPDVS/CCTV System         Intrusion Alarm System         Central Control Panel         Instance         Instance Condition	DocumentedCLOCK NOT OPERATIONALClassrooms and Corridors20EACHREPLACEPRIORITY 3LEVEL 2No violations recordedInspectedUnder constructionInspectedInspectedCustodian's Office3- Fair
Source of Installation Year         Deficiency         Deficiency Location/Instance         Deficiency Quantity         Quantity Uom         Potential Action         Urgency of Action         Purpose of Action         Violations         ECURITY         IPDVS/CCTV System         Intrusion Alarm System         Central Control Panel         Instance         Instance Quantity	DocumentedCLOCK NOT OPERATIONALClassrooms and Corridors20EACHREPLACEPRIORITY 3LEVEL 2No violations recordedInspectedInspectedInspectedInspectedCustodian's Office3- Fair1
Source of Installation Year         Deficiency         Deficiency Location/Instance         Deficiency Quantity         Quantity Uom         Potential Action         Urgency of Action         Purpose of Action         Violations         ECURITY         IPDVS/CCTV System         Intrusion Alarm System         Central Control Panel         Instance         Instance Quantity         Instance Quantity         Instance Quantity         Instance Quantity	DocumentedCLOCK NOT OPERATIONALClassrooms and Corridors20EACHREPLACEPRIORITY 3LEVEL 2No violations recordedInspectedUnder constructionInspectedInspectedCustodian's Office3- Fair1EACH
Source of Installation Year         Deficiency         Deficiency Location/Instance         Deficiency Quantity         Quantity Uom         Potential Action         Urgency of Action         Purpose of Action         Violations         ECURITY         IPDVS/CCTV System         Intrusion Alarm System         Central Control Panel         Instance         Instance Quantity         Instance Quantity         Instance Quantity         Instance Quantity         Instance Quantity         Instance Quantity         Instance Quantity	DocumentedCLOCK NOT OPERATIONALClassrooms and Corridors20EACHREPLACEPRIORITY 3LEVEL 2No violations recordedInspectedInspectedInspectedInspectedCustodian's Office3- Fair1EACHVista - 50P
Source of Installation Year         Deficiency         Deficiency Location/Instance         Deficiency Quantity         Quantity Uom         Potential Action         Urgency of Action         Purpose of Action         Violations         ECURITY         IPDVS/CCTV System         Intrusion Alarm System         Central Control Panel         Instance         Instance Quantity         Instance Quantity         Instance Quantity         Instance Quantity	DocumentedCLOCK NOT OPERATIONALClassrooms and Corridors20EACHREPLACEPRIORITY 3LEVEL 2No violations recordedInspectedUnder constructionInspectedInspectedCustodian's Office3- Fair1EACH

# **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

iestion	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REWIRE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Building Perimeters
Deficiency Quantity	13
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
ERVICE SWITCH	Inspected
Instance	Basement Electrical Meter Room
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
Manufacturer	Metropolitan
EquipmentId	AC Service Switch
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1961
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Basement Electrical Meter Room
Deficiency Quantity	1
Quantity Uom	EACH

# Building Condition Assessment Survey 2023-2024

### **Electrical Inspection**

nicui Inspection	1
Question	Response
SERVICE SWITCH	
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Basement Electrical Meter Room
Instance Condition	3- Fair
Instance Quantity	
Instance Quantity Uom	EACH
Manufacturer	Metropolitan
EquipmentId	N/A
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1961
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Basement Electrical Meter Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Basement Electrical Meter Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	Boiler Room Service Switch
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD Number of Spares	Inspected 4
Fused Disconnect Switch Type Instance	Basement Electrical Room
	3- Fair
Instance Condition	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan Electric
EquipmentId	N/A
Capacity/Size Quantity	400
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1972
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Basement Electrical Room
Deficiency Quantity	1

# **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

uestion	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Inspected
Instance	Basement Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan Electric
EquipmentId	N/A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1961
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Basement Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Does not exist
FELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist