lectrical Inspe							M0
Asset:		LT LRNG CTR (81) - N	MANHATTAN, 212 V	W 120TH STRE		, NY, 100	
Inspection Id	Inspection Type				Time In		Last Edited
	ELECTRICAL				2024-01-17	09:23AM	2024-02-13 07:25AN
set Data							
Question				Answer			
Have any Systems/Major Building Components been upgraded?		?	Systems:	Partial Molded Case			
				Years:	2023, 2015, 2011, 20	06, 2003,	2001, 1999
				Systems:	LAN		
				Years:	2022		
				Systems:		ce Mounte	ed, Recessed Mounted)
				Years:	2019		
				Systems:	Pendant LED Lightin	g, Public	Address System
				Years:	2017		
				Systems:	Computer Lab - Room		
				**	Receptacles), Partial	Security I	Lighting
				Years:	2014	1.0	
				Systems:	Auditorium Local So	una Syste	m
				Years:	2013		Y 41 0 (00
				Systems:	Detectors)	chboard, I	Fire Alarm System (CO
				Years:	2011		
				Systems:	Fire Alarm System (I	Except CC	Detector)
				Years:	2005		
				Systems:	Interior Fluorescent I	Lighting	
				Years:	2004		
				Systems:	Emergency Light/Exi	t Light Pa	inel
				Years:	2003		
				Systems:	Intrusion Alarm Syste	em	
				Years:	2000		
Type of Service				Below G	ound		
	e Whiteboard (IWB)			Yes			
	on In Electrical Room			No			
	) INTERCOMS IN	N FIRE RESCUE ARE	AS				
Question	T :f- D Ai-t	A Eine D A	4/ II-14: D		Response		
your building		nce Areas, Fire Rescue Are	as, and/or Holding Roof	ns in	No		
iority Conditi	ion						
Exist Prio	•	Condition	Component	Location	Person(s) Perso	` ′	Photo
	egory	Description	Affected	Description	Notified Title		Image
No condition re	corded						
nspection Question				Response	<u> </u>		
Electrical				response	•		
ATHLETIC	FIELD			Does not	exist		
AUDITORIUM			Inspected				
·	stance on Basement			Inspected			
House Ligh							
	stance on Basement			Inspected			
Do	oes a Chandelier Exis	it?		No			
-	Fixture - Fluorescen	ıt					
Ins	stance on Basement			Does not	exist		
Lighting	Fixture - HID						
Ins	stance on Basement			Does not	exist		
Lighting	Fixture - Incandesco	ent					

Electrical Inspection		M081
Question	Response	

Question	Response
AUDITORIUM	<u>·</u>
House Lighting	
Lighting Fixture - Incandescent	
Pendant Mounted	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Instance on Basement	Does not exist
Local Sound System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Installation Year	2013
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
Projection System	
Instance on Basement	Does not exist
Theater Lighting System	
Instance on Basement	Does not exist
CAFETERIA	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
COMPUTER LAB	Inspected
Instance on Room 201	Inspected
Power Panel?	Yes

#### **Building Condition Assessment Survey 2023-2024**

uestion	Response	
	Response	
COMPUTER LAB	Towards d	
Instance on Rooms 208, 217	Inspected	
Power Panel?	Yes	
Instance on Rooms 213, 303	Inspected	
Power Panel?	No	
Lighting		
Instance on Room 201	Inspected	
Instance on Rooms 208, 217	Inspected	
Instance on Rooms 213, 303	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 201	Inspected	
Instance on Rooms 208, 217	Inspected	
Instance on Rooms 213, 303	Inspected	
Pendant Mounted		
Instance on Room 201	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 208, 217	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 213, 303	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 201	Does not exist	
Instance on Rooms 208, 217	Does not exist	
Instance on Rooms 213, 303	Does not exist	
Recessed Mounted		
Instance on Room 201	Does not exist	
Instance on Rooms 208, 217	Does not exist	
Instance on Rooms 213, 303	Does not exist	
Lighting Fixture - HID		
Instance on Room 201	Does not exist	
Instance on Rooms 208, 217	Does not exist	
Instance on Rooms 213, 303	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 201	Does not exist	
Instance on Rooms 208, 217	Does not exist	
Instance on Rooms 213, 303	Does not exist	
Lighting Fixture - LED		
Instance on Room 201	Does not exist	
Instance on Rooms 208, 217	Does not exist	
Instance on Rooms 213, 303	Does not exist	
Raceway With Receptacles		
Instance on Room 201	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 208, 217	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Luctures on Booms 212, 202	Incorporated	

Inspected 3- Fair

No deficiencies recorded

Instance on Rooms 213, 303

Instance Condition
Deficiency

Question	Response
GYMNASIUM	Does not exist
KITCHEN	Does not exist
LIBRARY	Does not exist
LOCKER ROOM	Does not exist
MULTIPURPOSE ROOM	Inspected
Instance on 1st Floor	Inspected
Lighting	пърсски
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	<u> </u>
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Does not exist
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
SCIENCE DEMO ROOM	Inspected
Instance on Rooms 211, 311	Inspected
Power Panel?	No
Alternative Use	Yes
Lighting	
Instance on Rooms 211, 311	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 211, 311	Inspected
Pendant Mounted	
Instance on Rooms 211, 311	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	December 11
Instance on Rooms 211, 311	Does not exist
Recessed Mounted	December 11
Instance on Rooms 211, 311	Does not exist
Lighting Fixture - HID	Dogg mot projet
Instance on Rooms 211, 311	Does not exist
Lighting Fixture - Incandescent	Dogs not swist
Instance on Rooms 211, 311	Does not exist
Lighting Fixture - LED	

### **Building Condition Assessment Survey 2023-2024**

1		
Question	Response	
SCIENCE DEMO ROOM		
Emergency Gas Shut-Off Valve		
Instance on Rooms 211, 311	Does not exist	
Emergency Shut-Off Power		
Instance on Rooms 211, 311	Does not exist	
Power Supply		
Instance on Rooms 211, 311	Does not exist	
Projection System		
Instance on Rooms 211, 311	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	3- Fair	
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS	
Deficiency Location/Instance Deficiency Quantity	Boiler Room 1	
Denoted Quantity	1	

### **Building Condition Assessment Survey 2023-2024**

icui Inspection		MIUOI
uestion	Response	
EMERGENCY LIGHT/EXIT LIGHT PANEL		
Quantity Uom	EACH	
Potential Action	INSTALL NEW PANEL BOARD	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
- · · · · · · · · · · · · · · · · · · ·	Does not exist	
EXIT/EMERGENCY LIGHT		
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	

### **Building Condition Assessment Survey 2023-2024**

incui inspection		1/1001
Question	Response	
FIRE ALARM SYSTEM		
Main Panel		
Bell At Panel		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	EST 2	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2005	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Does not exist	
LAN	Inspected	
	Inspected	
Local Distribution Frame (I/LDF)  Condition	1- Good	
Deficiency	No deficiencies recorded	
	Inspected	
Main Equipment Rack (MDF)  Condition	1- Good	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	

uestion	Response
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	14
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Room 108
Deficiency Quantity	
	1 FACH
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	Room 101
Deficiency Quantity	
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 410
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Visiplex
Installation Year	2017
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 100A
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
	2000
Installation Year Source of Installation Year	
	Inspector Estimate
Deficiency	PANEL NOT CONNECTED TO EMERGENCY POWER SOURCE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 4

ical Inspection	Resnanse
SECURITY	Response
Intrusion Alarm System Central Control Panel	
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	
	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance	Exterior Walls - Building Perimeter
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
	Electrical Meter Room 004A
Instance Instance Condition	2- Between Good and Fair
-	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	Service Switch #1
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2011
Source of Installation Year	Documented  No deficiencies recorded
Deficiency	
SWITCHBOARD	Inspected
Number of Spares	1
Fused Disconnect Switch Type	Inspected
Instance	Boiler Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	MDP Section #1, 2, 3
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)

### **Building Condition Assessment Survey 2023-2024**

Duestion	Dognango	
zuestion – – – – – – – – – – – – – – – – – – –	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	